

# CONTENT

## Содержание

ALFA ROMEO .....	4	MITSUBISHI .....	41
AUDI .....	5	NISSAN .....	44
BMW .....	9	OPEL .....	46
CHERY .....	11	PEUGEOT .....	50
CHEVROLET .....	11	PORSCHE .....	53
CITROEN .....	11	RENAULT .....	53
DAEWOO .....	14	ROVER .....	56
DAIHATSU .....	15	SAAB .....	57
FIAT .....	15	SEAT .....	57
FORD .....	18	SKODA .....	60
GAZ .....	22	SSANGYONG .....	62
GREAT WALL .....	22	SUBARU .....	62
HONDA .....	22	SUZUKI .....	63
HYUNDAI .....	24	TOYOTA .....	64
INFINITI .....	26	UAZ .....	67
IZH .....	27	VOLKSWAGEN .....	67
ISUZU .....	27	VOLVO .....	73
JAGUAR .....	27	ZAZ .....	77
JEEP .....	27	Illustrations .....	78
KIA .....	27		
LADA .....	29	<b>Cross reference:</b>	
LANCIA .....	30	ATE - LYNXauto .....	138
LAND ROVER .....	31	Lucas/TRW - LYNXauto .....	139
LEXUS .....	32	Ferodo - LYNXauto .....	142
LIFAN .....	32	Kashiyama/Nissinbo .....	144
MAZDA .....	32	OE - LYNXauto .....	145
MERCEDES-BENZ .....	34	Application .....	151

## REMARKS

### Условные обозначения. сокращения

<b>ABS</b>	Антиблокировочная система
<b>EDS</b>	Система электронной блокировки дифференциала
<b>ESP</b>	Электронная система динамической стабилизации
<b>FWD</b>	Передний привод
<b>RWD</b>	Задний привод
<b>Automatic gear</b>	АКПП
<b>Manual gear</b>	МКПП
<b>Ch.N<sub>e</sub></b>	Номер кузова
<b>Disc rear brakes</b>	Задние тормоза - дисковые
<b>Drum rear brakes</b>	Задние тормоза - барабанные
<b>Fixed pin</b>	Фиксирующий штифт
<b>For a car with the extra load</b>	Для авто с повышенной нагрузкой
<b>Not for a car with the extra load</b>	Не для авто с повышенной нагрузкой
<b>Production (USA, Japan...)</b>	Страна-производитель
<b>Ventilated discs</b>	Вентилируемые диски
<b>Wear sensor</b>	Датчик износа
<b>With / without sports package</b>	С / без спорт-пакета (-ом)
<b>Without Electronic parking brake</b>	Без электронного стояночного тормоза
<b>With Electronic parking brake</b>	С электронным стояночным тормозом
<b>3-doors / 5-doors</b>	3-дверная / 5-дверная версия
<b>(1ZF,1ZM...)</b>	Вариант оснащения
<b>14" (15",16"...)</b>	Посадочный диаметр колесного диска

### BD-7501

└──────────────────┘ дисковые  
                          тормозные колодки





### BS-7501

└──────────────────┘ барабанные  
                          тормозные колодки





# • ALFA ROMEO



ALFA ROMEO					
<b>145</b>					
1.4 66kW	07/94-09/96	LUC	BD-2805		
1.4 76kW	01/97-01/01	ATE	BD-2801		
		LUC	BD-2805		
1.6 Twin Spark 88kW	11/00-10/01	ATE	BD-2801	LUC (ABS)	BD-2819
1.7 95kW	07/94-09/96	LUC	BD-2805	LUC	BD-2818
1.8 Twin Spark 103kW	10/96-02/99	ATE	BD-2802	LUC	BD-2819
1.9 TD	07/94-09/96	LUC	BD-2805	LUC	BD-2818
1.9 TD 66kW	01/97-02/99	ATE	BD-2801	LUC (ABS)	BD-2819
		ATE	BD-2802		
1.9 JTD 77kW	03/99-10/01	ATE	BD-2802	LUC (ABS)	BD-2819
2.0 110kW	10/95-10/01	ATE	BD-2803	LUC	BD-2818
				LUC (10/96>)	BD-2819
<b>146</b>					
1.4 66kW	05/95-01/01	LUC (>09/96)	BD-2805		
		ATE (10/96>)	BD-2801		
1.6 76kW	05/95-01/01	LUC (>09/96)	BD-2805		
		ATE (10/96>)	BD-2801		
1.7 95kW	05/95-09/96	LUC	BD-2805	LUC	BD-2818
1.8 Twin Spark 103kW	10/96-10/01	ATE (>02/99)	BD-2802	LUC	BD-2818
		ATE	BD-2803	LUC	BD-2819
1.9 D 66kW	07/94-02/99	LUC (>09/96)	BD-2805	LUC	BD-2818
		ATE (10/96>)	BD-2802		
1.9 D 77kW	03/99-10/01	ATE	BD-2802	LUC	BD-2819
2.0 110kW	10/95-10/01	ATE (>09/96)	BD-2803	LUC	BD-2818
		ATE (10/96>)	BD-2803	LUC	BD-2819
<b>147</b>					
1.6 Twin Spark 76kW	10/00-02/01	ATE	BD-2825	LUC	BD-2827
1.6 Twin Spark 88kW	10/00-	ATE	BD-2803	LUC	BD-2827
1.9 D	10/00-	ATE	BD-2803	LUC	BD-2827
2.0 110kW	10/00-	ATE	BD-2803	LUC	BD-2827
<b>156</b>					
1.6 Twin Spark 88kW	11/97-09/05	ATE (>04/00)	BD-2803	LUC	BD-2824
		ATE (05/00-02/01)	BD-2825		
		ATE (03/01>)	BD-2803		
1.8 Twin Spark 106kW	11/97-09/05	ATE (>04/00)	BD-2803	LUC	BD-2824
		ATE (05/00-02/01)	BD-2825		
		ATE (03/01>)	BD-2803		
1.9 JTD 81kW	05/00-09/05	ATE (>02/01)	BD-2825	LUC	BD-2824
		ATE (03/01>)	BD-2803		
2.0 Twin Spark 110/122kW	05/00-09/05	ATE	BD-2803	LUC	BD-2824
<b>166</b>					
2.0 Twin Spark 114kW	08/98-	ATE	BD-2822	LUC	BD-2824
2.0 Turbo 151kW	08/98-	BRE	BD-2823	LUC	BD-2824
2.4 D	08/98-	ATE	BD-2822	LUC	BD-2824
2.5 V6 24V	08/98-	BRE	BD-2823	LUC	BD-2824
3.0 V6 162kW	08/98-	BRE	BD-2823	LUC	BD-2824
<b>Spider</b>					
1.8 106kW	06/00-	ATE	BD-2803	LUC	BD-2819
2.0 Twin Spark 110kW	08/95-08/97	ATE	BD-2803	LUC	BD-2818
2.0 V6 Turbo/Twin Spark	09/97-	ATE	BD-2803	LUC	BD-2819
3.0 V6 141kW	08/95-08/01	ATE	BD-2803	LUC	BD-2818





							
<b>AUDI</b>							
<b>80</b>							
1.6 51/55kW	09/86-08/91	LUC	BD-1201				
		LUC (wear sensor)	BD-1207				
1.6 75kW	08/89-07/92	LUC	BD-1201	LUC			BD-1208
		LUC (wear sensor)	BD-1207				
1.6 52kW	08/92-07/93	LUC	BD-1201	LUC			BD-1208
		LUC (wear sensor)	BD-1201				
1.6 74kW	08/93-07/96	LUC	BD-1205	LUC			BD-1208
1.6 D 59kW	08/89-08/91	LUC	BD-1201				
		LUC (wear sensor)	BD-1207				
1.8 GTE/E 81/82kW	09/86-08/91	LUC	BD-1201	LUC			BD-1208
		LUC (wear sensor)	BD-1207				
1.9 TD/TDi 55/66kW	09/91-01/96	LUC (>07/93)	BD-1201	LUC			BD-1208
		LUC (08/93->)	BD-1205				
2.0 82kW	08/89-08/91	LUC	BD-1201	LUC			BD-1208
		LUC (wear sensor)	BD-1207				
2.0 66kW	09/91-12/94	LUC (>07/93)	BD-1201	LUC			BD-1208
		LUC (08/93->)	BD-1205				
2.0 E 85/103kW	08/93-07/96	LUC	BD-1205	LUC			BD-1208
2.3 E 98kW	09/91-12/94	LUC (>07/93)	BD-1201	LUC			BD-1208
		LUC (08/93->)	BD-1205				
2.6 E 110kW	08/92-07/96	LUC (>07/93)	BD-1201	LUC			BD-1208
		LUC (08/93->)	BD-1205				
<b>100</b>							
2.0 74kW	12/90-07/93	ATE	BD-1209				
2.0 E 85/103kW	08/92-07/94	ATE	BD-1209	LUC			BD-1208
2.2 Turbo 121kW	08/84-11/90	LUC	BD-1207	LUC			BD-1208
2.3 100kW	08/86-11/90	LUC (14")	BD-1207	LUC			BD-1208
2.3 E 98kW	12/90-07/94	ATE	BD-1209	LUC			BD-1208
2.4 D 60kW	12/90-07/93	ATE	BD-1209				BD-1208
2.5 TDi 85kW	12/90-07/94	ATE	BD-1209	LUC			BD-1208
2.6 110kW	08/92-07/94	ATE	BD-1209	LUC			BD-1208
2.8 128kW	08/91-07/94	ATE	BD-1209	LUC			BD-1208
<b>100 Quattro</b>							
1.8 66kW	09/84-11/90	LUC	BD-1207	LUC			BD-1208
2.0 85/103kW	08/91-07/94	ATE	BD-1209	LUC			BD-1208
2.2 121kW	09/84-07/86	LUC	BD-1207	LUC			BD-1208
2.2 S4 Turbo 169kW	08/93-06/94	ATE	BD-1210	LUC			BD-1208
2.3 E 98kW	12/90-07/94	ATE	BD-1209	LUC			BD-1208
2.6 110kW	08/92-07/94	ATE	BD-1209	LUC			BD-1208
2.8 128kW	08/91-07/94	ATE	BD-1209	LUC			BD-1208
4.2 S4 V8 206kW	10/92-07/94	LUC	BD-1210	LUC			BD-1208
<b>A2</b>							
1.2 TDi 45kW	03/01-08/05	ATE	BD-1211				
1.4 55kW	02/00-08/05	ATE	BD-1202				
<b>A3 (8L1)</b>							
1.6 74kW	07/96-05/03	ATE (>03/99)	BD-8003	LUC			BD-1206
		KEL (04/99->)	BD-1202				
1.8 92kW	09/96-05/03	ATE (>03/99)	BD-8003	LUC			BD-1206
		KEL (04/99->)	BD-1202				
1.8 Turbo 110kW	07/96-05/03	ATE (>03/99)	BD-1213	LUC			BD-1206
		ATE (04/99->)	BD-1212				
1.9 TDi	07/96-05/03	ATE (>03/99)	BD-8003	LUC			BD-1206
		KEL (04/99->)	BD-1202				





• AUDI

					
<b>A3 II (8P1 / 8PA)</b>					
1.6 75/85kW	03/03 -	ATE (1ZM,1ZF)	<b>BD-1202</b>	LUC (1KQ,1KD)	<b>BD-1206</b>
		ATE (1ZE,1ZD,1LJ,1ZP)	<b>BD-1203</b>	LUC (1KZ,1KJ,1KE,1KF)	<b>BD-1204</b>
		ATE (1LK)	<b>BD-8016</b>		
1.8 TFSI 118kW	03/03 -	ATE (1ZM,1ZF)	<b>BD-1202</b>	LUC (1KQ,1KD)	<b>BD-1206</b>
		ATE (1ZE,1ZD,1LJ,1ZP)	<b>BD-1203</b>	LUC (1KZ,1KJ,1KE,1KF)	<b>BD-1204</b>
		ATE (1LK)	<b>BD-8016</b>		
1.9 TDi 77kW	03/03 -	ATE (1ZM,1ZF)	<b>BD-1202</b>	LUC (1KQ,1KD)	<b>BD-1206</b>
		ATE (1ZE,1ZD,1LJ,1ZP)	<b>BD-1203</b>	LUC (1KZ,1KJ,1KE,1KF)	<b>BD-1204</b>
		ATE (1LK)	<b>BD-8016</b>		
2.0 FSI 110kW	03/03 -	ATE (1ZM,1ZF)	<b>BD-1202</b>	LUC (1KQ,1KD)	<b>BD-1206</b>
		ATE (1ZE,1ZD,1LJ,1ZP)	<b>BD-1203</b>	LUC (1KZ,1KJ,1KE,1KF)	<b>BD-1204</b>
		ATE (1LK)	<b>BD-8016</b>		
2.0 TDi 100/103kW	03/03-	ATE (1ZM,1ZF)	<b>BD-1202</b>	LUC (1KQ,1KD)	<b>BD-1206</b>
		ATE (1ZE,1ZD,1LJ,1ZP)	<b>BD-1203</b>	LUC (1KZ,1KJ,1KE,1KF)	<b>BD-1204</b>
<b>A4 (8D2, B5)</b>					
1.6 74kW	07/95-11/00	LUC (>07/97)	<b>BD-1205</b>	LUC (>02/97)	<b>BD-1208</b>
		LUC (08/97-02/99)	<b>BD-1214</b>	LUC (03/97>)	<b>BD-1206</b>
		LUC (1LZ)	<b>BD-1215</b>		
1.8 85/92kW	07/95-11/00	LUC (>07/97)	<b>BD-1205</b>	LUC (>02/97)	<b>BD-1208</b>
		LUC (08/97-02/99)	<b>BD-1214</b>	LUC (03/97>)	<b>BD-1206</b>
		LUC (1LZ)	<b>BD-1215</b>		
1.8 T 110kW	03/99-11/00	ATE	<b>BD-1216</b>	LUC	<b>BD-1206</b>
1.9 TDI	07/95-11/00	LUC (>07/97)	<b>BD-1205</b>	LUC (>02/97)	<b>BD-1208</b>
		LUC (08/97-02/99)	<b>BD-1214</b>	LUC (03/97>)	<b>BD-1206</b>
		LUC (1LZ)	<b>BD-1215</b>		
2.4 120kW	08/97-11/00	ATE (>02/99)	<b>BD-1213</b>	LUC (>02/99)	<b>BD-8002</b>
		ATE (03/99>)	<b>BD-1216</b>	LUC (03/99>)	<b>BD-1206</b>
2.5 TDI 110kW	08/97-11/00	ATE (>02/99)	<b>BD-1213</b>	LUC	<b>BD-1206</b>
		ATE (03/99>)	<b>BD-1216</b>		
2.6 110kW	10/94-11/00	LUC	<b>BD-1215</b>	LUC (>02/97)	<b>BD-1208</b>
		ATE (03/99>)	<b>BD-1216</b>	LUC (03/97>)	<b>BD-8002</b>
2.8 128kW	10/94-07/97	ATE	<b>BD-1213</b>	LUC	<b>BD-1208</b>
2.8 142kW	08/97-11/00	ATE (>02/99)	<b>BD-1213</b>	LUC (>02/99)	<b>BD-8002</b>
		ATE (03/99>)	<b>BD-1216</b>	LUC (03/99>)	<b>BD-1206</b>
<b>A4 (8E2, B6)</b>					
1.6 75kW	11/00-10/04	LUC (1LZ)	<b>BD-1215</b>	LUC (1KD,1KP)	<b>BD-1206</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b>		
1.8 T 110-140kW	11/00-10/04	LUC (1LZ)	<b>BD-1215</b>	LUC (1KD,1KP)	<b>BD-1206</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b>		
1.9 TDI 74kW	04/01-10/04	LUC (1LZ)	<b>BD-1215</b>	LUC (1KD,1KP)	<b>BD-1206</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b>		
2.0 96kW	11/00-10/04	LUC (1LZ)	<b>BD-1215</b>	LUC (1KD,1KP)	<b>BD-1206</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b>		
2.0 FSI 110kW	11/00-10/04	LUC (1LZ)	<b>BD-1215</b>	LUC (1KD,1KP)	<b>BD-1206</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b>		
2.4 120/125kW	04/01-10/04	LUC (1LZ)	<b>BD-1215</b>	LUC (1KD,1KP)	<b>BD-1206</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b>		
2.5 TDI 114kW	04/01-10/04	LUC (1LZ)	<b>BD-1215</b>	LUC (1KD,1KP)	<b>BD-1206</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b>		
3.0 V6 162kW	11/00-12/04	LUC (1LZ)	<b>BD-1215</b>	LUC (1KD,1KP)	<b>BD-1206</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b>		
<b>A4 (8EC)</b>					
1.8 T 120kW	11/04-11/07	LUC (1LZ)	<b>BD-1215</b>	LUC (1KW)	<b>BD-1204</b>
		ATE (1LA, 1LC)	<b>BD-1217</b>	LUC (1KD,1KP)	<b>BD-1206</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b>		





			
1.9 TDI 85kW	11/04-11/07	LUC (1LZ)	<b>BD-1215</b> LUC (1KW) <b>BD-1204</b>
		ATE (1LA, 1LC)	<b>BD-1217</b> LUC (1KD,1KP) <b>BD-1206</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b>
2.0 96kW	11/04-11/07	LUC (1LZ)	<b>BD-1215</b> LUC (1KW) <b>BD-1204</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b> LUC (1KD,1KP) <b>BD-1206</b>
		ATE (1LA, 1LC)	<b>BD-1217</b>
2.0 TFSI 147kW	11/04-11/07	LUC (1LZ)	<b>BD-1215</b> LUC (1KW) <b>BD-1204</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b> LUC (1KD,1KP) <b>BD-1206</b>
		ATE (1LA, 1LC)	<b>BD-1217</b>
2.5 TDI 120kW	11/04-11/07	LUC (1LZ)	<b>BD-1215</b> LUC (1KW) <b>BD-1204</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b> LUC (1KD,1KP) <b>BD-1206</b>
		ATE (1LA, 1LC)	<b>BD-1217</b>
3.0 TDI 150kW	11/04-11/07	LUC (1LZ)	<b>BD-1215</b> LUC (1KW) <b>BD-1204</b>
		ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b> LUC (1KD,1KP) <b>BD-1206</b>
		ATE (1LA, 1LC)	<b>BD-1217</b>
<b>A4 (8K2)</b>			
1.8 TFSI 88kW	01/08-	ATE (1LA)	<b>BD-1219</b> LUC <b>BD-1223</b>
		ATE (1LT)	<b>BD-1220</b>
		ATE (1LJ)	<b>BD-1221</b>
1.8 TFSI 118kW	01/08-	ATE (1LA)	<b>BD-1219</b> LUC <b>BD-1223</b>
		ATE (1LT)	<b>BD-1220</b>
		ATE (1LJ)	<b>BD-1221</b>
2.0 TFSI 132kW	06/08-	ATE (1LA)	<b>BD-1219</b> LUC <b>BD-1223</b>
		ATE (1LT)	<b>BD-1220</b>
		ATE (1LJ)	<b>BD-1221</b>
<b>A5 (8T)</b>			
1.8 TFSI	05/09-	ATE (1LA)	<b>BD-1219</b> LUC <b>BD-1223</b>
		ATE (1LT)	<b>BD-1220</b>
		ATE (1LJ)	<b>BD-1221</b>
2.0 TDI	05/09-	ATE (1LA)	<b>BD-1219</b> LUC <b>BD-1223</b>
		ATE (1LT)	<b>BD-1220</b>
		ATE (1LJ)	<b>BD-1221</b>
2.0 TFSI 132kW	05/09-	ATE (1LA)	<b>BD-1219</b> LUC <b>BD-1223</b>
		ATE (1LT)	<b>BD-1220</b>
		ATE (1LJ)	<b>BD-1221</b>
<b>A6 (4A, C4)</b>			
1.8 92kW	08/95-01/98	ATE	<b>BD-1209</b> LUC <b>BD-1208</b>
1.9 TDI 66kW	06/94-01/98	ATE	<b>BD-1209</b> LUC <b>BD-1208</b>
2.0 16V 103kW	06/94-01/98	ATE	<b>BD-1209</b> LUC <b>BD-1208</b>
2.3 98kW	06/94-01/96	ATE	<b>BD-1209</b> LUC <b>BD-1208</b>
2.5 TDI 85/103kW	06/94-05/97	ATE	<b>BD-1209</b> LUC <b>BD-1208</b>
2.6 102/110kW	06/94-10/97	ATE	<b>BD-1209</b> LUC <b>BD-1208</b>
2.8 142kW	06/94-04/97	ATE	<b>BD-1209</b> LUC <b>BD-1208</b>
<b>A6 (4B, C5)</b>			
1.8 85kW	05/97-10/00	ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b> LUC <b>BD-1206</b>
1.8 T 110/132kW	11/00-12/04	ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b> LUC <b>BD-1206</b>
1.9 TDI 81-96kW	05/97-01/05	ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b> LUC <b>BD-1206</b>
2.0 96kW	06/01-12/04	ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b> LUC <b>BD-1206</b>
2.4 100-125kW	05/97-12/04	ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b> LUC <b>BD-1206</b>
2.5 TDI 110-132kW	05/97-12/04	ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b> LUC <b>BD-1206</b>
2.7 T 169/184kW	02/99-01/05	LUC (1LX ; >4BX060000)	<b>BD-1210</b> LUC <b>BD-1206</b>
		LUC (1LX; 4BX060000 >)	<b>BD-1218</b>
2.8 142kW	05/97-01/05	ATE (1LB, 1LE, 1LF, 1LT)	<b>BD-1216</b> LUC <b>BD-1206</b>
		LUC (1LX; 4BX060000 >)	<b>BD-1218</b>

• AUDI

				
<b>A6 (4F2)</b>				
2.0 TDI 103kW	05/04-	ATE (1LT)	<b>BD-1216</b> LUC (1KD)	<b>BD-1204</b>
		ATE (1ZL,1LH,1LA,1LC)	<b>BD-1217</b> LUC (1KQ)	<b>BD-8030</b>
		ATE (1LJ)	<b>BD-1222</b>	
2.0 TFSI 125kW	06/05-	ATE (1LT)	<b>BD-1216</b> LUC (1KD)	<b>BD-1204</b>
		ATE (1LG, 1LD, 1ZL, 1LH)	<b>BD-1217</b> LUC (1KQ)	<b>BD-8030</b>
		ATE (1LJ)	<b>BD-1222</b>	
2.4 130kW	05/04-	ATE (1LT)	<b>BD-1216</b> LUC (1KD)	<b>BD-1204</b>
		ATE (1LG,1LD,1ZL,1LH)	<b>BD-1217</b> LUC (1KQ)	<b>BD-8030</b>
		ATE (1LJ)	<b>BD-1222</b>	
2.7 TDI 132kW	11/04-	ATE (1LT)	<b>BD-1216</b> LUC (1KD)	<b>BD-1204</b>
		ATE (1LG,1LD,1ZL,1LH)	<b>BD-1217</b> LUC (1KQ)	<b>BD-8030</b>
		ATE (1LJ)	<b>BD-1222</b>	
3.2 FSI 188kW	05/04-	ATE (1LT)	<b>BD-1216</b> LUC (1KD)	<b>BD-1204</b>
		ATE (1LG,1LD,1ZL,1LH)	<b>BD-1217</b> LUC (1KQ)	<b>BD-8030</b>
		ATE (1LJ)	<b>BD-1222</b>	
<b>A8 (4D2 / 4D8)</b>				
2.5 TDI V6 24V 110kW	06/97-05/00	LUC (>09/98)	<b>BD-1210</b> LUC (>09/98)	<b>BD-1208</b>
		LUC (10/98>)	<b>BD-1218</b> LUC (10/98>)	<b>BD-1206</b>
2.8 128kW	06/94-05/00	LUC (>09/98)	<b>BD-1210</b> LUC (>09/98)	<b>BD-1208</b>
		LUC (10/98>)	<b>BD-1218</b> LUC (10/98>)	<b>BD-1206</b>
3.7 32V 169kW	07/95-09/98	LUC	<b>BD-1210</b> LUC	<b>BD-1208</b>
3.7 V8 40V 191kW	10/98-10/02	LUC	<b>BD-1218</b> LUC	<b>BD-1206</b>
4.2 V8	10/98-10/02	LUC	<b>BD-1218</b> LUC	<b>BD-1206</b>
<b>A8 (4E)</b>				
3.7 Quattro 206kW	10/02-08/10	ATE (1LG)	<b>BD-1217</b> LUC	<b>BD-1224</b>
		ATE (1LL,1LM,1LJ,1LK)	<b>BD-1222</b>	
4.0 TDI Quattro 202kW	10/02-08/10	ATE (1LG)	<b>BD-1217</b> LUC	<b>BD-1224</b>
		ATE (1LL,1LM,1LJ,1LK)	<b>BD-1222</b>	
4.2 V8 Quattro 246kW	10/02-08/10	ATE (1LG)	<b>BD-1217</b> LUC	<b>BD-1224</b>
		ATE (1LL,1LM,1LJ,1LK)	<b>BD-1222</b>	
<b>Cabriolet</b>				
1.8 92kW	04/97-08/00	LUC	<b>BD-1205</b> LUC	<b>BD-1208</b>
1.9 D 66kW	05/95-08/00	LUC	<b>BD-1205</b> LUC	<b>BD-1208</b>
2.0 85kW	01/93-10/98	LUC	<b>BD-1205</b> LUC	<b>BD-1208</b>
2.3 E 98kW	05/91-07/94	LUC (>07/92)	<b>BD-1201</b> LUC	<b>BD-1208</b>
		LUC (08/92>)	<b>BD-1205</b>	
2.6 110kW	08/93-08/00	LUC	<b>BD-1205</b> LUC	<b>BD-1208</b>
<b>Coupe</b>				
1.8 82kW	08/88-07/91	LUC	<b>BD-1201</b> LUC	<b>BD-1208</b>
2.0 85kW	08/89-07/93	LUC	<b>BD-1201</b> LUC	<b>BD-1208</b>
2.0 103kW	08/94-06/96	LUC	<b>BD-1205</b> LUC	<b>BD-1208</b>
2.2 E 100kW	08/88-07/92	LUC	<b>BD-1201</b> LUC	<b>BD-1208</b>
2.3 E 98/125kW	08/88-07/94	LUC	<b>BD-1201</b> LUC	<b>BD-1208</b>
2.6 110kW	08/94-05/96	LUC	<b>BD-1205</b> LUC	<b>BD-1208</b>
<b>Q5</b>				
2.0 TFSI	11/08-	ATE (1LA,1LJ,1LP,1ZB)	<b>BD-1219</b> LUC (1KE,1KW)	<b>BD-1223</b>
2.0 TDI	11/08-	ATE (1LA,1LJ,1LP,1ZB)	<b>BD-1219</b> LUC (1KE,1KW)	<b>BD-1223</b>
3.2 FSI	11/08-	ATE (1LA,1LJ,1LP,1ZB)	<b>BD-1219</b> LUC (1KE,1KW)	<b>BD-1223</b>
<b>Q7</b>				
3.0 TDI 171kW	05/06-	BRE	<b>BD-8019</b> LUC (1KF)	<b>BD-8007</b>
3.6 FSI 206kW	05/06-	BRE	<b>BD-8019</b> LUC (1KF)	<b>BD-8007</b>
4.2 FSI 257kW	05/06-	BRE	<b>BD-8019</b> LUC (1KF)	<b>BD-8007</b>
<b>TT</b>				
1.8 T 110/132kW	10/98-	ATE (>07/99)	<b>BD-1213</b> LUC	<b>BD-1206</b>
		ATE	<b>BD-1212</b>	





			
<b>BMW</b>			
<b>1 (E81)</b>			
116i 85/90kW	10/04-	LUC	<b>BD-1429</b> ATE <b>BD-1430</b>
118i 95kW	10/04-	LUC	<b>BD-1429</b> ATE <b>BD-1430</b>
118 D 90kW	10/04-	LUC	<b>BD-1429</b> <b>BD-1430</b>
		ATE	<b>BD-1422</b>
120i 110kW	10/04-	ATE (>02/06)	<b>BD-1422</b> <b>BD-1430</b>
		LUC (02/06>)	<b>BD-1429</b>
<b>3 (E30)</b>			
316i 74/75kW	05/87-08/90	LUC	<b>BD-1404</b> ATE (+ ABS) <b>BD-1405</b>
318 77/85kW	08/82-04/91	LUC	<b>BD-1404</b> ATE (+ ABS) <b>BD-1405</b>
320 92/95kW	09/82-04/91	LUC	<b>BD-1404</b> ATE (+ ABS) <b>BD-1405</b>
324 D/TD 63/85kW	09/88-04/91	LUC	<b>BD-1404</b> ATE <b>BD-1405</b>
<b>3 (E36)</b>			
316i 73/75kW	09/90-01/98	ATE	<b>BD-1406</b> ATE (+ ABS) <b>BD-1407</b>
318i 83/85kW	09/90-01/98	ATE	<b>BD-1406</b> ATE (+ ABS) <b>BD-1407</b>
318 is 103kW	11/95-01/98	ATE	<b>BD-1406</b> ATE (+ ABS) <b>BD-1407</b>
320i 110kW	09/90-01/98	ATE	<b>BD-1406</b> ATE <b>BD-1407</b>
323i 2.5 125kW	08/94-01/98	ATE	<b>BD-1406</b> ATE <b>BD-1407</b>
325 141kW	09/90-09/95	ATE	<b>BD-1406</b> ATE <b>BD-1407</b>
325 TD 85kW	09/90-01/98	ATE	<b>BD-1406</b> ATE <b>BD-1407</b>
<b>3 (E46)</b>			
316i 77/85kW	02/98-02/05	ATE	<b>BD-1408</b> ATE <b>BD-6501</b>
318i 87kW	02/98-02/05	ATE	<b>BD-1408</b> ATE <b>BD-6501</b>
318i 105kW	09/01-02/05	ATE	<b>BD-1408</b> ATE <b>BD-6501</b>
318 D 85 kW	02/98-02/05	ATE	<b>BD-1408</b> ATE <b>BD-6501</b>
320i 110kW	02/98-07/00	ATE	<b>BD-1408</b> ATE <b>BD-6501</b>
320 D 100/110kW	02/98-02/05	ATE	<b>BD-1408</b> ATE <b>BD-6501</b>
320i 125kW	08/00-02/05	ATE	<b>BD-1408</b> ATE <b>BD-6501</b>
323i 125kW	02/98-07/00	ATE	<b>BD-1408</b> ATE <b>BD-6501</b>
325i 141kW	08/00-02/05	ATE	<b>BD-1408</b> ATE <b>BD-6501</b>
330i 170kW	09/99-02/05	ATE	<b>BD-1410</b> ATE <b>BD-1403</b>
<b>3 (E90)</b>			
316i	01/05-	ATE (Eng. N43, N45N)	<b>BD-1421</b> ATE (Eng. N43, N45N) <b>BD-1430</b>
		ATE (Eng. N45)	<b>BD-1422</b>
318i 95kW	09/05-	ATE (Eng. N43, N46N; not for a car with the extra load; RUS)	<b>BD-1421</b> ATE (Eng. N43, N46N) <b>BD-1420</b>
		ATE (Eng. N46; not for a car with the extra load)	<b>BD-1422</b> ATE (Eng. N46) <b>BD-1430</b>
		ATE (Eng. N46N; for a car with the extra load; RUS)	<b>BD-1423</b>
		ATE (Eng. N46; for a car with the extra load)	<b>BD-1414</b>
318 D 90kW	09/07-	ATE (Eng. N47)	<b>BD-1421</b> ATE (Eng. N47) <b>BD-1420</b>
		ATE (Eng. M47N)	<b>BD-1422</b> ATE (Eng. M47N) <b>BD-1430</b>
		ATE (Eng. M47N; for a car with the extra load)	<b>BD-1414</b>
320i 110kW	01/05-	ATE (Eng. N43, N46N; not for a car with the extra load; RUS)	<b>BD-1421</b> ATE (Eng. N43, N46N; RUS) <b>BD-1420</b>
		ATE (Eng. N46; for a car with the extra load)	<b>BD-1422</b> ATE (Eng. N46; RUS) <b>BD-1430</b>
		ATE (Eng. N46N)	<b>BD-1423</b>
		ATE (Eng. N46; for a car with the extra load)	<b>BD-1414</b>
325i 160kW	01/05-	ATE (Eng. N52N, N53)	<b>BD-1423</b> <b>BD-1420</b>
		ATE (Eng. N52, N52N, N53; for a car with the extra load)	<b>BD-1414</b>
330i 190kW	09/05-	ATE (Eng. N52, N52N)	<b>BD-1414</b>
<b>5 (E34)</b>			
518i 83/85kW	04/89-10/95	ATE	<b>BD-1411</b> ATE <b>BD-1412</b>
520i 95/110kW	01/88-10/95	ATE	<b>BD-1411</b> ATE <b>BD-1412</b>
525i 125/141kW	01/88-10/95	ATE	<b>BD-1411</b> ATE <b>BD-1412</b>
525 TD 85/105kW	11/90-10/95	ATE	<b>BD-1411</b> ATE <b>BD-1412</b>
530i 138kW	01/88-10/95	ATE	<b>BD-1411</b> ATE <b>BD-1412</b>
535i 155kW	02/88-10/95	ATE	<b>BD-1411</b> ATE <b>BD-1412</b>

• **BMW**





			
<b>5 (E34)</b>			
540i 210kW	03/92-10/92	ATE	BD-1411 ATE BD-1412
<b>5 (E39)</b>			
520i 110kW	11/95-06/03	ATE (Eng. M52; >10/96)	BD-1410 ATE BD-1413
		ATE (Eng. M52; 10/96>)	BD-1424
520i 125kW	08/00-06/03	ATE (Eng. M54)	BD-1424 ATE BD-1413
520 D 100kW	09/99-06/03	ATE	BD-1424 ATE BD-1413
523i 125kW	11/95-07/00	ATE (>10/96)	BD-1410 ATE BD-1413
		ATE (10/96>)	BD-1424
525i 141kW	08/00-06/03	ATE	BD-1424 ATE BD-1413
525 TD 85/105kW	11/95-06/03	ATE (>10/96)	BD-1410 ATE BD-1413
		ATE (10/96>)	BD-1424
528i 142kW	11/95-06/03	ATE (>10/96)	BD-1410 ATE BD-1413
		ATE (10/96>)	BD-1424
530i 170kW	08/00-06/03	ATE	BD-1401 ATE BD-1413
530 D 135/142kW	05/98-06/03	ATE (>09/00)	BD-1424 ATE BD-1413
		ATE (09/00>)	BD-1401
535i 173/180kW	11/95-06/03	ATE (>10/96)	BD-1410 ATE BD-1413
		ATE (10/96>)	BD-1401
540i 210kW	11/95-06/03	ATE	BD-1401 ATE BD-1413
<b>5 (E60)</b>			
520i 125kW	07/03-	ATE (MT)	BD-1414 ATE BD-1419
		ATE (AT)	BD-1415
523i 130kW	07/05-	ATE	BD-1414 ATE BD-1419
		ATE (for a car with the extra load)	BD-1415
525i 141kW	09/03-	ATE	BD-1414 ATE BD-1419
		ATE (for a car with the extra load)	BD-1415
525i 160kW	09/03-	ATE (N52; RUS)	BD-1415 ATE BD-1419
530i 170kW	07/03-	ATE	BD-1415 ATE BD-1419
530i 190kW	07/03-	ATE	BD-1415 ATE BD-1419
540i 225kW	07/05-	ATE	BD-1415 ATE BD-1425
545i 245kW	09/03-	ATE	BD-1415 ATE BD-1425
<b>730 (E32)</b>			
730i 145kW	07/86-05/94	ATE	BD-1411 ATE BD-1412
735i 155kW	07/86-08/92	ATE	BD-1411 ATE BD-1412
740i 210kW	09/91-05/94	ATE	BD-1411 ATE BD-1412
<b>7 (E38)</b>			
725 D 105kW	02/96-05/00	ATE	BD-1416 ATE BD-1403
728i 142kW	11/95-11/01	ATE	BD-1416 ATE BD-1403
730i 160kW	06/94-11/01	ATE	BD-1416 ATE BD-1403
730 D 135/142kW	05/98-11/01	ATE	BD-1416 ATE BD-1403
735i 173kW	11/95-11/01	ATE	BD-1416 ATE BD-1403
740i 210kW	03/96-11/01	ATE	BD-1401 ATE BD-1403
<b>7 (E65)</b>			
730i 170kW	03/03-	ATE	BD-1415 ATE BD-1426
730i 190kW	03/03-	ATE	BD-1415 ATE BD-1426
730 D 160/170kW	10/02-	ATE	BD-1415 ATE BD-1426
735i 200kW	11/01-	ATE	BD-1415 ATE BD-1426
740i 225kW	07/05-	ATE	BD-1415 ATE BD-1426
740 D 190kW	10/02-	ATE	BD-1415 ATE BD-1425
745i 245kW	11/01-	ATE	BD-1415 ATE BD-1425
<b>X3 (E83)</b>			
2.0 110kW	07/05-	ATE	BD-1427 ATE BD-1403
2.0 D 110kW	10/04-	ATE	BD-1427 ATE BD-1403
2.5 141kW	01/04-	ATE	BD-1427 ATE BD-1403
3.0 170kW	01/04-	ATE	BD-1427 ATE BD-1403







• BMW — CHERY — CHEVROLET — CITROEN





				
3.0 D 160kW	01/04-	ATE	BD-1427 ATE	BD-1403
<b>X5 (E53)</b>				
3.0 163/170kW	07/00-02/07	ATE	BD-1401 ATE	BD-1403
3.0 D 135kW	05/01-02/07	ATE	BD-1401 ATE	BD-1403
4.4 210kW	07/00-02/07	ATE	BD-1401 ATE	BD-1403
<b>X5 (E70)</b>				
3.0 200kW	02/07-	ATE	BD-1417 ATE	BD-1428
3.0 D 173kW	02/07-	ATE	BD-1417 ATE	BD-1428
3.0 SD 210kW	02/07-	ATE	BD-1417 ATE (10/09>)	BD-1428
3.5 D 210kW	10/08-	ATE	BD-1417 ATE	BD-1428
4.8 261kW	02/07-	ATE	BD-1418	BD-1425
<b>CHERY</b>				
<b>Amulet</b>				
1.6 69kW	10/06-	ATE	BD-1201	
<b>Tiggo</b>				
2.0 (4G63)	06/05-	LUC	BD-1205	BD-7510
<b>CHEVROLET</b>				
<b>Aveo</b>				
1.2 53kW	02/05-11/11	AKE	BD-1803	
1.4 69kW	02/05-11/11	AKE	BD-1803	
1.5 62kW	02/05-11/11	AKE	BD-1803	
<b>Aveo</b>				
1.4 75kW	12/11-		BD-1810	
1.6 85kW	12/11-		BD-1810	
<b>Cruze</b>				
1.6 80kW	06/09-	ATE (15")	BD-1810	BD-1811
		ATE (16")	BD-1813	
1.8 104kW	06/09-	ATE (15")	BD-1810	BD-1811
		ATE (16")	BD-1813	
<b>Epica</b>				
2.0 94/105kW	05/05-	SUM	BD-1808	MAN
		AKE	BD-1812	
2.5 115kW	06/06-	SUM	BD-1808	MAN
		AKE	BD-1812	
<b>Lanos</b>				
1.5	03/05-		BD-1801	BS-1800
1.6 16V	03/05-		BD-1805	BS-1800
<b>Lacetti</b>				
1.4 16V 70kW	03/05-		BD-1805	BD-1807
1.6 80kW	03/05-		BD-1805	BD-1807
1.8 90kW	03/05-		BD-1805	BD-1807
<b>Niva</b>				
1.7 61kW	08/02-		BD-4602	BS-4602
1.8 16V 92kW	08/04-		BD-4602	BS-4602
<b>Rezzo</b>				
1.6 77/79kW	03/05-		BD-1805	
2.0 89/90kW	03/05-		BD-1805	
<b>Spark</b>				
0.8 37kW	05/05-	AKE	BD-1801	BS-1801
1.0 46kW	05/05-	AKE	BD-1801	BS-1801
<b>Trans Sport</b>				
3.4 138kW	11/96-	MAN	BD-5924	
<b>CITROEN</b>				
<b>Berlingo</b>				
1.1 44kW	07/96-	LUC (>10/01)	BD-2203	
		BOS (10/01>)	BD-2201	





# • CITROEN

				
<b>Berlingo</b>				
1.4 55kW	07/96-	LUC (>10/01)	<b>BD-2203</b>	
		BOS (10/01>)	<b>BD-2201</b>	
1.6 80kW	10/00-	LUC (>10/01)	<b>BD-2203</b>	
		BOS (10/01>)	<b>BD-2201</b>	
		BOS (+ESP)	<b>BD-2202</b>	
1.6 HDi 55/66kW	07/05-	BOS	<b>BD-2201</b>	
		BOS (+ESP)	<b>BD-2202</b>	
1.8 66kW	05/97-	LUC (>10/01)	<b>BD-2203</b>	
		BOS (10/01>)	<b>BD-2201</b>	
1.8 43kW	05/97-	LUC (>10/01)	<b>BD-2203</b>	
		BOS (10/01>)	<b>BD-2201</b>	
1.9 50/51kW	07/96-	LUC (>10/01)	<b>BD-2203</b>	
		BOS (10/01>)	<b>BD-2201</b>	
		BOS (+ESP)	<b>BD-2202</b>	
2.0 HDi 66kW	08/99-	LUC (>10/01)	<b>BD-2203</b>	
		BOS (10/01>)	<b>BD-2201</b>	
		BOS (+ESP)	<b>BD-2202</b>	
<b>C3</b>				
1.1 44kW	02/02-10/09	LUC	<b>BD-2204</b>	
1.4 55kW	02/02-10/09	LUC	<b>BD-2204</b>	
1.4 HDi 16V 66kW	02/02-10/09	LUC	<b>BD-2205</b>	LUC <b>BD-1206</b>
1.4 HDi 50kW	02/02-10/09	LUC	<b>BD-2204</b>	LUC <b>BD-1206</b>
1.6 16V 80kW	02/02-10/09	LUC	<b>BD-2205</b>	LUC <b>BD-1206</b>
<b>C4</b>				
1.4 16V 65kW	11/04-07/11	BOS (+ ESP)	<b>BD-2202</b>	BOS <b>BD-2211</b>
		BOS (- ESP)	<b>BD-2201</b>	TRW <b>BD-8002</b>
1.6 16V 80kW	11/04-07/11	BOS (+ ESP)	<b>BD-2202</b>	BOS <b>BD-2211</b>
		BOS (- ESP)	<b>BD-2201</b>	TRW <b>BD-8002</b>
2.0 16V 100/103kW	11/04-07/11	ATE	<b>BD-2206</b>	BOS <b>BD-2211</b>
				TRW <b>BD-8002</b>
2.0 16V 130kW	11/04-07/11	ATE	<b>BD-2206</b>	BOS <b>BD-2211</b>
				TRW <b>BD-8002</b>
<b>C4 (B7)</b>				
1.6 VTi 120 88kW	08/11-	ATE	<b>BD-2223</b>	TRW (Without Electronic parking brake) <b>BD-1206</b>
<b>C5 (DC_)</b>				
1.8 16V 85kW	05/01-08/04	BOS	<b>BD-2207</b>	CIT <b>BD-2210</b>
2.0 16V 100kW	05/01-08/04	BOS	<b>BD-2208</b>	CIT <b>BD-2210</b>
2.0 80kW	05/01-08/04	BOS	<b>BD-2208</b>	CIT <b>BD-2210</b>
2.2 98kW	05/01-08/04	BOS	<b>BD-2209</b>	CIT <b>BD-2210</b>
3.0 V6 152kW	05/01-08/04	BOS	<b>BD-2209</b>	CIT <b>BD-2210</b>
<b>C5 (RC_)</b>				
1.8 16V 85/92kW	09/04-03/08	BOS	<b>BD-2207</b>	CIT <b>BD-2210</b>
2.0 16V 103kW	09/04-03/08	BOS	<b>BD-2208</b>	CIT <b>BD-2210</b>
2.0 HDi 100kW	09/04-03/08	BOS	<b>BD-2209</b>	CIT <b>BD-2210</b>
2.2 HDi 98/125kW	09/04-03/08	BOS	<b>BD-2209</b>	CIT <b>BD-2210</b>
3.0 V6 152kW	09/04-03/08	BOS	<b>BD-2209</b>	CIT <b>BD-2210</b>
<b>C5 (RD_)</b>				
1.6 T 115kW	04/08-	ATE	<b>BD-2224</b>	TRW (Without Electronic parking brake) <b>BD-6111</b>
				TRW (With Electronic parking brake) <b>BD-5901</b>
2.0 103kW	04/08-	ATE	<b>BD-2224</b>	TRW (Without Electronic parking brake) <b>BD-6111</b>
				TRW (With Electronic parking brake) <b>BD-5901</b>
2.0 HDi 100kW	04/08-	ATE	<b>BD-2224</b>	TRW (Without Electronic parking brake) <b>BD-6111</b>
				TRW (With Electronic parking brake) <b>BD-5901</b>
<b>C8</b>				
2.0 100kW	07/02-	LUC	<b>BD-2212</b>	





			
2.0 HDi 79kW	07/02-	LUC	BD-2212
2.2 116kW	07/02-	LUC	BD-2212
2.2 HDi 94kW	07/02-	LUC	BD-2212
3.0 V6 150kW	07/02-	LUC	BD-2212
<b>C-Crosser</b>			
2.4 16V 125kW	07/08-		BD-5501 AKE
2.2 HDi 115kW	03/07-		BD-5501 AKE
<b>Dispatch</b>			
1.9 D	10/95-	BDX	BD-2213
2.0 HDi	02/00-	LUC	BD-2214
		BDX	BD-2213
<b>Evasion</b>			
1.8 73kW	02/96-08/00	BDX	BD-2213
1.9 TD 66kW	11/94-08/00	LUC	BD-2214 ATE (+ ABS)
2.0 89kW	11/94-10/02	LUC	BD-2214
2.0 Turbo CT 108kW	06/94-10/02	LUC	BD-2214 ATE (+ ABS)
2.0 80kW	09/99-10/02	LUC	BD-2214 ATE
2.1 TD 80kW	06/96-12/99	LUC	BD-2214
<b>Jumper</b>			
2.0 HDi 62kW	02/02-02/07	1100, 1400	BD-2215 (drum rear brakes)
		1800	BD-2216 (disc rear brakes)
2.0 80kW	02/02-02/07	1100, 1400	BD-2215 (drum rear brakes)
		1800	BD-2216 (disc rear brakes)
2.2 HDi 74kW	02/02-02/07	1100, 1400	BD-2215 (drum rear brakes)
		1800	BD-2216 (disc rear brakes)
2.8 HDi 94kW	02/02-02/07	1100, 1400	BD-2215 (drum rear brakes)
		1800	BD-2216 (disc rear brakes)
<b>Jumper</b>			
2.2 D	02/07-	1100, 1500	BD-2828
		1700	BD-2829
2.3 D	02/07-	1100, 1500	BD-2828
		1700	BD-2829
3.0 D	02/07-	1100, 1500	BD-2828
		1700	BD-2829
<b>Jumpy</b>			
1.6 58kW	10/95-08/00	BDX	BD-2213
1.9 TD 66kW	10/95-08/00	LUC	BD-2214
		BDX	BD-2213
2.0 HDi 69kW	02/00-	LUC	BD-2214
		BDX	BD-2213
2.0 69kW	09/00-	LUC	BD-2214
		BDX	BD-2213
<b>Relay</b>			
2.0	02/02-	LUC	BD-2215
2.0 HDi	02/02-	LUC	BD-2215 BRE
2.2 HDi	02/02-	LUC	BD-2215 BRE
2.8 HDi	02/02-	LUC	BD-2215 BRE
2.8 HDi	02/02-	LUC	BD-2216 BRE
<b>Synergie</b>			
1.9 D 66kW	10/95-10/99	LUC	BD-2214 ATE
2.0 89kW	10/95-12/01	LUC	BD-2214 ATE
2.0 D 80kW	09/99-10/02	LUC	BD-2214 ATE
2.0 T 108kW	09/00-10/02	LUC	BD-2214 ATE
<b>Xsara</b>			
1.4 55kW	07/97-08/05	ATE (>08/00)	BD-2219
		BOS (09/00>)	BD-2201





# • CITROEN — DAEWOO

					
<b>Xsara</b>					
1.5 D 42kW	05/98-08/00	ATE	BD-2219		
1.6 66/80kW	07/97-08/05	ATE (>08/00)	BD-2219	BDX	BD-2222
		BOS (09/00>)	BD-2201		
1.8 66/81kW	07/97-08/00	LUC	BD-2203	BDX	BD-2222
		BOS	BD-2220		
		ATE (+ ABS)	BD-2219		
1.8 D	05/98-08/00	ATE (+ ABS)	BD-2219		
1.9 D 51kW	07/97-08/00	ATE	BD-2219		
2.0 16V 120kW	01/98-08/00	LUC	BD-2203	BDX	BD-2222
2.0 100kW	01/98-08/00	BOS	BD-2220	BDX	BD-2222
2.0 120kW	01/98-	LUC	BD-2221	BDX	BD-2222
2.0 HDi 66kW	06/99-08/05	LUC	BD-2203	BDX	BD-2222
		BOS (>08/00)	BD-2220		
		BOS (09/00>)	BD-2201		
<b>Xsara Break</b>					
1.4 55kW	05/98-08/00	ATE	BD-2219		
		LUC (+ ABS)	BD-2203		
		BOS (+ ABS)	BD-2220		
1.5 D 42kW	05/98-08/00	ATE	BD-2219		
		LUC (+ ABS)	BD-2203		
		BOS (+ ABS)	BD-2220		
1.6 66kW	05/98-08/00	ATE	BD-2219		
		LUC (+ ABS)	BD-2203		
		BOS (+ ABS)	BD-2220		
1.8 66-81kW	05/98-08/00	LUC	BD-2203	BDX	BD-2222
		BOS	BD-2220	BDX	BD-2222
1.8 D 43kW	05/98-05/99	ATE	BD-2219		
		LUC (+ ABS)	BD-2203		
		BOS (+ ABS)	BD-2220		
1.9 D 51kW	05/98-08/00	ATE	BD-2219		
		LUC (+ ABS)	BD-2203		
		BOS (+ ABS)	BD-2220		
2.0 D 66kW	06/99-	LUC	BD-2203	BDX	BD-2222
		BOS (>08/00)	BD-2220	BDX	BD-2222
		LUC (08/00>)	BD-2221	BDX	BD-2222
<b>Xsara Picasso</b>					
1.6 65/70kW	09/00-	BOS	BD-2201		
1.8 16V 85kW	09/00-	BOS	BD-2201		
2.0 HDi 66kW	09/00-	BOS	BD-2201		
<b>DAEWOO</b>					
<b>Aranos</b>					
1.5 66kW	01/95-11/97	ATE	BD-1402		
1.8 70kW	01/95-11/97	ATE	BD-1402		
2.0 77kW	01/95-11/97	ATE	BD-1402		
<b>Espero</b>					
1.5 66kW	01/95-09/99	ATE	BD-1402		BS-1800
1.8 70kW	01/95-09/99	ATE	BD-1402		BS-1800
2.0 77kW	01/95-09/99	ATE	BD-1402		BS-1800
<b>Lanos</b>					
1.4 55kW	04/97-	ATE (13")	BD-5903		BS-1800
		AKE	BD-1801		
1.5 63kW	04/97-	ATE (13")	BD-5903		BS-1800
		AKE (13")	BD-1801		
		ATE (14")	BD-1805		





					
1.6 78kW	04/97-	ATE	BD-1402		BS-1800
		AKE (13")	BD-1801		
		ATE (14")	BD-1805		
<b>Leganza</b>					
2.0 98kW	06/97-	ATE	BD-1805	LUC	BD-1802
2.2 100kW	04/99-	ATE	BD-1805	LUC	BD-1802
<b>Matiz</b>					
0.8 38kW	04/98-	AKE	BD-1801		BS-1801
1.0 47kW	11/02-	AKE	BD-1801		BS-1801
<b>Nexia</b>					
1.5 GL 55/66kW	01/95-08/97	ATE	BD-5903		BS-1800
1.5 GLX/GTX 66kW	01/95-08/97	ATE	BD-1402		BS-1800
1.5 SOHC 8V GL/GLX	01/95-	GM	BD-5905		BS-1800
1.5 DOHC 16V	06/02-	AKE (13")	BD-1801		BS-1800
		AKE (14")	BD-1805		
<b>Nubira</b>					
1.6 78kW	05/97-	ATE	BD-1805		BS-1800
2.0 16V 98kW	05/97-	ATE	BD-1805		BD-1802
<b>Nubira II</b>					
1.6 80kW	07/03-	AKE	BD-1805		
1.8 90kW	07/03-	AKE	BD-1805		
<b>Tacuma</b>					
1.8 74kW	03/00-	AKE	BD-1805		
<b>Tico</b>					
0.8 35kW	04/96-08/00	MAN	BD-1809		
<b>DAIHATSU</b>					
<b>Charade</b>					
1.0 38/42kW	03/93-03/96	AKE	BD-2402		
1.3 62kW	03/93-04/01	AKE	BD-2402	SUM (+ ABS)	BD-2404
		AKE	BD-2402		
1.5 66kW	06/94-11/99	AKE	BD-2402	SUM (+ ABS)	BD-2404
		AKE	BD-2402		
1.6 77kW	03/93-03/96	AKE	BD-2402	SUM	BD-2404
<b>Gran Move</b>					
1.5 66kW	02/97-06/98	AKE	BD-2402	SUM (+ ABS)	BD-2404
		AKE	BD-2402		
1.6 67kW	07/98-	AKE	BD-2402	SUM (+ ABS)	BD-2404
		AKE	BD-2402		
<b>Terios</b>					
1.3 61kW	02/97-10/05	SUM	BD-2403		
1.5 16V 77kW	11/05-	SUM	BD-2403		
<b>FIAT</b>					
<b>Brava</b>					
1.2 16V 59/60kW	09/98-05/02	ATE	BD-2801		
1.4 59kW	10/95-08/98	ATE	BD-2801		
1.6 66/76kW	10/95-05/02	ATE (MT)	BD-2801		
	09/98-08/00	ATE (AT)	BD-2802		
1.8 83kW	10/95-08/00	ATE	BD-2802		
1.9 TD 55kW	09/96-08/00	ATE	BD-2801		
1.9 JTD 74kW	09/98 -10/01	ATE	BD-2802		
<b>Bravo</b>					
1.2 59/60kW	09/98-05/02	ATE	BD-2801		
1.4 59kW	10/95-08/98	ATE	BD-2801		
1.4 Turbo 110kW	04/07-	ATE	BD-2800		
1.6 76kW	09/98-05/02	ATE (AT)	BD-2802		
		ATE (MT)	BD-2801		

• FIAT





			
<b>Bravo</b>			
1.8 83kW	11/96-08/00	ATE	BD-2802
1.9 D 48kW	10/95-08/00	ATE	BD-2801
1.9 JTD 74kW	09/98-05/02	ATE	BD-2802
2.0 108/113kW	11/96-08/00	ATE	BD-2803 LUC
<b>Coupe</b>			
1.8 96kW	11/95-08/96	ATE	BD-2803 LUC
	09/96-08/00	ATE	BD-2803 LUC
2.0 102/108kW	02/94-08/96	LUC (>06/95)	BD-2804 LUC
		ATE (07/95>)	BD-2803
2.0 102-143kW	09/96-08/00	ATE	BD-2803 LUC
<b>Croma</b>			
1.9 JTD/TD 66kW	09/89-12/96	LUC	BD-2805 LUC
2.0	04/95-12/96	LUC	BD-2805 LUC (+ ABS)
2.0 Turbo iE 110/114kW	04/95-12/96	LUC	BD-2804
2.5 T 118kW	03/93-12/96	LUC	BD-2806 LUC
<b>Doblo</b>			
1.2 47kW	11/00-	ATE	BD-2807
1.6 76kW	09/01-	ATE	BD-2807
1.9 D 46kW	11/00-	ATE	BD-2807
<b>Ducato (230)</b>			
1.9 D 51-68kW (1.0 T / 1.4 T)	02/94-02/02	LUC	BD-2808
2.5 D 4x4 (1.0 T / 1.4 T)	02/94-02/02	LUC	BD-2809
2.5 D (1.8 T)	02/94-01/02	LUC	BD-2810
2.5 TDI (1.0 T / 1.4 T)	02/94-01/02	LUC	BD-2215
2.8 HDi (1.0 T / 1.4 T)	02/94-01/02	LUC	BD-2215 BRE
2.8 HDi (1.8 T)	02/94-01/02	LUC	BD-2216 BRE
<b>Ducato (244 / RUS)</b>			
2.0 HDi 62kW	02/02-02/07	1100, 1400	BD-2215 (drum rear brakes)
		1800	BD-2216 (disc rear brakes)
2.0 80kW	02/02-02/07	1100, 1400	BD-2215 (drum rear brakes)
		1800	BD-2216 (disc rear brakes)
2.2 HDi 74kW	02/02-02/07	1100, 1400	BD-2215 (drum rear brakes)
		1800	BD-2216 (disc rear brakes)
2.8 HDi 94kW	02/02-02/07	1100, 1400	BD-2215 (drum rear brakes)
		1800	BD-2216 (disc rear brakes)
<b>Ducato (250)</b>			
2.2 D	02/07-	1100, 1500	BD-2828
		1700	BD-2829
2.3 D	02/07-	1100, 1500	BD-2828
		1700	BD-2829
3.0 D	02/07-	1100, 1500	BD-2828
		1700	BD-2829
<b>Grande Punto</b>			
1.2 48kW	10/05-	BOS	BD-2812
1.4 57kW	10/05-	BOS	BD-2812
<b>Marea</b>			
1.4	08/96-02/99	ATE	BD-2801
1.6 16V 76kW	08/96-02/02	ATE	BD-2801
1.8 16V 83kW	08/96-08/00	ATE	BD-2802
1.9 TD 55kW	08/96-08/00	ATE	BD-2801
1.9 JTD/TD 74kW	08/96-08/02	ATE	BD-2802
2.4 TD 91kW	11/96-03/97	ATE	BD-2803 LUC
2.4 JTD 91/100kW	04/97-08/00	ATE	BD-2803 LUC
<b>Marea 150</b>			
2.0 20V 108/113kW	10/96-02/99	ATE	BD-2803 LUC

				
2.0 20V 108/113kW	03/99-08/02	ATE	BD-2803 LUC	BD-2819
<b>Marea Weekend</b>				
1.4	08/96-02/99	ATE	BD-2802	
1.6 16V 76kW	08/96-02/99	ATE	BD-2813	
1.8 16V 83kW	08/96-02/99	ATE	BD-2813	
<b>Marea Weekend 75</b>				
1.9 TD 55kW	08/96-02/99	ATE	BD-2801	
<b>Marea Weekend 100</b>				
1.9 TD 74kW	08/96-02/99	ATE	BD-2813	
<b>Marea Weekend 150</b>				
2.0 108/113kW	10/96-08/02	ATE	BD-2803 LUC (>02/99)	BD-2818
			LUC (03/99>)	BD-2819
<b>Multipla</b>				
1.6 71/76kW	02/99-04/02	ATE	BD-2803	
1.6	05/02-	ATE	BD-2803 BOS	BD-2821
1.9 JTD 76kW	08/98-03/02	ATE	BD-2803	
<b>Palio</b>				
1.2 55kW	06/98-	ATE	BD-2814	
<b>Palio Weekend</b>				
1.2 55kW	07/97-08/00	ATE	BD-2814	
		ATE (+ ABS)	BD-2807	
1.6 74kW	07/97-08/02	ATE	BD-2814	
		ATE (+ ABS)	BD-2807	
<b>Panda</b>				
1.1 40kW	01/03-	BOS	BD-2815	
1.2 44kW	01/03-	BOS	BD-2815	
<b>Punto</b>				
1.1 40kW	08/93-07/99	BDX	BD-2815	
1.2 44kW	10/93-04/99	LUC	BD-2805	
		BDX	BD-2815	
1.2 8V 44kW	09/99-	LUC	BD-2816	
1.4 GT 98kW	10/93-07/99	LUC	BD-2805 LUC	BD-2818
1.6 65kW	04/94-10/97	LUC	BD-2805	
1.7 D 42kW	04/94-10/98	BDX	BD-2815	
1.7 TD 52kW	01/94-07/99	LUC	BD-2805	
1.8 96kW	08/99-06/03	ATE	BD-2807	
<b>Regata</b>				
1.5 55/60kW	02/84-06/89	LUC	BD-2805	
1.6 60/74kW	06/84-06/89	LUC	BD-2805	
1.7 D 44kW	06/84-06/89	LUC	BD-2805	
1.9 D 48kW	05/84-06/89	LUC	BD-2805	
<b>Scudo</b>				
1.6 58kW	01/96-08/00	BDX	BD-2213	
1.9 D/TD 51-68kW	01/96-	BDX	BD-2213	
2.0 100kW	09/99-	BDX	BD-2213	
		LUC	BD-2214	
2.0 D	09/99-	BDX	BD-2213	
		LUC	BD-2214	
<b>Seicento</b>				
Electro 30kW	06/98-	LUC	BD-2805	
0.9 29kW	03/98-02/00	BDX	BD-2816	
1.1 40kW	03/98-	BDX	BD-2816	
<b>Stilo</b>				
1.2 59kW	10/01-	BOS	BD-2812 BOS	BD-2821
1.6 76kW	10/01-	BOS	BD-2812 BOS	BD-2821
2.4 125kW	10/01-	BOS	BD-2800 BOS	BD-2821





# • FIAT — FORD





			
<b>Strada</b>			
1.2 44/54kW	02/00-	ATE	<b>BD-2807</b>
1.7 D 51kW	02/00-05/01	ATE	<b>BD-2807</b>
1.9 D 46/59kW	06/01-	ATE	<b>BD-2807</b>
<b>Tempra</b>			
1.4 51kW	04/90-07/96	LUC (+ ABS, MT)	<b>BD-2805</b> LUC <b>BD-2818</b>
1.6 55/66kW	04/90-07/96	LUC (+ ABS)	<b>BD-2805</b> LUC <b>BD-2818</b>
1.8 66/77kW	04/90-07/96	LUC	<b>BD-2805</b> LUC (+ ABS) <b>BD-2818</b>
1.9 TD 59/66kW	06/90-07/96	LUC	<b>BD-2805</b> LUC (+ ABS) <b>BD-2818</b>
2.0 85kW	04/90-07/96	LUC	<b>BD-2805</b> LUC (+ ABS) <b>BD-2818</b>
<b>Tipo</b>			
1.4 52kW	03/88-09/95	LUC	<b>BD-2805</b> LUC (+ ABS) <b>BD-2818</b>
1.6 55-66kW	03/88-04/95	LUC	<b>BD-2805</b> LUC (+ ABS) <b>BD-2818</b>
1.7 D 43kW	11/92-09/95	LUC	<b>BD-2805</b> LUC (+ ABS) <b>BD-2818</b>
1.8 66-100kW	06/88-09/95	LUC	<b>BD-2805</b> LUC (+ ABS) <b>BD-2818</b>
1.9 TD 59/66kW	06/88-09/95	LUC	<b>BD-2805</b> LUC (+ ABS) <b>BD-2818</b>
2.0 85kW	03/88-10/92	LUC	<b>BD-2805</b> LUC (+ ABS) <b>BD-2818</b>
<b>Ulysse</b>			
1.8 73kW	04/96-08/00	BDX	<b>BD-2213</b> ATE (+ ABS) <b>BD-2218</b>
1.9 TD 66kW	11/94-05/02	LUC	<b>BD-2214</b> ATE (+ ABS) <b>BD-2218</b>
2.0 89kW	04/94-05/02	LUC	<b>BD-2214</b> ATE (+ ABS) <b>BD-2218</b>
2.0 D 80kW	06/99-05/02	LUC	<b>BD-2214</b> ATE (+ ABS) <b>BD-2218</b>
2.1 D 80kW	04/96-12/99	LUC	<b>BD-2214</b> ATE (+ ABS) <b>BD-2218</b>
<b>Ulysse II</b>			
2.0 100kW	08/02-	TRW	<b>BD-2212</b>
2.0 JTD 79kW	08/02-	TRW	<b>BD-2212</b>
2.2 JTD 94kW	08/02-	TRW	<b>BD-2212</b>
<b>Uno</b>			
1.0 33kW	04/84-12/94	BDX	<b>BD-2817</b>
1.1 37-42kW	12/83-12/94	BDX	<b>BD-2817</b>
1.4 51kW	01/92-12/94	BDX	<b>BD-2817</b>
1.4 Turbo 82kW	01/89-12/94	LUC	<b>BD-2805</b>
1.4 TD 52kW	04/84-12/91	BDX	<b>BD-2817</b>
1.5 55kW	04/84-12/94	BDX	<b>BD-2817</b>
1.7 D 42kW	04/84-12/91	BDX	<b>BD-2817</b>
1.9 D 44kW	01/89-12/91	BDX	<b>BD-2817</b>
<b>FORD</b>			
<b>C-Max</b>			
1.6 74kW	03/07-	ATE	<b>BD-3001</b> ATE <b>BD-5901</b>
1.8 92kW	03/07-	ATE	<b>BD-3001</b> ATE <b>BD-5901</b>
2.0 107kW	03/07-	ATE	<b>BD-3001</b> ATE <b>BD-5901</b>
2.0 TDCi	03/07-	ATE	<b>BD-3001</b> ATE <b>BD-5901</b>
<b>Cougar</b>			
2.0 16V 96kW	08/98-12/01	ATE	<b>BD-3012</b> BDX <b>BD-3014</b>
2.5 ST 151kW	01/00-12/01	ATE	<b>BD-3011</b> BDX <b>BD-3014</b>
2.5 V6 24V	08/98-12/01	ATE	<b>BD-3012</b> BDX <b>BD-3014</b>
<b>Escort</b>			
1.3 44kW	09/90-12/92	BDX	<b>BD-3015</b>
1.4 55kW	09/90-10/98	BDX (>06/97)	<b>BD-3015</b>
		BDX (07/97>)	<b>BD-3016</b>
1.6 66kW	09/90-10/98	BDX (>06/97)	<b>BD-3015</b>
		BDX (07/97>)	<b>BD-3016</b>
1.6 66/77kW	09/90-12/96	BDX (>12/94)	<b>BD-3015</b> ATE <b>BD-3018</b>
		ATE (01/95>)	<b>BD-3017</b>







				
1.8 77kW	09/90-12/96	BDX (>12/94) ATE (01/95>)	BD-3015 ATE BD-3017	BD-3018
1.8 77/85kW	01/95-10/98	ATE (>08/95) BDX ATE (08/95>)	BD-3015 ATE BD-3016 BD-3017	BD-3018
1.8 D 44kW	09/90-10/98	BDX BDX	BD-3015 ATE BD-3016	BD-3018
2.0 RS (4x4) 110kW	08/90-12/94	ATE	BD-3017 ATE	BD-3018
<b>Fiesta (JA, JB)</b>				
1.2 55kW	09/95-01/02	ATE (>01/00; ventilated discs) ATE (>01/00) ATE (02/00>) ATE (02/00>; ventilated discs)	BD-3019 LKD (+ ABS) BD-3020 BD-3021 BD-5108	BS-3001
1.3 37kW	09/95-01/02	ATE (>01/00; ventilated discs) ATE (>01/00) ATE (02/00>) ATE (02/00>; ventilated discs)	BD-3019 LKD (+ ABS) BD-3020 BD-3021 BD-5108	BS-3001
1.4 66kW	01/96-01/02	ATE ATE (>01/00; ventilated discs) ATE (02/00>; ventilated discs)	BD-3020 LKD (+ ABS) BD-3019 BD-5108	BS-3001
1.6 76kW	02/00-01/02	ATE	BD-5108 LKD (+ ABS)	BS-3001
1.8 D 44kW	09/95-01/02	ATE ATE (ventilated discs)	BD-3020 LKD (+ ABS) BD-3019	BS-3001
1.8 TDi 55kW	02/00-01/02	ATE ATE (ventilated discs)	BD-3021 LKD (+ ABS) BD-5108	BS-3001
<b>Fiesta (JH, JD)</b>				
1.3 51kW	11/01-12/08	ATE	BD-5108 LKD (+ ABS)	BS-3001
1.4 59kW	11/01-12/08	ATE	BD-5108 LKD (+ ABS)	BS-3001
1.4 TDCi 50kW	11/01-12/08	ATE	BD-5108 LKD (+ ABS)	BS-3001
1.6 16V 74kW	11/01-12/08	ATE	BD-5108 LKD (+ ABS)	BS-3001
<b>Fiesta (JH, JD)</b>				
1.25 44kW	01/09-	LUC	BD-5123	
1.4 71kW	01/09-	LUC	BD-5123	
<b>Focus I (DAW, DBW, DFW)</b>				
1.4 16V 55kW	08/98-12/04	ATE	BD-3009	BS-3000
1.6 16V 74kW	08/98-12/04	ATE	BD-3009 LUC (+ ABS)	BD-3010
				(drum rear brakes) BS-3000
1.8 16V 85kW	08/98-12/04	ATE	BD-3009 LUC (+ ABS)	BD-3010
				(drum rear brakes) BS-3000
1.8 TDDi 66kW	08/98-12/04	ATE	BD-3009	BS-3000
1.8 TDCi 74/85kW	06/00-12/04	ATE	BD-3009 LUC	BD-3010
2.0 96kW	08/98-12/04	ATE	BD-3009 LUC	BD-3010
2.0 ST170 127kW	02/01-12/04	ATE	BD-3022 LUC	BD-3010
<b>Focus II</b>				
1.4 59kW	01/05-04/11	ATE	BD-3001 ATE	BD-5901
1.6 74/85kW	01/05-04/11	ATE	BD-3001 ATE	BD-5901
1.8 92kW	01/06-04/11	ATE	BD-3001 ATE	BD-5901
1.8 TDCi 85kW	01/05-04/11	ATE	BD-3001 ATE	BD-5901
2.0 107kW	01/05-04/11	ATE	BD-3001 ATE	BD-5901
<b>Focus III</b>				
1.6 77kW	05/11-	ATE	BD-3001 ATE	BD-5901
1.6 92kW	05/11-	ATE	BD-3001 ATE	BD-5901
1.6 EcoBoost 110kW	05/11-	ATE	BD-3001 ATE	BD-5901
2.0 110kW	05/11-	ATE	BD-3001 ATE	BD-5901
2.0 TDCi 103kW	05/11-	ATE	BD-3001 ATE	BD-5901





• FORD

			
<b>Focus C-Max</b>			
1.6 74kW	10/03-04/07	ATE	BD-3001 ATE BD-5901
1.6 TDCi 66/80kW	10/03-04/07	ATE	BD-3001 ATE BD-5901
1.8 88/92kW	10/03-04/07	ATE	BD-3001 ATE BD-5901
2.0 107kW	04/04-04/07	ATE	BD-3001 ATE BD-5901
2.0 TDCi 100kW	10/03-04/07	ATE	BD-3001 ATE BD-5901
<b>Fusion</b>			
1.4 59kW	08/02-03/12	ATE	BD-5108 BS-3001
1.4 TDCi 50kW	08/02-03/12	ATE	BD-5108 BS-3001
1.6 74kW	08/02-03/12	ATE	BD-5108 BS-3001
<b>Galaxy (WGR)</b>			
1.9 TDi 66-85kW	10/95-04/00	ATE	BD-3023 LUC BD-1206
1.9 TDi 85kW	05/00-05/06	ATE	BD-1216 LUC BD-1206
		ATE (16")	BD-3026 LUC BD-3025
2.0 85kW	10/95-04/00	ATE	BD-3023 LUC BD-1206
2.3 107kW	09/96-04/00	ATE	BD-3023 LUC BD-1206
2.3 103kW	05/00-05/06	ATE	BD-3024 LUC BD-1206
		ATE (16")	BD-3026 LUC BD-3025
2.8 128kW	10/95-05/06	ATE (>04/00)	BD-3023 LUC BD-1206
		ATE	BD-3026 LUC BD-3027
<b>Galaxy II</b>			
2.0 107kW	06/06-	ATE	BD-3004 BD-3005
2.0 TDCi 96/103kW	06/06-	ATE	BD-3004 BD-3005
2.3 118kW	07/07-	ATE	BD-3004 BD-3005
<b>Granada</b>			
2.0 80-92kW	10/84-10/92	ATE	BD-3017
2.0 85kW	11/92-09/94	ATE	BD-3011
		ATE	BD-3012
2.5 TD	11/92-09/94	ATE	BD-3012
2.9 V6 24V Cosworth	05/92-01/95	ATE	BD-3013
<b>KA</b>			
1.3 37/44kW	09/96-02/03	ATE (>02/00)	BD-3020
		ATE (03/00->)	BD-3021
1.6 70kW	03/03-	ATE	BD-5108
<b>Kuga</b>			
2.0 TDCi 100kW	03/08-	ATE	BD-3001 BD-3005
<b>Maverick (UDS, UNS)</b>			
2.4 87kW	02/93-04/00	LUC	BD-3028
2.7 D 74kW	02/93-04/00	LUC	BD-3028
<b>Maverick</b>			
2.0 16V 91kW	02/01-	ATE	BD-5115
2.3 16V 110kW	02/01-	ATE	BD-5115
3.0 24V 145/149kW	02/01-	ATE	BD-5115
<b>Mondeo I</b>			
1.6 66kW	02/93-08/96	ATE (wear sensor)	BD-3012 BDX BD-3014
		ATE (14")	BD-3011
1.8 85kW	02/93-08/96	ATE (wear sensor)	BD-3012 BDX BD-3014
		ATE (14")	BD-3011
1.8 TD 66kW	02/93-08/96	ATE (wear sensor)	BD-3012 BDX BD-3014
		ATE (14")	BD-3011
2.0 100kW	02/93-08/96	ATE (wear sensor)	BD-3012 BDX BD-3014
		ATE (15"/4x4)	BD-3013
<b>Mondeo II (BAP)</b>			
1.6 66kW	09/96-09/00	ATE	BD-3011 BDX BD-3014





				
1.8 85kW	09/96-09/00	ATE	<b>BD-3011</b> BDX	<b>BD-3014</b>
		ATE (wear sensor)	<b>BD-3012</b>	
1.8 TD 66kW	09/96-09/00	ATE	<b>BD-3011</b> BDX	<b>BD-3014</b>
		ATE (wear sensor)	<b>BD-3012</b>	
2.0 100kW	09/96-09/00	ATE	<b>BD-3011</b> BDX	<b>BD-3014</b>
		ATE (wear sensor)	<b>BD-3012</b>	
		ATE (15"/4x4)	<b>BD-3013</b>	
2.5 24V 125kW	10/94-09/00	ATE	<b>BD-3013</b> BDX	<b>BD-3014</b>
<b>Mondeo III</b>				
1.8 81/92kW	10/00-03/07	BOS	<b>BD-3006</b> BOS (>09/04)	<b>BD-3007</b>
				BOS (09/04>)
2.0 107kW	10/00-03/07	BOS	<b>BD-3006</b> BOS (>09/04)	<b>BD-3007</b>
				BOS (09/04>)
2.0 D/TDi	10/00-09/04	BOS	<b>BD-3006</b> BOS (>09/04)	<b>BD-3007</b>
2.5 125kW	10/00-03/07	BOS	<b>BD-3006</b> BOS (>09/04)	<b>BD-3007</b>
				BOS (09/04>)
3.0 V6 24V 150kW	09/04-03/07	BOS	<b>BD-3006</b> BOS	<b>BD-3008</b>
<b>Mondeo IV</b>				
1.6 81/92kW	04/07-	ATE	<b>BD-3004</b> BOS	<b>BD-3005</b>
1.8 TDCi 74kW	04/07-	ATE	<b>BD-3004</b> BOS	<b>BD-3005</b>
2.0 107kW	04/07-	ATE	<b>BD-3004</b> BOS	<b>BD-3005</b>
2.0 TDCi 96/103kW	04/07-	ATE	<b>BD-3004</b> BOS	<b>BD-3005</b>
2.3 118kW	04/07-	ATE	<b>BD-3004</b> BOS	<b>BD-3005</b>
<b>Orion</b>				
1.3 44kW	09/90-08/93	BDX	<b>BD-3015</b>	
1.4 52/54kW	09/90-08/93	BDX	<b>BD-3015</b>	
1.6 66/77kW	09/90-08/93	BDX	<b>BD-3015</b> ATE (+ ABS)	<b>BD-3018</b>
1.8 D 44kW	09/90-08/93	BDX	<b>BD-3015</b> ATE (+ ABS)	<b>BD-3018</b>
<b>Probe</b>				
2.0	11/93-12/97	SUM	<b>BD-5101</b> NBK	<b>BD-3029</b>
2.5 119kW	11/93-12/97	SUM	<b>BD-5101</b> NBK	<b>BD-3029</b>
<b>Puma</b>				
1.4 16V 66kW	02/98-12/01	ATE (>02/00)	<b>BD-3019</b>	
		ATE (03/00>)	<b>BD-5108</b>	
1.6 16V 76kW	07/00-05/02	ATE	<b>BD-5108</b>	
1.7 16V 92kW	06/97-12/01	ATE (>02/00)	<b>BD-3019</b>	
		ATE (03/00>)	<b>BD-5108</b>	
<b>Scorpio</b>				
1.8 66kW	10/84-10/88	ATE	<b>BD-3017</b> LUC	<b>BD-3030</b>
2.0 77kW	10/84-08/92	ATE	<b>BD-3017</b> LUC	<b>BD-3030</b>
2.0 85kW	09/92-08/98	ATE	<b>BD-3011</b> LUC	<b>BD-3030</b>
		ATE (wear sensor)	<b>BD-3012</b>	
2.3 16V 108kW	06/96-08/98	ATE	<b>BD-3011</b> LUC	<b>BD-3030</b>
2.4 92kW	09/92-09/94	ATE	<b>BD-3012</b>	
2.5 TD 85kW	09/92-08/98	ATE (>09/94)	<b>BD-3012</b>	
		ATE (10/94>)	<b>BD-3011</b> LUC	<b>BD-3030</b>
2.9 107-143kW	09/92-09/94	ATE	<b>BD-3012</b>	
2.9 110/152kW	10/94-06/96	ATE	<b>BD-3011</b> LUC	<b>BD-3030</b>
2.9 24V 152kW	10/94-08/98	ATE	<b>BD-3013</b> LUC	<b>BD-3030</b>
<b>Sierra</b>				
1.6 55/59kW	03/87-03/93	ATE	<b>BD-3017</b> LUC (+ ABS)	<b>BD-3030</b>
1.8 64/66kW	03/87-03/93	ATE	<b>BD-3017</b> LUC (+ ABS)	<b>BD-3030</b>
1.8 TD 55kW	10/89-03/93	ATE	<b>BD-3017</b> LUC (+ ABS)	<b>BD-3030</b>
2.0 74-92kW	03/87-03/93	ATE	<b>BD-3017</b> LUC (+ ABS)	<b>BD-3030</b>
2.3 D 49kW	03/87-01/90	ATE	<b>BD-3017</b> LUC (+ ABS)	<b>BD-3030</b>
2.9 107/110kW	10/88-03/93	ATE	<b>BD-3017</b> LUC	<b>BD-3030</b>





• **FORD — GAZ — GREAT WALL — HONDA**

					
<b>S-Max</b>					
2.0 107kW	06/06-	ATE	BD-3004		BD-3005
2.3 118kW	06/06-	ATE	BD-3004		BD-3005
2.0 TDCi	06/06-	ATE	BD-3004		BD-3005
<b>Tourneo Connect</b>					
1.8 TDCi	09/02-	ATE	BD-3022		
1.8 16V 85kW	09/02-	ATE	BD-3022		
<b>Transit V / VI</b>					
2.0	06/94-03/00	BDX	BD-3031		
2.0 D	06/00-06/06	BOS (FWD)	BD-3032		
		BOS (RWD)	BD-3033		
2.3	08/00-06/06	BOS (FWD)	BD-3032		
		BOS (RWD)	BD-3033		
2.4 TD	08/00-06/06	BOS (FWD)	BD-3032		
		BOS (RWD)	BD-3033		
2.5 (14/15")	06/94-03/00	BDX	BD-3031		
<b>Transit VII</b>					
2.2 TDCi 81/96kW	07/06-	BOS (RWD)	BD-3002	BOS	BD-3003
		BOS (FWD)	BD-3034		
2.4 TDCi 85/103kW	07/06-	BOS (RWD)	BD-3002	BOS	BD-3003
		BOS (FWD)	BD-3034	BRE	BD-3035
<b>Transit Connect</b>					
1.8 TDCi	09/02-	ATE	BD-3022		
1.8	09/02-	ATE	BD-3022		
<b>Capri</b>					
1.6	08/90-12/96	SUM	BD-5105	SUM	BD-2404
<b>GAZ</b>					
<b>Gazelle</b>					
2.3	05/93-	LUC	BD-4604		
2.5	05/93-	LUC	BD-4604		
<b>Sobol</b>					
2.3	01/98-	LUC	BD-4604		
<b>Volga 3102 / 3110</b>					
2.3	05/93-	LUC	BD-4604		
2.5	05/93-	LUC	BD-4604		
<b>GREAT WALL</b>					
<b>Hover</b>					
2.4 92kW	11/05-		BD-3804		BD-3803
<b>Deer G3</b>					
2.2 (4x4) 75kW	11/05-		BD-7501		
<b>Deer G5</b>					
2.2 (4x4) 75kW	11/05-		BD-7501		
<b>HONDA</b>					
<b>Accord</b>					
1.6 85kW	10/98-12/02	LUC	BD-3420		
1.9 85kW	01/96-09/98	AKE (AT)	BD-3405	AKE	BD-3402
		AKE (MT)	BD-3421		
1.8 100kW	10/98-12/02	LUC	BD-3422	LUC	BD-3425
2.0 85/96kW	01/93-09/98	AKE (AT)	BD-3405	AKE	BD-3402
		AKE (MT)	BD-3421		
2.0 108kW	10/98-12/02	LUC	BD-3422	LUC	BD-3425
2.0 D 77kW	01/96-09/98	AKE	BD-3421	AKE	BD-3402
		LUC	BD-3422	LUC	BD-3425
2.2 VTEC 110kW	01/96-09/98	AKE	BD-3405	AKE	BD-3402
2.2 Type R 156kW	10/98-12/02	AKE	BD-3405	LUC	BD-3425




				
<b>Accord VIII (CL)</b>				
2.0 114kW	03/03-	ATE	BD-3413 LUC	BD-3425
		ATE (4WD)	BD-3403	
2.4 140kW	03/03-	ATE	BD-3413 LUC	BD-3425
<b>Accord IX (CU1)</b>				
2.0 115kW	10/08-	ATE (Manual gear)	BD-3423 NIS (Manual gear)	BD-3431
		AKE (Automatic gear)	BD-3424 AKE (Automatic gear)	BD-3402
2.4 148kW	10/08-	ATE (Manual gear)	BD-3423 NIS (Manual gear)	BD-3431
		AKE (Automatic gear)	BD-3424 AKE (Automatic gear)	BD-3402
<b>Accord Coupe</b>				
2.0 98kW	08/93-12/97	AKE	BD-3405 AKE	BD-3402
2.0 16V 108kW	01/98-10/02	AKE	BD-3405 AKE	BD-3402
2.2 110kW	08/93-12/97	AKE	BD-3405 AKE	BD-3402
3.0 147kW	01/98-06/03	AKE	BD-3405 AKE	BD-3402
<b>Civic (EG, EH)</b>				
1.3 55kW	01/92-10/95	AKE	BD-3412	
1.5 66/69kW	01/92-10/95	SUM	BD-3407	
1.6 69-118kW	01/92-10/95	SUM	BD-3407	
<b>Civic (EJ9, EK3/4)</b>				
1.4 66kW	11/95-03/01	SUM (>12/97)	BD-3407	
		SUM (01/98->)	BD-3406	
1.5 84kW	11/95-03/01	LUC	BD-3426	
		SUM	BD-3406	
1.6 Vtec 92kW	11/95-03/01	LUC	BD-3426 AKE	BD-3428
		SUM	BD-3406	
1.6 VTi 118kW	11/95-03/02	LUC	BD-3426 AKE	BD-3428
		SUM	BD-3406	
2.0 D 63kW	01/97-10/00	LUC	BD-3426 AKE	BD-3428
<b>Civic (EN)</b>				
1.4	12/00-09/05	LUC	BD-3426 AKE	BD-3402
		AKE	BD-3406	
1.6 81kW	12/00-09/05	LUC	BD-3426 AKE	BD-3402
		AKE	BD-3406	
2.0 Type R 147kW	07/01-09/05	SUM	BD-3408 AKE	BD-3402
<b>Civic (FD1, FK1)</b>				
1.8 (4D) 102kW	01/06-	SUM	BD-3403	BD-3401
1.8 (5D) 102kW	01/06-	SUM	BD-3427	BD-3432
<b>Civic Coupe (EJ)</b>				
1.5 (EJ2) 74kW	08/93-12/95	SUM	BD-3407	
1.6 VTEC (EJ1) 92kW	08/93-12/00	SUM	BD-3406	
1.6 77kW (EJ6)	01/96-12/97	SUM	BD-3407	
1.6 VTEC (EJ6/EJ8)	04/99-12/00	SUM	BD-3406	
1.7 88kW	01/01-12/05	SUM	BD-3406 AKE	BD-3402
<b>Concerto</b>				
1.4 61kW	10/89-10/92	LUC	BD-3426	
1.5 16V 66kW	11/92-05/95	LUC	BD-3426 AKE (+ABS)	BD-3428
1.6 16V 78-90kW	10/89-05/95	LUC	BD-3426 AKE	BD-3428
1.8 D 58kW	08/94-10/96	LUC	BD-3426	
1.8 TD 65kW	08/94-10/96	LUC	BD-3426 AKE	BD-3428
<b>CR-V</b>				
2.0 16V 94/108kW	02/97-02/02	AKE	BD-3405	
2.0 110kW	06/02-09/06	AKE	BD-3404 AKE	BD-3401
2.0 i-VTEC 110kW	10/06-	BOS	BD-3418 BOS	BD-3430
2.4 i-VTEC 122kW	10/06-	BOS	BD-3418 BOS	BD-3430
<b>CRX</b>				
1.6 ESi 92kW	06/92-04/98	SUM	BD-3406	

# • HONDA — HYUNDAI

			
<b>CRX</b>			
1.6 VTi 118kW	06/92-04/98	SUM	BD-3406 AKE BD-3428
<b>HR-V</b>			
1.6 16V 77/91kW	02/99-10/06	AKE	BD-3405
<b>Integra</b>			
1.8 140kW	02/98-10/00	AKE	BD-3429 AKE BD-3402
2.0 118/162kW	02/02-	LUC	BD-3405 AKE BD-3402
<b>Jazz</b>			
1.2 57kW	03/02-		BD-3407
1.4 61kW	03/02-		BD-3407
<b>Legend</b>			
2.7 124kW	05/87-12/90	AKE	BD-3429 AKE BD-3402
3.2 151kW	01/91-12/95	AKE	BD-3405 AKE BD-3402
3.5 151kW	01/96-12/98	AKE	BD-3405 AKE BD-3402
<b>NSX</b>			
3.0 188/201kW	07/90-10/96	AKE	BD-3405
3.2 206kW	11/96-06/05	AKE	BD-3405
<b>Prelude</b>			
2.0 16V 98kW	01/92-10/00	AKE	BD-3405 AKE BD-3402
2.2 16V 136kW	01/93-09/96	AKE	BD-3405 AKE BD-3402
2.2 147kW	10/96-10/00	AKE	BD-3405 AKE BD-3402
2.3	01/92-09/96	AKE	BD-3405 AKE BD-3402
<b>S2000</b>			
2.0 177kW	03/99-		BD-3408 AKE BD-3402
<b>Shuttle</b>			
2.2 16V 110kW	03/95-12/97	AKE	BD-3405 AKE BD-3402
2.3 110kW	01/98-10/00	AKE	BD-3405 AKE BD-3402
<b>HYUNDAI</b>			
<b>Accent (X-3)</b>			
1.3 44-62kW	07/94-01/00	AKE	BD-3601
1.5 65-73kW	09/94-01/00	AKE	BD-3601
<b>Accent (LC)</b>			
1.3 55-63kW	01/00-	AKE	BD-3601 BS-3601
1.5 66kW	01/00-	AKE	BD-3601 BS-3601
<b>Accent (MC)</b>			
1.4 GL 71kW	11/05-	MAN	BD-3608 MAN BD-4407
1.5 CRDi	11/05-	MAN	BD-3608 MAN BD-4407
1.6 GLS 82kW	11/05-	MAN	BD-3608 MAN BD-4407
<b>Coupe</b>			
1.6 84kW	11/96-01/02	MAN	BD-3607 SUM BD-3612
2.0 100kW	04/96-01/02	MAN	BD-3607 SUM BD-3612
<b>Elantra (Lantra)</b>			
1.5 63kW	02/91-05/95	AKE	BD-3601
1.6 78/84kW	02/91-05/95	MAN	BD-5708
1.6 66/84kW	06/95-05/00	MAN	BD-5708 SUM (+ABS) BD-3612
1.8 93kW	06/92-05/95	MAN	BD-5708
1.8 94kW	06/95-05/00	MAN	BD-5708 SUM (+ABS) BD-3612
2.0 102kW	06/97-05/00	MAN	BD-5708 SUM (+ABS) BD-3612
<b>Elantra (XD)</b>			
1.6 79kW	06/00-06/06	AKE (>09/01)	BD-3607 SUM BD-3612
		MAN (>07/03)	BD-3611
		MAN (08/03->)	BD-3610
1.8 96kW	06/00-06/06	AKE (>09/01)	BD-3607 SUM BD-3612
		MAN (>07/03)	BD-3611
		MAN (08/03->)	BD-3610





					
2.0 103kW	06/00-06/06	AKE (>09/01) MAN (>07/03) MAN (08/03>)	BD-3607 BD-3611 BD-3610	SUM	BD-3612
<b>Elantra (HD)</b>					
1.6 90kW	07/06-		BD-3602		BD-3605
2.0 105kW	07/06-		BD-3602		BD-3605
<b>Excel</b>					
1.3	07/90-08/98	AKE	BD-3601		
1.5	07/90-08/98	AKE	BD-3601		
<b>Getz</b>					
1.1 46/49kW	09/02-	AKE	BD-3601	(disc rear brakes)	BD-3605
				(drum rear brakes)	BS-3600
1.3 60/63kW	09/02-	AKE	BD-3601	(disc rear brakes)	BD-3605
				(drum rear brakes)	BS-3600
1.4 71kW	08/05-	AKE	BD-3601	(disc rear brakes)	BD-3605
				(drum rear brakes)	BS-3600
1.6 77/78kW	09/02-	AKE	BD-3601	(disc rear brakes)	BD-3605
				(drum rear brakes)	BS-3600
<b>H100 / H100 Porter</b>					
2.4	07/94-10/01	LUC	BD-3604		
2.5 D	07/93-10/00	LUC	BD-3604		
2.5 D	10/00-	LUC	BD-3604		
<b>H-1</b>					
2.4	10/97-	MAN	BD-3613		
2.5 D	10/97-	MAN	BD-3613		
<b>H150</b>					
2.5 D	07/94-10/02	LUC	BD-3604		
<b>H200</b>					
2.5 TD	10/97-	MAN	BD-3613		
<b>i30</b>					
1.4 77kW	11/07-	MAN	BD-4404	MAN	BD-4407
1.6 90kW	11/07-	MAN	BD-4404	MAN	BD-4407
2.0 105kW	11/07-	MAN	BD-4404	MAN	BD-4407
<b>iX35</b>					
2.0 110kW	09/10-		BD-3621		BD-4407
2.0 CRDi 100kW	09/10-		BD-3621		BD-4407
<b>Matrix</b>					
1.5 D 60kW	08/01-03/02	AKE	BD-3607		
1.6 76kW	06/01-	AKE (>03/02) MAN (04/02>)	BD-3607 BD-3611	(04/02>)	BD-3605
1.8 90kW	06/01-	AKE (>03/02) MAN (04/02>)	BD-3607 BD-3611	(04/02>)	BD-3605
<b>Pony</b>					
1.3 43kW	07/90-12/99	AKE	BD-3601		
1.5 53-62kW	07/90-12/95	AKE	BD-3601		
<b>Santa-Fe (SM)</b>					
2.0 99kW	08/01-02/06	AKE	BD-3614	MAN	BD-3605
2.0 CRDi	08/01-02/06	AKE	BD-3614	MAN	BD-3605
2.4 100/107kW	08/01-02/06	AKE	BD-3614	MAN	BD-3605
2.7 V6 127kW	08/01-02/06	AKE	BD-3614	MAN	BD-3605
<b>Santa-Fe (CM)</b>					
2.2 CRDi 102/110kW	03/06-	MAN	BD-3615	MAN	BD-3616
2.2 CRDi 145kW	02/09-	MAN	BD-3615	MAN	BD-3623
2.4 128kW	11/10-	MAN	BD-3615	MAN	BD-3623
2.7 125kW	03/06-	MAN	BD-3615	MAN	BD-3616
2.7 V6 139kW	03/06-	MAN	BD-3615	MAN	BD-3616

# • HYUNDAI — INFINITI





			
<b>Santamo</b>			
2.0 102kW	10/98-10/02	SUM	BD-5509 AKE (+ABS) BD-5508
<b>Satellite</b>			
2.4 82kW	07/94-	LUC (RWD)	BD-3604
		MAN (4x4/RWD)	BD-3613
2.5 57-73kW	07/94-	LUC (RWD)	BD-3604
		MAN (4x4/RWD)	BD-3613
<b>S-Coupe</b>			
1.5 65kW	07/92-04/96	AKE	BD-3601
<b>Solaris</b>			
1.4 79kW	09/10-		BD-3619 (disc rear brakes) BD-3620
			(drum rear brakes) BS-3600
1.6 90kW	09/10-		BD-3619 (disc rear brakes) BD-3620
			(drum rear brakes) BS-3600
<b>Sonata I</b>			
1.8 70kW	10/88-06/96	MAN	BD-3607
2.0 74-96kW	10/88-05/01	MAN	BD-3607
2.4 83kW	10/88-06/93	MAN	BD-3607
3.0 107kW	09/90-06/96	MAN	BD-3607 AKE BD-3618
<b>Sonata II</b>			
1.8 72kW	07/96-05/98	MAN	BD-3607
2.0 77-102kW	07/93-05/98	MAN	BD-3607 AKE BD-3618
3.0 107kW	07/96-05/98	MAN	BD-3607 AKE BD-3618
<b>Sonata III (EF)</b>			
2.0 100kW	06/98-05/01	MAN	BD-3607 MAN BD-3605
2.4 105kW	06/98-05/01	MAN	BD-3607 MAN BD-3605
2.5 V6 24V 118kW	06/98-09/01	MAN	BD-3607 MAN BD-3605
<b>Sonata IV (EU4)</b>			
2.0 96kW	10/01-	MAN	BD-3602 MAN BD-3605
2.7 V6 127kW	10/01-	MAN	BD-3602 MAN BD-3605
<b>Sonata V (NF)</b>			
2.0 106kW	12/04-	MAN	BD-3602 MAN BD-3605
2.4 16V 119kW	12/04-	MAN	BD-3602 MAN BD-3605
3.3 171kW	12/04-	MAN	BD-3602 MAN BD-3605
<b>Sonata VI (YF)</b>			
2.0 110kW	06/10-		BD-3624 BD-4407
2.4 131kW	06/10-		BD-3624 BD-4407
<b>Starex</b>			
2.4 (4x4/RWD) 82kW	10/97-	MAN	BD-3613
2.5 D (4x4/RWD) 59kW	10/97-	MAN	BD-3613
<b>Terracan</b>			
2.5 TD 74kW	12/01-	MAN	BD-3617 BD-3606
2.9 CRDi	12/01-	MAN	BD-3617 BD-3606
<b>Tiburon</b>			
1.6 84kW	08/99-01/02	MAN	BD-3607 SUM BD-3612
2.0 101kW	08/99-01/02	MAN	BD-3607 SUM BD-3612
<b>Tucson</b>			
2.0 104kW	08/04-	MAN	BD-3602 MAN BD-3605
2.0 CRDi	08/04-	MAN	BD-3602 MAN BD-3605
2.7 129kW	08/04-	MAN	BD-3602 MAN BD-3605
<b>INFINITI</b>			
<b>G20</b>			
2.0 85kW	04/90-12/91	SUM	BD-5708 SUM BD-5702
	01/92-12/96	SUM	BD-3607 SUM BD-5702







• INFINITI — IZH — ISUZU — JAGUAR — JEEP — KIA





					
<b>FX</b>					
35 206kW	01/03-	TOK	BD-5737		BD-5706
37 235kW	11/08-	TOK	BD-5742		BD-5743
45 232kW	01/03-	TOK	BD-5737		BD-5706
<b>IZH</b>					
<b>2126 ODA</b>					
1.5 59kW	12/93-06/05		BD-4605		
1.6 55kW	12/93-06/05		BD-4605		
1.7 63kW	12/93-06/05		BD-4605		
<b>ISUZU</b>					
<b>Trooper</b>					
3.0 DTi 118kW	04/00-	SUM	BD-3802	SUM	BD-3803
3.1 D 84kW	08/91-07/98	SUM	BD-3802	SUM	BD-3803
3.2 130kW	08/91-07/98	SUM	BD-3802	SUM	BD-3803
3.5 158kW	04/00-	SUM	BD-3802	SUM	BD-3803
<b>JAGUAR</b>					
<b>X-Type</b>					
2.0 D 96kW	07/03-10/05	BOS	BD-3006	BOS	BD-3007
2.2 D 114kW	10/05-	BOS	BD-3006	BOS	BD-3007
2.5 V6 144kW	03/01-	BOS	BD-3006	BOS	BD-3007
3.0 V6 169kW	03/01-	BOS	BD-3006	BOS	BD-3007
<b>JEEP</b>					
<b>Cherokee</b>					
2.5 89kW	10/89-12/96	KEL	BD-4200		
2.5 TD 85kW	10/89-02/97	KEL	BD-4200		
4.0 127/135kW	10/89-12/96	KEL	BD-4200		
<b>Grand Cherokee I</b>					
2.5 TD 85kW	10/94-12/96	KEL	BD-4200		
4.0	10/93-12/96	KEL	BD-4200		
5.2 158/164kW	10/93-02/97	KEL	BD-4200		
<b>Grand Cherokee II</b>					
2.7 CRD 120kW	10/01-06/05	AKE	BD-4201		
3.1 TD 103kW	04/99-06/05	ATE	BD-4202		
4.0 140kW	04/99-06/05	ATE	BD-4202		
4.7 V8 164kW	08/00-06/05	ATE (>09/01)	BD-4202		
		AKE (10/01-09/04)	BD-4201		
		AKE (10/04>)	BD-4203		
<b>Grand Cherokee III</b>					
3.0 CRD	07/05-		BD-4203		
3.7 V6	07/05-		BD-4203		
4.7 V8	10/07-		BD-4201		
5.7 V8	07/05-		BD-4203		
<b>Wrangler</b>					
2.5 76/89kW	10/87-02/97	KEL	BD-4200		
4.0 128kW	10/91-02/97	KEL	BD-4200		
<b>KIA</b>					
<b>Besta</b>					
2.2 D 50kW	07/92-10/97	AKE	BD-4405		
<b>Bongo</b>					
2.7 D	03/97-05/02	AKE	BD-4405		
<b>Carens</b>					
1.6 77kW	07/02-		BD-4404		
1.8 93kW	07/02-		BD-4404		
2.0 CRDi	07/02-		BD-4404		





• KIA

					
<b>Carnival</b>					
2.5 121kW	10/98-05/01	KEL	BD-4200		
		SUM	BD-4406		
2.9 TDi 93kW	10/98-05/01	KEL	BD-4200		
		SUM	BD-4406		
<b>Carnival II</b>					
2.5 110kW	01/02-	SUM	BD-4406		
		KEL	BD-4200		
2.9 D 106kW	01/02-	SUM	BD-4406		
		KEL	BD-4200		
<b>Cee'd</b>					
1.4 80kW	12/06-	MAN	BD-4404	MAN	BD-4407
1.6 90kW	12/06-	MAN	BD-4404	MAN	BD-4407
2.0 105kW	12/06-	MAN	BD-4404	MAN	BD-4407
<b>Cerato</b>					
1.6 77kW	07/04-10/08	MAN	BD-4402	MAN	BD-3612
1.6 CRDi	07/04-10/08	MAN	BD-4402	MAN	BD-3612
2.0 105kW	07/04-10/08	MAN	BD-4402	MAN	BD-3612
<b>Cerato II</b>					
1.6 93kW	11/08-	MAN	BD-4404	MAN	BD-4407
2.0 115kW	11/08-	MAN	BD-4404	MAN	BD-4407
<b>Clarus</b>					
1.8 85kW	07/96-12/01	ATE	BD-4408		BD-4401
		SUM	BD-4403		
2.0 98kW	07/96-12/01	ATE	BD-4408		BD-4401
		SUM	BD-4403		
<b>Credos</b>					
1.8	06/96-11/98	ATE	BD-4408		
<b>K2500</b>					
2.5 D 69kW	01/02-	AKE	BD-4405		
<b>K2700</b>					
2.7 D 59kW	07/98-05/02	AKE	BD-4405		
<b>Magentis</b>					
2.0 100kW	05/01-07/05	AKE	BD-3607	MAN	BD-3605
2.5 V6 124kW	05/01-07/05	AKE	BD-3607	MAN	BD-3605
<b>Magentis II</b>					
2.0 106kW	08/05-	MAN	BD-3602	MAN	BD-3605
2.0 CRDi	04/06-	MAN	BD-3602	MAN	BD-3605
2.7 138kW	08/05-	MAN	BD-3602	MAN	BD-3605
<b>Opirus</b>					
3.5 149kW	09/03-		BD-3614	MAN	BD-3605
<b>Picanto</b>					
1.0 45kW	09/05-	MAN	BD-4409		
1.1 48kW	05/04-	MAN	BD-4409		
<b>Pride</b>					
1.1 40kW	05/91-04/94	SUM	BD-4410		
1.3 51/53kW	05/91-05/01	SUM	BD-4410		
<b>Pro Cee'd</b>					
1.4 80kW	12/06-	MAN	BD-4404	MAN	BD-4407
1.6 90kW	12/06-	MAN	BD-4404	MAN	BD-4407
2.0 105kW	12/06-	MAN	BD-4404	MAN	BD-4407
<b>Rio</b>					
1.3 55kW	09/00-02/05	SUM (>06/02)	BD-5105		BS-3602
		SUM (14"; 07/02>)	BD-4403		
		SUM (13"; 07/02>)	BD-4416		





					
1.5 72kW	09/00-02/05	SUM (>06/02)	BD-5105		BS-3602
		SUM (14"; 07/02>)	BD-4403		
		SUM (13"; 07/02>)	BD-4416		
<b>Rio II</b>					
1.4 16V 71kW	03/05-09/11	MAN	BD-3608	MAN	BD-4407
1.5 CRDi	03/05-09/11	MAN	BD-3608	MAN	BD-4407
1.6 16V 82kW	03/05-09/11	MAN	BD-3608	MAN	BD-4407
<b>Rio III</b>					
1.4 79kW	10/11-		BD-3619	(disc rear brakes)	BD-3620
				(drum rear brakes)	BS-3600
1.6 90kW	10/11-		BD-3619	(disc rear brakes)	BD-3620
				(drum rear brakes)	BS-3600
<b>Sedona</b>					
2.5 121kW	06/99-05/01	KEL (>05/00)	BD-4200		
		SUM (06/00>)	BD-4406		
2.9 TDi 93kW	06/99-05/01	KEL (>05/00)	BD-4200		
		SUM (06/00>)	BD-4406		
<b>Shuma</b>					
1.6 75kW	02/01-08/04	SUM	BD-4403		BD-4401
		ATE	BD-4415		
<b>Sorento (JC)</b>					
2.4 102kW	08/02-11/06	SUM	BD-4411	SUM	BD-4413
2.5 CRDi 103kW	08/02-11/06	SUM	BD-4411	SUM	BD-4413
2.5 CRDi 125kW	12/06-	MAN	BD-4411	SUM	BD-4413
3.3 V6 177kW	12/06-	SUM	BD-4411	SUM	BD-4413
3.3 V6 182kW	12/07-	MAN	BD-4411	SUM	BD-4413
3.5 V6 143kW	08/02-11/06	SUM	BD-4411	SUM	BD-4413
<b>Sorento (XM)</b>					
2.2 CRDi	11/09-	MAN	BD-3615	MAN	BD-3623
2.4 128kW	11/09-	MAN	BD-3615	MAN	BD-3623
<b>Soul</b>					
1.6 93kW	03/09-	MAN	BD-3602	AKE	BD-3620
<b>Spectra</b>					
1.6 16V 75kW	02/04-	SUM	BD-4403	(drum rear brakes)	BS-4400
				(disc rear brakes)	BD-4401
<b>Sportage (K00)</b>					
2.0 16V (4WD) 94kW	05/94-08/04	SUM	BD-4414		
2.0 TD (4WD) 61kW	05/94-08/04	SUM	BD-4414		
<b>Sportage II (JE)</b>					
2.0 16V 104kW	09/04-08/10	MAN	BD-3602	MAN	BD-3605
2.0 CRDi	09/04-08/10	MAN	BD-3602	MAN	BD-3605
2.7 V6 (4WD) 129kW	09/04-08/10	MAN	BD-3602	MAN	BD-3605
<b>Sportage III (SL)</b>					
2.0 110kW	09/10-		BD-3621		BD-4407
2.0 CRDi 100kW	09/10-		BD-3621		BD-4407
<b>LADA</b>					
<b>2101 - 2107</b>					
1.2-1.6	01/70-	BDX	BD-4603		BS-4602
<b>2108 - 21099 Samara</b>					
1.1-1.5	09/84-12/03	LUC	BD-4605		BS-4601
<b>2110 - 2112</b>					
1.5	01/95-09/05	LUC	BD-4601		BS-4601
1.6	10/05-	LUC	BD-4601		BS-4601
<b>2113 - 2115</b>					
1.5	01/00-	LUC	BD-4601		BS-4601





# • LADA — LANCIA

					
<b>1117 - 1119 Kalina</b>					
1.4 16V	08/05-	LUC	<b>BD-4601</b>		<b>BS-4601</b>
				(ABS)	<b>BS-4603</b>
1.6	08/05-	LUC	<b>BD-4601</b>		<b>BS-4601</b>
				(ABS)	<b>BS-4603</b>
<b>2170 - 2172 Priora</b>					
1.6	03/08-	LUC	<b>BD-4601</b>		<b>BS-4601</b>
				(ABS)	<b>BS-4603</b>
<b>2121 Niva</b>					
1.6 54/56kW	07/77-10/94	BDX	<b>BD-4602</b>		<b>BS-4602</b>
<b>21213 Niva</b>					
1.7 59kW	11/94-	BDX	<b>BD-4602</b>		<b>BS-4602</b>
<b>2123 Chevrolet-Niva</b>					
1.7 62kW	01/00-	BDX	<b>BD-4602</b>		<b>BS-4602</b>
<b>OKA 1111/1113</b>					
0.65	09/89-06/98		<b>BD-4607</b>		
0.75	01/98-		<b>BD-4607</b>		
<b>LANCIA</b>					
<b>Dedra</b>					
1.6 55/57kW	07/95-02/97	LUC	<b>BD-2805</b>	LUC	<b>BD-2818</b>
1.6 76kW	09/96-09/99	ATE	<b>BD-2802</b>	LUC	<b>BD-2819</b>
1.8 77kW	09/89-06/95	LUC	<b>BD-2805</b>	LUC (+ABS)	<b>BD-2818</b>
1.8 74-80kW	07/94-06/96	ATE	<b>BD-2802</b>	LUC	<b>BD-2818</b>
1.8 83/96kW	07/96-08/97	LUC	<b>BD-2805</b>	LUC	<b>BD-2819</b>
1.8 GT 16V	03/96-09/99	LUC	<b>BD-2804</b>	LUC (>12/97)	<b>BD-2818</b>
				LUC (01/98>)	<b>BD-2819</b>
2.0 83/86kW	09/89-06/95	LUC	<b>BD-2805</b>	LUC (+ABS)	<b>BD-2818</b>
2.0 Turbo 16V 102/119kW	04/90-02/96	LUC	<b>BD-2804</b>	LUC	<b>BD-2818</b>
2.0 83/86kW	07/95-08/97	LUC	<b>BD-2805</b>	LUC (>06/96)	<b>BD-2818</b>
				LUC (07/96>)	<b>BD-2819</b>
<b>Dedra Integrale</b>					
2.0 Turbo 124kW	09/89-06/95	LUC	<b>BD-2804</b>	LUC	<b>BD-2818</b>
2.0 124kW	07/95-02/96	ATE	<b>BD-2803</b>	LUC	<b>BD-2818</b>
<b>Delta</b>					
1.6 55kW	11/93-10/94	LUC	<b>BD-2805</b>	LUC (+ABS)	<b>BD-2818</b>
1.6 66/76kW	05/95-05/00	ATE	<b>BD-2801</b>	LUC (>10/96; +ABS)	<b>BD-2818</b>
				LUC (11/96>; +ABS)	<b>BD-2819</b>
1.8 76kW	05/95-10/96	ATE	<b>BD-2802</b>	LUC	<b>BD-2818</b>
		LUC	<b>BD-2805</b>		
1.8 83kW	11/96-09/99	ATE	<b>BD-2802</b>	LUC	<b>BD-2819</b>
		LUC	<b>BD-2805</b>	LUC	<b>BD-2819</b>
1.8 GT 96kW	02/96-05/00	ATE	<b>BD-2803</b>	LUC	<b>BD-2818</b>
				LUC	<b>BD-2819</b>
1.9 TD 66kW	11/94-05/00	LUC	<b>BD-2805</b>	LUC	<b>BD-2818</b>
		ATE	<b>BD-2802</b>		
2.0 GT 137/142kW	05/95-05/00	ATE	<b>BD-2803</b>	LUC (>10/96)	<b>BD-2818</b>
				LUC (10/96>)	<b>BD-2819</b>
<b>Kappa</b>					
2.0 107-151kW	10/94-12/01	LUC	<b>BD-2804</b>	LUC	<b>BD-2824</b>
		ATE (05/98>)	<b>BD-2822</b>		
2.0 Turbo 162kW	03/98-12/01	BRE	<b>BD-2823</b>	LUC	<b>BD-2824</b>
2.4 129kW	10/94-12/01	LUC	<b>BD-2804</b>	LUC	<b>BD-2824</b>
		ATE (05/98>)	<b>BD-2822</b>		
2.4 D 91kW	10/94-04/98	LUC	<b>BD-2804</b>	LUC	<b>BD-2824</b>
2.4 JTD 100kW	02/98-12/01	ATE	<b>BD-2822</b>	LUC	<b>BD-2824</b>





				
3.0 150kW	10/94-04/98	LUC (>04/98) BRE (05/98->)	BD-2804 LUC BD-2823	BD-2824
<b>Lybra</b>				
1.6 76kW	07/99-	ATE	BD-2825 LUC	BD-2827
1.8 96kW	07/99-	ATE	BD-2803 LUC	BD-2827
1.9 D 77kW	07/99-09/01	ATE	BD-2803 LUC	BD-2827
2.0 113kW	07/99-	ATE	BD-2803 LUC	BD-2827
2.4 D 99kW	07/99-	ATE	BD-2803 LUC	BD-2827
<b>Thema</b>				
2.0	06/87-09/94	LUC	BD-2805 LUC	BD-2820
2.0 Turbo 16V	01/92-05/95	LUC	BD-2806 LUC	BD-2820
3.0 V6 126kW	11/92-09/94	LUC	BD-2806 LUC	BD-2820
<b>Thesis</b>				
2.0 136kW	11/02-	LUC	BD-2826	
2.4 125kW	11/02-	LUC	BD-2826	
3.0 V6 158kW	11/02-	LUC	BD-2826	
<b>Y</b>				
1.1 40kW	09/95-07/00	BDX LUC	BD-2816 BD-2805	
1.2 44kW	09/95-	BDX LUC	BD-2816 BD-2805	
1.4 55/59kW	09/95-07/97	LUC	BD-2805	
<b>LAND ROVER</b>				
<b>Defender 90</b>				
2.5 TDi 83kW	04/93-12/94	LOC	BD-5000 LOC	BD-5006
2.5 TDi 83kW	01/95-03/98	LOC	BD-5001 LOC	BD-5006
2.5 TD5 90kW	04/98-	LOC	BD-5001	
<b>Defender 110</b>				
2.5	09/90-12/94	LOC	BD-5001	
2.5 D 83kW	09/90-12/94	LOC	BD-5001	
3.5 98kW	09/90-12/94	LOC	BD-5001	
<b>Defender 130</b>				
2.5 D 83kW	09/90-12/94	LOC	BD-5001	
3.5 98kW	09/90-08/93	LOC	BD-5001	
<b>Discovery</b>				
2.0 99kW	07/94-12/98	LOC	BD-5000 LOC	BD-5006
2.5 TDi 83kW	10/89-06/94	LOC	BD-5000 LOC	BD-5006
2.5 TDi 83/90kW	07/94-12/98	LOC	BD-5000 LOC	BD-5006
2.5 TDi 102kW	01/99-06/04	LUC	BD-5002	
3.5 113kW	10/89-06/94	LOC	BD-5000 LOC	BD-5006
4.0 134kW	07/94-12/98	LOC	BD-5000 LOC	BD-5006
4.0 136kW	01/99-06/04	LUC	BD-5002	
<b>Discovery (LA)</b>				
2.7 TD	09/09-		BD-5003	BD-5009
<b>Freelander</b>				
1.8 86kW	10/00-10/06	LUC	BD-5005	
2.0 TD 82kW	10/00-10/06	LUC	BD-5005	
2.5 V6 130kW	10/00-10/06	LUC	BD-5005	
<b>Freelander II</b>				
2.2 TD4 112/118kW	10/06-	ATE	BD-3004	BD-3005
3.2 171kW	10/06-	ATE	BD-3004	BD-3005
<b>Range Rover</b>				
2.5 TD	10/89-04/94	LOC	BD-5000 LOC	BD-5006
2.5 DT 83/100kW	05/94-01/02	LUC	BD-5002 LOC	BD-5008
3.5	10/89-08/91	LOC	BD-5000 LOC	BD-5006
3.9 127kW	10/89-04/94	LOC	BD-5000 LOC	BD-5006

• LAND ROVER — LEXUS — LIFAN — MAZDA





			
<b>Range Rover</b>			
4.0 136kW	05/94-01/01	LUC	BD-5002 LOC BD-5008
4.3 148kW	09/91-04/94	LUC	BD-5000 LOC BD-5006
4.6 160kW	05/94-01/02	LUC	BD-5002 LOC BD-5008
<b>Range Rover (LM)</b>			
3.0 TD 130kW	03/02-	ATE (>ch.Nr:5A999999)	BD-1401 ATE (>ch.Nr:5A999999) BD-1403
		LUC (ch.Nr:6A000001 >)	BD-5003 LUC (ch.Nr:6A000001 >) BD-5009
		BRE (ch.Nr:6A000001 >)	BD-5004
3.6 TD	05/05-	ATE (>ch.Nr:9A999999)	BD-1401 ATE (>ch.Nr:9A999999) BD-1403
		BRE (ch.Nr:6A000001 >)	BD-5004 LUC (ch.Nr:6A000001 >) BD-5009
4.2 291kW	05/05-	ATE (>ch.Nr:9A999999)	BD-1401 ATE (>ch.Nr:9A999999) BD-1403
		BRE (ch.Nr:6A000001 >)	BD-5004 LUC (ch.Nr:6A000001 >) BD-5009
4.4 210/225kW	03/02-	ATE (>ch.Nr:5A999999)	BD-1401 ATE (>ch.Nr:5A999999) BD-1403
		LUC (ch.Nr:6A000001 >)	BD-5003 LUC (ch.Nr:6A000001 >) BD-5009
<b>Range Rover Sport (LS)</b>			
2.7 TDVM 140kW	02/05-	TRW (>6A953688)	BD-5003 TRW BD-5009
		BRE (6A953689 >)	BD-5004
3.6 TD	02/05-	BRE	BD-5004 TRW BD-5009
4.2 291kW	02/05-	BRE	BD-5004 TRW BD-5009
4.4 225kW	02/05-	TRW	BD-5003 BD-5009
		BRE	BD-5004
<b>LEXUS</b>			
<b>GS (S147/S160)</b>			
300 156kW	03/93-08/97	SUM	BD-7524 AKE BD-7528
300 161/163kW	09/97-03/05	SUM	BD-7524 SUM BD-7518
430 208kW	07/00-03/05	SUM	BD-7524 SUM BD-7518
<b>GS (S190)</b>			
300 183kW	05/05-	AKE	BD-7566 AKE BD-7544
430 208kW	04/05-	AKE	BD-7566 AKE BD-7544
<b>IS (E10)</b>			
200 114kW	04/99-03/05	SUM	BD-7524 SUM BD-7518
300 157kW	07/01-03/05	SUM	BD-7524 SUM BD-7518
<b>IS (E20)</b>			
250 153kW	04/05-		BD-7589 AKE BD-7544
<b>LX 470 (J100)</b>			
470 170kW	02/02-06/08	SUM	BD-7503 BD-7527
<b>LX 570 (J201)</b>			
570	07/08-		BD-7580 BD-7581
<b>RX (XU1)</b>			
300 148kW	07/00-08/01	SUM	BD-7506 AKE BD-7521
300 148kW	08/01-05/03	AKE	BD-7529 AKE BD-7521
<b>RX (MCU)</b>			
300 150kW	05/03-12/08	SUM	BD-7525 SUM BD-7534
350 203kW	02/06-12/08	SUM	BD-7525 SUM BD-7534
<b>RX (MCU)</b>			
270 138kW	02/09-		BD-7596 BD-7597
350 AWD 204kW	02/09-		BD-7596 BD-7597
450h 183kW	02/09-		BD-7596 BD-7597
<b>SC</b>			
430 210kW	05/01-	SUM	BD-7524
<b>LIFAN</b>			
<b>Solano</b>			
1.6	03/10-		BD-7526 BD-7517
<b>MAZDA</b>			
<b>121</b>			
1.1 42kW	11/87-01/91	SUM	BD-4410

					
1.2 55kW	01/96-10/02	ATE	BD-3020		
1.3 44kW	11/87-01/91	SUM	BD-4410		
1.3 39/53kW	02/91-12/95	SUM	BD-5105		
1.3 37/44kW	01/96-10/02	ATE	BD-3020		
1.8 D 44kW	01/96-10/02	ATE	BD-3020		
<b>2 (DY)</b>					
1.2 55kW	04/03-09/07	ATE	BD-5108		BS-3001
1.4 59kW	04/03-09/07	ATE	BD-5108		BS-3001
<b>2 (DE)</b>					
1.3 55kW	10/07-	LUC	BD-5123		
1.5 76kW	10/07-	LUC	BD-5123		
<b>323 (BG/BA)</b>					
1.3 49/54kW	06/89-07/98	SUM	BD-5105		
1.5 65kW	05/94-04/98	SUM	BD-5105		
1.6 62/65kW	06/89-04/94	SUM	BD-5105		
1.7 D 41kW	06/89-04/94	SUM	BD-5105		
1.8 94kW	06/89-04/94	SUM	BD-5105		
		SUM	BD-5120		
1.8 84kW	05/94-04/98	SUM	BD-5120		
2.0 D 52kW	03/97-04/98	SUM	BD-5120		
<b>323 (BJ)</b>					
1.4 53kW	10/00-12/03	SUM	BD-5103	AKE (+ABS)	BD-5104
1.5 16V 65kW	08/98-01/01	SUM	BD-5103		
1.6 72kW	10/00-12/03	SUM	BD-5101	AKE	BD-5104
1.8 84kW	05/98-09/00	SUM	BD-5101	AKE	BD-5104
2.0 D 52/66kW	05/98-09/00	SUM	BD-5101		
2.0 TD 74kW	10/00-12/03	SUM	BD-5101	AKE	BD-5104
<b>3 (BK12/BK14)</b>					
1.4 59/62kW	10/03-06/09	ATE	BD-3001	ATE	BD-5901
1.6 TDi 80kW	10/03-06/09	ATE	BD-3001	ATE	BD-5901
1.6 77kW	10/03-06/09	ATE	BD-3001	ATE	BD-5901
2.0 110kW	10/03-06/09	ATE	BD-3001	ATE	BD-5901
<b>3 (BL)</b>					
1.6 77kW	06/09-	ATE	BD-3001	ATE	BD-5901
2.0 110kW	06/09-	ATE	BD-3001	ATE	BD-5901
<b>5</b>					
1.8 85kW	03/05-	ATE	BD-3001	ATE	BD-5901
2.0 107kW	03/05-	ATE	BD-3001	ATE	BD-5901
2.0 D 81/105kW	03/05-	ATE	BD-3001	ATE	BD-5901
<b>626 (GE)</b>					
1.8 77kW	08/91-10/97	SUM	BD-5101	NBK	BD-3029
2.0 85kW	08/91-03/97	SUM	BD-5101	NBK	BD-3029
2.0 D 55kW	08/91-03/97	SUM	BD-5101	NBK	BD-3029
2.5 120kW	08/91-03/97	SUM	BD-5101	NBK	BD-3029
<b>626 (GF)</b>					
1.8 66kW	04/97-07/99	SUM (14")	BD-5101	AKE	BD-5104
		SUM (15")	BD-5119		
1.8 74kW	08/99-04/02	SUM (14")	BD-5101	AKE	BD-5104
		SUM (15")	BD-5119		
2.0 85kW	04/97-07/99	SUM (14")	BD-5101	AKE	BD-5104
		SUM (15")	BD-5119		
2.0 85/100kW	08/99-04/02	SUM (15")	BD-5119	AKE	BD-5104
<b>6 (GG)</b>					
1.8 88kW	04/02-06/07	SUM	BD-5111	AKE	BD-5104
2.0 104/108kW	04/02-06/07	AKE	BD-5112	AKE	BD-5104
2.3 122kW	04/02-06/07	AKE	BD-5112	AKE	BD-5104

## • MAZDA — MERCEDES-BENZ





			
<b>6 (GH)</b>			
1.8 88kW	08/07-	AKE	BD-5118 AKE BD-5104
2.0 108kW	08/07-	AKE	BD-5118 AKE BD-5104
2.5 125kW	08/07-	AKE	BD-5118 AKE BD-5104
<b>CX-7</b>			
2.3 Turbo 190kW	10/07-	SUM	BD-5116 BD-5124
2.5 MZR	10/07-	SUM	BD-5116 BD-5124
<b>Demio</b>			
1.3	01/03-	ATE	BD-5105
1.5	01/03-	ATE	BD-5105
<b>E2200</b>			
2.2 D (RWD)	09/99-	SUM	BD-5113
<b>MPV</b>			
2.5 D 85kW	12/95-05/99	SUM	BD-5113 AKE BD-5121
3.0 V6 109/113kW	12/95-05/99	SUM	BD-5113 AKE BD-5121
<b>MX-3</b>			
1.6 65/80kW	03/91-12/98	SUM	BD-5120 SUM (+ ABS) BD-2404
1.8 98kW	03/91-12/98	SUM	BD-5120 SUM (+ ABS) BD-2404
<b>MX-5 (NA)</b>			
1.6 66kW	12/94-	SUM	BD-5122
1.8 96kW	09/93-11/94	SUM	BD-5122
<b>MX-5 (NB)</b>			
1.6 16V 81kW	05/98-01/01	SUM	BD-5122
1.8 16V 103kW	05/98-01/01	SUM	BD-5122
<b>MX-6</b>			
2.0 85kW	07/91-02/97	SUM	BD-5101 NBK BD-3029
2.5 121kW	07/91-02/97	SUM	BD-5101 NBK BD-3029
<b>Premacy</b>			
1.8 74kW	07/99-	SUM	BD-5101 AKE (08/01>) BD-5104
2.0 96kW	07/99-	SUM	BD-5101 AKE (08/01>) BD-5104
2.0 D 66/74kW	08/01-	SUM	BD-5101 AKE (08/01>) BD-5104
<b>Tribute</b>			
2.0 91kW	03/00-	ATE	BD-5115
2.3 AWD 110kW	04/04-	ATE	BD-5115
3.0 V6 145kW	03/00-	ATE	BD-5115
<b>Xedos 6</b>			
1.6 16V 79/83kW	01/92-10/98	SUM	BD-5101 NBK BD-3029
2.0 103/106kW	01/92-10/99	SUM	BD-5101 NBK BD-3029
<b>Xedos 9</b>			
2.0 105kW	09/93-08/00	AKE	BD-5114 AKE BD-5121
2.3 155kW	11/94-08/00	AKE	BD-5114 AKE BD-5121
2.5 123kW	09/93-10/02	AKE	BD-5114 AKE BD-5121
<b>MERCEDES-BENZ</b>			
<b>190 (W201)</b>			
1.8 E 80kW	10/88-05/93	LUC	BD-5304 ATE (+ ASR) BD-5311
			ATE (- ASR) BD-5322
2.0 77-85kW	07/85-05/93	LUC	BD-5304 ATE (- ASR) BD-5322
			ATE (+ ASR) BD-5311
2.0 D 55-66kW	11/86-05/93	LUC	BD-5304 ATE (- ASR) BD-5322
			ATE (+ ASR) BD-5311
2.3 E 16V 125-136kW	10/83-09/88	LUC	BD-5301 ATE BD-5312
2.3 E 97/100kW	11/86-05/93	LUC	BD-5304 ATE (- ASR) BD-5322
			ATE (+ ASR) BD-5311
2.5-16 E 143kW	01/87-08/91	LUC	BD-5301 ATE BD-5312
2.5 E 173kW	05/91-05/93	ATE	BD-5305 ATE BD-5314



			
2.5 D/TD	10/84-05/93	LUC	<b>BD-5304</b> ATE (- ASR) <b>BD-5322</b>
			ATE (+ ASR) <b>BD-5311</b>
2.6 E 118/122kW	11/86-05/93	LUC	<b>BD-5304</b> ATE (- ASR) <b>BD-5322</b>
			ATE (+ ASR) <b>BD-5311</b>
<b>200 (W124/C124)</b>			
2.0 75-90kW	03/85-05/93	LUC	<b>BD-5301</b> ATE (+ ASR) <b>BD-5311</b>
			ATE (- ASR) <b>BD-5312</b>
<b>220 (S124)</b>			
2.2 110kW	06/92-05/93	LUC	<b>BD-5301</b> ATE <b>BD-5314</b>
<b>230 (W124/C124)</b>			
2.3 97/100kW	03/85-05/93	LUC	<b>BD-5301</b> ATE (+ ASR) <b>BD-5311</b>
			ATE (- ASR) <b>BD-5312</b>
<b>230 (S124)</b>			
2.3 97/100kW	03/85-05/93	LUC	<b>BD-5301</b> ATE <b>BD-5314</b>
<b>250 (W124)</b>			
2.5 TD 93kW	03/85-08/89	LUC	<b>BD-5301</b> ATE (+ ASR) <b>BD-5311</b>
		LUC	<b>BD-5301</b> ATE (- ASR) <b>BD-5312</b>
<b>260 (W124)</b>			
2.6 122kW	03/85-05/93	LUC	<b>BD-5301</b> ATE <b>BD-5314</b>
<b>280 (S124)</b>			
2.8 24V	06/92-05/93	LUC	<b>BD-5301</b> ATE <b>BD-5314</b>
<b>300 (W124)</b>			
3.0 D/TD (RWD/4 Matic)	03/85-05/93	LUC	<b>BD-5301</b> ATE (+ ASR) <b>BD-5311</b>
		LUC	<b>BD-5301</b> ATE (- ASR) <b>BD-5312</b>
<b>300 (C124)</b>			
3.0 132/138kW	05/87-05/93	LUC	<b>BD-5301</b> ATE (+ ASR) <b>BD-5311</b>
			ATE (- ASR) <b>BD-5312</b>
3.0 CE-24 162kW	09/89-05/93	ATE	<b>BD-5305</b> ATE <b>BD-5314</b>
<b>300 (W124)</b>			
3.0 E (RWD/4 Matic) 132/138kW	09/89-05/93	LUC	<b>BD-5301</b> ATE (+ ASR) <b>BD-5311</b>
			ATE (- ASR) <b>BD-5312</b>
3.0 24V 162kW	09/89-05/93	ATE	<b>BD-5305</b> ATE <b>BD-5314</b>
<b>300 (S124)</b>			
3.0 D/TD	03/85-08/89	LUC	<b>BD-5301</b> ATE <b>BD-5314</b>
3.0 TE	09/89-05/93	LUC	<b>BD-5301</b> ATE <b>BD-5314</b>
3.0 E-24 162kW	09/89-05/93	ATE	<b>BD-5305</b> ATE <b>BD-5314</b>
<b>400 (W124)</b>			
4.2 E 205kW	08/92-06/93	ATE	<b>BD-5305</b> ATE <b>BD-5314</b>
<b>500 (W124)</b>			
5.0 E 240kW	01/91-06/93	ATE	<b>BD-5305</b> ATE <b>BD-5314</b>
<b>A-Class (W168)</b>			
A 140 60kW	03/01-08/04	LUC	<b>BD-5306</b>
A 160 75kW	06/97-02/01	LUC	<b>BD-5306</b>
A 160 L (Long Chassis) 75kW	03/01-08/04	LUC	<b>BD-5306</b> LUC <b>BD-5310</b>
A 170 CDI 66kW	03/98-08/04	LUC	<b>BD-5306</b>
A 170 CDI 70kW	03/01-08/04	LUC	<b>BD-5306</b> LUC <b>BD-5310</b>
A 190 92kW	02/99-08/04	LUC	<b>BD-5306</b> LUC <b>BD-5310</b>
A 210 103kW	02/02-08/04	LUC	<b>BD-5306</b> LUC <b>BD-5310</b>
<b>A-Class (W169)</b>			
A 150 70kW	09/04-	LUC	<b>BD-5307</b> LUC <b>BD-5310</b>
A 160 CDI 60kW	09/04-	LUC	<b>BD-5307</b> LUC <b>BD-5310</b>
A 170 85kW	09/04-	LUC	<b>BD-5308</b> LUC <b>BD-5310</b>
A 200 100kW	09/04-	LUC	<b>BD-5308</b> LUC <b>BD-5310</b>
<b>B-Class (W245)</b>			
B 150 70kW	03/05-	LUC	<b>BD-5308</b> LUC <b>BD-5310</b>
B 170 85kW	03/05-	LUC	<b>BD-5308</b> LUC <b>BD-5310</b>





# • MERCEDES-BENZ

			
<b>B-Class (W245)</b>			
B 200 100kW	03/05-	LUC	<b>BD-5309</b> LUC <b>BD-5310</b>
B 200 CDI 103kW	03/05-	LUC	<b>BD-5309</b> LUC <b>BD-5310</b>
<b>C-Class (W202)</b>			
C 180 90kW	06/93-05/00	LUC	<b>BD-5303</b> ATE (+ ASR) <b>BD-5311</b>
			ATE (- ASR) <b>BD-5312</b>
			ATE (01/96>) <b>BD-5313</b>
C 200 100kW	06/93-05/00	LUC	<b>BD-5303</b> ATE (+ ASR) <b>BD-5311</b>
			ATE (- ASR) <b>BD-5312</b>
			ATE (01/96>) <b>BD-5313</b>
C 200 D 55kW	06/93-12/95	LUC	<b>BD-5303</b> ATE (+ ASR) <b>BD-5311</b>
			ATE (- ASR) <b>BD-5312</b>
C 200 Kompressor 132/141kW	09/95-10/00	ATE	<b>BD-5302</b> ATE (>03/97) <b>BD-5314</b>
			ATE (04/97>) <b>BD-5315</b>
C 200 D 65/75kW	01/96-05/00	LUC	<b>BD-5303</b> ATE <b>BD-5313</b>
C 220 110kW	06/93-05/00	LUC	<b>BD-5303</b> ATE (+ ASR) <b>BD-5311</b>
			ATE (- ASR) <b>BD-5312</b>
			ATE (01/96>) <b>BD-5313</b>
C 220 D 70kW	06/93-12/95	LUC	<b>BD-5303</b> ATE (+ ASR) <b>BD-5311</b>
			ATE (- ASR) <b>BD-5312</b>
C 220 CDI 92kW	01/96-05/00	LUC	<b>BD-5303</b> ATE <b>BD-5313</b>
C 230 Kompressor 142kW	09/95-06/96	ATE	<b>BD-5302</b> ATE <b>BD-5314</b>
			ATE <b>BD-5315</b>
C 240 125kW	07/96-10/00	ATE	<b>BD-5302</b> ATE <b>BD-5315</b>
C 250 83kW	06/93-08/95	LUC	<b>BD-5303</b> ATE (+ ASR) <b>BD-5311</b>
			ATE (- ASR) <b>BD-5312</b>
C 250 TD 110kW	09/95-10/00	ATE	<b>BD-5302</b> ATE (>06/96) <b>BD-5314</b>
			ATE (07/96>) <b>BD-5315</b>
C 280 142kW	06/93-01/96	LUC	<b>BD-5303</b> ATE (+ ASR) <b>BD-5311</b>
			ATE (- ASR) <b>BD-5312</b>
C 280 145kW	09/95-10/00	ATE	<b>BD-5302</b> ATE (>10/97) <b>BD-5314</b>
			ATE (11/97>) <b>BD-5315</b>
C 36 AMG 206kW	02/94-03/97	ATE	<b>BD-5305</b> ATE (>08/95) <b>BD-5314</b>
			ATE (09/95>) <b>BD-5316</b>
<b>C-Class (S202)</b>			
C 180 90kW	02/96-10/00	LUC	<b>BD-5303</b> ATE (>03/97) <b>BD-5314</b>
			ATE (04/97>) <b>BD-5315</b>
C 200 D 65/75kW	07/95-03/97	LUC	<b>BD-5303</b> ATE <b>BD-5314</b>
C 200 Kompressor 132/141kW	09/95-10/00	ATE	<b>BD-5302</b> ATE (>03/97) <b>BD-5314</b>
			ATE (04/97>) <b>BD-5315</b>
C 200 100kW	02/96-10/00	LUC	<b>BD-5303</b> ATE (>03/97) <b>BD-5314</b>
			ATE (04/97>) <b>BD-5315</b>
C 200 D/CDI 65/75kW	04/97-05/00	LUC	<b>BD-5303</b> ATE <b>BD-5315</b>
C 220 D 55/70kW	02/96-10/00	LUC	<b>BD-5303</b> ATE (>03/97) <b>BD-5314</b>
			<b>BD-5303</b> ATE (04/97>) <b>BD-5315</b>
C 230 Kompressor 142kW	07/96-05/00	ATE	<b>BD-5302</b> ATE <b>BD-5315</b>
C 240 125kW	07/96-10/00	ATE	<b>BD-5302</b> ATE <b>BD-5315</b>
C 250 TD 110kW	06/96-02/01	ATE	<b>BD-5302</b> ATE (>03/97) <b>BD-5314</b>
			ATE (04/97>) <b>BD-5315</b>
C 280 145kW	11/97-10/00	ATE	<b>BD-5302</b> ATE <b>BD-5315</b>
<b>C-Class (W203)</b>			
C 180 95kW	06/00-08/02	LUC (without sports package)	<b>BD-5317</b> ATE <b>BD-5315</b>
C 180 Kompressor 105kW	05/02-03/07	LUC (without sports package)	<b>BD-5317</b> ATE <b>BD-5315</b>
C 200 Kompressor 120kW	06/00-03/07	LUC (without sports package)	<b>BD-5317</b> ATE <b>BD-5315</b>
C 200 CDI 85kW	06/00-03/07	LUC (without sports package)	<b>BD-5317</b> ATE <b>BD-5315</b>
C 220 CDI 105kW	06/00-03/07	LUC (without sports package)	<b>BD-5317</b> ATE <b>BD-5315</b>





					
C 230 Kompressor 141kW	02/04-03/07	LUC (without sports package)	BD-5317		
C 240 125kW	06/00-03/07	LUC (without sports package)	BD-5317		
C 320 160kW	06/00-03/07	LUC (without sports package)	BD-5317		
<b>C-Class (CL203)</b>					
C 180 95kW	06/00-08/02	LUC (without sports package)	BD-5317	ATE	BD-5315
C 180 Kompressor 105kW	05/02-	LUC (without sports package)	BD-5317	ATE	BD-5315
C 200 Kompressor 120kW	06/00-	LUC (without sports package)	BD-5317	ATE	BD-5315
C 220 CDI 105kW	06/00-	LUC (without sports package)	BD-5317	ATE	BD-5315
C 230 Kompressor 141kW	09/00-07/02	LUC (without sports package)	BD-5317		
<b>C-Class (W204)</b>					
C 180 Kompressor 115kW	04/07-	LUC	BD-5318	ATE	BD-5319
C 200 CDI 100kW	04/07-	LUC	BD-5318	ATE	BD-5319
C 200 Kompressor 135kW	04/07-	LUC	BD-5318	ATE	BD-5319
C 220 CDI 125kW	04/07-	LUC	BD-5318	ATE	BD-5319
C 230 150kW	04/07-	LUC	BD-5318	ATE	BD-5319
C 280 170kW	04/07-	LUC	BD-5318	ATE	BD-5319
C 320 CDI 165kW	04/07-	LUC	BD-5318	ATE	BD-5319
C 350 200kW	04/07-	LUC	BD-5318	ATE	BD-5319
<b>CLK-Class (C208)</b>					
CLK 200 Kompressor 141kW	04/97-07/02	ATE	BD-5302	ATE (1 fixed pin)	BD-5315
CLK 200 100kW	06/98-07/02	ATE	BD-5302	ATE (1 fixed pin)	BD-5315
CLK 230 Kompressor 142kW	04/97-07/02	ATE	BD-5302	ATE (1 fixed pin)	BD-5315
CLK 320 160kW	04/97-07/02	ATE	BD-5320	ATE (2 fixed pin)	BD-5316
CLK 430 205kW	04/97-07/02	ATE	BD-5320	ATE (2 fixed pin)	BD-5316
<b>CLK-Class (C209)</b>					
CLK 200 Kompressor 120kW	09/02-	ATE (without sports package)	BD-5317	ATE	BD-5315
CLK 240 125kW	06/02-	ATE (without sports package)	BD-5317	ATE	BD-5315
CLK 320 160kW	06/02-	ATE (without sports package)	BD-5317	ATE	BD-5315
<b>E-Class (W124)</b>					
E 200 100kW	06/93-06/95	LUC	BD-5301	ATE (+ ASR)	BD-5311
				ATE (- ASR)	BD-5312
E 200 D 55kW	06/93-06/95	LUC	BD-5301	ATE (+ ASR)	BD-5311
				ATE (- ASR)	BD-5312
E 220 110kW	06/93-06/95	LUC	BD-5301	ATE (+ ASR)	BD-5311
				ATE (- ASR)	BD-5312
E 250 TD 93kW	06/93-06/95	LUC	BD-5301	ATE (+ ASR)	BD-5311
				ATE (- ASR)	BD-5312
E 280 145kW	06/93-06/95	LUC	BD-5301	ATE (+ ASR)	BD-5311
				ATE (- ASR)	BD-5312
E 300 (4 Matic) 132kW	06/93-06/95	LUC	BD-5301	ATE (+ ASR)	BD-5311
				ATE (- ASR)	BD-5312
E 300 TD 108kW	06/93-06/95	LUC	BD-5301	ATE (+ ASR)	BD-5311
				ATE (- ASR)	BD-5312
E 320 162kW	06/93-07/96	ATE	BD-5305	ATE	BD-5314
E 420 205kW	06/93-06/95	ATE	BD-5305	ATE	BD-5314
E 500 235kW	06/93-06/95	ATE	BD-5305	ATE	BD-5316
<b>E-Class (C124)</b>					
E 200 100kW	06/93-07/96	LUC	BD-5301	ATE (+ ASR)	BD-5311
				ATE (- ASR)	BD-5312
E 220 110kW	06/93-07/96	LUC	BD-5301	ATE (+ ASR)	BD-5311
				ATE (- ASR)	BD-5312
E 320 162kW	06/93-07/96	ATE	BD-5305	ATE	BD-5314
E 36 AMG 195kW	06/93-02/95	ATE	BD-5305	ATE	BD-5314
<b>E-Class (S124)</b>					
E 200 100kW	06/93-07/96	LUC	BD-5301	ATE	BD-5314
E 220 110kW	06/93-07/96	LUC	BD-5301	ATE	BD-5314

# • MERCEDES-BENZ





			
<b>E-Class (S124)</b>			
E 250 TD 93kW	06/93-01/96	LUC	<b>BD-5301</b> ATE <b>BD-5314</b>
E 280 145kW	06/93-01/96	LUC	<b>BD-5301</b> ATE <b>BD-5314</b>
E 300 (4 Matic) 132kW	06/93-01/96	LUC	<b>BD-5301</b> ATE <b>BD-5314</b>
E 300 TD (RWD/4 Matic) 108kW	06/93-01/96	LUC	<b>BD-5301</b> ATE <b>BD-5314</b>
E 320 162kW	06/93-07/96	ATE	<b>BD-5305</b> ATE <b>BD-5314</b>
<b>E-Class (W210)</b>			
E 200 100kW	07/95-03/02	ATE	<b>BD-5302</b> ATE (>06/96) <b>BD-5314</b>
			ATE (07/96>) <b>BD-5315</b>
E 200 Kompressor 137kW	04/97-03/02	ATE	<b>BD-5320</b> ATE <b>BD-5321</b>
E 200 65kW	07/95-06/96	ATE	<b>BD-5302</b> ATE <b>BD-5314</b>
E 200 CDI 65kW	07/96-03/02	ATE	<b>BD-5302</b> ATE <b>BD-5315</b>
E 200 CDI 75-105kW	05/98-03/02	ATE	<b>BD-5302</b> ATE <b>BD-5315</b>
E 220 55/70kW	07/95-06/96	ATE	<b>BD-5302</b> ATE <b>BD-5314</b>
E 220 CDI 75-105kW	07/96-03/02	ATE	<b>BD-5302</b> ATE <b>BD-5315</b>
E 230 110kW	07/95-10/97	ATE	<b>BD-5302</b> ATE (>06/96) <b>BD-5314</b>
			ATE (07/96>) <b>BD-5315</b>
E 240 125kW	04/97-03/02	ATE (+ ESP)	<b>BD-5320</b> ATE (+ EDS) <b>BD-5321</b>
		ATE (- ESP)	<b>BD-5302</b> ATE (- EDS) <b>BD-5315</b>
E 250 83kW	07/95-08/99	ATE	<b>BD-5302</b> ATE <b>BD-5314</b>
E 250 TD 110kW	07/96-07/00	ATE	<b>BD-5302</b> ATE <b>BD-5315</b>
E 270 CDI 125kW	07/99-03/02	ATE	<b>BD-5320</b> ATE <b>BD-5321</b>
E 280 142kW	07/95-06/96	ATE	<b>BD-5320</b> ATE <b>BD-5316</b>
E 280 (RWD/4 Matic) 150kW	04/97-03/02	ATE	<b>BD-5320</b> ATE <b>BD-5321</b>
E 290 TD 95kW	07/95-08/99	ATE	<b>BD-5302</b> ATE (>06/96) <b>BD-5314</b>
			ATE (07/96>) <b>BD-5315</b>
E 300 100kW	07/95-10/97	ATE	<b>BD-5302</b> ATE (1 fixed pin) <b>BD-5315</b>
E 300 TDI 130kW	10/96-08/99	ATE	<b>BD-5320</b> ATE <b>BD-5321</b>
E 320 162kW	07/95-06/97	ATE	<b>BD-5320</b> ATE (2 fixed pin) <b>BD-5316</b>
E 320 (RWD/4 Matic) 165kW	07/96-03/02	ATE	<b>BD-5320</b> ATE <b>BD-5321</b>
E 320 CDI 145kW	07/99-03/02	ATE	<b>BD-5320</b> ATE <b>BD-5321</b>
E 420 205kW	07/95-10/97	ATE	<b>BD-5305</b> ATE (>06/96) <b>BD-5316</b>
			ATE (07/96>) <b>BD-5321</b>
E 430 205kW	04/97-03/02	ATE	<b>BD-5305</b> ATE (>03/98; 2 fixed pin) <b>BD-5316</b>
			ATE (04/98>) <b>BD-5321</b>
<b>E-Class (S210)</b>			
E 200 100kW	02/96-07/00	ATE	<b>BD-5302</b> ATE <b>BD-5316</b>
E 200 Kompressor 137kW	11/97-07/00	ATE	<b>BD-5320</b> ATE <b>BD-5316</b>
E 220 CDI 92/105kW	06/98-03/02	ATE	<b>BD-5302</b> ATE <b>BD-5316</b>
E 230 110kW	02/96-10/97	ATE	<b>BD-5302</b> ATE <b>BD-5316</b>
E 240 125kW	10/97-03/03	ATE (+ ESP; >07/00)	<b>BD-5320</b> ATE <b>BD-5316</b>
		ATE (- ESP; >07/00)	<b>BD-5302</b>
		ATE (08/00>)	<b>BD-5302</b>
E 250 TD 83/110kW	11/97-09/99	ATE	<b>BD-5302</b> ATE <b>BD-5316</b>
E 270 CDI 125kW	07/99-03/03	ATE	<b>BD-5320</b> ATE <b>BD-5316</b>
E 280 (RWD/4 Matic) 150kW	11/97-03/03	ATE	<b>BD-5320</b> ATE <b>BD-5316</b>
E 290 TD 95kW	02/96-08/99	ATE	<b>BD-5302</b> ATE <b>BD-5316</b>
E 320 (RWD/4 Matic) 165kW	04/97-03/03	ATE	<b>BD-5320</b> ATE <b>BD-5316</b>
E 320 CDI 145kW	07/99-03/03	ATE	<b>BD-5320</b> ATE <b>BD-5316</b>
E 420 205kW	02/96-10/97	ATE	<b>BD-5305</b> ATE <b>BD-5316</b>
E 430 205kW	11/97-07/99	ATE	<b>BD-5305</b> ATE <b>BD-5316</b>
<b>E-Class (W211)</b>			
E 200 Kompressor 120kW	04/02-12/08	BOS (without sports package)	<b>BD-5323</b> ATE <b>BD-5325</b>
E 200 CDI 75/90kW	04/02-12/08	BOS	<b>BD-5323</b> ATE <b>BD-5325</b>
E 220 CDI 110kW	04/02-12/08	BOS	<b>BD-5323</b> ATE <b>BD-5325</b>
E 240 130kW	04/02-12/08	BOS	<b>BD-5323</b> ATE <b>BD-5325</b>

			
E 270 CDI 130kW	04/02-12/08	BOS	<b>BD-5323</b> ATE <b>BD-5325</b>
E 320 165kW	04/02-12/08	BRE	<b>BD-5324</b> ATE <b>BD-5325</b>
		BOS (vers. USA/Japan)	<b>BD-5323</b>
E 350 200kW	03/05-12/08	BRE	<b>BD-5324</b> ATE <b>BD-5325</b>
E 500 225kW	04/02-12/08	BRE	<b>BD-5324</b> ATE <b>BD-5325</b>
<b>E-Class (W212)</b>			
E 200 CGI	01/09-	LUC (212.048, without sports package)	<b>BD-5318</b> ATE <b>BD-5325</b>
		LUC (212.148, with sports package)	<b>BD-5350</b>
E 200 CDI	01/09-	LUC	<b>BD-5318</b> ATE <b>BD-5325</b>
E 220 CDI	01/09-	LUC	<b>BD-5318</b> ATE <b>BD-5325</b>
E 250 CDI	01/09	LUC (> ch.Nr. A001284)	<b>BD-5318</b> ATE <b>BD-5325</b>
		LUC (ch.Nr. A001285 >)	<b>BD-5350</b>
E 250 CGI	01/09	LUC	<b>BD-5350</b> ATE <b>BD-5325</b>
E 300 (RWD/4 Matic)	01/09-	LUC	<b>BD-5350</b> ATE <b>BD-5325</b>
E 350 (RWD/4 Matic)	01/09-	LUC	<b>BD-5350</b> ATE <b>BD-5325</b>
<b>M-Class (W163)</b>			
ML 230 110kW	02/98-06/05	KEL	<b>BD-5326</b> KEL (Ch. A083269>) <b>BD-5328</b>
ML 270 CDI 120kW	02/98-06/05	KEL (>Ch. A289559)	<b>BD-5326</b> KEL (>Ch. A289559) <b>BD-5328</b>
		BRE (Ch. A289560>)	<b>BD-5327</b> KEL (Ch. A289560>) <b>BD-5329</b>
ML 320 160kW	02/98-06/05	KEL (>Ch. A289559)	<b>BD-5326</b> KEL (>Ch. A289559) <b>BD-5328</b>
		BRE (Ch. A289560>)	<b>BD-5327</b> KEL (Ch. A289560>) <b>BD-5329</b>
ML 430 200kW	02/98-06/05	KEL (>Ch. A145272)	<b>BD-5326</b> KEL <b>BD-5329</b>
		BRE (Ch. A145273>)	<b>BD-5327</b>
ML 55 AMG 255kW	02/00-06/05	BRE	<b>BD-5327</b> KEL <b>BD-5329</b>
<b>M-Class (W164)</b>			
ML 280 CDI 140kW	07/05-	ATE	<b>BD-5330</b> ATE <b>BD-5332</b>
ML 320 CDI 165kW	07/05-	ATE	<b>BD-5330</b> ATE <b>BD-5332</b>
ML 350 200kW	07/05-	ATE	<b>BD-5330</b> ATE <b>BD-5332</b>
ML 500 225kW	07/05-	ATE	<b>BD-5331</b> ATE <b>BD-5332</b>
		ATE (vers. USA/Japan)	<b>BD-5330</b>
<b>S-Class (W140)</b>			
S 280 142kW	06/93-01/99	ATE	<b>BD-5333</b> ATE <b>BD-5316</b>
S 300 TD 130kW	06/96-08/98	ATE	<b>BD-5333</b> ATE <b>BD-5316</b>
S 320 170kW	06/93-08/98	ATE	<b>BD-5333</b> ATE <b>BD-5316</b>
S 350 TD 110kW	06/93-08/98	ATE	<b>BD-5333</b> ATE <b>BD-5316</b>
S 420 210kW	06/93-08/98	ATE	<b>BD-5333</b> ATE <b>BD-5316</b>
S 500 240kW	06/93-08/98	ATE	<b>BD-5333</b> ATE <b>BD-5316</b>
S 600 290/300kW	06/93-08/98	ATE	<b>BD-5333</b> ATE <b>BD-5316</b>
<b>S-Class (W220)</b>			
S 280 150kW	10/98-10/05	ATE (>09/02)	<b>BD-5327</b> ATE (>09/02) <b>BD-5334</b>
		ATE (10/02>)	<b>BD-5324</b> ATE (10/02>) <b>BD-5325</b>
S 320 165kW	10/98-10/05	ATE (>09/02)	<b>BD-5327</b> ATE (>09/02) <b>BD-5334</b>
		ATE (10/02>)	<b>BD-5324</b> ATE (10/02>) <b>BD-5325</b>
S 430 205kW	09/98-10/05	ATE (>09/02)	<b>BD-5327</b> ATE (>09/02) <b>BD-5334</b>
		ATE (10/02>)	<b>BD-5324</b> ATE (10/02>) <b>BD-5325</b>
S 500 225kW	09/98-10/05	ATE (>09/02)	<b>BD-5327</b> ATE (>09/02) <b>BD-5334</b>
		ATE (10/02>)	<b>BD-5324</b> ATE (10/02>) <b>BD-5325</b>
S 55 AMG 265kW	09/99-09/02	ATE	<b>BD-5327</b> ATE <b>BD-5334</b>
S 600 270kW	09/98-09/02	ATE	<b>BD-5327</b> ATE <b>BD-5334</b>
S 600 368kW	09/02-10/05	ATE	<b>BD-5324</b> ATE <b>BD-5325</b>
<b>S-Class (W221)</b>			
S 350 200kW	10/05-	BRE	<b>BD-5349</b> ATE <b>BD-5325</b>
S 500 285kW	10/05-	BRE	<b>BD-5349</b> ATE <b>BD-5325</b>
<b>SL-Class (R129)</b>			
SL 280 142kW	06/93-05/98	ATE (-ESP)	<b>BD-5305</b> ATE <b>BD-5314</b>





# • MERCEDES-BENZ

				
<b>SL-Class (R129)</b>				
SL 280 150kW	06/98-07/01	ATE (>12/99)	<b>BD-5305</b> ATE	<b>BD-5316</b>
		ATE (01/00>)	<b>BD-5327</b>	
SL 320 170kW	06/93-07/01	ATE (-ESP; >06/98)	<b>BD-5305</b> ATE (>05/98)	<b>BD-5314</b>
		ATE (01/00>)	<b>BD-5327</b> ATE (06/98>)	<b>BD-5316</b>
SL 500 225/235kW	06/93-05/98	ATE (>06/98)	<b>BD-5305</b> ATE (>05/98)	<b>BD-5314</b>
		ATE (06/98>)	<b>BD-5327</b> ATE (06/98>)	<b>BD-5316</b>
SL 600 290kW	06/93-07/01	ATE	<b>BD-5305</b> ATE	<b>BD-5316</b>
SL 60 AMG 280kW	11/94-07/99	ATE	<b>BD-5305</b> ATE	<b>BD-5316</b>
<b>SLK-Class (R170)</b>				
SLK 200 100kW / Kompressor 140kW	09/96-03/00	ATE	<b>BD-5302</b> ATE (>01/97)	<b>BD-5314</b>
				ATE (02/97>)
SLK 230 Kompressor 142kW	09/96-03/00	ATE	<b>BD-5302</b> ATE (>01/97)	<b>BD-5314</b>
				ATE (02/97>)
SLK 230 160kW	10/99-04/04	ATE	<b>BD-5320</b> ATE	<b>BD-5315</b>
<b>G-Class (W461)</b>				
2.9 D 70kW	06/93-07/01	PER	<b>BD-5335</b>	
	06/93-07/01	BDX	<b>BD-5336</b>	
<b>G-Class (W463)</b>				
230 G 93kW	09/89-05/93	BDX	<b>BD-5336</b>	
230 GE 66/93kW	07/82-07/00	PER	<b>BD-5335</b>	
		BDX	<b>BD-5336</b>	
250 GD 69kW	09/89-05/93	PER	<b>BD-5335</b>	
		BDX	<b>BD-5336</b>	
300 GD 83kW	09/89-08/93	PER	<b>BD-5335</b>	
		BDX	<b>BD-5336</b>	
300 GE 125kW	09/89-05/93	PER	<b>BD-5335</b>	
350 GD TD 100kW	09/93-08/96	PER	<b>BD-5335</b>	
		BDX	<b>BD-5336</b>	
G 270 115kW	08/01-	PER	<b>BD-5335</b> BOS	<b>BD-5340</b>
G 300 130kW	09/96-07/00	PER	<b>BD-5335</b> BOS	<b>BD-5340</b>
G 320 158kW	09/93-	PER	<b>BD-5335</b> BOS	<b>BD-5340</b>
G 36 AMG 200kW	09/95-08/99	PER	<b>BD-5335</b> BOS	<b>BD-5340</b>
G 400 184kW	07/00-	BDX	<b>BD-5336</b> BOS	<b>BD-5340</b>
		PER	<b>BD-5335</b>	
G 500 218kW	04/97-	BDX	<b>BD-5336</b> BOS	<b>BD-5340</b>
		PER	<b>BD-5335</b>	
G 55 AMG 260kW	09/99-	BDX	<b>BD-5336</b> BOS	<b>BD-5340</b>
		PER	<b>BD-5335</b>	
<b>GL-Class (X164)</b>				
GL 320 CDI	09/06-	ATE (without sports package)	<b>BD-5330</b> ATE	<b>BD-5332</b>
		ATE	<b>BD-5331</b>	
GL 350 CDI	06/09-	ATE (without sports package)	<b>BD-5330</b> ATE	<b>BD-5332</b>
		ATE	<b>BD-5331</b>	
GL 420 CDI	09/06-	ATE	<b>BD-5331</b>	<b>BD-5332</b>
GL 450	09/06-	ATE	<b>BD-5331</b>	<b>BD-5332</b>
<b>MB100</b>				
2.0	04/88-10/95	BDX	<b>BD-5336</b>	
2.4	04/88-10/95	BDX	<b>BD-5336</b>	
<b>Sprinter 2-T (901, 902)</b>				
208 D, 210 D, 212 D, 214 60-105kW	02/95-04/00	ATE	<b>BD-5337</b> ATE	<b>BD-5338</b>
208 CDi, 211 CDi, 213 CDi, 216 CDi 60-115kW	05/00-05/06	ATE	<b>BD-5337</b> ATE	<b>BD-5338</b>
<b>Sprinter 3-T (903)</b>				
308 D, 310 D, 312 D, 314	02/95-04/00	ATE	<b>BD-5337</b> ATE	<b>BD-5338</b>
		BOS	<b>BD-5339</b> BOS	<b>BD-5340</b>





• MERCEDES-BENZ — MITSUBISHI

					
308 CDI, 311 CDI, 313 CDI, 314, 316 CDI	05/00-05/06	ATE BOS	BD-5337 BD-5339	ATE BOS	BD-5338 BD-5340
<b>Sprinter 4-T (904)</b>					
408 D, 410 D, 412 D, 414 (4x4)	02/95-04/00	ATE BOS	BD-5337 BD-5339	BOS	BD-5340
408 CDI, 411 CDI, 413 CDI, 414, 416 CDI (4x4)	05/00-05/06	BOS	BD-5339	BOS	BD-5340
<b>Sprinter 3-T (906)</b>					
209 CDI, 211 CDI, 213 CDI, 215 CDI, 218 CDI	06/06-	BRE	BD-5341	BOS	BD-5342
<b>Sprinter 5-T (906)</b>					
509 CDI, 511 CDI, 515 CDI, 518 CDI	06/06-	BRE	BD-5343	BOS	BD-5344
<b>Vaneo (W414)</b>					
1.6 60/75kW	10/01-	TRW	BD-5345	LUC	BD-5310
1.7 CDI 55/67kW	10/01-	TRW	BD-5345	LUC	BD-5310
1.9 92kW	10/01-	TRW	BD-5345	LUC	BD-5310
<b>Viano (W639)</b>					
3.2 140/160kW	09/04-	BOS	BD-5348		
2.2 CDI 80/110kW	09/04-	BOS	BD-5348		
<b>Vito (W638)</b>					
2.2 CDI 60-90kW	01/99-07/03	ATE	BD-5337	ATE	BD-5346
		BOS	BD-5339	BOS	BD-5347
2.3 CDI 58-72kW	11/95-02/99	ATE	BD-5337	ATE	BD-5346
		BOS	BD-5339	BOS	BD-5347
2.0 95kW	11/95-07/03	ATE	BD-5337	ATE	BD-5346
		BOS	BD-5339	BOS	BD-5347
2.3 105kW	05/97-07/03	ATE	BD-5337	ATE	BD-5346
		BOS	BD-5339	BOS	BD-5347
<b>V-class (638/2)</b>					
V 200 95kW	08/96-07/03	ATE	BD-5337	ATE	BD-5346
		BOS	BD-5339	BOS	BD-5347
V 200 CDI 75kW	03/99-07/03	BOS	BD-5339	BOS	BD-5347
V 220 CDI 90kW	03/99-07/03	ATE	BD-5337	ATE	BD-5346
		BOS	BD-5339	BOS	BD-5347
V 230 105kW	08/96-07/03	ATE	BD-5337	ATE	BD-5346
		BOS	BD-5339	BOS	BD-5347
V 230 TD 72kW	08/96-02/99	ATE	BD-5337	ATE	BD-5346
		BOS	BD-5339	BOS	BD-5347
V 280 128kW	07/97-07/03	BOS	BD-5339	BOS	BD-5347
<b>MITSUBISHI</b>					
<b>ASX</b>					
1.6 86kW	08/10-	AKE	BD-5504	AKE	BD-5507
1.8 103kW	08/10-	AKE	BD-5504	AKE	BD-5507
2.0 110kW	08/10-	AKE	BD-5504	AKE	BD-5507
<b>Carisma</b>					
1.6 66-76kW	03/95-05/03	LUC (>05/99)	BD-5521	AKE (+ABS)	BD-5516
		LUC (06/99->)	BD-5526	LUC	BD-5523
		LUC (09/00>; 15")	BD-5522		
1.8 85kW	03/95-05/03	LUC (>08/00)	BD-5526	AKE (+ABS)	BD-5516
		LUC (09/00>; 15")	BD-5522	LUC	BD-5523
1.8 GD <sub>i</sub> 92kW	06/99-05/03	LUC (>08/00)	BD-5526	AKE (+ABS)	BD-5516
		LUC (09/00>; 15")	BD-5522	LUC	BD-5523
1.9 TD 66kW	06/96-08/00	LUC	BD-5526	AKE (+ABS)	BD-5516
		LUC (15")	BD-5522	LUC	BD-5523
<b>Challenger</b>					
2.5	11/98-09/00	AKE (16")	BD-5501		
2.5	11/98-09/00	AKE (15")	BD-5501		
3.0	11/98-	AKE	BD-5501		





# • MITSUBISHI





				
<b>Colt</b>				
1.3 55kW	11/94-02/96	SUM	BD-5524 AKE	BD-5516
1.3 GLX 55kW	03/96-07/01	SUM	BD-5524	
1.6 GLXi 83kW	12/91-02/96	SUM	BD-5524 AKE	BD-5516
1.6 GLX 66kW	12/91-07/00	SUM	BD-5524	
1.8 GTi 16V 100kW	07/90-11/91	SUM	BD-5509	
1.8 GTi 103kW	12/91-02/96	SUM	BD-5509 AKE	BD-5516
<b>Colt (Z3)</b>				
1.1 55kW	06/04-	LUC (14")	BD-5526	
1.3 70kW	06/04-	LUC (14")	BD-5526	
1.5 80kW	06/04-	LUC (14")	BD-5526	
		LUC (15")	BD-5522	
<b>Eclipse</b>				
2.0 16V 110kW	10/90-04/96	SUM	BD-5509	
2.0 GT 157kW	05/96-10/00	SUM	BD-5509 AKE	BD-5508
2.4 GS 16V 105kW	05/96-10/00	SUM	BD-5509 AKE	BD-5508
<b>Galant</b>				
1.8 66kW	06/90-10/92	SUM	BD-5509	
1.8 93kW	11/92-09/96	SUM	BD-5509 AKE	BD-5508
2.0 (4x4) 101/110kW	11/92-09/96	SUM	BD-5509 AKE	BD-5508
2.0 D 66kW	11/92-09/96	SUM	BD-5509 AKE	BD-5508
2.5 V6 (4x4) 125kW	11/92-09/96	AKE	BD-5501 AKE	BD-5508
<b>Galant (EA)</b>				
2.0 100kW	10/96-07/00	SUM (>11/97)	BD-5509 AKE	BD-5508
		AKE (12/97>)	BD-5501	
2.0 98kW	08/00-10/04	AKE	BD-5504 AKE	BD-5508
2.4 GDi 106/110kW	03/99-10/04	AKE (>07/00)	BD-5501 AKE	BD-5508
		AKE (08/00>)	BD-5504	
2.5 V6 118/120kW	10/96-10/04	AKE (>07/00)	BD-5501 AKE	BD-5508
		AKE (08/00>)	BD-5504	
<b>L200</b>				
2.0 90kW	09/96-05/00	AKE	BD-5520	
2.4 (4x4) 97kW	11/96-07/01	AKE (>05/00)	BD-5520	
		AKE (06/00>)	BD-5501	
2.5 D/TD (4x4)	09/96-07/01	AKE (>05/00)	BD-5520	
		AKE (06/00>)	BD-5501	
2.5 D	10/05-		BD-5529	
<b>L300</b>				
2.0 85kW	09/95-10/98	AKE	BD-5520	
2.5 D 64kW	06/94-05/99	AKE	BD-5520	
<b>L400</b>				
2.5 D/TD	09/96-	AKE	BD-5520 AKE	BD-5502
<b>Lancer</b>				
1.3 55kW	11/94-07/01	SUM	BD-5524 AKE (>02/96)	BD-5516
1.6 83kW	06/92-02/96	SUM	BD-5524 AKE	BD-5516
1.6 66kW	03/96-09/00	SUM	BD-5524 AKE	BD-5516
1.8 GTi 16V 100kW	08/90-02/96	SUM	BD-5509 AKE	BD-5516
2.0 D 50kW	08/93-02/96	SUM	BD-5524 AKE	BD-5516
<b>Lancer IX</b>				
1.3 60kW	09/03-07/07	AKE	BD-5504 AKE	BD-5505
		SUM	BD-5503	
1.6 72kW	09/03-07/07	AKE	BD-5504 AKE	BD-5505
		SUM	BD-5503	
2.0 99kW	12/03-07/07	AKE	BD-5504 AKE	BD-5505
		SUM	BD-5503	







			
<b>Lancer X</b>			
1.5 80kW	08/07-	AKE	BD-5504 AKE BD-5505
1.8 105kW	02/08-	AKE	BD-5504 AKE BD-5505
2.0 110kW	08/07-	AKE	BD-5504 AKE BD-5505
<b>Outlander</b>			
2.0 100kW, 4WD	05/03-	AKE	BD-5501 AKE BD-5505
2.0 Turbo 147kW (4WD)	05/03-	AKE	BD-5501 AKE BD-5505
		(production USA)	BD-5504
2.4 118kW (4WD)	05/03-	AKE	BD-5501 AKE BD-5505
		(production USA)	BD-5504
<b>Outlander XL</b>			
2.4 125kW	03/07-	AKE	BD-5501 AKE BD-5507
3.0 162kW	03/07-	AKE	BD-5501 AKE BD-5507
<b>Pajero</b>			
2.4 82kW	03/91-03/00	AKE	BD-5501 AKE BD-5502
2.5 D 73kW	03/91-03/00	AKE	BD-5501 AKE BD-5502
			SUM BD-5511
2.5 TDiC	04/00-10/03	SUM	BD-5506 AKE BD-5507
2.8 TD 92kW	06/94-03/00	AKE	BD-5501 AKE BD-5502
3.0 V6 110/130kW	03/91-03/00	AKE	BD-5501 AKE BD-5502
3.2 Di-D 118/121kW	04/00-07/06	SUM	BD-5506 AKE BD-5507
3.5 V6 143/153kW	06/94-03/00	AKE	BD-5501 AKE BD-5502
3.5 V6 GDi 149kW	04/00-07/06	SUM	BD-5506 AKE BD-5507
<b>Pajero IV</b>			
3.0 130kW	02/07-		BD-5506 AKE BD-7505
3.2 D-ID	02/07-	(3-doors)	BD-5506 (3-doors) BD-5507
		(5-doors)	BD-7549 (5-doors) BD-7505
3.8 184kW	02/07-	(3-doors)	BD-5506 (3-doors) BD-5507
		(5-doors)	BD-7549 (5-doors) BD-7505
<b>Pajero Sport (K9W)</b>			
2.5 TDiC 73kW	11/98-09/00	AKE	BD-5501 AKE BD-5507
			SUM BD-5511
2.5 TDiC 85kW	07/02-12/08	SUM	BD-5506 AKE BD-5507
			SUM BD-5511
3.0 V6 130kW	11/98-12/08	AKE	BD-5501 SUM BD-5511
<b>Pajero Sport (KH8W)</b>			
2.5 D	01/09-		BD-5529
3.0 161kW	01/09-		BD-5529
3.2 D	01/09-		BD-5529
3.5 152kW	01/09-		BD-5529
<b>Pajero Pinin</b>			
1.8 84/88kW	10/99-	SUM	BD-5512 AKE BD-5508
2.0 95kW	10/00-	SUM	BD-5512 AKE BD-5508
<b>Santamo</b>			
2.0 16V 102kW	10/98-	SUM	BD-5509 AKE BD-5508
<b>Sigma</b>			
3.0 130/151kW	11/90-10/96	AKE	BD-5501 AKE BD-5502
<b>Space Gear</b>			
2.0 85kW	12/94-05/00	AKE	BD-5520
2.4 97kW	12/94-05/00	AKE	BD-5520
2.5 TDiC 73kW	11/96-05/00	AKE	BD-5520
<b>Space Runner</b>			
1.8 85/90kW (4x4/FWD)	06/91-09/99	SUM	BD-5509 AKE (+ABS) BD-5508
2.0 TD 60kW	06/91-09/99	SUM	BD-5509 AKE (+ABS) BD-5508
2.0 100kW	10/99-04/03	AKE (>04/00)	BD-5501 AKE BD-5508
		AKE (05/00->)	BD-5504





# • MITSUBISHI — NISSAN

				
<b>Space Runner</b>				
2.4 110kW	10/99-04/03	AKE (>04/00)	<b>BD-5501</b> AKE	<b>BD-5508</b>
		AKE (05/00>)	<b>BD-5504</b>	
<b>Space Star</b>				
1.3 63kW	08/98-	LUC	<b>BD-5526</b>	
1.6 72kW	04/01-	LUC	<b>BD-5526</b> LUC	<b>BD-5523</b>
1.8 GDi 90kW	08/98-	LUC	<b>BD-5526</b> LUC	<b>BD-5523</b>
1.9 Di-D 75kW	08/00-	LUC	<b>BD-5526</b> LUC	<b>BD-5523</b>
<b>Space Wagon</b>				
1.8 90kW (4x4/FWD)	05/91-12/93	SUM	<b>BD-5509</b> AKE (+ABS)	<b>BD-5508</b>
1.8 D 55kW	05/91-12/93	SUM	<b>BD-5509</b> AKE (+ABS)	<b>BD-5508</b>
2.0 98kW (4x4/FWD)	06/92-11/98	SUM	<b>BD-5509</b> AKE (+ABS)	<b>BD-5508</b>
2.0 D 60kW	06/92-11/98	SUM	<b>BD-5509</b> AKE (+ABS)	<b>BD-5508</b>
2.4 GDi 110kW	12/98-08/03	AKE	<b>BD-5501</b>	
<b>NISSAN</b>				
<b>100NX</b>				
1.6 66kW	01/92-07/96	SUM	<b>BD-5110</b>	
<b>200SX</b>				
1.8 Turbo 124kW	09/88-03/94	SUM (>08/91)	<b>BD-3607</b>	
		SUM (09/91>)	<b>BD-5701</b>	
<b>Almera (N15)</b>				
1.4 55/64kW	07/95-12/99	SUM	<b>BD-5703</b> AKE (+ ABS />05/98)	<b>BD-5718</b>
		SUM (06/97>)	<b>BD-5710</b> SUM	<b>BD-5702</b>
1.6 66/73kW	07/95-12/99	SUM	<b>BD-5703</b> AKE (+ ABS />05/98)	<b>BD-5718</b>
		SUM (06/97>)	<b>BD-5710</b> SUM	<b>BD-5702</b>
2.0 D 55kW	07/95-12/99	SUM	<b>BD-5703</b> AKE (+ ABS />05/98)	<b>BD-5718</b>
		SUM (06/97>)	<b>BD-5710</b> SUM	<b>BD-5702</b>
<b>Almera (N16)</b>				
1.5 66kW	04/00-11/02	LUC (-ABS)	<b>BD-5735</b> LUC	<b>BD-5736</b>
		LUC (+ABS)	<b>BD-5713</b> SUM	<b>BD-5702</b>
1.5 72kW	12/02-10/06	LUC	<b>BD-5713</b> LUC	<b>BD-5736</b>
1.8 84kW	04/00-11/02	LUC (-ABS)	<b>BD-5735</b> LUC	<b>BD-5736</b>
		LUC (+ABS)	<b>BD-5713</b> SUM	<b>BD-5702</b>
1.8 85kW	12/02-10/06	LUC	<b>BD-5713</b> LUC	<b>BD-5736</b>
2.2 DiTD 81kW	04/00-11/02	LUC	<b>BD-5735</b> SUM	<b>BD-5702</b>
		LUC (+ABS)	<b>BD-5713</b>	
<b>Almera Classic</b>				
1.6 79kW	11/06-		<b>BD-3409</b>	<b>BS-5716</b>
<b>Almera Tino</b>				
1.8 84kW	08/00-10/06	LUC	<b>BD-3422</b> LUC	<b>BD-5736</b>
2.0 100kW	08/00-10/06	LUC	<b>BD-3422</b> LUC	<b>BD-5736</b>
2.2 Di 85/100kW	08/00-10/06	LUC	<b>BD-3422</b> LUC	<b>BD-5736</b>
<b>Juke</b>				
1.6 86kW	09/10-	SUM	<b>BD-5701</b> AKE	<b>BD-5706</b>
1.6 DIG-T 140kW	09/10-	SUM	<b>BD-5701</b> AKE	<b>BD-5706</b>
<b>Maxima (J30)</b>				
3.0 125kW	11/91-09/94	SUM	<b>BD-5701</b> SUM	<b>BD-3612</b>
<b>Maxima QX (A32)</b>				
2.0 103kW	10/94-02/00	SUM (>12/95)	<b>BD-5701</b> SUM	<b>BD-5702</b>
		AKE	<b>BD-5705</b>	
3.0 142kW	10/94-02/00	AKE	<b>BD-5705</b> SUM	<b>BD-5702</b>
<b>Maxima QX (A33)</b>				
2.0 103kW	03/00-	AKE	<b>BD-5705</b> SUM	<b>BD-5702</b>
		TOK (01/04>)	<b>BD-5737</b>	
2.5 154kW	03/00-10/03	AKE	<b>BD-5705</b> SUM	<b>BD-5702</b>
		TOK (01/04>)	<b>BD-5737</b>	





					
3.0 147kW	08/00-	AKE TOK (01/04>)	BD-5705 BD-5737	SUM	BD-5702
<b>Micra (K11)</b>					
1.0 40kW	08/92-12/02	AKE	BD-5738		
1.3 55kW	08/92-12/02	AKE	BD-5738		
1.5 D 42kW	09/00-12/02	AKE	BD-5738		
<b>Micra (K12)</b>					
1.0 48kW	01/03-	LUC	BD-5739		
1.2 48/59kW	01/03-	LUC	BD-5739		
1.4 65kW	01/03-	LUC	BD-5739		
1.5 dCi 48-63kW	01/03-	LUC	BD-5739		
<b>Murano (Z50)</b>					
3.5 172kW	03/04-12/07	SUM	BD-5725	AKE	BD-5706
<b>Murano (Z51)</b>					
3.5 195kW	01/08-	SUM	BD-5725	AKE	BD-5706
<b>Note</b>					
1.4 65kW	03/06-	LUC	BD-5739		
1.6 81kW	03/06-	LUC	BD-5739		
<b>Pathfinder</b>					
2.5 TD	10/05-	SUM (17")	BD-5725	TOK	BD-5741
<b>Patrol GR</b>					
2.8 TDiC, 95kW	10/97-05/00	AKE	BD-5715		BD-5710
3.0 DTI 116kW	05/00-02/10	AKE	BD-5715		BD-5710
4.2 TD 107kW	10/97-02/10	AKE	BD-5715		BD-5710
<b>Prairie</b>					
2.0 72kW (4x4/FWD)	10/88-03/92	SUM	BD-5708		
2.4 98kW (4x4/FWD)	04/92-07/94	SUM	BD-3607		
<b>Primastar</b>					
1.9 D 60kW	07/02-	LUC	BD-6303		
2.0 88kW	07/02-	LUC	BD-6303		
2.5 D 107kW	07/02-	LUC	BD-6303		
<b>Primera (P10)</b>					
1.6 66-75kW	06/90-05/96	AKE	BD-5740	LUC (+ABS)	BD-5736
2.0 85kW	05/90-03/98	LUC	BD-5735	LUC	BD-5736
2.0 D 55kW	12/90-05/96	AKE	BD-5740		
<b>Primera (P11)</b>					
1.6 16V 66-78kW	06/96-12/01	LUC (14")	BD-5735	LUC	BD-5736
		LUC (15")	BD-5713		
1.8 16V 84kW	06/99-12/01	LUC (14")	BD-5735	LUC	BD-5736
		LUC (15")	BD-5713		
2.0 16V 96-110kW	06/96-12/01	LUC (14")	BD-5735	LUC	BD-5736
		LUC (15")	BD-5713		
2.0 TD 66kW	06/96-12/01	LUC (14")	BD-5735	LUC	BD-5736
		LUC (15")	BD-5713		
<b>Primera (P12)</b>					
1.6 78/80kW	01/02-	LUC	BD-3422	ATE	BD-6302
1.8 85kW	01/02-	LUC	BD-3422	ATE	BD-6302
2.0 103kW	01/02-	LUC	BD-3422	ATE	BD-6302
2.2 D 93kW	01/02-	LUC	BD-3422	ATE	BD-6302
<b>Qashqai</b>					
1.6 84kW	02/07-	AKE	BD-5711	AKE	BD-5706
2.0 103kW	02/07-	AKE	BD-5711	AKE	BD-5706
2.0 103kW (4WD)	02/07-	AKE	BD-5711	AKE	BD-5706
<b>Serena</b>					
1.6 71kW	07/92-12/00	LUC	BD-3028		
2.0 16V 93kW	07/92-09/01	LUC	BD-3028		





• NISSAN — OPEL

					
<b>Serena</b>					
2.0 D 49kW	07/92-09/94	LUC	BD-3028		
2.3 D 55kW	10/94-09/01	LUC	BD-3028		
<b>Sunny</b>					
1.4 55kW	01/92-06/95	SUM	BD-5110		
1.6 66kW (4x4/FWD)	01/92-06/95	SUM	BD-5110		
2.0 D 55kW	01/92-06/95	SUM	BD-5110		
<b>Teana (J31)</b>					
2.3 127kW	08/05-08/08	SUM	BD-5701 AKE	BD-5706	
3.5 170kW	08/05-08/08	SUM	BD-5701 AKE	BD-5706	
<b>Teana (J32)</b>					
2.5 134kW	09/08-	SUM	BD-5701 AKE	BD-5706	
3.5 183kW	09/08-	SUM	BD-5701 AKE	BD-5706	
<b>Terrano II</b>					
2.4 85-91kW	02/93-02/02	LUC	BD-3028		
2.7 D 74/92kW	02/93-02/02	LUC	BD-3028		
<b>Tiida</b>					
1.6 81kW	08/07-		BD-5701	BD-5706	
1.8 93kW	08/07-		BD-5701	BD-5706	
<b>X-Trail (T30)</b>					
2.0 103kW	07/01-05/07		BD-5704 AKE	BD-5706	
2.2 D 84/100kW	07/01-05/07		BD-5704 AKE	BD-5706	
<b>X-Trail (T31)</b>					
2.0 103kW	06/07-	SUM	BD-5711 AKE	BD-5706	
2.5 124kW	06/07-	SUM	BD-5711 AKE	BD-5706	
<b>OPEL</b>					
<b>Agila</b>					
1.0 12V 43kW	03/00-	BOS	BD-5906		
1.2 16V 55kW	03/00-	BOS	BD-5906		
<b>Ascona</b>					
1.3 44/55kW	08/81-10/88	DEL	BD-5905		
1.6 55/66kW	08/81-10/88	DEL	BD-5905		
1.6 D 40kW	09/81-10/88	DEL	BD-5905		
1.8 85kW	09/81-10/88	DEL	BD-5905		
2.0 85kW	08/81-10/88	DEL	BD-5905		
<b>Astra F</b>					
1.4 44/55kW	09/91-01/98	ATE	BD-5903	BS-1800	
1.4 16V 60/66kW	09/92-01/98	ATE	BD-1402	BS-1800	
1.6 52/55kW	09/91-01/98	ATE	BD-5903	BS-1800	
1.6 16V 74kW	09/94-01/98	ATE	BD-1402	BS-1800	
1.7 TD 42/50kW	09/91-08/94	ATE	BD-1402	BS-1800	
1.7 TDS 60kW	09/91-01/98	ATE	BD-5903	BS-1800	
1.8 66kW	09/91-08/94	ATE	BD-5903	BS-1800	
1.8 85/92kW	09/94-08/98	ATE	BD-1402	ATE	BD-5909
2.0 85/100kW	09/94-08/98	ATE	BD-1402	ATE	BD-5909
<b>Astra G</b>					
1.2 16V 48/55kW	02/98-12/04	ATE	BD-5907	BOS	BD-5910
				LUC (06/01-12/04)	BD-5911
1.4 16V 66kW	02/98-12/04	ATE	BD-5907	BOS	BD-5910
				LUC (06/01-12/04)	BD-5911
1.6 55/62kW	02/98-12/04	ATE	BD-5907	BOS	BD-5910
				LUC (06/01-12/04)	BD-5911
1.6 16V 74kW	02/98-12/04	ATE	BD-5907	BOS	BD-5910
				LUC (06/01-12/04)	BD-5911
1.7 DTi 55kW	02/98-12/04	ATE	BD-5907	BOS	BD-5910
				LUC (06/01-12/04)	BD-5911





				
1.8 16V 85/92kW	02/98-12/04	ATE (+ ABS)	<b>BD-5904</b> BOS	<b>BD-5910</b>
		ATE (- ABS)	<b>BD-5907</b> LUC (06/01-12/04)	<b>BD-5911</b>
2.0 100kW	02/98-08/00	ATE (+ ABS)	<b>BD-5904</b> BOS	<b>BD-5910</b>
		ATE (- ABS)	<b>BD-5907</b>	
2.0 Turbo OPC 141kW	06/02-12/04	ATE	<b>BD-5912</b> LUC	<b>BD-5911</b>
2.0 Di 60kW	02/98-08/00	ATE	<b>BD-5907</b> BOS	<b>BD-5910</b>
2.0 Di/DTi 74kW	02/98-12/04	ATE (+ ABS)	<b>BD-5904</b> BOS	<b>BD-5910</b>
		ATE (- ABS)	<b>BD-5907</b> LUC (06/01-12/04)	<b>BD-5911</b>
<b>Astra H</b>				
1.4 66kW	12/04-	ATE	<b>BD-5908</b>	<b>BD-5911</b>
1.6 77kW	12/04-	ATE	<b>BD-5908</b>	<b>BD-5911</b>
1.7 CDTI 59/74kW	12/04-	ATE	<b>BD-5908</b>	<b>BD-5911</b>
1.8 92/103kW	12/04-	ATE	<b>BD-5908</b>	<b>BD-5911</b>
2.0 Turbo 147/177kW	12/04-	ATE	<b>BD-5908</b>	<b>BD-5911</b>
<b>Astra H GTC</b>				
1.6 77/85kW	03/05-	ATE	<b>BD-5908</b>	<b>BD-5911</b>
1.6 Turbo 132kW	02/07-	ATE	<b>BD-5908</b>	<b>BD-5911</b>
1.8 103kW	01/06-	ATE	<b>BD-5908</b>	<b>BD-5911</b>
2.0 Turbo 125/147kW	03/05-	ATE	<b>BD-5908</b>	<b>BD-5911</b>
<b>Astra J</b>				
1.4 Turbo 103kW	12/09-	ATE (15")	<b>BD-1810</b>	<b>BD-1811</b>
		ATE (16", 17")	<b>BD-1813</b>	
1.6 85kW	12/09-	ATE (15")	<b>BD-1810</b>	<b>BD-1811</b>
		ATE (16", 17")	<b>BD-1813</b>	
1.6 Turbo 132kW	12/09-	ATE (15")	<b>BD-1810</b>	<b>BD-1811</b>
		ATE (16", 17")	<b>BD-1813</b>	
<b>Calibra</b>				
2.0 85/100kW	06/90-08/97	ATE	<b>BD-1402</b> ATE	<b>BD-5909</b>
2.0 Turbo 16V 150kW (4x4)	08/91-08/97	ATE	<b>BD-5913</b> ATE	<b>BD-5909</b>
2.5 V6 125kW	09/93-05/98	ATE (>08/95)	<b>BD-5913</b> ATE	<b>BD-5909</b>
		ATE (08/95>)	<b>BD-5914</b>	
<b>Corsa A</b>				
1.0 33kW	09/82-08/90	DEL	<b>BD-5905</b>	
1.2 33kW	09/82-03/93	DEL	<b>BD-5905</b>	
1.3 44kW	09/82-08/91	DEL	<b>BD-5905</b>	
1.3 52kW	09/91-03/93	ATE	<b>BD-5903</b>	
1.4 44kW	08/88-08/91	DEL	<b>BD-5905</b>	
1.4 60kW	09/91-03/93	ATE	<b>BD-5903</b>	
1.5 D 37kW	09/87-08/91	DEL	<b>BD-5905</b>	
1.5 D 53kW	09/91-03/93	ATE	<b>BD-5903</b>	
1.6 GSI 55-74kW	09/88-03/93	DEL	<b>BD-5905</b>	
		ATE	<b>BD-5903</b>	
<b>Corsa B</b>				
1.0 12V 40kW	02/97-08/00	ATE	<b>BD-5903</b>	
1.2 33kW	08/94-08/00	ATE	<b>BD-5903</b>	
1.4 44-66kW	04/93-08/00	ATE	<b>BD-5903</b>	
1.5 D 37kW	03/93-08/00	ATE	<b>BD-5903</b>	
1.6 78/80kW	04/93-08/00	ATE	<b>BD-5903</b>	
1.7 D 44kW	03/96-08/00	ATE	<b>BD-5903</b>	
<b>Corsa C</b>				
1.0 44kW	09/00-07/06	LUC	<b>BD-5915</b>	
1.2 55kW	09/00-07/06	LUC	<b>BD-5915</b>	
1.4 66kW	09/00-07/06	LUC	<b>BD-5915</b>	
1.7 DTi/Di	09/00-07/06	LUC	<b>BD-5915</b>	
<b>Corsa D</b>				
1.0 44kW	07/06-	BOS	<b>BD-5916</b> BOS	<b>BD-5917</b>

• OPEL





			
<b>Corsa D</b>			
1.2 59kW	07/06-	BOS	BD-5916 BOS BD-5917
1.4 66kW	07/06-	BOS	BD-5916 BOS BD-5917
<b>Frontera A</b>			
2.0 85kW	08/91-08/98	AKE (>Ch.707326)	BD-5918 SUM BD-3803
		AKE (Ch.707326>)	BD-3802
2.5 TD 85kW	09/96-08/98	AKE (>Ch.707326)	BD-5918 SUM BD-3803
		AKE (Ch.707326>)	BD-3802
2.8 TD 83kW	03/95-08/98	AKE (>Ch.707326)	BD-5918 SUM BD-3803
		AKE (Ch.707326>)	BD-3802
<b>Frontera B</b>			
2.2 100kW	09/98-02/04	SUM	BD-5919 SUM BD-3803
2.2 D 85kW	09/98-02/04	SUM	BD-5919 SUM BD-3803
3.2 151kW	09/98-02/04	SUM	BD-5919 SUM BD-3803
<b>Kadett</b>			
1.2 40kW	09/84-05/92	DEL	BD-5905
1.3 44/55kW	09/84-05/92	DEL	BD-5905
1.4 44/55kW	09/88-05/92	DEL	BD-5905
1.5 D 53kW	09/87-05/92	DEL	BD-5905
1.6 55/66kW	09/84-05/92	DEL	BD-5905
1.7 D 42kW	09/89-05/92	DEL	BD-5905
1.8 66/74kW	09/84-05/92	DEL	BD-5905
1.8 74/85kW	09/84-05/92	ATE	BD-1402
2.0 85kW	09/84-08/89	DEL	BD-5905
2.0 GS/GT 110kW	09/89-05/92	ATE	BD-1402 ATE BD-5909
<b>Meriva</b>			
1.6 77kW	01/06-	ATE	BD-5908 LUC BD-5911
1.6 16V 74kW	04/03-	ATE	BD-5908 LUC BD-5911
1.7 D 74kW	08/03-	ATE	BD-5908 LUC BD-5911
1.8 92kW	08/03-	ATE	BD-5908 LUC BD-5911
<b>Monterey</b>			
3.0 D 117kW	09/97-08/00	SUM	BD-3802 SUM BD-3803
3.1 D 84kW	08/91-05/98	SUM	BD-3802 SUM BD-3803
3.2 130kW	08/91-05/98	SUM	BD-3802 SUM BD-3803
3.5 158kW	09/97-08/00	SUM	BD-3802 SUM BD-3803
<b>Movano</b>			
1.9 DTi 59kW	12/99-	BOS	BD-5920
2.2 DTi 66kW	12/99-	BOS (15")	BD-5920
		BOS (16")	BD-5921
2.5 D	12/99-	BOS (15")	BD-5920
		BOS (16")	BD-5921
2.8 DTi 84kW	11/98-	BOS (15")	BD-5920
		BOS (16")	BD-5921
<b>Omega A</b>			
1.8 65/85kW	09/86-09/89	DEL	BD-5905 ATE (09/88>) BD-5902
2.0 73/74kW	09/88-03/94	ATE	BD-1402 ATE (09/88>) BD-5902
2.3 TD 66kW	09/86-08/88	DEL	BD-5905
2.3 D 74kW	09/88-03/94	DEL (>08/89)	BD-5905 ATE BD-5902
		ATE (09/89>)	BD-1402
2.4 92kW	09/88-03/94	ATE	BD-1402 ATE BD-5902
2.6 110kW	09/90-03/94	LUC	BD-5922 ATE BD-5902
3.0 24V 147/150kW	09/88-03/94	LUC	BD-5922 ATE BD-5902
<b>Omega B</b>			
2.0 85/100kW	05/94-07/00	ATE (>05/97)	BD-5913 ATE BD-5902
		ATE (05/97>)	BD-5922
2.0 DTi 74kW	09/97-07/00	LUC	BD-5922 ATE BD-5902

				
2.2 106kW	09/99-07/03	LUC	BD-5922 ATE	BD-5902
2.2 DTI 16V 88kW	08/00-07/03	LUC	BD-5922 ATE	BD-5902
2.5 V6 125kW	05/94-07/00	LUC	BD-5922 ATE	BD-5902
2.5 DTI 96/110kW	05/94-07/03	LUC	BD-5922 ATE	BD-5902
3.0 V6 155kW	05/94-05/01	LUC	BD-5922 ATE	BD-5902
3.2 V6 160kW	05/01-07/03	LUC	BD-5922 ATE	BD-5902
<b>Signum</b>				
1.8 90/103kW	05/03-	ATE	BD-5923	
1.9 CDTI 74-110kW	04/04-	ATE	BD-5923	
2.0 DTI 74kW	05/03-	ATE	BD-5923	
2.0 Turbo 129kW	05/03-	ATE	BD-5923	
2.2 DTI 92kW	05/03-	ATE	BD-5923	
<b>Sintra</b>				
2.2 104kW	08/94-04/01	MAN	BD-5924	
2.2 D 85kW	08/88-07/91	MAN	BD-5924	
3.0 148kW	08/91-07/92	MAN	BD-5924	
<b>Tigra</b>				
1.4 16V 66kW	07/94-12/00	ATE	BD-5903	
1.6 16V 74/78kW	08/91-06/94	ATE	BD-5903	
<b>Vectra A</b>				
1.6 55/60kW	08/88-08/95	DEL (>08/91)	BD-5905	
		ATE (09/91>)	BD-5903	
1.7 D 42-60kW	08/88-08/95	DEL (>08/91)	BD-5905	
		ATE (09/91>)	BD-5903	
1.8 CAT 66kW	03/90-08/95	ATE (AT)	BD-1402	
		DEL (>08/91)	BD-5905	
		ATE (09/91>)	BD-5903	
2.0i 85/92kW	08/88-08/92	ATE	BD-1402 ATE	BD-5909
2.0i 16V 100/110kW	02/90-08/94	ATE	BD-1402 ATE	BD-5909
<b>Vectra B</b>				
1.6 55kW	09/95-04/02	ATE	BD-1402	
1.6 16V 74kW	09/95-04/02	ATE	BD-1402 ATE	BD-5902
1.7 TD 60kW	09/95-12/98	ATE	BD-1402 ATE	BD-5902
1.8 85/92kW	09/95-04/02	ATE (>09/00)	BD-1402 ATE	BD-5902
		ATE (09/00>)	BD-5914	
2.0 DTi 74kW	06/97-04/02	ATE (>09/00)	BD-1402 ATE	BD-5902
		ATE (09/00>)	BD-5914	
2.2 16V 108kW	09/00-04/02	ATE	BD-5914 ATE	BD-5902
2.5 V6 125kW	10/95-09/00	ATE	BD-5914 ATE	BD-5902
2.6 V6 125kW	09/00-04/02	ATE	BD-5914 ATE	BD-5902
<b>Vectra C</b>				
1.6 16V 74kW	06/04-10/08	ATE	BD-5923 ATE	BD-6302
1.6 77kW	01/06-10/08	ATE	BD-5923 ATE	BD-6302
1.8 81/90kW	04/02-10/08	ATE	BD-5923 ATE	BD-6302
1.8 103kW	01/06-10/08	ATE	BD-5923 ATE	BD-6302
2.0 Turbo 129kW	03/03-10/08	ATE	BD-5923 ATE	BD-6302
2.0 DTi/Di 74kW	04/02-10/08	ATE	BD-5923 ATE	BD-6302
2.2 16V 108kW	04/02-10/08	ATE	BD-5923 ATE	BD-6302
<b>Zafira A</b>				
1.6 16V 74kW	02/99-06/05	ATE	BD-5904 BOS	BD-5910
				LUC (06/01>)
1.8 16V 85/92kW	02/99-06/05	ATE	BD-5904 BOS	BD-5910
				LUC (06/01>)
2.0 OPC 141/147kW	11/01-06/05	ATE	BD-5912 LUC	BD-5911
2.0 Di 60kW	02/99-05/01	ATE	BD-5904 BOS	BD-5910





# • OPEL — PEUGEOT

				
<b>Zafira A</b>				
2.0 DTi 74kW	07/00-06/05	ATE	<b>BD-5904</b> BOS	<b>BD-5910</b>
			LUC (06/01>)	<b>BD-5911</b>
2.2 16V 108kW	09/00-06/05	ATE	<b>BD-5904</b> BOS	<b>BD-5910</b>
			LUC (06/01>)	<b>BD-5911</b>
2.2 D 92kW	01/02-06/05	ATE	<b>BD-5904</b> LUC	<b>BD-5911</b>
<b>Zafira B</b>				
1.6 77/85kW	07/05-	ATE	<b>BD-5908</b> LUC	<b>BD-5911</b>
1.8 103kW	07/05-	ATE	<b>BD-5908</b> LUC	<b>BD-5911</b>
1.9 CDTI 74-110kW	07/05-	ATE	<b>BD-5908</b> LUC	<b>BD-5911</b>
2.0 147kW	07/05-	ATE	<b>BD-5908</b> LUC	<b>BD-5911</b>
2.0 177kW	01/06-	ATE	<b>BD-5923</b> LUC	<b>BD-5911</b>
<b>PEUGEOT</b>				
<b>107</b>				
1.0 50kW	06/05-	BOS	<b>BD-6103</b>	
1.4 Hdi 40kW	06/05-	BOS	<b>BD-6103</b>	
<b>205</b>				
1.0 33kW	10/87-07/98	LUC	<b>BD-6104</b>	
		BDX	<b>BD-6105</b>	
1.1 36-44kW	10/87-07/98	LUC	<b>BD-6104</b>	
		BDX	<b>BD-6105</b>	
1.4 44-59kW	10/87-07/98	LUC	<b>BD-6104</b>	
		BDX	<b>BD-6105</b>	
1.6 53-65kW	10/87-07/98	LUC	<b>BD-6104</b>	
		BDX	<b>BD-6105</b>	
<b>206</b>				
1.1 44kW	09/98-	BOS	<b>BD-6106</b> LUC	<b>BS-6301</b>
1.4 55kW	09/98-	BOS	<b>BD-6106</b> LUC	<b>BS-6301</b>
1.4 16V 65kW	10/03-	BOS	<b>BD-2201</b>	
1.6 65kW	09/98-12/00	BOS	<b>BD-6106</b> LUC	<b>BS-6301</b>
1.6 16V 80kW	12/00-	BOS (Ch.09079>)	<b>BD-2201</b> BDX	<b>BD-2222</b>
		BOS (>Ch.08777)	<b>BD-2220</b>	
1.9 D 51kW	09/98-07/00	BOS	<b>BD-6106</b> LUC	<b>BS-6301</b>
2.0 99kW	04/99-	BOS (>Ch.08777)	<b>BD-2220</b> BDX	<b>BD-2222</b>
2.0 100kW	10/00-	BOS	<b>BD-2201</b> BDX	<b>BD-2222</b>
2.0 HDi	09/01-	BOS	<b>BD-2201</b>	
<b>207</b>				
1.4 53kW	02/06-	BOS	<b>BD-2201</b>	
1.4 16V 65kW	02/06-	BOS	<b>BD-2201</b>	
1.6 16V 80kW	02/06-	BOS	<b>BD-2202</b>	<b>BD-2211</b>
1.6 Turbo 16V 110kW	02/06-	BOS	<b>BD-2202</b>	<b>BD-2211</b>
<b>306</b>				
1.4 55kW	04/93-05/01	ATE (+ABS)	<b>BD-6107</b> LUC	<b>BS-6301</b>
		ATE	<b>BD-2219</b> LUC	<b>BS-6301</b>
		BOS	<b>BD-6106</b>	
1.6 65kW	05/97-05/01	ATE (+ABS)	<b>BD-6107</b> LUC	<b>BS-6301</b>
		ATE	<b>BD-2219</b>	
1.8 74kW	05/93-04/99	ATE	<b>BD-6107</b> LUC	<b>BS-6301</b>
		ATE (03/97>)	<b>BD-2219</b>	
1.8 16V 81kW	05/97-05/01	LUC	<b>BD-2203</b> BDX	<b>BD-2222</b>
2.0 16V 97kW	03/97-05/01	LUC	<b>BD-2221</b> BDX	<b>BD-2222</b>
2.0 HDi 66kW	06/99-05/01	BOS	<b>BD-2220</b>	
		LUC	<b>BD-2203</b>	
<b>307</b>				
1.4 55kW	08/00-09/03	BOS	<b>BD-2201</b> BOS	<b>BD-2211</b>







				
1.4 16V 65kW	10/03-09/07	BOS (- ESP)	BD-2201 LUC	BD-8002
		BOS (+ ESP)	BD-2202 BOS	BD-2211
1.4 HDi 50kW	10/01-09/07	BOS	BD-2201 LUC	BD-8002
1.6 16V 80kW	08/00-09/07	BOS (- ESP)	BD-2201 LUC	BD-8002
		BOS (+ ESP)	BD-2202 BOS	BD-2211
2.0 16V 100kW	08/00-09/07	BOS	BD-2202 LUC	BD-8002
2.0 16V 130kW	06/05-09/07	ATE	BD-2206 BOS	BD-2211
2.0 D 66/79kW	08/00-09/07	BOS	BD-2202 LUC	BD-8002
<b>308</b>				
1.4 16V 70kW	09/07-	BOS	BD-6102 LUC	BD-1206
1.6 103/110kW	09/07-	BOS	BD-6102 LUC	BD-1206
1.6 128kW	09/07-	BOS	BD-6102 LUC	BD-1206
1.6 HDi 80kW	09/07-	BOS	BD-6102 LUC	BD-1206
<b>309</b>				
1.1 40kW	10/85-10/91	BDX	BD-6105	
		LUC	BD-6104	
1.3 47kW	10/85-10/93	BDX	BD-6105	
		LUC	BD-6104	
1.4 49/55kW	10/85-10/93	BDX	BD-6105	
		LUC	BD-6104	
1.6 53-76kW	05/87-10/93	LUC	BD-6104	
		BDX	BD-6105	
1.8 D 44kW	10/85-10/93	BDX	BD-6105	
		LUC	BD-6104	
<b>405</b>				
1.4 47/55kW	06/87-10/95	BDX	BD-6105	
1.6 65kW	07/87-05/97	BDX	BD-6105	
1.8 74kW	08/92-12/95	BDX	BD-6105	
1.8 TD 66kW	06/87-08/90	BDX	BD-6105	
1.9 D 47kW	08/92-10/95	BDX	BD-6105	
<b>406</b>				
1.6 65/66kW	06/96-03/04	LUC	BD-6108	
1.8 16V 85kW	04/99-05/04	LUC	BD-6108	
1.9 D 55kW	08/95-03/99	LUC	BD-6108	
1.9 TD 68kW	06/98-05/04	LUC (15")	BD-2221	
2.0 16V 100/103kW	09/00-05/04	LUC	BD-2221 ATE	BD-6109
2.0 D 66kW	02/99-05/04	LUC	BD-2221	
2.0 D 79/80kW	09/00-05/04	LUC	BD-2221	
2.1 TD 80kW	08/95-06/04	LUC	BD-2221	
2.2 116kW	09/00-05/04	LUC	BD-2221 ATE	BD-6109
2.2 HDi 98kW	09/00-05/04	LUC	BD-2221 ATE	BD-6109
3.0 V6 24V 140/152kW	05/97-05/04	LUC	BD-2221 ATE	BD-6109
<b>406 Coupe</b>				
2.0 16V 97/100kW	05/97-12/04	LUC	BD-2221 ATE	BD-6109
2.2 116kW	03/02-12/04	LUC	BD-2221 ATE	BD-6109
2.2 HDi 98kW	09/00-12/04	BRE	BD-2221 ATE	BD-6109
<b>407</b>				
1.8 85kW	05/04-	LUC	BD-6101 TRW	BD-6111
1.8 16V 92kW	10/05-	LUC	BD-6101 TRW	BD-6111
2.0 100kW	05/04-	LUC	BD-6101 TRW	BD-6111
2.0 16V 103kW	10/05-	LUC	BD-6101 TRW	BD-6111
2.2 116kW	05/04-	LUC	BD-6110 TRW	BD-6111
2.2 16V 120kW	10/05-	LUC	BD-6110 TRW	BD-6111
<b>605</b>				
2.0 79/89kW	04/91-09/99	BDX	BD-6112 ATE	BD-5346
2.1 D 60kW	04/91-08/97	BDX	BD-6112 ATE	BD-5346





# • PEUGEOT





			
<b>605</b>			
2.5 TD 95kW	07/94-09/99	BDX	BD-6112 ATE BD-5346
3.0 123kW	03/91-09/99	BDX	BD-6112 ATE BD-5346
3.0 V6 140kW	04/91-09/99	BDX	BD-6112 ATE BD-5346
<b>607</b>			
2.0 100kW	01/00-01/05	LUC	BD-2221 ATE BD-6109
2.0 HDi 80kW	01/00-01/05	LUC	BD-2221 ATE BD-6109
2.2 16V 116kW	01/00-01/05	LUC	BD-2221 ATE BD-6109
2.2 D 98kW	01/00-01/05	LUC	BD-2221 ATE BD-6109
3.0 V6 152kW	01/00-01/05		ATE BD-6109
<b>806</b>			
1.8 73kW	07/95-08/02	BDX	BD-2213
1.9 D 66/68kW	07/95-05/00	LUC	BD-2214 ATE BD-2218
2.0 89-108kW	08/94-08/02	LUC	BD-2214 ATE BD-2218
2.0 D 80kW	08/99-08/02	LUC	BD-2214 ATE BD-2218
2.1 D 80kW	06/96-08/99	LUC	BD-2214 ATE BD-2218
<b>807</b>			
2.0 100kW	06/02-	LUC	BD-2212
2.0 HDi	06/02-	LUC	BD-2212
2.2 116kW	06/02-	LUC	BD-2212
<b>1007</b>			
1.4 55/65kW	04/05-		BD-2201
<b>4007</b>			
2.2 HDi 115kW	03/07-		BD-5501 AKE BD-5507
2.4 16V 125kW	02/08-		BD-5501 AKE BD-5507
<b>Boxer</b>			
1.9 D 51-68kW (1.0 T / 1.4 T)	02/94-02/02	LUC	BD-2808
2.5 D 4x4 (1.0 T / 1.4 T)	02/94-02/02	LUC	BD-2809
2.5 D (1.8 T)	02/94-01/02	LUC	BD-2810
2.5 TDI (1.0 T / 1.4 T)	02/94-01/02	LUC	BD-2215
2.8 HDi (1.0 T / 1.4 T)	02/94-01/02	LUC	BD-2215 BRE BD-2217
2.8 HDi (1.8 T)	02/94-01/02	LUC	BD-2216 BRE BD-2217
<b>Boxer (244)</b>			
2.0	04/02-02/07	1000, 1400	BD-2215 (drum rear brakes) BS-2800
		1800	BD-2216 (disc rear brakes) BD-2217
2.2 HDi	04/02-02/07	1000, 1400	BD-2215 (drum rear brakes) BS-2800
		1800	BD-2216 (disc rear brakes) BD-2217
<b>Boxer (250)</b>			
2.2 D	02/07-	1100, 1500	BD-2828
		1700	BD-2829
2.3 D	02/07-	1100, 1500	BD-2828
		1700	BD-2829
3.0 D	02/07-	1100, 1500	BD-2828
		1700	BD-2829
<b>Expert</b>			
1.6 58kW	02/96-08/03	BDX	BD-2213
1.8 74kW	02/96-08/03	BDX	BD-2213
1.9 D 51/66kW (WB Short)	02/96-08/03	BDX	BD-2213
1.9 D 51/66kW (WB Long)	02/96-08/03	LUC	BD-2214
2.0 HDi (WB Short)	07/00-08/03	BDX	BD-2213
2.0 HDi (WB Long)	07/00-08/03	LUC	BD-2214
<b>Partner</b>			
1.1 44kW	07/96-04/08	LUC (>08/00)	BD-2203
		BOS (- ESP; 10/01>)	BD-2201
		BOS (+ ESP; 10/01>)	BD-2202

• PEUGEOT — PORSCHE — RENAULT





					
1.4 55kW	07/96-04/08	LUC (>08/00)	BD-2203		
		BOS (- ESP; 10/01>)	BD-2201		
		BOS (+ ESP; 10/01>)	BD-2202		
1.6 80kW	07/96-04/08	LUC (>08/00)	BD-2203		
		BOS (- ESP; 10/01>)	BD-2201		
		BOS (+ ESP; 10/01>)	BD-2202		
1.9 51kW	11/96-04/08	LUC (>08/00)	BD-2203		
		BOS (- ESP; 10/01>)	BD-2201		
		BOS (+ ESP; 10/01>)	BD-2202		
2.0 D 66kW	10/99-08/01	LUC	BD-2203		
<b>PORSCHE</b>					
<b>Cayenne (955)</b>					
3.2 184kW	10/03-06/10	BRE	BD-8005	BRE (17"/18")	BD-8007
S 4.5 250kW	10/03-06/10	BRE (17")	BD-8005	BRE (17"/18")	BD-8007
4.5 Turbo 331kW	10/03-06/10	BRE	BD-8019	BRE (17"/18")	BD-8007
<b>Cayenne (958)</b>					
3.6 220kW	07/10-	BRE	BD-8031	BRE (1KY, 1KZ)	BD-8029
S 4.8 294kW	07/10-	BRE	BD-8031	BRE (1KY, 1KZ)	BD-8029
<b>RENAULT</b>					
<b>19</b>					
1.2 40kW	07/88-11/95	LUC	BD-6301		
		BDX	BD-6105		
1.4 43-59kW	05/92-11/95	LUC	BD-6301		
		BDX	BD-6105		
1.7 54/66kW	07/88-11/95	LUC	BD-6301	BDX	BD-2222
		BDX	BD-6105		
1.8 65-79kW	10/91-02/97	LUC	BD-6301	BDX	BD-2222
		BDX	BD-6105	BDX	BD-6305
1.9 47kW	05/92-05/96	LUC	BD-6301	BDX	BD-2222
		BDX	BD-6105		
<b>21</b>					
1.4 50kW	07/89-05/93	BDX	BD-6105		
		LUC	BD-6301		
1.7 54/66kW	04/86-10/94	BDX	BD-6105		
		LUC	BD-6301		
1.9 D 47kW	04/86-05/93	LUC	BD-6301		
<b>25</b>					
2.0 74-103kW	05/84-03/92	LUC	BD-6301		
2.1 D 46-63kW	06/87-03/92	LUC	BD-6301		
2.2 79kW	05/84-05/88	LUC	BD-6301		
<b>Avantime</b>					
2.0 16V 120kW	11/01-05/03	LUC	BD-6303	LUC	BD-1206
2.2 D 110kW	05/02-05/03	LUC	BD-6303	LUC	BD-1206
3.0 V6 152kW	09/01-05/03	LUC	BD-6303	LUC	BD-1206
<b>Clio</b>					
1.1 35kW	05/90-02/98	LUC	BD-6301		
		BDX	BD-6105		
1.2 40-44kW	06/94-02/98	LUC	BD-6301		
		BDX	BD-6105		
1.4 55-59kW	05/90-02/98	LUC	BD-6301	BDX	BD-6305
		BDX	BD-6105		
1.8 65-80kW	06/94-02/98	LUC	BD-6301	BDX	BD-6305
		BDX	BD-6105		
1.9 D 47kW	06/94-02/98	BDX	BD-6105		
		LUC	BD-6301		
2.0 Williams 108kW	01/94-02/98	LUC	BD-6301	BDX	BD-6305





# • RENAULT

				
<b>Clio II</b>				
1.2 43/44kW	03/98-05/05	LUC	<b>BD-6301</b> BOS	<b>BS-6300</b>
		BDX	<b>BD-6105</b> LUC	<b>BS-6301</b>
1.4 55kW	03/98-05/05	LUC	<b>BD-6301</b> BOS	<b>BS-6300</b>
			LUC	<b>BS-6301</b>
1.4 16V 72kW	06/01-05/05	LUC	<b>BD-6301</b> BDX	<b>BD-6305</b>
1.6 66/79kW	03/98-05/05	LUC	<b>BD-6301</b> BOS	<b>BS-6300</b>
1.9 47kW	03/98-05/05	LUC	<b>BD-6301</b> LUC	<b>BS-6301</b>
2.0i 16V Sport 16V	11/00-12/02	LUC	<b>BD-6304</b> BDX	<b>BD-6305</b>
<b>Clio III</b>				
1.2 16V 48/55kW	06/05-	LUC	<b>BD-5739</b> TRW	<b>BD-6306</b>
1.4 16V	06/05-	LUC	<b>BD-5739</b> TRW	<b>BD-6306</b>
1.5 dCi	06/05-	LUC	<b>BD-5739</b> TRW	<b>BD-6306</b>
1.6 16V	06/05-	LUC	<b>BD-5739</b> TRW	<b>BD-6306</b>
<b>Duster</b>				
1.6 74kW	01/12-		<b>BD-5739</b>	
2.0 96kW	01/12-	(- ABS)	<b>BD-5739</b>	
		(+ ABS)	<b>BD-6317</b>	
<b>Espace</b>				
1.9 D 72kW	02/99-10/02	LUC	<b>BD-6307</b>	
2.0 80kW	06/84-12/90	LUC	<b>BD-6301</b>	
2.0 84kW	11/96-10/02	LUC	<b>BD-6307</b>	
2.0 16V 103kW	10/98-10/02	LUC	<b>BD-6307</b> BRE	<b>BD-6308</b>
2.1 D 65kW	06/84-12/90	LUC	<b>BD-6301</b>	
2.2 79kW	07/86-12/90	LUC	<b>BD-6301</b>	
2.2 12V TD 83kW	08/00-10/02	LUC	<b>BD-6307</b>	
2.2 dCi 95kW	10/00-10/02	LUC	<b>BD-6303</b> LUC	<b>BD-1206</b>
3.0 V6 140kW	10/98-10/02	LUC	<b>BD-6303</b> LUC	<b>BD-1206</b>
<b>Express</b>				
1.0 31kW	09/91-04/95	BDX	<b>BD-6105</b>	
		LUC	<b>BD-6301</b>	
1.1 34kW	09/85-08/97	BDX	<b>BD-6105</b>	
		LUC	<b>BD-6301</b>	
1.2 40kW	05/95-08/97	LUC	<b>BD-6301</b>	
		BDX	<b>BD-6105</b>	
1.4 43kW	09/85-04/95	LUC	<b>BD-6301</b>	
		BDX	<b>BD-6105</b>	
1.6 D 40kW	09/91-11/98	LUC	<b>BD-6301</b>	
		BDX	<b>BD-6105</b>	
1.9 D 40/47kW	10/86-08/93	BDX	<b>BD-6105</b>	
		LUC	<b>BD-6301</b>	
<b>Fluence</b>				
1.6 81kW	05/10-	ATE	<b>BD-6317</b>	<b>BD-1206</b>
2.0 103kW	05/10-	ATE	<b>BD-6317</b>	<b>BD-1206</b>
<b>Grand Espace</b>				
2.0 84kW	02/98-10/02	LUC	<b>BD-6307</b>	
2.2 TD 84kW	02/98-10/02	LUC	<b>BD-6307</b>	
3.0	02/98-10/02	LUC	<b>BD-6307</b> BRE	<b>BD-6308</b>
<b>Kangoo</b>				
1.2 43kW	03/98-	BDX	<b>BD-6309</b>	
1.4 55kW	06/97-	BDX	<b>BD-6309</b>	
1.5 dCi 42-62kW	12/01-	BDX	<b>BD-6309</b>	
1.6 16V 70kW	06/01-	BDX	<b>BD-6309</b>	
1.9 D 40/47kW	08/97-	BDX	<b>BD-6309</b>	





					
<b>Koleos</b>					
2.0 D 110kW	10/08-	SUM	BD-5725 AKE	BD-5706	
2.5 126kW	10/08-	SUM	BD-5725 AKE	BD-5706	
<b>Laguna</b>					
1.6 79kW	03/98-03/01	LUC	BD-6310 LUC	BS-6301	
1.8 88kW	04/98-03/01	LUC	BD-6310 BRE	BD-6308	
1.9 D 72kW	07/98-03/01	LUC	BD-6310 LUC	BS-6301	
2.0 83kW	04/94-03/01	LUC	BD-6310 LUC	BS-6301	
				BRE (>01/97)	BD-6308
				BRE (02/97->)	BD-6313
2.9 140kW	07/98-03/01	LUC	BD-6310 BRE	BD-6313	
3.0 V6	04/94-01/97	LUC	BD-6310 BRE	BD-6308	
<b>Laguna II</b>					
1.6 79kW	03/01-11/07	ATE (15")	BD-6311 ATE	BD-6302	
		ATE (16"/17")	BD-6312		
1.8 16V 85/89kW	03/01-11/07	ATE (15")	BD-6311 ATE	BD-6302	
		ATE (16"/17")	BD-6312		
1.9 dCi 68/74kW	03/01-11/07	ATE (15")	BD-6311 ATE	BD-6302	
		ATE (16"/17")	BD-6312		
2.0 16V 150kW	03/01-11/07	ATE (15")	BD-6311 ATE	BD-6302	
		ATE (16"/17")	BD-6312		
2.2 D 110kW	03/01-11/07	ATE (16"/17")	BD-6312 ATE	BD-6302	
3.0 V6 152kW	03/01-11/07	ATE	BD-6312 ATE	BD-6302	
<b>Laguna Grandtour</b>					
1.6 79kW	03/98-03/01	LUC	BD-6310 BRE	BD-6313	
1.8 88kW	09/98-02/01	LUC	BD-6310		
2.0 83kW	06/95-02/01	LUC	BD-6310		
2.2 D 61kW	11/95-01/97	LUC	BD-6310 BRE	BD-6308	
2.2 D 61kW	02/97-02/01	LUC	BD-6310 BRE	BD-6313	
<b>Laguna Grandtour II</b>					
1.6 79kW	03/01-	ATE	BD-6312 ATE	BD-6302	
1.8	03/01-	ATE	BD-6312 ATE	BD-6302	
1.9 DCi	03/01-	ATE	BD-6312 ATE	BD-6302	
2.0 16V 103kW	03/01-	ATE	BD-6312 ATE	BD-6302	
2.2 DCi	10/01-	ATE	BD-6312 ATE	BD-6302	
<b>Logan</b>					
1.4 55kW	11/04-		BD-6301	BS-6300	
1.6 64/75kW	11/04-		BD-6301	BS-6300	
<b>Megane</b>					
1.4 55kW	02/97-08/02	LUC (>02/99)	BD-6301		
		LUC	BD-6304		
1.6 16V 79kW	03/99-08/02	LUC	BD-6304		
1.8 85kW	01/01-08/02	LUC	BD-6304 LUC	BD-1206	
1.9 D 47/66kW	10/95-08/02	LUC (>02/99)	BD-6301		
		LUC	BD-6304		
2.0	01/96-08/02	LUC	BD-6301		
	03/99-08/02	LUC	BD-6304		
<b>Megane II</b>					
1.4 72kW	11/02-12/08	BOS	BD-6314 LUC	BD-1206	
		ATE (15")	BD-6315		
1.6 83kW	11/02-12/08	BOS	BD-6314 LUC	BD-1206	
		ATE (15")	BD-6315		
		ATE (16"/17")	BD-6316		
1.9 dCi 88kW	11/02-12/08	BOS	BD-6314 LUC	BD-1206	
		ATE (15")	BD-6315		
		ATE (16"/17")	BD-6316		

# • RENAULT — ROVER





			
<b>Megane II</b>			
2.0 16V 99kW	11/02-12/08	BOS	BD-6314 LUC BD-1206
		ATE (15")	BD-6315
		ATE (16"/17")	BD-6316
<b>Megane III</b>			
1.6 81kW	01/09-	ATE	BD-6317 Without Electronic parking brake BD-1206
2.0 103kW	01/09-	ATE	BD-6317 Without Electronic parking brake BD-1206
<b>Megane Grandtour</b>			
1.4 55kW	07/97-08/02	LUC	BD-6301
1.6 79kW	01/01-08/02	LUC	BD-6304
1.6 79kW	03/99-08/02	LUC	BD-6301
1.8 85kW	02/00-08/02	LUC	BD-6304 LUC BD-1206
1.9 D 47kW	03/99-09/00	LUC	BD-6301
1.9 D	10/00-08/02	LUC	BD-6304 BDX BD-6305
			LUC BD-1206
<b>Megane Scenic</b>			
1.4 55kW	01/97-09/99	LUC	BD-6301
1.6 55/66kW	01/97-09/99	LUC (>09/98)	BD-6301
		LUC (09/98>)	BD-6304
1.9 D 47-66kW	01/97-09/99	LUC	BD-6310
2.0 84kW	01/97-09/99	LUC	BD-6310
<b>Sandero</b>			
1.4 55kW	03/08-		BD-6301 BS-6300
1.6 64/75kW	03/08-		BD-6301 BS-6300
<b>Scenic</b>			
1.4 16V 70kW	09/99-08/03	LUC	BD-6304 LUC BD-1206
1.6 16V 79kW	09/99-08/03	LUC	BD-6304 LUC BD-1206
1.8 16V 85kW	09/99-08/03	LUC	BD-6304 LUC BD-1206
1.9 D 72kW	10/99-08/03	LUC	BD-6304 LUC BD-1206
2.0 103kW	03/99-08/03	LUC	BD-6304 LUC BD-1206
<b>Scenic II</b>			
1.4 72kW	06/03-	BDX	BD-6314
1.5 dCi 60/74kW	06/03-	BDX	BD-6314
1.6 83kW	06/03-	BDX	BD-6314
1.9 dCi 88kW	06/03-	BDX	BD-6314
2.0 99kW	06/03-	BDX	BD-6314
<b>ROVER</b>			
<b>25</b>			
1.1 55kW	07/99-06/04	LUC	BD-3426
1.4 62/76kW	07/99-06/04	LUC	BD-3426
1.6 80kW	07/99-06/04	LUC	BD-3426
1.8 85/107kW	07/99-06/04	LUC	BD-3426
2.0 D 74kW	07/99-06/04	LUC	BD-3426
<b>45</b>			
1.4 76kW	01/00-06/04	LUC	BD-3426
1.6 80kW	04/99-06/04	LUC	BD-3426
1.8 86kW	04/99-06/04	LUC	BD-3426
2.0 110kW	04/99-06/04	LUC	BD-3426 AKE BD-3428
2.0 D 74kW	04/99-06/04	LUC	BD-3426
<b>75</b>			
1.8 88/110kW	02/00-10/05	ATE	BD-6500 ATE BD-6501
2.0 V6 110kW	02/00-10/05	ATE	BD-6500 ATE BD-6501
2.0 D 85kW	02/00-10/05	ATE	BD-6500 ATE BD-6501
2.5 V6 129kW	02/00-10/05	ATE	BD-6500 ATE BD-6501

							
<b>SAAB</b>							
<b>900</b>							
2.0 96-136kW	08/94-02/98	ATE (>07/96)	<b>BD-5913</b>	ATE		<b>BD-5909</b>	
		ATE (08/96>)	<b>BD-5914</b>	ATE		<b>BD-5902</b>	
2.3 16V 110kW	11/93-02/98	ATE (>07/96)	<b>BD-5913</b>	ATE		<b>BD-5909</b>	
		ATE (08/96>)	<b>BD-5914</b>	ATE		<b>BD-5902</b>	
2.5 V6 24V 125kW	07/93-02/98	ATE (>07/96)	<b>BD-5913</b>	ATE		<b>BD-5909</b>	
		ATE (08/96>)	<b>BD-5914</b>	ATE		<b>BD-5902</b>	
<b>9000</b>							
2.0 16V 92-96kW	09/89-08/93	ATE	<b>BD-6700</b>	ATE		<b>BD-6701</b>	
2.0 16V Turbo 118-129kW	09/87-08/93	ATE	<b>BD-6700</b>	ATE		<b>BD-6701</b>	
2.0 16V Turbo CD 136kW	09/89-12/98	ATE	<b>BD-6700</b>	ATE		<b>BD-6701</b>	
2.3 16V Turbo CD 107-165kW	09/89-12/98	ATE	<b>BD-6700</b>	ATE		<b>BD-6701</b>	
3.0 V6 24V 155kW	10/94-12/98	ATE	<b>BD-6700</b>	ATE		<b>BD-6701</b>	
<b>9-3 (YS3D)</b>							
2.0 96-151kW	03/98-09/02	ATE	<b>BD-5912</b>	ATE		<b>BD-5902</b>	
2.2 TiD 85/92kW	03/98-08/02	ATE	<b>BD-5912</b>	ATE		<b>BD-5902</b>	
2.3 Turbo 110/165kW	03/98-09/02	ATE (17")	<b>BD-5912</b>	ATE		<b>BD-5902</b>	
<b>9-3 (YS3F)</b>							
1.8i 90kW	07/03-	ATE (15")	<b>BD-5923</b>	ATE		<b>BD-6302</b>	
1.8 t 110kW	07/03-	ATE (15")	<b>BD-5923</b>	ATE		<b>BD-6302</b>	
		ATE (16")	<b>BD-6702</b>				
2.0 Turbo 129/154kW	09/02-	ATE (15")	<b>BD-5923</b>	ATE		<b>BD-6302</b>	
		ATE (16")	<b>BD-6702</b>				
2.2 TiD 92kW	06/02-	ATE	<b>BD-5923</b>	ATE		<b>BD-6302</b>	
		ATE (16")	<b>BD-6702</b>				
<b>9-5</b>							
2.0 t 110kW	07/99-08/05	ATE (>Ch.X3025751)	<b>BD-5914</b>				
		ATE (Ch.X3025752>)	<b>BD-5912</b>	ATE (Ch.X3025752>)		<b>BD-6501</b>	
2.2 TiD 88kW	03/02-08/05	ATE (>Ch.X3025751)	<b>BD-5914</b>				
		ATE (Ch.X3025752>)	<b>BD-5912</b>	ATE (Ch.X3025752>)		<b>BD-6501</b>	
2.3 t 125/136kW	09/97-08/05	ATE (>Ch.X3025751)	<b>BD-5914</b>				
		ATE (Ch.X3025752>)	<b>BD-5912</b>	ATE (Ch.X3025752>)		<b>BD-6501</b>	
3.0 V6 147kW	01/98-07/99	ATE (>Ch.X3025751)	<b>BD-5914</b>				
		ATE (Ch.X3025752>)	<b>BD-5912</b>	ATE (Ch.X3025752>)		<b>BD-6501</b>	
3.0 TiD 130kW	07/01-08/05	ATE (>Ch.X3025751)	<b>BD-5914</b>				
		ATE (Ch.X3025752>)	<b>BD-5912</b>	ATE (Ch.X3025752>)		<b>BD-6501</b>	
<b>SEAT</b>							
<b>Alhambra</b>							
1.8 T 110kW	05/98-07/00	ATE	<b>BD-3023</b>	LUC		<b>BD-1206</b>	
1.9 TDi 66/81kW	04/96-07/00	ATE	<b>BD-3023</b>	LUC		<b>BD-1206</b>	
2.0 85kW	04/96-07/00	ATE	<b>BD-3023</b>	LUC		<b>BD-1206</b>	
<b>Alhambra II</b>							
1.8 T 110kW	08/00-05/02	ATE (15")	<b>BD-3024</b>	LUC		<b>BD-3025</b>	
		ATE	<b>BD-1216</b>	LUC		<b>BD-3027</b>	
		ATE (16")	<b>BD-3026</b>				
1.9 TDi	08/00-05/02	ATE (15")	<b>BD-3024</b>	LUC		<b>BD-3025</b>	
		ATE (15")	<b>BD-1216</b>	LUC		<b>BD-3027</b>	
		ATE (16")	<b>BD-3026</b>				
2.0 85kW	08/00-05/02	ATE (15")	<b>BD-3024</b>	LUC		<b>BD-3025</b>	
		ATE	<b>BD-1216</b>	LUC		<b>BD-3027</b>	
		ATE (16")	<b>BD-3026</b>				
2.8 V6 150kW	06/00-	ATE	<b>BD-3026</b>	LUC		<b>BD-3027</b>	
<b>Arosa</b>							
1.0 37kW	05/97-06/04	ATE	<b>BD-8008</b>				
1.4 44kW	05/97-06/04	ATE	<b>BD-8008</b>				





• SEAT





			
<b>Arosa</b>			
1.4 16V 74kW	01/00-06/04	LUC	BD-8009 LUC BD-1206
1.4 TDI 55kW	01/00-06/04	ATE (>05/03)	BD-8008
		LUC (06/03>)	BD-8009
1.7 SDI 44kW	08/97-06/04	ATE	BD-8008
<b>Cordoba (6K2/C2)</b>			
1.0 37kW	09/96-05/99	KEL	BD-8010
		ATE (Ch.6KW000500> ; +ABS)	BD-8011 LUC (+ ABS) BD-8002
1.4 44kW	06/94-05/99	KEL (Ch.6KTR099020> ; +ABS)	BD-8012
		KEL (Ch.6KV241400>)	BD-8010
		ATE (Ch.6KW000500> ; +ABS)	BD-8013
1.4 16V 74kW	09/96-05/99	KEL	BD-8010 LUC BD-1206
		ATE (Ch.6KW000500> ; +ABS)	BD-8011
		ATE (Ch.6KW000500> ; +ABS)	BD-8013
1.6 55kW	10/93-05/99	KEL	BD-8004
		ATE	BD-8013
1.6 74kW	07/96-05/99	LUC	BD-8009
1.8 66kW	01/95-05/99	KEL	BD-8004
		ATE	BD-8013
1.8 16V 95kW	02/94-05/99	LUC (ventilated discs)	BD-8014 LUC BD-8002
		LUC	BD-8009
1.9 TD 66kW	10/95-05/99	LUC	BD-8009
1.9 TD 81kW	03/97-05/99	LUC	BD-1214
2.0 85/110kW	07/96-05/99	LUC	BD-8009 LUC BD-8002
<b>Cordoba SW (6K5)</b>			
1.4 44/55kW	05/99-09/02	ATE	BD-8011
1.6 74kW	06/99-09/02	LUC	BD-8009 LUC BD-1206
1.9 TDi 66/81kW	06/99-09/02	LUC	BD-8009 LUC BD-8002
<b>Cordoba II (6L2)</b>			
1.2 47kW	09/02-	ATE (1LQ,1ZF)	BD-1202
1.4 55kW	09/02-	ATE (1LQ,1ZF)	BD-1202
1.4 55kW	09/02-	ATE (1LQ,1ZF)	BD-1202
1.9 47kW	09/02-	ATE (1LQ,1ZF)	BD-1202
1.9 TDi 74kW	09/02-	ATE (1LQ,1ZF)	BD-1202 LUC BD-1206
<b>Ibiza II (6K1)</b>			
1.0 33kW	03/93-08/99	KEL	BD-8012
		ATE	BD-8011
1.3 40kW	03/93-08/99	KEL	BD-8012
1.4 44kW	09/93-08/99	KEL	BD-8012
		KEL (+ ABS)	BD-8010
1.4 44/74kW	05/93-08/99	ATE	BD-8011
1.6 55kW	05/93-08/99	ATE	BD-8013
		KEL	BD-8004
1.6 74kW	04/96-08/99	LUC	BD-8009
1.8 16V 95kW	05/93-08/99	LUC	BD-8014 LUC BD-8002
1.8 66kW	05/93-08/99	ATE	BD-8013
		KEL	BD-8004
1.9 D 47-55kW	01/95-08/99	KEL	BD-8004
		ATE	BD-8013
2.0 16V 110kW	08/96-08/99	LUC	BD-8014 LUC BD-8002
<b>Ibiza III (6K1)</b>			
1.4 16V 74kW	08/99-02/02	LUC	BD-8009
1.6 55kW	08/99-02/02	ATE	BD-8011 LUC BD-8002
1.6 74kW	08/99-02/02	LUC	BD-8009
1.8 20V 115kW	05/99-02/02	LUC	BD-8009 LUC BD-8002
1.9 SDi 50kW	08/99-02/02	ATE	BD-8011







					
1.9 TDi 81kW	08/99-02/02	LUC	BD-8009		
<b>Ibiza IV (6L1)</b>					
1.2 47kW	02/02-09/09	LUC	BD-8015		
		ATE	BD-8003		
1.4 16V 55/74kW	02/02-09/09	LUC	BD-8015	LUC	BD-1206
		ATE	BD-8003		
1.4 TDi 55kW	02/02-09/09	LUC	BD-8015	LUC	BD-1206
		ATE	BD-8003		
1.9 SDi 48kW	02/02-09/09	LUC	BD-8015	LUC	BD-1206
		ATE	BD-8003		
1.9 TDi 96kW	02/02-09/09	LUC	BD-8015	LUC	BD-1206
		ATE	BD-8003		
<b>Ibiza V (6J5)</b>					
1.4 TSI 90kW	05/08-	ATE (14")	BD-8003	LUC (1KT, 1KK)	BD-1206
		ATE (14", wear sensor)	BD-1202		
		ATE (15")	BD-1203		
1.6 MPI 75kW	05/08-	ATE (14")	BD-8003	LUC (1KT, 1KK)	BD-1206
		ATE (14", wear sensor)	BD-1202		
		ATE (15")	BD-1203		
<b>Leon (1M1)</b>					
1.4 16V 55kW	11/99-07/05	ATE	BD-8003	LUC	BD-1206
		ATE (wear sensor)	BD-1202		
1.6 MPI 74kW	11/99-07/05	ATE	BD-8003	LUC	BD-1206
		ATE (wear sensor)	BD-1202		
1.8 20V 92kW	11/99-07/05	ATE	BD-8003	LUC	BD-1206
		ATE (wear sensor)	BD-1202		
1.8 20V T Sport 132kW	11/99-07/05	ATE	BD-1213	LUC	BD-1206
		ATE	BD-1216		
1.9 TDi 66/81kW	11/99-07/05	ATE	BD-8003	LUC	BD-1206
		ATE (wear sensor)	BD-1202		
1.9 TDi 110kW	05/01-07/05	ATE	BD-1216	LUC	BD-1206
<b>Leon (1P1)</b>					
1.4 TSI 92kW	09/05-	ATE (1ZF,1ZM)	BD-1202	LUC (1KD)	BD-1206
		ATE (1LZ, 1ZE)	BD-1203	LUC (1KZ, 1KY, 1KT, 1KS)	BD-1204
1.6 75kW	09/05-	ATE (1ZF,1ZM)	BD-1202	LUC (1KD)	BD-1206
		ATE (1LZ, 1ZE)	BD-1203	LUC (1KZ, 1KY, 1KT, 1KS)	BD-1204
1.8 TSI 118kW	09/05-	ATE (1ZF,1ZM)	BD-1202	LUC (1KD)	BD-1206
		ATE (1LZ, 1ZE)	BD-1203	LUC (1KZ, 1KY, 1KT, 1KS)	BD-1204
<b>Toledo (1L)</b>					
1.6 52/55kW	05/91-03/99	KEL (>08/95)	BD-8004		
		ATE (09/95>)	BD-8013		
1.8 66kW	05/91-03/99	KEL (>08/95)	BD-8004		
		ATE (09/95>)	BD-8013	LUC	BD-8002
1.8 16V 92/98kW	05/91-03/99	LUC	BD-8014	LUC	BD-8002
1.9 D 50kW	05/91-03/99	KEL (>08/95)	BD-8004		
		ATE (09/95>)	BD-8013		
1.9 TDi 66kW	08/95-03/99	LUC (>08/98)	BD-8014		
		LUC (08/98>)	BD-1205		
1.9 TDi 81kW	05/96-08/99	LUC	BD-8009	LUC	BD-1206
2.0 85kW	05/91-03/99	LUC (>03/96)	BD-8014	LUC	BD-8002
		LUC (04/96>)	BD-1205	LUC	BD-1206
2.0 16V 110kW	11/93-03/99	LUC	BD-1205	LUC	BD-1206
<b>Toledo II (1M2)</b>					
1.4 16V 55kW	07/99-05/06	ATE (>01/01)	BD-8003	LUC	BD-1206
		ATE (02/01>)	BD-1202		





• SEAT — SKODA

				
<b>Toledo II (1M2)</b>				
1.6 74kW	05/99-05/06	ATE (>01/01)	<b>BD-8003</b> LUC	<b>BD-1206</b>
		ATE (02/01>)	<b>BD-1202</b>	
1.8 20V 92kW	04/99-05/06	ATE (>01/01)	<b>BD-8003</b> LUC	<b>BD-1206</b>
		ATE (02/01>)	<b>BD-1202</b>	
1.8 20VT 132kW	05/01-05/06	ATE	<b>BD-1212</b> LUC	<b>BD-1206</b>
1.9 TDi 66/81kW	07/99-05/06	ATE (>01/01)	<b>BD-8003</b> LUC	<b>BD-1206</b>
		ATE (02/01>)	<b>BD-1202</b>	
2.3 V5 110kW	04/99-09/04	ATE	<b>BD-1213</b> LUC	<b>BD-1206</b>
2.3 V5 20V 125kW	04/99-09/04	ATE	<b>BD-1212</b> LUC	<b>BD-1206</b>
<b>Toledo III (5P2)</b>				
1.6 75kW	10/04-	ATE (1ZF)	<b>BD-1202</b> LUC (1KD)	<b>BD-1206</b>
		ATE (1ZE)	<b>BD-1203</b> LUC (1KZ, 1KF, 1KJ)	<b>BD-1204</b>
1.8 TFSI 118kW	10/04-	ATE (1ZF)	<b>BD-1202</b> LUC (1KD)	<b>BD-1206</b>
		ATE (1ZE)	<b>BD-1203</b> LUC (1KZ, 1KF, 1KJ)	<b>BD-1204</b>
2.0 TDI 103kW	10/04-	ATE (1ZF)	<b>BD-1202</b> LUC (1KD)	<b>BD-1206</b>
		ATE (1ZE)	<b>BD-1203</b> LUC (1KZ, 1KF, 1KJ)	<b>BD-1204</b>
<b>SKODA</b>				
<b>Fabia (6Y2)</b>				
1.0 37kW	09/99-08/02	ATE (1LM)	<b>BD-8008</b>	
1.2 40/47kW	08/02-03/07	ATE (1LB,1LM)	<b>BD-8008</b>	
		ATE (1LQ,1LR)	<b>BD-8003</b>	
1.4 44kW	09/99-03/07	ATE (1LB, 1LM)	<b>BD-8008</b>	
		ATE (1LQ,1LR)	<b>BD-8003</b>	
1.4 16V 55/74kW	09/99-03/07	ATE (1LB,1LM)	<b>BD-8008</b> LUC	<b>BD-1206</b>
		ATE (1LQ,1LR)	<b>BD-8003</b>	
		ATE (wear sensor; 1LQ,1LR)	<b>BD-1202</b>	
1.9 SDI 47kW	12/99-07/05	ATE	<b>BD-8003</b>	
		ATE (wear sensor)	<b>BD-1202</b>	
1.9 TDI 74kW	01/00-03/07	ATE	<b>BD-8003</b> LUC	<b>BD-1206</b>
		ATE (wear sensor)	<b>BD-1202</b>	
2.0 85kW	07/01-03/07	LUC	<b>BD-8015</b> LUC	<b>BD-1206</b>
<b>Fabia (5J2)</b>				
1.2 44/51kW	04/07-	ATE (1ZG)	<b>BD-8003</b> LUC	<b>BD-1206</b>
		ATE (1LB)	<b>BD-8008</b>	
		ATE (1LR, wear sensor)	<b>BD-1202</b>	
		TRW	<b>BD-8015</b>	
		KEL (1ZE,)	<b>BD-8035</b>	
1.4 63kW	04/07-	ATE (1ZG)	<b>BD-8003</b> LUC	<b>BD-1206</b>
		ATE	<b>BD-8008</b>	
		ATE (1LR, wear sensor)	<b>BD-1202</b>	
		TRW	<b>BD-8015</b>	
		KEL (1ZE)	<b>BD-8035</b>	
1.6 77kW	04/07-	ATE (1ZG)	<b>BD-8003</b> LUC	<b>BD-1206</b>
		ATE	<b>BD-8008</b>	
		ATE (1LR, wear sensor)	<b>BD-1202</b>	
		TRW	<b>BD-8015</b>	
		KEL (1ZE)	<b>BD-8035</b>	
<b>Felicia</b>				
1.3 40-50kW	05/95-11/00	LUC	<b>BD-6900</b>	
1.6 55kW	08/96-11/00	LUC	<b>BD-6900</b>	
1.9 D 47kW	11/95-11/00	LUC	<b>BD-6900</b>	
<b>Octavia (1U2/1U5)</b>				
1.4 44kW	04/99-07/00	ATE	<b>BD-8003</b>	





					
1.4 16V 55kW	08/00-10/10	ATE	<b>BD-8003</b>	LUC (ABS)	<b>BD-1206</b>
		ATE (wear sensor / 14")	<b>BD-1202</b>		
1.6 55/74/75kW	09/96-10/10	ATE (>07/00)	<b>BD-8003</b>	LUC	<b>BD-1206</b>
		ATE (08/00> ; wear sensor)	<b>BD-1202</b>		
1.8 92kW	09/96-07/00	ATE	<b>BD-8003</b>	LUC	<b>BD-1206</b>
		ATE (wear sensor)	<b>BD-1202</b>		
1.8 T 110kW	08/97-10/10	ATE (>07/00)	<b>BD-1213</b>	LUC	<b>BD-1206</b>
		ATE (08/00> ; 4x4/FWD)	<b>BD-1212</b>		
1.8 RS 132kW	05/01-10/10	ATE	<b>BD-1212</b>	LUC	<b>BD-1206</b>
1.9 SDi 50kW	06/97-07/00	ATE	<b>BD-8003</b>		
		ATE (wear sensor)	<b>BD-1202</b>		
1.9 TDi 66/81kW	09/96-07/00	ATE	<b>BD-8003</b>		
		KEL (wear sensor)	<b>BD-1202</b>		
1.9 TDi 96kW	01/03-10/10	ATE	<b>BD-1212</b>	LUC	<b>BD-1206</b>
2.0 85kW	04/99-10/10	ATE	<b>BD-8003</b>	LUC	<b>BD-1206</b>
		ATE (wear sensor)	<b>BD-1202</b>		
		ATE (16")	<b>BD-1212</b>		
<b>Octavia II (1Z3/1Z5)</b>					
1.4 55/59kW	06/04-	ATE (1ZE)	<b>BD-1203</b>	LUC (1KF, 1KT)	<b>BD-1204</b>
		ATE (1ZF, 1ZM)	<b>BD-1202</b>	LUC (1KD)	<b>BD-1206</b>
1.4 TSI 90kW	06/08-	ATE (1ZE)	<b>BD-1203</b>	LUC (1KF, 1KT)	<b>BD-1204</b>
		ATE (1ZF, 1ZM)	<b>BD-1202</b>	LUC (1KD)	<b>BD-1206</b>
1.6 MPI 75kW	06/04-	ATE (1ZE)	<b>BD-1203</b>	LUC (1KF, 1KT)	<b>BD-1204</b>
		ATE (1ZF, 1ZM)	<b>BD-1202</b>	LUC (1KD)	<b>BD-1206</b>
1.6 FSI 85kW	06/04-	ATE (1ZE)	<b>BD-1203</b>	LUC (1KF, 1KT)	<b>BD-1204</b>
		ATE (1ZF, 1ZM)	<b>BD-1202</b>	LUC (1KD)	<b>BD-1206</b>
1.8 TSI 112kW	07/07-	ATE (1ZE)	<b>BD-1203</b>	LUC (1KF, 1KT)	<b>BD-1204</b>
		ATE (1ZF, 1ZM)	<b>BD-1202</b>	LUC (1KD)	<b>BD-1206</b>
2.0 FSI 110kW	11/04-	ATE (1ZE)	<b>BD-1203</b>	LUC (1KF, 1KT)	<b>BD-1204</b>
		ATE (1ZF, 1ZM)	<b>BD-1202</b>	LUC (1KD)	<b>BD-1206</b>
2.0 TDi 103kW	06/04-	ATE (1ZE)	<b>BD-1203</b>	LUC (1KF, 1KT)	<b>BD-1204</b>
		ATE (1ZF, 1ZM)	<b>BD-1202</b>	LUC (1KD)	<b>BD-1206</b>
2.0 RS 147kW	02/06-	ATE	<b>BD-1203</b>		<b>BD-1204</b>
<b>Roomster</b>					
1.2 47kW	09/06-	ATE	<b>BD-8003</b>	LUC	<b>BD-1206</b>
		ATE (wear sensor)	<b>BD-1202</b>		
		TRW	<b>BD-8015</b>		
1.4 63kW	09/06-	ATE	<b>BD-8003</b>	LUC	<b>BD-1206</b>
		ATE (wear sensor)	<b>BD-1202</b>		
		TRW	<b>BD-8015</b>		
1.6 77kW	09/06-	ATE	<b>BD-8003</b>	LUC	<b>BD-1206</b>
		ATE (wear sensor)	<b>BD-1202</b>		
		TRW	<b>BD-8015</b>		
<b>Superb (3U4)</b>					
1.8 T 110kW	02/02-06/08	ATE	<b>BD-1216</b>	LUC	<b>BD-1206</b>
1.9 TDI 74/96kW	02/02-06/08	ATE	<b>BD-1216</b>	LUC	<b>BD-1206</b>
2.0 85kW	02/02-06/08	ATE	<b>BD-1216</b>	LUC	<b>BD-1206</b>
2.5 TDI 114kW	02/02-06/08	ATE	<b>BD-1216</b>	LUC	<b>BD-1206</b>
2.8 V6 142kW	02/02-06/08	ATE	<b>BD-1216</b>	LUC	<b>BD-1206</b>
<b>Superb (3T)</b>					
1.8 TSI 118kW	07/08-	ATE (1ZE, 1LJ)	<b>BD-1203</b>	LUC (1KF, 1KJ)	<b>BD-1204</b>
2.0 TDI 103/125kW	07/08-	ATE (1ZE, 1LJ)	<b>BD-1203</b>	LUC (1KF, 1KJ)	<b>BD-1204</b>





# • SKODA — SSANGYONG — SUBARU

			
<b>Yeti</b>			
1.2 TSI 77kW	11/09-	ATE (1ZE, 1ZA)	<b>BD-1203</b> LUC (1KD) <b>BD-1206</b>
		ATE (1ZF)	<b>BD-1202</b> LUC (1KJ) <b>BD-1204</b>
1.8 TSI 112kW	11/09-	ATE (1ZE, 1ZA)	<b>BD-1203</b> LUC (1KD) <b>BD-1206</b>
		ATE (1ZF)	<b>BD-1202</b> LUC (1KJ) <b>BD-1204</b>
<b>SSANGYONG</b>			
<b>Actyon</b>			
2.0 Xdi 104kW	11/05-		<b>BD-3614</b> <b>BD-7000</b>
<b>Actyon new (C200) / Korando</b>			
2.0 D 129kW	06/11-		<b>BD-3615</b> <b>BD-3620</b>
<b>Kyron</b>			
2.0 Xdi 104kW	05/05-		<b>BD-3614</b> <b>BD-7000</b>
2.7 Xdi 121kW	05/05-		<b>BD-3614</b> <b>BD-7000</b>
<b>Rexton</b>			
2.7 Xdi 120kW	08/04-		<b>BD-5708</b> <b>BD-7000</b>
3.2 162kW	08/04-		<b>BD-5708</b> <b>BD-7000</b>
<b>SUBARU</b>			
<b>Forester (SF)</b>			
2.0 90/92kW	08/97-08/02	AKE	<b>BD-7104</b> AKE <b>BD-7106</b>
2.0 Turbo 125kW	06/98-04/01	AKE	<b>BD-7104</b> AKE <b>BD-7106</b>
<b>Forester (SG)</b>			
2.0 92kW	09/02-01/08	TOK	<b>BD-7101</b> AKE <b>BD-7106</b>
2.0 S Turbo 130kW	09/02-01/08	TOK	<b>BD-7101</b> AKE <b>BD-7106</b>
2.5 155kW	12/03-01/08	TOK	<b>BD-7101</b> AKE <b>BD-7106</b>
<b>Forester (SH)</b>			
2.0 110kW	02/08-		<b>BD-7101</b> <b>BD-7103</b>
2.0 D 108kW	02/08-		<b>BD-7101</b> <b>BD-7103</b>
2.5 169kW	02/08-		<b>BD-7101</b>
<b>Impreza (GC)</b>			
1.6 (4WD/FWD) 66kW	10/92-11/00	AKE	<b>BD-7112</b> SUM (+ ABS) <b>BD-7109</b>
		AKE	<b>BD-7112</b>
1.8 76kW	10/92-11/00	AKE	<b>BD-7112</b> SUM (+ ABS) <b>BD-7109</b>
2.0 85kW	10/95-12/00	AKE (>08/96)	<b>BD-7112</b> SUM (+ ABS) <b>BD-7109</b>
		AKE (01/99>)	<b>BD-7105</b>
2.0 Turbo (4WD) 155/160kW	03/94-12/00	AKE (>08/96)	<b>BD-7112</b> SUM (+ ABS) <b>BD-7109</b>
		AKE	<b>BD-7104</b>
		AKE (01/99>)	<b>BD-7105</b>
<b>Impreza II (GD/GG)</b>			
1.6 70kW AWD	12/00-12/07	AKE	<b>BD-7105</b>
		TOK	<b>BD-7101</b>
2.0 92kW	12/00-12/07	SUM (>10/02)	<b>BD-7104</b> AKE <b>BD-7106</b>
		TOK (11/02>)	<b>BD-7101</b>
		SUM	<b>BD-7107</b>
2.0 Turbo 160kW	12/00-12/07	SUM	<b>BD-7107</b> AKE <b>BD-7108</b>
<b>Impreza III (GR)</b>			
1.5 79kW	01/08-	TOK	<b>BD-7101</b> AKE <b>BD-7103</b>
2.0 110kW	01/08-	TOK	<b>BD-7101</b> AKE <b>BD-7103</b>
<b>Legacy (BC)</b>			
1.8 76kW	05/89-12/93	AKE	<b>BD-7112</b> SUM (+ ABS) <b>BD-7109</b>
2.0 85kW	08/91-12/93	AKE	<b>BD-7112</b> SUM (+ ABS) <b>BD-7109</b>
2.2 100kW	05/89-12/93	AKE	<b>BD-7112</b> SUM (+ ABS) <b>BD-7109</b>
<b>Legacy II (BD/BG)</b>			
2.0 85kW	09/94-03/99	AKE (>05/96)	<b>BD-7112</b> SUM <b>BD-7109</b>
		AKE (05/96>)	<b>BD-7105</b>





					
2.2 94/96kW	09/94-03/99	AKE (>05/96)	BD-7112	SUM	BD-7109
		AKE (05/96>)	BD-7105		
2.5 110kW	06/96-09/98	AKE	BD-7104	SUM	BD-7109
<b>Legacy III (BE/BH)</b>					
2.0 92kW	10/98-07/03	AKE (>07/00)	BD-7105	SUM	BD-7109
		AKE (08/00>)	BD-7104	AKE	BD-7106
2.5 115kW	10/98-07/03	AKE (>07/00)	BD-7105	SUM	BD-7109
		AKE (08/00>)	BD-7104	AKE	BD-7106
<b>Legacy IV</b>					
2.0 101kW	09/03-09/09	SUM	BD-7101	AKE	BD-7103
2.5 121kW	09/03-09/09	SUM	BD-7101	AKE	BD-7106
3.0 180kW	09/03-09/09	AKE	BD-7111	AKE	BD-7106
<b>Legacy V</b>					
2.0 110kW	10/09-		BD-7101		BD-7103
2.5 123kW	10/09-		BD-7101		BD-7103
<b>Outback</b>					
2.5 115kW	10/00-09/09	AKE	BD-7104	AKE	BD-7106
				AKE (11/03>)	BD-7103
3.0 154kW	10/00-09/09	AKE	BD-7104	AKE	BD-7106
3.0 180kW	11/03-09/09	AKE	BD-7111	AKE	BD-7106
<b>SUZUKI</b>					
<b>Baleno</b>					
1.3 52/63kW	03/95-05/02	SUM (>01/99)	BD-7306		
		SUM (02/99>)	BD-7310		
1.6 72kW	03/95-05/02	SUM (>01/99)	BD-7306		
		SUM (02/99>)	BD-7310		
1.8 89kW	03/95-05/02	SUM (>01/99)	BD-7306		
		SUM (02/99>)	BD-7310		
1.9 TD 55kW	02/99-05/02	SUM	BD-7310		
<b>Grand Vitara (FT/GT)</b>					
2.0 94kW	03/98-04/05	SUM	BD-5102		
		AKE	BD-7305		
2.0 D 64/80kW	03/98-04/05	SUM	BD-5102		
2.5 V6 116kW	03/98-04/05	SUM	BD-5102		
2.7 V6 127/135kW	09/01-04/05	SUM	BD-5102		
<b>Grand Vitara (JT)</b>					
1.6 78kW	05/05-	SUM	BD-7302		
2.0 103kW	10/05-	SUM	BD-7302		BD-5706
2.4 124kW	10/05-	SUM	BD-7302		BD-5706
<b>Jimny</b>					
1.3 59kW	09/98-	SUM	BD-7304		
<b>Liana</b>					
1.3 66kW	03/02-	AKE	BD-7311		BS-7302
1.6 76kW	03/02-	AKE	BD-7311		BS-7302
<b>Samurai</b>					
1.3 33-51kW	08/92-08/00	SUM	BD-7304		
1.9 TD 46kW	11/98-	SUM	BD-7304		
<b>Swift (SG)</b>					
1.3 68kW	05/05-	LUC (HUNGARY)	BD-5739		
		SUM (JAPAN, R.H.)	BD-7303		
1.5 75kW	05/05-	LUC (HUNGARY)	BD-5739		
		SUM (JAPAN, R.H.)	BD-7303		
<b>SX4</b>					
1.5 73kW	06/06-	LUC	BD-7313	07/09-	BD-3402
1.6 79kW	06/06-	LUC	BD-7313	07/09-	BD-3402

# • SUZUKI — TOYOTA

					
<b>Vitara</b>					
1.9 D 50/55kW	01/95-03/98	SUM	<b>BD-5102</b>		
2.0 V6 100kW	01/95-03/98	SUM	<b>BD-5102</b>		
2.0 D 52/64kW	01/95-03/98	SUM	<b>BD-5102</b>		
<b>Wagon R+</b>					
1.3 56kW	05/00-	BOS	<b>BD-5906</b>		
<b>TOYOTA</b>					
<b>Auris</b>					
1.4 VVTi 71kW	03/07-	AKE	<b>BD-7542</b>	AKE	<b>BD-7543</b>
		BOS (production GB)	<b>BD-7546</b>	BOS (production GB)	<b>BD-7547</b>
1.6 VVTi 91kW	03/07-	AKE	<b>BD-7542</b>	AKE	<b>BD-7543</b>
		BOS (production GB)	<b>BD-7546</b>	BOS (production GB)	<b>BD-7547</b>
1.4 D-4D 66kW	03/07-	AKE	<b>BD-7542</b>	AKE	<b>BD-7543</b>
		BOS (production GB)	<b>BD-7546</b>	BOS (production GB)	<b>BD-7547</b>
<b>Avensis (T22)</b>					
1.6 74/81kW	10/97-02/03	ATE (drum rear brakes)	<b>BD-7590</b>		
		ATE (>07/01)	<b>BD-7558</b>		
		ATE (07/01>)	<b>BD-7545</b>		
1.8 VVTi 95kW	07/00-02/03	ATE (drum rear brakes)	<b>BD-7590</b>		
		ATE (>07/01)	<b>BD-7558</b>		
		ATE (07/01>)	<b>BD-7545</b>		
2.0 94kW	10/97-06/00	ATE (drum rear brakes)	<b>BD-7590</b>		
		ATE	<b>BD-7558</b>		
2.0 VVTi 110kW	07/00-02/03	ATE (drum rear brakes)	<b>BD-7590</b>		
		ATE (>07/01)	<b>BD-7558</b>		
		ATE (07/01>)	<b>BD-7545</b>		
2.0 D 66kW	10/97-06/00	ATE (drum rear brakes)	<b>BD-7590</b>		
		ATE	<b>BD-7558</b>		
2.0 D-4D 81kW	07/00-02/03	ATE (drum rear brakes)	<b>BD-7590</b>		
		ATE (>07/01)	<b>BD-7558</b>		
		ATE (07/01>)	<b>BD-7545</b>		
<b>Avensis (T25)</b>					
1.6 VVTi 81kW	04/03-10/08	BOS	<b>BD-7548</b>	BOS	<b>BD-7539</b>
1.8 95kW	04/03-10/08	BOS	<b>BD-7548</b>	BOS	<b>BD-7539</b>
2.0 108kW	04/03-10/08	BOS	<b>BD-7548</b>	BOS	<b>BD-7539</b>
2.4 120/125kW	04/03-10/08	BOS	<b>BD-7548</b>	BOS	<b>BD-7539</b>
<b>Avensis (T27)</b>					
1.8 108kW	02/09-		<b>BD-7598</b>		<b>BD-7599</b>
2.0 112kW	02/09-		<b>BD-7598</b>		<b>BD-7599</b>
<b>Avensis Verso</b>					
2.0 VVTi 110kW	08/01-	AKE	<b>BD-7531</b>	SUM	<b>BD-7574</b>
		ATE	<b>BD-7545</b>		
2.0 D-4D 85kW	08/01-	AKE	<b>BD-7531</b>	SUM	<b>BD-7574</b>
		ATE	<b>BD-7545</b>		
<b>Aygo</b>					
1.0 VVTi 50kW	07/05-		<b>BD-6103</b>		
<b>Camry (V20)</b>					
2.2 96kW	08/96-10/01	SUM (14")	<b>BD-7516</b>	AKE (08/99>)	<b>BD-7517</b>
		AKE (15"; 08/99>)	<b>BD-7529</b>		
3.0 140kW	08/96-10/01	SUM (14")	<b>BD-7516</b>	AKE	<b>BD-7521</b>
		AKE (15"; 08/99>)	<b>BD-7529</b>	AKE (08/99>)	<b>BD-7517</b>
		AKE (US; 08/99>)	<b>BD-7520</b>		
<b>Camry (V30)</b>					
2.4 VVTi 112kW	11/01-05/06	AKE	<b>BD-7522</b>	AKE	<b>BD-7523</b>
3.0 V6 137kW	11/01-05/06	AKE	<b>BD-7522</b>	AKE	<b>BD-7523</b>





					
<b>Camry (V40)</b>					
2.4 123kW	06/06-10/11		BD-7530		BD-7532
3.5 24V 204kW	06/06-10/11		BD-7530		BD-7532
<b>Camry (V50)</b>					
2.5 135kW	11/11-		BD-7530		BD-7532
3.5 204kW	11/11-		BD-7530		BD-7532
<b>Carina II</b>					
1.6 66/72kW	12/87-03/92	AKE (13")	BD-7533		
		AKE (14")	BD-7591		
2.0 GLi 89kW	12/87-09/97	AKE (13")	BD-7533	AKE	BD-7521
		AKE (14")	BD-7591		
		AKE (14", ABS)	BD-7591		
2.0 D 54kW	03/88-03/92	AKE	BD-7533		
<b>Carina E</b>					
1.6 73-85kW	02/92-09/97	AKE	BD-7516		
1.8 79kW	01/95-09/97	AKE	BD-7516		
2.0 GLi 93/98kW	04/92-09/97	AKE	BD-7516		
2.0 D 54/61kW	04/92-09/97	AKE	BD-7516		
<b>Celica</b>					
1.6 GT 83-91kW	04/86-09/89	AKE	BD-7533		
1.8 85kW	11/93-01/98	AKE	BD-7516	AKE	BD-7521
1.8 VVTi 105/141kW	08/02-08/05	AKE	BD-7507	AKE	BD-7538
2.0 GTi/Turbo (4WD/FWD) 136kW	03/88-01/94	AKE (>08/90)	BD-7533	AKE	BD-7521
		AKE	BD-7591		
2.0 125kW	04/96-12/99	SUM	BD-7520	AKE	BD-7521
<b>Corolla</b>					
1.3 55kW	08/87-12/92	AKE	BD-7533		
1.3 53-65kW (E10)	12/92-04/97	AKE	BD-7516		BS-7502
1.3 63kW (E11)	04/97-01/02	AKE	BD-7529		
		AKE (production Japan)	BD-7516	AKE	BD-7521
		LUC (production GB)	BD-7592		
1.6 66/77kW	08/87-04/92	AKE	BD-7533		
1.6 84kW (E10)	09/92-04/97	AKE	BD-7516		BS-7503
1.6 79/81kW (E11)	04/97-01/02	AKE	BD-7529		BS-7503
		AKE (production Japan)	BD-7516	AKE	BD-7521
		LUC (production GB)	BD-7592		
1.8 86kW (E10)	05/92-04/97	AKE	BD-7516	AKE	BD-7521
2.0 D 53kW (E10)	05/92-04/97	AKE	BD-7516		
2.0 D 53kW (E11)	04/97-02/00	AKE	BD-7529		
<b>Corolla (E12)</b>					
1.4 VVTi 71kW	01/02-10/06	LUC	BD-7540	LUC	BD-7541
1.6 VVTi 81kW	01/02-10/06	LUC (production GB)	BD-7540	LUC	BD-7541
		AKE (production Japan)	BD-7526		
1.8 VVTLi 141kW	01/02-10/06	LUC (production GB)	BD-7540	LUC	BD-7541
		AKE (production Japan)	BD-7526		
2.0 D-4D 66/81kW	01/02-10/06	LUC	BD-7540	LUC	BD-7541
<b>Corolla (E15)</b>					
1.4 VVTi 71kW	11/06-	AKE	BD-7542	AKE	BD-7543
1.6 VVTi 91kW	11/06-	AKE	BD-7542	AKE	BD-7543
<b>Corolla Verso (E12J)</b>					
1.4 VVTi 71kW	01/02-05/04	AKE (production Japan)	BD-7526	AKE	BD-7538
	08/02-05/04	AKE (production GB)	BD-7540	LUC	BD-7541
1.6 VVTi 81kW	01/02-05/04	AKE	BD-7507	AKE	BD-7538
1.8 VVTi 99kW	04/02-05/04	AKE	BD-7507	AKE	BD-7538
2.0 D-4D 66kW	04/02-05/04	AKE	BD-7507	AKE	BD-7538

• TOYOTA





					
<b>Corolla Verso (ZER/ZZE)</b>					
1.6 81kW	05/04-	BOS	BD-7548	BD-7539	
1.8 95kW	05/04-	BOS	BD-7548	BD-7539	
<b>Land Cruiser (J7)</b>					
2.4 77/84kW	01/90-03/96	SUM	BD-7501	SUM	BD-7505
2.4 84kW	06/93-03/96	SUM	BD-7504		
2.4 TD 66kW	01/90-01/95	SUM	BD-7501	SUM	BD-7505
3.0 TD 92kW	05/93-03/96	SUM	BD-7501	SUM	BD-7505
3.4 D 70kW	01/91-03/96	SUM	BD-7501	SUM	BD-7505
4.2 D 96kW	02/90-01/95	SUM	BD-7504		
<b>Land Cruiser (J80)</b>					
4.0 115kW	01/90-01/95	SUM	BD-7504	SUM	BD-7505
4.2 D 99/118kW	02/90-01/95	SUM	BD-7504	SUM	BD-7505
4.2 TD 125kW	02/95-01/98	SUM	BD-7501	SUM	BD-7505
4.5 151kW	02/95-01/98	SUM	BD-7501	SUM	BD-7505
<b>Land Cruiser (J90)</b>					
3.0 TD 92kW	04/96-07/00	SUM	BD-7501	SUM	BD-7505
3.0 D-4D 120kW	10/00-08/02	SUM	BD-7501	SUM	BD-7505
3.4 24V 131kW	04/96-08/02	SUM	BD-7501	SUM	BD-7505
<b>Land Cruiser (J100)</b>					
4.2 TD 150kW	01/98-12/07	SUM	BD-7503	SUM	BD-7527
4.7 173kW	01/98-12/07	SUM	BD-7503	SUM	BD-7527
<b>Land Cruiser (J200)</b>					
4.5 TD 195/210kW	01/08-		BD-7580		BD-7581
4.7 202kW	01/08-		BD-7580		BD-7581
<b>Land Cruiser Prado (J120)</b>					
3.0 D-4D 120kW	01/03-04/10	SUM	BD-7549	SUM	BD-7505
4.0 183kW	01/03-04/10	SUM	BD-7549	SUM	BD-7505
<b>Land Cruiser Prado (J150)</b>					
2.7 120kW	05/10-	SUM	BD-7549	SUM	BD-7505
3.0 TD 127kW	05/10-	SUM	BD-7549	SUM (wear sensor)	BD-7503
					BD-7505
4.0 207kW	05/10-	SUM	BD-7549	SUM (wear sensor)	BD-7503
					BD-7505
<b>MR2</b>					
1.8 16V 103kW	04/00-	AKE	BD-7526		
<b>Paseo</b>					
1.5 66kW	08/95-09/99	AKE	BD-7533		
<b>Picnic</b>					
2.0 90/94kW	08/96-12/01	AKE	BD-7516		
2.2 D 66kW	08/97-12/01	AKE	BD-7516		
<b>Previa</b>					
2.0 D-4D 85kW	03/01-09/05	AKE	BD-7529	SUM	BD-7574
2.4 16V 115kW	08/00-	AKE	BD-7529	SUM	BD-7574
<b>Prius</b>					
1.5 53kW	05/00-01/04	AKE	BD-7526	AKE	BD-7538
1.5 57kW	01/04-01/09	AKE	BD-7526	AKE	BD-7538
1.8 73kW	01/09-	AKE	BD-7550		BD-7543
<b>RAV 4 (SXA1)</b>					
2.0 95kW	11/95-06/00	AKE	BD-7516		
<b>RAV 4 (XA2)</b>					
1.8 VVTi 92kW	02/01-10/05	AKE	BD-7511	AKE	BD-7510
2.0 VVTi (4WD) 110kW	06/00-10/05	AKE	BD-7511	AKE	BD-7510
2.0 D-4D (4WD) 85kW	09/01-10/05	AKE	BD-7511	AKE	BD-7510




• TOYOTA — UAZ — VOLKSWAGEN





				
<b>RAV 4 (ACA/ACE)</b>				
2.0 VVTi 112kW	03/06-	AKE	BD-7572	BD-7532
2.2 D-4D 100kW	03/06-	AKE	BD-7572	BD-7532
<b>Starlet</b>				
1.0 40kW	12/89-12/92	AKE	BD-7533	
1.3 55kW	12/89-12/95	AKE	BD-7533	
<b>Supra</b>				
3.0 243kW	05/93-06/96	SUM	BD-7524	BD-7528
<b>Yaris (CP10)</b>				
1.0 50kW	08/99-03/06	AKE (drum rear brakes)	BD-7519	BS-7501
		AKE (disc rear brakes)	BD-7526	BD-7538
		BOS	BD-7593	
1.3 63kW	11/99-03/06	AKE (drum rear brakes)	BD-7519	BS-7501
		AKE (disc rear brakes)	BD-7526	BD-7538
		BOS	BD-7593	
1.4 D-4D 55kW	12/01-03/06	AKE	BD-7519	BD-7538
		AKE (+ABS)	BD-7526	
		BOS	BD-7593	
1.5 78kW	04/01-03/06	AKE	BD-7526	BD-7538
		BOS	BD-7593	
<b>Yaris II</b>				
1.0 VVTi 51kW	10/06-	ATE	BD-7594	BD-7543
				BS-7501
1.3 VVTi 64kW	10/06-	ATE	BD-7594	BD-7543
<b>Yaris Verso</b>				
1.3 63kW	11/99-09/05	AKE	BD-7526	BD-7538
1.4 D-4D 55kW	10/01-09/05	AKE	BD-7526	BD-7538
1.5 78kW	10/00-09/05	AKE	BD-7526	BD-7538
<b>UAZ</b>				
<b>31512</b>				
2.5	01/98-		BD-4606	
<b>3160</b>				
2.7	01/94-12/04		BD-4606	
<b>3162</b>				
2.7	01/97-12/04		BD-4606	
<b>3163 Patriot</b>				
2.7	01/05-		BD-4606	
<b>Hunter</b>				
2.7	01/05-		BD-4606	
2.9	01/05-		BD-4606	
<b>VOLKSWAGEN</b>				
<b>Bora</b>				
1.4 16V 55kW	03/00-05/05	ATE (1LQ, 1LS, 1LR, 1ZM; 14/15")	BD-8003	BD-1206
		ATE (1LQ, 1ZF, 14")	BD-1202	
1.6 74-81kW	08/98-05/05	ATE (>Ch.1JX800000; 1LQ, 1LS, 1LR, 1ZM)	BD-8003	BD-1206
		ATE (Ch.1JY000001>; 1LQ, 1ZF)	BD-1202	
1.8 (4Motion/FWD) 92kW	08/98-05/05	ATE (>Ch.1JX800000; 1LJ)	BD-8003	BD-1206
		ATE (Ch.1JY000001>; wear sensor; 1ZP, 1ZM, 1LS)	BD-1202	
1.8 T 110kW	05/00-05/05	ATE (Ch.1JY000001>; 1ZE, 1ZD)	BD-1212	BD-1206
1.9 SDI (4Motion/FWD) 50kW	08/98-05/05	ATE (>Ch.1JX800000; 1LQ, 1LS, 1LR, 1ZM)	BD-8003	BD-1206
		ATE (Ch.1JY000001>; 1LQ, 1ZF, 1ZP)	BD-1202	
1.9 TDI (4Motion/FWD) 96/110kW	10/00-05/05	ATE (Ch.1JY000001>; 1LE, 1LJ, 1ZD, 1ZE, 1ZQ)	BD-1212	BD-1206
2.0 (4Motion/FWD) 85kW	10/98-05/05	ATE (>Ch.1JX800000; 1LQ, 1LS, 1LR, 1ZM)	BD-8003	BD-1206
		ATE (Ch.1JY000001>; 1LQ, 1ZF, 1ZP)	BD-1202	
2.3 VR5 (4Motion/FWD) 110/125kW	10/98-05/05	ATE (>Ch.1JX800000)	BD-1213	BD-1206
		ATE (Ch.1JY000001>)	BD-1212	





# • VOLKSWAGEN

			
<b>Bora</b>			
2.8 V6 (4Motion) 150kW	02/99-05/05	ATE Ch.1JY000001> (1ZD,1ZE,1LE)	BD-1212 LUC BD-1206
<b>Caddy</b>			
1.5 51kW	08/85-08/92	KEL	BD-8004
1.6 55kW	01/83-08/92	KEL	BD-8004
1.6 D 40kW	01/83-08/92	KEL	BD-8004
1.8 70kW	08/85-08/92	KEL	BD-8004
<b>Caddy II</b>			
1.4 44kW	11/95-07/03	LUC (> 9KT-514500)	BD-1205
		LUC (9KT-514501 >)	BD-8009
1.6 55kW	11/95-10/00	LUC (> 9KT-514500)	BD-1205
		LUC (9KT-514501 >)	BD-8009
1.9 SDI 47kW	11/95-07/03	LUC	BD-1205
1.9 TDI 66kW	11/95-07/03	LUC	BD-8009
<b>Caddy III</b>			
1.4 55/59kW	03/04-	ATE (1ZM,1ZF)	BD-1202
		ATE (1ZE)	BD-1203
1.6 75kW	03/04-	ATE (1ZM,1ZF)	BD-1202
		ATE (1ZE)	BD-1203
1.9 TDI 77kW	03/04-	ATE (1ZM,1ZF)	BD-1202
		ATE (1ZE)	BD-1203
<b>Corrado</b>			
1.8 16V 100kW	09/88-07/92	LUC	BD-8014 LUC BD-8002
1.8 G60 118kW	09/88-12/93	LUC	BD-1205 LUC BD-8002
2.0 85/100kW	08/91-12/95	LUC	BD-8014 LUC BD-8002
2.9 VR6 140kW	08/91-12/95	LUC	BD-8014 LUC BD-8002
<b>Golf III</b>			
1.4 40/44kW	11/91-08/97	KEL	BD-8004
		ATE (- ABS)	BD-8013
		ATE (+ ABS)	BD-8011
1.6 74kW	07/95-08/97	LUC (AT / 1LY,1ZK,1LF; 14")	BD-8014 LUC BD-8002
		LUC (1LL,1LV; 14")	BD-1205
1.6 55kW	09/92-08/97	ATE (- ABS / 1LK,1LM; 13")	BD-8013
		ATE (+ ABS)	BD-8011
1.8 55/66kW	11/91-08/97	LUC	BD-8014 LUC BD-8002
		LUC (10/94>)	BD-1205
		ATE (AT / Ch.1T028355>)	BD-8013
1.9 D 48/55kW	11/91-08/97	LUC (05/96>)	BD-8009
		KEL	BD-8004
1.9 TDI 66kW	08/93-08/97	ATE (08/95>)	BD-8013
		LUC (- ABS)	BD-1205 LUC BD-1206
		LUC (>05/96)	BD-8014
2.0 85kW	11/91-08/97	LUC (05/96>)	BD-8009
		LUC	BD-8014 LUC BD-8002
2.0 GTI 110kW	08/92-08/97	LUC (Syncro)	BD-8009
		LUC (>04/96)	BD-1205 LUC BD-8002
2.8 VR6 128kW	10/92-08/97	ATE (05/96>)	BD-1212 LUC BD-1206
		ATE	BD-1213 LUC BD-1206
<b>Golf IV</b>			
1.4 16V 55kW	09/97-05/05	ATE (>04/99 ; 14/15")	BD-8003 LUC BD-1206
		ATE (1LQ,1ZF; 14")	BD-1202
		ATE (1ZE,1ZD,1LJ)	BD-1212
1.6 74/75kW	08/97-06/05	LUC (>Ch.1JX800000; 1LQ,1ZM,1LS)	BD-8003 LUC BD-1206
		ATE (Ch.1JY000001>)	BD-1202
		ATE (1ZE,1ZD,1LJ)	BD-1212





				
1.6 16V 77kW	02/00-06/05	ATE (>Ch.1JX800000; 1LQ,1ZM,1LS)	<b>BD-8003</b> LUC	<b>BD-1206</b>
		ATE (Ch.1JY000001>)	<b>BD-1202</b>	
		ATE (1ZE,1ZD,1LJ)	<b>BD-1212</b>	
1.8 T 110/132kW	08/97-06/05	ATE (>Ch.1JX800000)	<b>BD-1213</b> LUC	<b>BD-1206</b>
		ATE (Ch.1JY000001>)	<b>BD-1212</b>	
1.8 92kW	08/97-06/05	ATE (>Ch.1JX800000; 1LQ,1ZM,1LS)	<b>BD-8003</b> LUC	<b>BD-1206</b>
		ATE (Ch.1JY000001>)	<b>BD-1202</b>	
1.9 SDI 50kW	08/97-06/05	ATE	<b>BD-8003</b> LUC	<b>BD-1206</b>
		ATE	<b>BD-1202</b>	
1.9 D 74/85kW	05/99-06/05	ATE (Ch.1JY000001>)	<b>BD-1202</b> LUC	<b>BD-1206</b>
		ATE (>Ch.1JX800000)	<b>BD-8003</b>	
1.9 TDI (4Motion/FWD) 96kW	11/00-06/05	ATE	<b>BD-1212</b> LUC	<b>BD-1206</b>
2.0 85kW	07/98-06/05	ATE (>Ch.1JX800000)	<b>BD-8003</b> LUC	<b>BD-1206</b>
		ATE (Ch.1JY000001>)	<b>BD-1202</b>	
<b>Golf V</b>				
1.4 16V 55kW	10/03-	ATE (1ZE,1ZP;1LJ)	<b>BD-1203</b>	
		ATE (1LK,1LM)	<b>BD-8016</b>	
		KEL (1LQ,1ZF,1ZM,1LS,1ZC)	<b>BD-1202</b>	
1.4 FSI 66kW	10/03-	ATE (1ZE,1ZP;1LJ)	<b>BD-1203</b> LUC (1KF,1KY,1KZ,1KE)	<b>BD-1204</b>
		ATE (1LK,1LM)	<b>BD-8016</b>	
		KEL (1LQ,1ZF,1ZM,1LS,1ZC)	<b>BD-1202</b>	
1.4 TSI 103/125kW	05/06-	ATE (1ZE,1ZP;1LJ)	<b>BD-1203</b> LUC (1KF,1KY,1KZ,1KE)	<b>BD-1204</b>
		ATE (1LK,1LM)	<b>BD-8016</b>	
		KEL (1LQ,1ZF,1ZM,1LS,1ZC)	<b>BD-1202</b>	
1.6 75kW	10/03-	ATE (1ZE,1ZP;1LJ)	<b>BD-1203</b> LUC (1KF,1KY,1KZ,1KE)	<b>BD-1204</b>
		ATE (1LK,1LM)	<b>BD-8016</b>	
		KEL (1LQ,1ZF,1ZM,1LS,1ZC)	<b>BD-1202</b>	
1.6 FSI 85kW	10/03-	ATE (1ZE,1ZP;1LJ)	<b>BD-1203</b> LUC (1KF,1KY,1KZ,1KE)	<b>BD-1204</b>
		ATE (1LK,1LM)	<b>BD-8016</b>	
		KEL (1LQ,1ZF,1ZM,1LS,1ZC)	<b>BD-1202</b>	
2.0 FSI 110kW	01/04-	ATE (1ZE,1ZP;1LJ)	<b>BD-1203</b> LUC (1KF,1KY,1KZ,1KE)	<b>BD-1204</b>
		ATE (1LK,1LM)	<b>BD-8016</b>	
		KEL (1LQ,1ZF,1ZM,1LS,1ZC)	<b>BD-1202</b>	
2.0 SDI 55kW	01/04-	ATE (1ZE,1ZP;1LJ)	<b>BD-1203</b> LUC (1KF,1KY,1KZ,1KE)	<b>BD-1204</b>
		ATE (1LK,1LM)	<b>BD-8016</b>	
		KEL (1LQ,1ZF,1ZM,1LS,1ZC)	<b>BD-1202</b>	
2.0 TDI 103kW	10/03-	ATE (1ZE,1ZP;1LJ)	<b>BD-1203</b> LUC (1KF,1KY,1KZ,1KE)	<b>BD-1204</b>
		ATE (1LK,1LM)	<b>BD-8016</b>	
		KEL (1LQ,1ZF,1ZM,1LS,1ZC)	<b>BD-1202</b>	
<b>Golf VI</b>				
1.4 TSI 90kW	10/08-	ATE (1ZE,1ZP)	<b>BD-1203</b> LUC (1KF,1KY,1KZ)	<b>BD-1204</b>
		ATE (1ZF)	<b>BD-1202</b> LUC (1KD)	<b>BD-1206</b>
		ATE (1LK,1LM,1ZK)	<b>BD-8016</b>	
1.6 75kW	10/08-	ATE (1ZE,1ZP)	<b>BD-1203</b> LUC (1KF,1KY,1KZ)	<b>BD-1204</b>
		ATE (1ZF)	<b>BD-1202</b> LUC (1KD)	<b>BD-1206</b>
		ATE (1LK,1LM,1ZK)	<b>BD-8016</b>	
<b>Jetta</b>				
1.3 40kW	08/83-07/91	KEL (AT)	<b>BD-8004</b>	
		KEL (MT)	<b>BD-8012</b>	
1.6 51/55kW	08/83-07/91	KEL (AT)	<b>BD-8004</b>	
		KEL (MT)	<b>BD-8012</b>	
1.6 D 40kW	08/83-07/91	KEL (AT)	<b>BD-8004</b>	
		KEL (MT)	<b>BD-8012</b>	
1.6 D 51/59kW	01/84-10/91	KEL	<b>BD-8004</b>	
1.8 66/72kW	08/87-07/91	KEL	<b>BD-8004</b>	
1.8 16V 95/102kW	08/88-10/91	LUC	<b>BD-8014</b> LUC	<b>BD-8002</b>





# • VOLKSWAGEN

				
<b>Jetta V (1K2)</b>				
1.4 TSI 90kW	07/06-12/11	ATE (1ZM)	<b>BD-1202</b> LUC	<b>BD-1204</b>
		ATE (1ZE,1ZP,1LJ,1ZD)	<b>BD-1203</b>	
1.6 75kW	10/05-12/11	ATE (1ZM)	<b>BD-1202</b> LUC	<b>BD-1204</b>
		ATE (1ZE, 1ZP, 1LJ, 1ZD)	<b>BD-1203</b>	
<b>Jetta VI (162)</b>				
1.4 TSI 90kW	02/12-	ATE (1ZM)	<b>BD-1202</b>	
		ATE (1ZE)	<b>BD-1203</b>	
1.6 75kW	02/12-	ATE (1ZM)	<b>BD-1202</b>	
		ATE (1ZE)	<b>BD-1203</b>	
<b>LT 28-46</b>				
2.3 105kW	06/98-	ATE	<b>BD-5337</b> BOS	<b>BD-5340</b>
2.5 SDI/TDI 55-80kW	06/98-	ATE	<b>BD-5337</b> BOS	<b>BD-5340</b>
2.8 D	06/98-	ATE	<b>BD-5337</b> BOS	<b>BD-5340</b>
<b>Lupo</b>				
1.0 37kW	10/98-07/05	ATE	<b>BD-8008</b>	
1.2 TD 45kW	07/99-07/05	ATE	<b>BD-1211</b>	
1.4 44/55kW	10/98-07/05	ATE	<b>BD-8008</b>	
1.4 16V 74kW	08/99-07/05	LUC	<b>BD-8009</b> LUC	<b>BD-1206</b>
1.4 D 55kW	01/99-07/05	LUC	<b>BD-8009</b>	
1.6 92kW	09/00-07/05	LUC	<b>BD-8009</b> LUC	<b>BD-1206</b>
1.7 SDi 44kW	10/98-07/05	ATE	<b>BD-8008</b>	
<b>Multivan V</b>				
1.9 TDI 77kW	04/03-	ATE	<b>BD-8001</b>	
2.0 85kW	04/03-	ATE	<b>BD-8001</b>	
2.5 TDI 120/128kW	04/03-	ATE	<b>BD-8001</b>	
<b>New Beetle</b>				
1.8 110kW	09/99-	ATE	<b>BD-1212</b> LUC	<b>BD-1206</b>
2.3 125kW	10/00-	ATE	<b>BD-1212</b> LUC	<b>BD-1206</b>
<b>Passat B3</b>				
1.6 53/55kW	04/88-09/91	KEL (- ABS)	<b>BD-8004</b>	
		LUC (+ ABS)	<b>BD-1205</b>	
1.6 TD 59kW	08/88-09/93	LUC (>12/89)	<b>BD-1201</b>	
		LUC (01/90>)	<b>BD-1205</b>	
1.8 66kW	04/88-09/93	LUC (>12/89)	<b>BD-1201</b>	
		LUC (01/90>)	<b>BD-1205</b>	
1.8 82kW	01/90-07/92	LUC	<b>BD-8014</b> LUC	<b>BD-8002</b>
1.8 G60 (Syncro) 118kW	09/89-09/93	LUC	<b>BD-1205</b> LUC	<b>BD-8002</b>
1.9 D 50/66kW	04/88-09/93	LUC (>12/89)	<b>BD-1201</b>	
		LUC (01/90>)	<b>BD-1205</b>	
2.0 85/100kW	01/90-07/95	LUC	<b>BD-8014</b> LUC	<b>BD-8002</b>
2.8 VR6 128kW	06/91-10/93	LUC	<b>BD-1205</b> LUC	<b>BD-8002</b>
<b>Passat B4</b>				
1.6 74kW	10/94-08/96	LUC (>Ch.3AT130756)	<b>BD-1205</b> LUC	<b>BD-1206</b>
		LUC (Ch.3AT130757>)	<b>BD-8014</b>	
1.8 55/66kW	10/93-08/96	LUC	<b>BD-1205</b> LUC (+ ABS)	<b>BD-1206</b>
1.9 TDI 66/81kW	10/93-08/96	LUC (>07/95)	<b>BD-1205</b> LUC	<b>BD-1206</b>
		LUC (08/95>)	<b>BD-8014</b>	
2.0 110kW	01/94-08/96	ATE (>07/95)	<b>BD-1213</b> LUC (>07/95)	<b>BD-8002</b>
		ATE (08/95>)	<b>BD-1213</b> LUC (08/95>)	<b>BD-1206</b>
2.0 79/85kW	08/94-08/96	LUC (>07/95)	<b>BD-8014</b> LUC (>07/95)	<b>BD-8002</b>
		LUC (08/95>)	<b>BD-8014</b> LUC (08/95>)	<b>BD-1206</b>
2.8 VR6 128kW	10/93-08/96	ATE (>07/95)	<b>BD-1213</b> LUC (>07/95)	<b>BD-8002</b>
		ATE (08/95>)	<b>BD-1213</b> LUC (08/95>)	<b>BD-1206</b>





			
<b>Passat B5 (3B2/3B3)</b>			
1.6 74kW	10/96-05/05	LUC (>Ch.3BX60000; 1LZ,1ZJ) ATE (10/00->)	BD-1214 LUC BD-1216
1.8 92kW	10/96-05/05	LUC (>Ch.3BX60000; 1LZ,1ZJ) ATE (10/00->) LUC (Ch.3BY000001>; >09/00)	BD-1214 LUC BD-1216 BD-1215
1.8 T 110kW	10/96-05/05	ATE (>Ch.3BX600000; 1LB,1ZC) ATE (Ch.3BY000001>; 1ZC,1LT)	BD-1213 LUC BD-1216
1.9 TDI 66kW	10/96-11/00	LUC (>Ch.3BX60000; 1LZ,1ZJ) LUC (Ch.3BY000001>; >09/00)	BD-1214 LUC BD-1215
1.9 TDI 81-96kW	10/96-05/05	ATE (>Ch.3BX600000; 1LB,1ZC) ATE (Ch.3BY000001>; 1ZC,1LT)	BD-1213 LUC BD-1216
2.0 88/96kW	04/00-05/05	ATE (15"/16")	BD-1216 LUC
2.3 VR5 110kW	10/96-10/00	ATE (>Ch.3BX600000; 1LB,1ZC)	BD-1213 LUC
2.3 V5 (4Motion/FWD) 125kW	11/00-05/05	ATE (Ch.3BY000001>; 16")	BD-1216 LUC
2.5 TDI 110kW	07/98-05/05	ATE (>Ch.3BX600000) ATE (Ch.3BY000001>; 16")	BD-1213 LUC BD-1216
2.8 V6 (FWD/Syncro) 142kW	05/97-05/05	ATE (>Ch.3BX600000) ATE (Ch.3BY000001>; 16")	BD-1213 LUC BD-1216 LUC
<b>Passat B6 (3C2)</b>			
1.6 75/85kW	05/05-08/10	ATE (1LJ, 1LH, 1ZG) ATE (1LK)	BD-1203 LUC >3C-7-300000 BD-8016 LUC 3C-8-300001>
2.0 FSI 110kW	05/05-08/10	ATE (1LJ, 1LH, 1ZG) ATE (1LK)	BD-1203 LUC >3C-7-300000 BD-8016 LUC 3C-8-300001>
2.0 TFSI 147kW	08/05-08/10	ATE (1LJ, 1LH, 1ZG) ATE (1LK)	BD-1203 LUC >3C-7-300000 BD-8016 LUC 3C-8-300001>
3.2 FSI 184kW	11/05-08/10	ATE (1LJ, 1LH, 1ZG) ATE (1LK)	BD-1203 LUC >3C-7-300000 BD-8016 LUC 3C-8-300001>
1.9 TDI 77kW	05/05-08/10	ATE (1LJ, 1LH, 1ZG) ATE (1LK)	BD-1203 LUC >3C-7-300000 BD-8016 LUC 3C-8-300001>
2.0 TDI 100/103kW	05/05-08/10	ATE (1LJ, 1LH, 1ZG) ATE (1LK)	BD-1203 LUC >3C-7-300000 BD-8016 LUC 3C-8-300001>
<b>Passat B7 (362)</b>			
1.4 T 90kW	09/10-	ATE (1ZM, 1ZG)	BD-1203 LUC (2EA)
1.8 T 111kW	09/10-	ATE (1ZM, 1ZG)	BD-1203 LUC (2EA)
<b>Phaeton</b>			
3.2 V6 177kW	04/02-	ATE (17")	BD-1222
4.2 V8 (4Motion) 246kW	05/03-	ATE (17")	BD-1222
5.0 TDI (4Motion) 230kW	11/02-	ATE (17")	BD-1222
<b>Polo III (6N1)</b>			
1.0 33kW	10/94-09/96	ATE	BD-8008
1.4 40/44kW	01/96-10/99	ATE	BD-8008
1.4 16V 74kW	04/96-10/99	LUC	BD-8009 LUC
1.6 55kW	02/95-10/99	ATE	BD-8008
1.6 GTi 88kW	09/98-10/99	LUC	BD-8009 LUC
1.7 SDi 42/44kW	04/97-10/99	ATE	BD-8008
1.9 D 47kW	07/96-10/99	ATE	BD-8008
<b>Polo IV (6N2)</b>			
1.4 40/44kW	10/99-09/01	ATE (+ ABS)	BD-8011
1.4 16V 74kW	10/99-09/01	LUC	BD-8009 LUC
1.7 SDi 44kW	10/00-10/01	ATE	BD-8009
1.9 TDi 47kW	10/99-10/01	LUC	BD-8009 LUC
<b>Polo (9N_)</b>			
1.2 40/47kW	11/01-	ATE (1LM,1ZN) ATE (wear sensor; 1LM,1ZN) KEL (1LQ,1LR,1ZG,1ZF) LUC (1LN,1ZD,1ZH)	BD-8008 BD-8017 BD-1202 BD-8015

# • VOLKSWAGEN





				
<b>Polo (9N_)</b>				
1.4 16V 55/74kW	11/01-	ATE (1LM,1ZN)	<b>BD-8008</b> LUC	<b>BD-1206</b>
		ATE (wear sensor; 1LM,1ZN)	<b>BD-8017</b>	
		LUC (1LN,1ZD,1ZH)	<b>BD-8015</b>	
		KEL (1LQ,1LR,1ZG,1ZF)	<b>BD-1202</b>	
1.4 FSI 63kW	05/02-	ATE (1LM,1ZN)	<b>BD-8017</b> LUC	<b>BD-1206</b>
		LUC (1LN,1ZD,1ZH)	<b>BD-8015</b>	
		KEL (1LQ,1LR,1ZG,1ZF)	<b>BD-1202</b>	
1.4 TDI 55kW	11/01-	ATE (1LM,1ZN)	<b>BD-8008</b> LUC	<b>BD-1206</b>
		ATE (wear sensor; 1LM,1ZN)	<b>BD-8017</b>	
		LUC (1LN,1ZD,1ZH)	<b>BD-8015</b>	
		KEL (1LQ,1LR,1ZG,1ZF)	<b>BD-1202</b>	
<b>Polo (sedan)</b>				
1.6 75kW	07/10-	ATE (1ZG)	<b>BD-8003</b> (1KH)	<b>BD-8037</b>
		KEL (1ZE)	<b>BD-8035</b> (1KC; drum rear brakes)	<b>BS-8001</b>
<b>Sharan</b>				
1.8 T 20V 110kW	09/97-	ATE (>02/00)	<b>BD-3023</b> LUC	<b>BD-1206</b>
		ATE (03/00>)	<b>BD-3024</b> LUC (Ch.7M1070000>)	<b>BD-3025</b>
		ATE (Ch.7M2000001>)	<b>BD-8018</b> LUC (>Ch.7M1070000)	<b>BD-3027</b>
1.9 TDI 85kW	09/95-	ATE (>02/00)	<b>BD-3023</b> LUC	<b>BD-1206</b>
		ATE (03/00>; 15")	<b>BD-3024</b> LUC (>Ch.7M1070000)	<b>BD-3025</b>
			LUC (Ch.7M2000001>)	<b>BD-3027</b>
1.9 TDI 96kW	11/02-	ATE (>Ch.7M1070000)	<b>BD-8018</b> LUC (>Ch.7M1070000)	<b>BD-3025</b>
		ATE	<b>BD-3026</b> LUC (Ch.7M2000001>)	<b>BD-3027</b>
2.0 85kW	09/95-	ATE (>02/00)	<b>BD-3023</b> LUC	<b>BD-1206</b>
		ATE (15")	<b>BD-3024</b> LUC	<b>BD-3025</b>
		ATE (16")	<b>BD-3026</b>	
2.8 VR6 128kW	09/95-02/00	ATE	<b>BD-3023</b> LUC	<b>BD-1206</b>
2.8 V6 150kW	03/00-	ATE	<b>BD-3026</b> LUC (>Ch.7M1070000)	<b>BD-3025</b>
			LUC (Ch.7M2000001>)	<b>BD-3027</b>
<b>Tiguan</b>				
1.4 TSI 110kW	10/07-	ATE (1UJ,1ZD)	<b>BD-8038</b> LUC (1KU)	<b>BD-8030</b>
2.0 TFSI 125kW	10/07-	ATE (1UJ,1ZD)	<b>BD-8038</b> LUC (1KU)	<b>BD-8030</b>
2.0 TDI 103kW	10/07-	ATE (1UJ,1ZD)	<b>BD-8038</b> LUC (1KU)	<b>BD-8030</b>
<b>Touareg (7LA, 7L6, 7L7)</b>				
2.5 TDI 128kW	01/03-09/10	ATE (1LB, 16")	<b>BD-8006</b> BRE (1KF,2EE)	<b>BD-8007</b>
		BRE (1LC, 17")	<b>BD-8005</b> ATE (1KE)	<b>BD-8034</b>
		BRE (1LF, 18")	<b>BD-8019</b>	
		BRE (1LU,1LT)	<b>BD-8031</b>	
		BRE (1LA,1LE)	<b>BD-8028</b>	
3.0 V6 TDI 165kW	01/05-09/10	ATE (1LB, 16")	<b>BD-8006</b> BRE (1KF,2EE)	<b>BD-8007</b>
		BRE (1LC, 17")	<b>BD-8005</b> ATE (1KE)	<b>BD-8034</b>
		BRE (1LF, 18")	<b>BD-8019</b>	
3.2 V6 162/177kW	10/02-09/10	ATE (1LB, 16")	<b>BD-8006</b> BRE (1KF,2EE)	<b>BD-8007</b>
		BRE (1LC, 17")	<b>BD-8005</b> ATE (1KE)	<b>BD-8034</b>
		BRE (1LF, 18")	<b>BD-8019</b>	
3.6 FSI 206kW	03/06-09/10	ATE (1LB, 16")	<b>BD-8006</b> BRE (1KF,2EE)	<b>BD-8007</b>
		BRE (1LC, 17")	<b>BD-8005</b> ATE (1KE)	<b>BD-8034</b>
		BRE (1LF, 18")	<b>BD-8019</b>	
		BRE (1LU,1LT)	<b>BD-8031</b>	
		BRE (1LA,1LE)	<b>BD-8028</b>	
4.2 V8 228kW	10/02-09/10	ATE (1LB, 16")	<b>BD-8006</b> BRE (1KF,2EE)	<b>BD-8007</b>
		BRE (1LC, 17")	<b>BD-8005</b> ATE (1KE)	<b>BD-8034</b>
		BRE (1LF, 18")	<b>BD-8019</b>	
		BRE (1LU,1LT)	<b>BD-8031</b>	
		BRE (1LA,1LE)	<b>BD-8028</b>	

			
<b>Touareg (7P5)</b>			
3.0 TDI 150kW	10/10-	BRE (1LC, 1LA, 1LE)	<b>BD-8028</b> BRE (1KJ, 2EG) <b>BD-8029</b>
3.0 TDI 176kW	10/10-	BRE (1LC, 1LA, 1LE)	<b>BD-8028</b> BRE (1KJ, 2EG) <b>BD-8029</b>
3.6 TSI 183kW	10/10-	BRE (1LC, 1LA, 1LE)	<b>BD-8028</b> BRE (1KJ, 2EG) <b>BD-8029</b>
<b>Touran</b>			
1.6 FSI 85kW	02/03-	ATE	<b>BD-1203</b> TRW <b>BD-1204</b>
1.9 TDi	02/03-	ATE	<b>BD-1203</b> TRW <b>BD-1204</b>
2.0 TDi	02/03-	ATE	<b>BD-1203</b> TRW <b>BD-1204</b>
2.0 FSI 110kW	10/03-	ATE	<b>BD-1203</b> TRW <b>BD-1204</b>
<b>Transporter T4</b>			
1.8 49kW	09/90-03/03	LUC	<b>BD-8023</b> LUC (05/97> / 16") <b>BD-3027</b>
1.9 D 45kW	09/90-03/03	LUC	<b>BD-8021</b> LUC (05/97> / 16") <b>BD-3027</b>
1.9 TD 50kW	09/90-03/03	LUC	<b>BD-8022</b> LUC (05/97> / 16") <b>BD-3027</b>
2.0 62kW	09/90-03/03	LUC	<b>BD-8023</b> LUC (05/97> / 16") <b>BD-3027</b>
2.4 D 55kW	09/90-03/03	ATE (+ EDS)	<b>BD-8024</b> LUC (05/97> / 16") <b>BD-3027</b>
2.4 D Syncro 57kW	09/90-03/03	ATE (16")	<b>BD-8025</b> LUC (05/97> / 16") <b>BD-3027</b>
2.5 81/85kW	09/90-03/03	LUC (15") Ch.7010000955>	<b>BD-8026</b> LUC (05/97> / 16") <b>BD-3027</b>
		ATE (+ EDS)	<b>BD-8024</b>
		ATE (- EDS)	<b>BD-8023</b>
2.5 D 65-111kW	09/90-03/03	ATE (16")	<b>BD-8018</b> LUC (05/97> / 16") <b>BD-3027</b>
2.8 VR6 103/150kW	09/90-03/03	ATE (15", ventilated)	<b>BD-8027</b> LUC (05/97> / 16") <b>BD-3027</b>
<b>Transporter T5</b>			
1.9 TDI 77kW	04/03-	ATE (2E3; 16")	<b>BD-8001</b> LUC (0WL,0WM,0WN,0WP) <b>BD-8033</b>
		ATE (2E4; 17")	<b>BD-8032</b> ATE (0E0,0E9,0WR) <b>BD-8034</b>
2.0 85kW	04/03-	ATE (2E3; 16")	<b>BD-8001</b> LUC (0WL,0WM,0WN,0WP) <b>BD-8033</b>
		ATE (2E4; 17")	<b>BD-8032</b> ATE (0E0,0E9,0WR) <b>BD-8034</b>
2.5 TDI 128kW	04/03-	ATE (2E3; 16")	<b>BD-8001</b> LUC (0WL,0WM,0WN,0WP) <b>BD-8033</b>
		ATE (2E4; 17")	<b>BD-8032</b> ATE (0E0,0E9,0WR) <b>BD-8034</b>
<b>Vento</b>			
1.4 40/44kW	11/91-04/96	KEL (>07/95)	<b>BD-8004</b>
		ATE (08/95>)	<b>BD-8013</b>
1.6 55kW	11/91-07/97	KEL (>07/95)	<b>BD-8004</b> LUC <b>BD-8002</b>
		ATE (13")	<b>BD-8013</b>
		LUC (15")	<b>BD-1205</b>
1.6 74kW	10/94-07/97	LUC (>05/96)	<b>BD-8014</b> LUC <b>BD-8002</b>
		LUC (1LD, 15")	<b>BD-1205</b>
		LUC (14")	<b>BD-8009</b>
1.8 55/66kW	11/91-07/97	KEL (>07/95)	<b>BD-8004</b> LUC <b>BD-8002</b>
		ATE (08/95>; 13")	<b>BD-8013</b>
		LUC (>05/96)	<b>BD-8014</b>
		LUC (06/96>; 1LD,1LL,1LV; 15")	<b>BD-1205</b>
		LUC (06/96>; 1LY,1ZK,1LF; 14")	<b>BD-8009</b>
1.9 D	11/91-07/97	KEL (>07/95)	<b>BD-8004</b> LUC <b>BD-8002</b>
		ATE (08/95>; 13")	<b>BD-8013</b>
		LUC (>05/96)	<b>BD-8014</b>
		LUC (06/96>; 1LD,1LL,1LV; 15")	<b>BD-1205</b>
		LUC (06/96>; 1LY,1ZK,1LF; 14")	<b>BD-8009</b>
2.0 85kW	07/94-07/97	LUC (>05/96)	<b>BD-8014</b> LUC <b>BD-8002</b>
		LUC (06/96>; 1LD,1LL,1LV; 15")	<b>BD-1205</b>
		LUC (06/96>; 1LY,1ZK,1LF; 14")	<b>BD-8009</b>
		ATE	<b>BD-1213</b>
		<b>VOLVO</b>	
<b>240</b>			
2.0 66-76kW	10/82-12/93	LUC	<b>BD-7800</b> LUC <b>BD-7801</b>
			ATE <b>BD-7802</b>





• VOLVO





			
<b>240</b>			
2.3 81-103kW	10/82-12/93	LUC	<b>BD-7800</b> LUC <b>BD-7801</b>
			ATE <b>BD-7802</b>
2.4 D 58/60kW	10/82-12/93	LUC	<b>BD-7800</b> LUC <b>BD-7801</b>
			ATE <b>BD-7802</b>
<b>440</b>			
1.6 61kW	09/91-12/96	LUC	<b>BD-7803</b> ATE (+ ABS) <b>BD-7805</b>
		ATE	<b>BD-7804</b>
1.7 64-75kW	09/91-12/96	LUC	<b>BD-7803</b> ATE (+ ABS) <b>BD-7805</b>
		ATE	<b>BD-7804</b>
1.7 Turbo 88/90kW	09/93-12/96	LUC	<b>BD-7804</b>
1.8 66kW	09/91-12/96	LUC	<b>BD-7803</b> ATE (+ ABS) <b>BD-7805</b>
		ATE	<b>BD-7804</b>
1.9 D 66kW	07/94-12/96	LUC	<b>BD-7803</b> ATE (+ ABS) <b>BD-7805</b>
		ATE	<b>BD-7804</b>
2.0 80kW	08/92-07/96	LUC	<b>BD-7803</b> ATE (+ ABS) <b>BD-7805</b>
		ATE	<b>BD-7804</b>
<b>460</b>			
1.6 61kW	07/92-07/96	LUC	<b>BD-7803</b> ATE (+ ABS) <b>BD-7805</b>
		ATE	<b>BD-7804</b>
1.7 64/75kW	09/89-07/96	LUC	<b>BD-7803</b> ATE (+ ABS) <b>BD-7805</b>
		ATE	<b>BD-7804</b>
1.8 66kW	08/91-07/96	LUC	<b>BD-7803</b> ATE (+ ABS) <b>BD-7805</b>
		ATE	<b>BD-7804</b>
1.9 D 66kW	07/94-07/96	LUC	<b>BD-7803</b> ATE (+ ABS) <b>BD-7805</b>
		ATE	<b>BD-7804</b>
2.0 80kW	07/92-07/96	LUC	<b>BD-7803</b> ATE (+ ABS) <b>BD-7805</b>
		ATE	<b>BD-7804</b>
<b>480</b>			
1.7 70-80kW	08/87-07/96	LUC	<b>BD-7803</b> ATE (+ ABS) <b>BD-7805</b>
2.0 81kW	08/92-07/96	ATE	<b>BD-7804</b> ATE (+ ABS) <b>BD-7805</b>
<b>740</b>			
2.0 76-118kW	09/87-08/92	LUC	<b>BD-7806</b> LUC <b>BD-7801</b>
		BDX	<b>BD-7807</b> ATE <b>BD-7802</b>
		LUC	<b>BD-7808</b>
2.3 83-140kW	09/87-08/92	LUC	<b>BD-7806</b> LUC <b>BD-7801</b>
		BDX	<b>BD-7807</b> ATE <b>BD-7802</b>
		LUC	<b>BD-7808</b>
2.4 D 60-90kW	09/87-08/92	LUC	<b>BD-7806</b> LUC <b>BD-7801</b>
		BDX	<b>BD-7807</b> ATE <b>BD-7802</b>
		LUC	<b>BD-7808</b>
<b>760</b>			
2.3 119kW	09/87-07/91	LUC	<b>BD-7806</b> LUC <b>BD-7809</b>
		BDX	<b>BD-7807</b> ATE <b>BD-7802</b>
2.4 TD 80/85kW	09/87-07/91	LUC	<b>BD-7806</b> LUC <b>BD-7809</b>
		BDX	<b>BD-7807</b> ATE <b>BD-7802</b>
2.8 105/108kW	09/87-08/91	LUC	<b>BD-7806</b> LUC <b>BD-7809</b>
		BDX	<b>BD-7807</b> ATE <b>BD-7802</b>
<b>850</b>			
2.0 93-154kW	09/92-02/97	ATE	<b>BD-7810</b> ATE <b>BD-7802</b>
2.3 T5 166kW	08/93-02/97	ATE	<b>BD-7810</b> ATE <b>BD-7802</b>
2.5 103-125kW	09/92-02/97	ATE	<b>BD-7810</b> ATE <b>BD-7802</b>
2.5 D 103kW	08/95-02/97	ATE	<b>BD-7810</b> ATE <b>BD-7802</b>
<b>940</b>			
2.0 82/114kW	01/92-10/98	BDX (>07/94)	<b>BD-7807</b> ATE <b>BD-7802</b>
		LUC (>07/94)	<b>BD-7806</b>
		LUC (08/94>; + ABS)	<b>BD-7808</b>



















				
2.3 85-121kW	09/90-10/98	BDX (>07/94)	<b>BD-7807</b> LUC (>12/91)	<b>BD-7801</b>
		LUC (>07/94)	<b>BD-7806</b> ATE (01/92>)	<b>BD-7802</b>
		LUC (08/94> + ABS)	<b>BD-7808</b>	
2.4 D 60/80kW	09/90-07/94	BDX	<b>BD-7807</b> LUC (>12/91)	<b>BD-7801</b>
		LUC	<b>BD-7806</b> ATE (01/92>)	<b>BD-7802</b>
2.4 TD 90kW	08/94-10/98	LUC (+ ABS)	<b>BD-7808</b> LUC	<b>BD-7801</b>
				<b>BD-7802</b> ATE
<b>960</b>				
2.4 TD 85kW	09/91-07/94	LUC	<b>BD-7806</b> LUC	<b>BD-7809</b>
		BDX	<b>BD-7807</b>	
		LUC (+ ABS)	<b>BD-7808</b>	
2.5 125kW	07/94-01/97	LUC	<b>BD-7806</b> LUC	<b>BD-7809</b>
		BDX	<b>BD-7807</b>	
		LUC (+ ABS)	<b>BD-7808</b>	
2.9 150kW	09/90-01/97	LUC	<b>BD-7806</b> LUC	<b>BD-7809</b>
		BDX	<b>BD-7807</b>	
		LUC (+ ABS)	<b>BD-7808</b>	
<b>C30</b>				
1.6 74kW	01/04-	ATE (15"/16")	<b>BD-3001</b> ATE	<b>BD-5901</b>
1.8 92kW	01/04-	ATE (15"/16")	<b>BD-3001</b> ATE	<b>BD-5901</b>
2.4 103/125kW	01/04-	ATE (15"/16")	<b>BD-3001</b> ATE	<b>BD-5901</b>
<b>C70</b>				
2.0 132kW	03/98-10/05	ATE	<b>BD-7810</b> ATE	<b>BD-7802</b>
		ATE (16")	<b>BD-7813</b>	
2.3 T5 180kW	03/98-10/05	ATE	<b>BD-7810</b> ATE	<b>BD-7802</b>
		ATE (16")	<b>BD-7813</b>	
<b>S40</b>				
1.6 77/80kW	01/96-12/03	LUC (>06/97)	<b>BD-5526</b> LUC	<b>BD-5523</b>
		LUC (07/97>)	<b>BD-5522</b>	
1.8 85/90kW	01/96-12/03	LUC (>06/97)	<b>BD-5526</b> LUC	<b>BD-5523</b>
		LUC (07/97>)	<b>BD-5522</b>	
1.9 T4 147kW	04/97-12/03	LUC (>06/97)	<b>BD-5526</b> LUC	<b>BD-5523</b>
		LUC (07/97>)	<b>BD-5522</b>	
1.9 TD 66kW	01/96-12/03	LUC (>06/97)	<b>BD-5526</b> LUC	<b>BD-5523</b>
		LUC (07/97>)	<b>BD-5522</b>	
2.0 100/103kW	07/95-12/03	LUC (>06/97)	<b>BD-5526</b> LUC	<b>BD-5523</b>
		LUC (07/97>)	<b>BD-5522</b>	
<b>S40 II</b>				
1.6 74kW	01/04-	ATE (15"/16")	<b>BD-3001</b> ATE	<b>BD-5901</b>
1.8 92kW	01/04-	ATE (15"/16")	<b>BD-3001</b> ATE	<b>BD-5901</b>
2.4 103/125kW	01/04-	ATE (15"/16")	<b>BD-3001</b> ATE	<b>BD-5901</b>
<b>V40</b>				
1.6 77/80kW	01/96-12/03	LUC (>06/97)	<b>BD-5526</b> LUC	<b>BD-5523</b>
		LUC (07/97>)	<b>BD-5522</b>	
1.8 85/90kW	01/96-12/03	LUC (>06/97)	<b>BD-5526</b> LUC	<b>BD-5523</b>
		LUC (07/97>)	<b>BD-5522</b>	
1.9 T4 147kW	04/97-12/03	LUC (>06/97)	<b>BD-5526</b> LUC	<b>BD-5523</b>
		LUC (07/97>)	<b>BD-5522</b>	
1.9 TD 66kW	01/96-12/03	LUC (>06/97)	<b>BD-5526</b> LUC	<b>BD-5523</b>
		LUC (07/97>)	<b>BD-5522</b>	
2.0 100/103kW	07/95-12/03	LUC (>06/97)	<b>BD-5526</b> LUC	<b>BD-5523</b>
		LUC (07/97>)	<b>BD-5522</b>	
<b>S60</b>				
2.0 T 132kW	09/01-09/10	ATE (15"/16")	<b>BD-7811</b> ATE	<b>BD-7812</b>
2.3 T5 184kW	11/00-09/10	ATE (15"/16")	<b>BD-7811</b> ATE	<b>BD-7812</b>
2.4 103kW	11/00-09/10	ATE (15"/16")	<b>BD-7811</b> ATE	<b>BD-7812</b>






• VOLVO











			
<b>S60</b>			
2.4 D 96kW	12/01-09/10	ATE (15"/16")	<b>BD-7811</b> ATE <b>BD-7812</b>
<b>S60 II</b>			
1.6 T3 110kW	09/10-	ATE (16")	<b>BD-3004</b> LUC (with Electronic parking brake) <b>BD-7817</b>
		ATE (17")	<b>BD-7816</b>
1.6 T4 132kW	09/10	ATE (16")	<b>BD-3004</b> LUC (with Electronic parking brake) <b>BD-7817</b>
		ATE (17")	<b>BD-7816</b>
2.0 T 149kW	09/10-	ATE (16")	<b>BD-3004</b> LUC (with Electronic parking brake) <b>BD-7817</b>
		ATE (17")	<b>BD-7816</b>
2.0 D3 120kW	09/10-	ATE (16")	<b>BD-3004</b> LUC (with Electronic parking brake) <b>BD-7817</b>
		ATE (17")	<b>BD-7816</b>
<b>S70</b>			
2.0 93-155kW	01/97-11/00	ATE	<b>BD-7810</b> ATE <b>BD-7802</b>
2.3 T5 176kW	01/97-11/00	ATE	<b>BD-7810</b> ATE <b>BD-7802</b>
2.3 Turbo 184kW	01/97-11/00	ATE (16")	<b>BD-7813</b> ATE <b>BD-7802</b>
2.4 103kW	08/99-11/00	ATE	<b>BD-7810</b> ATE <b>BD-7802</b>
2.5 D 103kW	01/97-11/00	ATE	<b>BD-7810</b> ATE <b>BD-7802</b>
<b>V70</b>			
2.0 105-166kW	01/97-03/00	ATE (15"/16")	<b>BD-7810</b> ATE <b>BD-7802</b>
		ATE (17")	<b>BD-7813</b>
2.0 T FWD 132kW	07/01-07/07	ATE (15"/16")	<b>BD-7811</b> ATE <b>BD-7812</b>
2.3 176/184kW	01/97-03/00	ATE (15"/16")	<b>BD-7810</b> ATE <b>BD-7802</b>
		ATE (17")	<b>BD-7813</b> LUC (AWD) <b>BD-7809</b>
2.3 T5 AWD/FWD 184kW	04/00-07/07	ATE (15"/16")	<b>BD-7811</b> ATE <b>BD-7812</b>
2.4 103/125kW	01/97-03/00	ATE (15"/16")	<b>BD-7810</b> ATE <b>BD-7802</b>
		ATE (17")	<b>BD-7813</b> LUC (AWD) <b>BD-7809</b>
2.4 103/147kW	04/00-07/07	ATE (15"/16")	<b>BD-7811</b> ATE <b>BD-7812</b>
<b>V70 XC</b>			
2.0 T AWD	11/98-03/00	ATE (16")	<b>BD-7810</b> ATE <b>BD-7802</b>
2.4 T AWD	11/98-03/00	ATE (16")	<b>BD-7810</b> LUC <b>BD-7809</b>
<b>V70 III</b>			
2.4 D	08/07-	ATE (16")	<b>BD-3004</b> LUC (without Electronic parking brake) <b>BD-3005</b>
		ATE (17")	<b>BD-7816</b> LUC (with Electronic parking brake) <b>BD-7817</b>
3.2 AWD/FWD	08/07-	ATE (16")	<b>BD-3004</b> LUC (without Electronic parking brake) <b>BD-3005</b>
		ATE (17")	<b>BD-7816</b> LUC (with Electronic parking brake) <b>BD-7817</b>
<b>XC70</b>			
2.4 T AWD 120/147kW	04/00-07/07	ATE	<b>BD-7811</b> ATE <b>BD-7812</b>
2.5 T AWD 154kW	09/02-07/07	ATE	<b>BD-7811</b> ATE <b>BD-7812</b>
<b>XC70 II</b>			
2.4 D	08/07-	ATE (16")	<b>BD-3004</b> LUC (without Electronic parking brake) <b>BD-3005</b>
		ATE (17")	<b>BD-7816</b> LUC (with Electronic parking brake) <b>BD-7817</b>
3.2 AWD	08/07-	ATE (16")	<b>BD-3004</b> LUC (without Electronic parking brake) <b>BD-3005</b>
		ATE (17")	<b>BD-7816</b> LUC (with Electronic parking brake) <b>BD-7817</b>
<b>S80</b>			
2.0 120/132kW	06/98-07/06	ATE	<b>BD-7811</b> ATE <b>BD-7812</b>
2.4 103/125kW	01/99-07/06	ATE	<b>BD-7811</b> ATE <b>BD-7812</b>
2.4 D 96/120kW	10/01-07/06	ATE	<b>BD-7811</b> ATE <b>BD-7812</b>
2.5 TD 103kW	01/99-07/06	ATE	<b>BD-7811</b> ATE <b>BD-7812</b>
2.8 T6 200kW	05/98-07/06	ATE	<b>BD-7811</b> ATE <b>BD-7812</b>
2.9 147/150kW	05/98-07/06	ATE	<b>BD-7811</b> ATE <b>BD-7812</b>
<b>S80 II</b>			
2.4 D 120kW	07/06-	ATE (16")	<b>BD-3004</b> LUC (without Electronic parking brake) <b>BD-3005</b>
		ATE (17")	<b>BD-7816</b> LUC (with Electronic parking brake) <b>BD-7817</b>
2.4 D5 136kW	07/06-	ATE (16")	<b>BD-3004</b> LUC (without Electronic parking brake) <b>BD-3005</b>
		ATE (17")	<b>BD-7816</b> LUC (with Electronic parking brake) <b>BD-7817</b>











			
2.5 T 147kW	07/06-	ATE (16")	<b>BD-3004</b> LUC (without Electronic parking brake) <b>BD-3005</b>
		ATE (17")	<b>BD-7816</b> LUC (with Electronic parking brake) <b>BD-7817</b>
<b>S90</b>			
3.0 132/150kW	01/97-05/98	LUC	<b>BD-7808</b>
<b>XC90</b>			
2.4 D 120kW	10/02-	ATE (16")	<b>BD-7811</b> ATE <b>BD-7815</b>
		ATE (17")	<b>BD-7814</b>
2.5 T 154kW	10/02-	ATE (16")	<b>BD-7811</b> ATE <b>BD-7815</b>
		ATE (17")	<b>BD-7814</b>
2.9 T6 200kW	10/02-	ATE (16")	<b>BD-7811</b> ATE <b>BD-7815</b>
		ATE (17")	<b>BD-7814</b>
<b>ZAZ</b>			
<b>Chance</b>			
1.3	06/07-		<b>BD-1801</b> <b>BS-1800</b>
1.5 63kW	06/07-		<b>BD-1801</b> <b>BS-1800</b>
<b>Tavria</b>			
1.1 37kW	01/89-06/96		<b>BD-4608</b>
1.3 44kW	01/89-06/96		<b>BD-4608</b>

<b>BD-1201</b>	119.0 x 70.0 x 19.5	<b>BD-1202</b>	146.0 x 54.6 x 19.0
			
<b>BD-1203</b>	156.4 x 71.4 x 20.3	155.2 x 66.0 x 20.3	
			
<b>BD-1204</b>	105.5 x 56.2 x 17.4	<b>BD-1205</b>	69.5 x 69.6 x 19.5
			
<b>BD-1206</b>	87.2 x 53.0 x 17.2	<b>BD-1208</b>	87.1 x 67.3 x 16.5
			
<b>BD-1207</b>	119.3 x 69.7 x 19.5		
			






<b>BD-1209</b>	156.5 x 74.2 x 19.6		
			
<b>BD-1212</b>	156.5 x 74.3 x 19.5		
			
<b>BD-1213</b>	156.4 x 74.3 x 20.4	<b>BD-1214</b>	119.2 x 69.5 x 19.6
			
<b>BD-1216</b>	156.5 x 74.3 x 19.6		
			
<b>BD-1215</b>	119.0 x 69.5 x 19.6		
			











<b>BD-1217</b>	156.4 x 72.8 x 19.8		
			
<b>BD-1218</b>	77.1 x 74.3	63.2 x 75.3	63.2 x 75.3
			
<b>BD-1219</b>	188.0 x 73.4 x 18.6		
			
<b>BD-1220</b>	155.1 x 72.0 x 19.5	155.1 x 67.0 x 19.5	
			
<b>BD-1222</b>	193.4 x 72.6 x 20.5		
			









<b>BD-1223</b>	116.4 x 68.8 x 17.5	<b>BD-1224</b>	116.2 x 59.0 x 17.5
			
<b>BD-1401</b>	156.8 x 73.1 x 17.8	<b>BD-1402</b>	156.8 x 52.2 x 17.4
			
<b>BD-1403</b>	123.3 x 59.5 x 17.1	<b>BD-1406</b>	150.9 x 57.1 x 16.2
			
<b>BD-1407</b>	123.2 x 43.5 x 16.6	<b>BD-1408</b>	150.1 x 57.6 x 17.7
			
<b>BD-1410</b>	156.9 x 63.4 x 19.5	<b>BD-1411</b>	156.0 x 61.9 x 20.2
			







<b>BD-1412</b>	122.1 x 45.0 x 15.9	<b>BD-1413</b>	122.2 x 45.0 x 16.3
			
<b>BD-1414</b>	154.7 x 63.5 x 19.8	155.4 x 63.5 x 19.8	
			
<b>BD-1415</b>	155.3 x 68.5 x 20.4		
			
<b>BD-1416</b>	120.0 x 74.1 x 17.8	<b>BD-1418</b>	193.1 x 79.2 x 20.0
			
<b>BD-1417</b>	171.1 x 76.8 x 20.0	170.2 x 76.8 x 20.0	
			























<b>BD-1419</b>	122.1 x 58.1 x 17.0	
		
<b>BD-1420</b>	123.1 x 43.5 x 17.1	123.1 x 48.1 x 17.1
		
<b>BD-1421</b>	154.8 x 63.6 x 20.0	
		
<b>BD-1422</b>	149.5 x 57.5 x 17.5	150.0 x 57.5 x 17.5
		
<b>BD-1423</b>	155.3 x 68.5 x 19.3	
		











<b>BD-1424</b>	154.8 x 63.6 x 20.0	155.4 x 63.6 x 20.0
		
<b>BD-1425</b>	139.7 x 68.0 x 16.8	
		
<b>BD-1426</b>	122.1 x 58.3 x 16.8	
		
<b>BD-1427</b>	156.4 x 63.6 x 20.0	
		
<b>BD-1428</b>	122.0 x 59.2 x 17.0	
		











<b>BD-1429</b>	131.4 x 53.5 x 17.6	
		
<b>BD-1430</b>	95.4 x 51.5 x 17.0	
		
<b>BD-1801</b>	127.2 x 47.5 x 16.0	<b>BD-1802</b> 113.9 x 55.0 x 15.5
		
<b>BD-1803</b>	133.1 x 49.2 x 17.5	<b>BD-1804</b> 121.0 x 37.0 x 13.8
		
<b>BD-1805</b>	143.2 x 50.7 x 18.0	<b>BD-1807</b> 104.6 x 39.2 x 14.7
		

<b>BD-1810</b>	148.0 x 60.4 x 19.0	
		
<b>BD-1811</b>	116.8 x 42.8 x 16.2	116.8 x 42.8 x 17.0
		
<b>BD-1812</b>	144.0 x 56.5 x 17.0	
		
<b>BD-1813</b>	148.0 x 61.2 x 19.0	
		
<b>BD-2201</b>	137.0 x 50.5 x 18.8	<b>BD-2202</b>
		










<b>BD-2203</b>	130.0 x 56.2 x 19.2	<b>BD-2204</b>	122.8 x 52.5 x 19.3
			
<b>BD-2206</b>	156.3 x 71.3 x 19.1	155.1 x 66.0 x 19.1	
			
<b>BD-2205</b>	128.7 x 56.1 x 19.2	<b>BD-2207</b>	148.8 x 49.7 x 17.7
			
<b>BD-2208</b>	148.7 x 59.2 x 18.0	<b>BD-2209</b>	169.0 x 61.4 x 18.0
			
<b>BD-2210</b>	73.1 x 70.6 x 15.2	<b>BD-2211</b>	95.2 x 47.1 x 17.5
			










<b>BD-2212</b>	147.1 x 59.5 x 19.3	<b>BD-2213</b>	140.1 x 68.8 x 18.4
			
<b>BD-2214</b>	129.0 x 59.0 x 19.2	<b>BD-2215</b>	140.8 x 67.0 x 19.3
			
<b>BD-2216</b>	165.0 x 69.2 x 19.2	<b>BD-2217</b>	109.9 x 50.3 x 20.1
			
<b>BD-2218</b>	123.2 x 43.2 x 17.0		
			
<b>BD-2219</b>	141.5 x 47.5 x 17.1		
			











<b>BD-2220</b>	130.9 x 52.5 x 17.9	<b>BD-2221</b>	130.0 x 56.5 x 19.1
			
<b>BD-2222</b>	105.0 x 55.0 x 11.0	<b>BD-2402</b>	127.6 x 45.4 x 15.5
			
<b>BD-2223</b>	155.2 x 64.7 x 18.8	155.2 x 57.7 x 18.3	
			
<b>BD-2224</b>	155.2 x 72.0 x 18.0	155.2 x 66.7 x 19.0	
			
<b>BD-2800</b>	150.9 x 57.5 x 19.3	<b>BD-2801</b>	151.6 x 52.4 x 17.5
			











<b>BD-2803</b>	156.5 x 59.0 x 18.9	
		
<b>BD-2807</b>	151.4 x 52.4 x 17.9	<b>BD-2812</b> 123.3 x 53.4 x 17.9
		
<b>BD-2815</b>	114.9 x 55.5 x 17.2	<b>BD-2824</b> 90.0 x 50.0 x 16.5
		
<b>BD-2828</b>	169.1 x 61.4 x 19.0	
		
<b>BD-2829</b>	169.1 x 69.1 x 19.0	
		























<b>BD-2830</b>	137.0 x 48.8 x 18.8	<b>BD-3001</b>	156.4 x 67.3 x 17.4
			
<b>BD-3002</b>	165.2 x 66.5 x 18.0	<b>BD-3003</b>	122.8 x 53.5 x 17.0
			
<b>BD-3004</b>	156.4 X 71.7 X 18.5	<b>BD-3005</b>	95.5 x 42.5 x 15.2
			
<b>BD-3006</b>	149.2 x 60.4 x 18.0	<b>BD-3007</b>	116.0 x 51.8 x 16.8
			
<b>BD-3008</b>	102.0 x 50.5 x 17.5		
			






<b>BD-3009</b>	178.2 x 58.5 x 19.1	
		
<b>BD-3010</b>	87.3 x 42.6 x 14.5	<b>BD-3011</b> 156.2 x 58.5 x 17.7
		
<b>BD-3012</b>	156.2 x 58.5 x 17.7	<b>BD-3013</b> 156.5 x 60.7 x 19.5
		
<b>BD-3014</b>	116.0 x 53.7 x 15.0	<b>BD-3016</b> 130.8 x 57.3 x 18.1
		
<b>BD-3018</b>	61.7 x 51.1 x 15.0	<b>BD-3019</b> 151.3 x 46.5 x 18.2
		











<b>BD-3020</b>	141.3 x 44.4 x 17.5	140.1 x 44.4 x 17.5
		
<b>BD-3021</b>	151.3 x 51.3 x 18.1	150.1 x 51.3 x 18.1
		
<b>BD-3022</b>	156.3 x 67.3 x 17.8	156.3 x 62.4 x 17.8
		
<b>BD-3023</b>	156.3 x 74.0 x 20.3	<b>BD-3024</b>
		
<b>BD-3025</b>	87.1 x 53.0 x 17.2	<b>BD-3026</b>
		

<b>BD-3027</b>	95.0 x 51.1 x 16.3	<b>BD-3028</b>	145.0 x 55.6 x 15.5
			
<b>BD-3029</b>	100.0 x 43.5 x 14.0	<b>BD-3030</b>	89.8 x 54.0 x 13.5
			
<b>BD-3032</b>	168.7 x 64.3 x 18.7		
			
<b>BD-3033</b>	168.7 x 65.2 x 18.7		
			
<b>BD-3034</b>	164.8 x 65.6 x 18.8	<b>BD-3401</b>	89.0 x 47.6 x 14.5
			











<b>BD-3402</b>	89.0 x 46.1 x 14.5	<b>BD-3403</b>	148.8 x 58.8 x 17.3
			
<b>BD-3404</b>	141.8 x 57.0 x 17.4	<b>BD-3405</b>	148.7 x 57.4 x 17.3
			
<b>BD-3406</b>	135.8 x 50.5 x 16.3	<b>BD-3407</b>	131.3 x 54.2 x 14.6
			
<b>BD-3408</b>	135.2 x 51.7 X 16.8	<b>BD-3409</b>	113.25 x 41.5 x 15.5
			
<b>BD-3412</b>	116.0 x 45.2 x 14.9	<b>BD-3413</b>	155.2 x 64.9 x 16.0
			











<b>BD-3418</b>	151.1 x 60.5 x 19.1	<b>BD-3421</b>	137.8 x 53.9 x 18.5
			
<b>BD-3422</b>	131.8 x 58.5 x 17.3	<b>BD-3424</b>	152.0 x 64.8 x 17.5
			
<b>BD-3425</b>	87.0 x 52.8 x 15.6	<b>BD-3426</b>	129.1 x 68.9 x 17.7
			
<b>BD-3423</b>	155.0 x 55.1 x 17.5	155.0 x 62.2 x 17.5	
			
<b>BD-3427</b>	131.7 x 55.0 x 17.5	<b>BD-3428</b>	88.8 x 35.3 x 13.2
			











<b>BD-3430</b>	108.8 x 42.1 x 16.5	
		
<b>BD-3431</b>	93.5 x 46.8 x 15.3	<b>BD-3432</b> 95.7 x 46.5 x 15.5
		
<b>BD-3601</b>	127.6 x 49.0 x 41.6	<b>BD-3602</b> 131.4 x 59.8 x 16.9
		
<b>BD-3604</b>	129.8 x 72.5 x 18.3	<b>BD-3605</b> 98.6 x 38.3 x 15.0
		
<b>BD-3606</b>	110.8 x 45.0 x 15.0	<b>BD-3607</b> 136.9 x 53.4 x 17.5
		











<b>BD-3608</b>	129.8 x 56.0 x 17.0	<b>BD-3610</b>	131.5 x 70.7 x 17.1
			
<b>BD-3611</b>	137.1 x 63.5 x 18.3		
			
<b>BD-3612</b>	85.4 x 46.6 x 14.1	<b>BD-3613</b>	147.1 x 53.7 x 16.2
			
<b>BD-3614</b>	137.8 x 40.5 x 15.5	<b>BD-3615</b>	156.8 x 61.2 x 17.3
			
<b>BD-3616</b>	118.5 x 47.3 x 15.7	<b>BD-3617</b>	149.0 x 58.2 x 15.7
			























<b>BD-3618</b>	137.8 x 40.5 x 15.5	<b>BD-3619</b>	132.8 x 58.2 x 17.0
			
<b>BD-3620</b>	99.8 x 41.2 x 15.5	<b>BD-3624</b>	130.0 x 56.5 x 17.0
			
<b>BD-3621</b>	137.8 x 61.0 x 16.6		
			
<b>BD-3623</b>	117.1 x 48.5 x 15.6		
			
<b>BD-3802</b>	138.0 x 56.8 x 16.3	<b>BD-3803</b>	109.6 x 42.5 x 15.8
			










<b>BD-3804</b>	167.1 x 54.2 x 16.8	<b>BD-4201</b>	157.8 x 60.5 x 19.5
			
<b>BD-4200</b>	177.2 x 55.0 x 17.2		
			
<b>BD-4202</b>	189.1 x 55.7 x 18.5		
			
<b>BD-4203</b>	176.1 x 57.2 x 18.6		
			
<b>BD-4401</b>	98.9 x 40.8 x 13.0	<b>BD-4403</b>	129.2 x 51.3 x 16.7
			











<b>BD-4404</b>	130.1 x 58.1 x 17.5	<b>BD-4406</b>	154.2 x 56.2 x 17.0
			
<b>BD-4407</b>	93.3 x 41.0 x 16.1	<b>BD-4408</b>	151.2 x 53.1 x 18.2
			
<b>BD-4409</b>	116.2 x 47.5 x 16.7	<b>BD-4411</b>	155.1 x 60.2 x 17.2
			
<b>BD-4413</b>	118.3 x 47.2 x 15.6	<b>BD-4414</b>	149.0 x 53.1 x 15.8
			
<b>BD-4415</b>	150.8 x 47.8 x 17.5	<b>BD-4416</b>	128.1 x 49.0 x 16.0
			

<b>BD-4601</b>	104.2 x 62.6 x 16.9	<b>BD-4602</b>	125.5 x 39.8 x 15.7
			
<b>BD-4603</b>	83.5 x 60.0 x 15.8	<b>BD-4605</b>	104.2 x 62.6 x 17.2
			
<b>BD-5000</b>	104.7 x 72.3 x 18.1	<b>BD-5002</b>	144.8 x 66.5 x 19.2
			
<b>BD-5003</b>	162.8 x 58.7 x 18.2	<b>BD-5004</b>	131.8 x 77.5 x 17.3
			
<b>BD-5005</b>	131.5 x 62.1 x 18.1	<b>BD-5008</b>	95.0 x 52.1 x 16.3
			











<b>BD-5009</b>	116.7 x 46.5 x 17.4	<b>BD-5101</b>	131.5 x 51.3 x 14.8
			
<b>BD-5102</b>	110.0 x 55.0 x 14.3	<b>BD-5103</b>	108.7 x 51.5 x 15.1
			
<b>BD-5104</b>	107.8 x 39.3 x 12.9	<b>BD-5105</b>	91.7 x 64.0 x 14.8
			
<b>BD-5108</b>	151.4 x 61.4 x 18.3		
			
<b>BD-5110</b>	108.5 x 48.0 x 16.3	<b>BD-5111</b>	132.0 x 56.1 x 16.0
			









<b>BD-5112</b>	132.0 x 59.5 x 17.8	<b>BD-5113</b>	139.2 x 59.1 x 16.0
			
<b>BD-5114</b>	142.1 x 59.3 x 16.6	<b>BD-5115</b>	156.4 x 66.5 x 19.8
			
<b>BD-5116</b>	139.0 x 58.0 x 17.5	<b>BD-5118</b>	136.8 x 59.0 x 17.5
			
<b>BD-5119</b>	131.9 x 56.2 x 16.8	<b>BD-5120</b>	91.7 x 71.2 x 15.2
			
<b>BD-5121</b>	117.0 x 42.5 x 15.5	<b>BD-5124</b>	110.6 x 46.2 x 17.0
			











<b>BD-5123</b>	125.6 x 51.7 x 15.3			
				
<b>BD-5301</b>	108.2 x 58.8 x 16.0	<b>BD-5302</b>	151.6 x 66.4 x 18.6	
				
<b>BD-5303</b>	108.0 x 74.7 x 19.3		<b>BD-5304</b>	95.0 x 50.6 x 17.5
				
<b>BD-5305</b>	99.9 x 73.4 x 17.7		<b>BD-5306</b>	117.2 x 57.3 x 17.0
				
<b>BD-5307</b>	116.6 x 64.2 x 18.7		<b>BD-5308</b>	116.6 x 64.2 x 19.6
				











<b>BD-5310</b>	95.5 x 41.5 x 14.5	<b>BD-5311</b>	61.7 x 54.4 x 15.0
			
<b>BD-5312</b>	61.7 x 54.3 x 15.5	<b>BD-5313</b>	63.7 x 63.7 x 15.5
			
<b>BD-5314</b>	61.7 x 58.5 x 15.2	<b>BD-5315</b>	63.5 x 72.9 x 15.4
			
<b>BD-5316</b>	61.8 x 69.8 x 15.3	<b>BD-5317</b>	131.2 x 69.9 x 19.4
			
<b>BD-5318</b>	146.4 x 71.5 x 20.5	<b>BD-5320</b>	156.5 x 63.7 x 20.2
			























<b>BD-5321</b>	63.8 x 78.3 x 15.4			
				
<b>BD-5322</b>	61.7 x 54.3 x 13.5	<b>BD-5323</b>	137.2 x 68.5 x 20.4	
				
<b>BD-5324</b>	120.1 x 74.5 x 17.8		<b>BD-5327</b>	120.1 x 71.5 x 17.8
				
<b>BD-5325</b>	141.2 x 59.3 x 15.7			
				
<b>BD-5326</b>	188.3 x 77.0 x 16.3			
				











<b>BD-5328</b>	140.2 x 50.4 x 16.6		
			
<b>BD-5329</b>	76.9 x 65.6 x 16.2	<b>BD-5333</b>	99.7 x 84.5 x 18.2
			
<b>BD-5330</b>	194.5 x 70.2 x 20.5		
			
<b>BD-5332</b>	140.2 x 52.0 x 17.7	141.5 x 59.7 x 17.7	
			
<b>BD-5334</b>	71.0 x 68.9 x 16.0	<b>BD-5335</b>	148.8 x 69.1 x 18.0
			











<b>BD-5337</b>	156.2 x 65.0 x 19.2	<b>BD-5338</b>	140.9 x 49.2 x 17.2
			
<b>BD-5339</b>	134.4 x 64.5 x 20.6	<b>BD-5340</b>	125.8 x 62.2 x 18.8
			
<b>BD-5341</b>	163.2 x 67.2 x 20.6	<b>BD-5342</b>	137.0 x 63.2 x 20.0
			
<b>BD-5343</b>	169.0 x 73.5 x 20.7	<b>BD-5344</b>	165.2 x 78.2 x 20.3
			
<b>BD-5345</b>	117.0 x 56.3 x 19.5	<b>BD-5346</b>	63.9 x 57.7 x 16.8
			

<b>BD-5347</b>	104.2 x 53.0 x 17.8	<b>BD-5348</b>	164.0 x 61.1 x 20.9
			
<b>BD-5349</b>	141.6 x 75.6 x 18.0	<b>BD-5501</b>	149.6 x 58.1 x 15.8
			
<b>BD-5350</b>	188.0 x 73.1 x 19.0	188.0 x 80.6 x 19.0	
			
<b>BD-5502</b>	107.8 x 43.5 x 14.3	<b>BD-5503</b>	114.0 x 50.4 x 15.5
			
<b>BD-5504</b>	144.9 x 51.8 x 15.7	<b>BD-5505</b>	105.9 x 35.5 x 15.2
			











<b>BD-5506</b>	139.0 x 58.8 x 15.5	<b>BD-5507</b>	91.0 x 42.1 x 15.3
			
<b>BD-5508</b>	123.0 x 48.0 x 15.4	<b>BD-5509</b>	127.8 x 52.0 x 15.5
			
<b>BD-5511</b>	78.1 x 59.2 x 14.8	<b>BD-5512</b>	107.6 x 36.3 x 15.2
			
<b>BD-5516</b>	98.8 x 37.5 x 14.3	<b>BD-5520</b>	137.8 x 55.0 x 15.5
			
<b>BD-5522</b>	130.2 x 78.3 x 17.4	<b>BD-5523</b>	86.8 x 47.0 x 15.3
			









<b>BD-5524</b>	114.2 x 50.0 x 15.0	<b>BD-5526</b>	130.2 x 72.7 x 15.0
			
<b>BD-5529</b>	155.3 x 51.1 x 15.3	<b>BD-5701</b>	137.0 x 53.0 x 16.8
			
<b>BD-5702</b>	105.5 x 47.1 x 16.3	<b>BD-5703</b>	103.0 x 53.3 x 17.5
			
<b>BD-5704</b>	158.8 x 56.4 x 16.5	<b>BD-5705</b>	139.0 x 59.5 x 14.8
			
<b>BD-5706</b>	105.4 x 34.4 x 14.0	<b>BD-5708</b>	137.0 x 54.0 x 16.7
			











<b>BD-5710</b>	121.1 x 45.6 x 15.8	<b>BD-5711</b>	141.5 x 58.9 x 17.0
			
<b>BD-5713</b>	108.6 x 48.5 x 16.4	<b>BD-5715</b>	166.2 x 61.6 x 18.8
			
<b>BD-5718</b>	99.5 x 40.0 x 15.0	<b>BD-5725</b>	157.0 x 58.6 x 16.4
			
<b>BD-5735</b>	129.3 x 57.3 x 17.5	<b>BD-5736</b>	82.2 x 57.1 x 15.7
			
<b>BD-5737</b>	135.5 x 70.0 x 15.5	<b>BD-5738</b>	120.8 x 45.0 x 15.0
			











<b>BD-5739</b>	116.2 x 52.5 x 17.0	<b>BD-5740</b>	127.8 x 50.3 x 16.0
			
<b>BD-5741</b>	110.7 x 41.0 x 15.7	<b>BD-5742</b>	127.0 x 75.7 x 16.0
			
<b>BD-5743</b>	99.8 x 59.8 x 13.8	<b>BD-5901</b>	123.2 x 58.5 x 15.7
			
<b>BD-5902</b>	61.6 x 61.1 x 15.3	<b>BD-5903</b>	141.2 x 36.4 x 16.7
			
<b>BD-5904</b>	156.3 x 77.6 x 19.2	<b>BD-5905</b>	99.9 x 58.6 x 14.9
			























<b>BD-5906</b>	130.0 x 43.2 x 15.3	<b>BD-5909</b>	61.7 x 57.5 x 15.5
			
<b>BD-5907</b>	178.2 x 62.5 x 18.5	160.0 x 63.0 x 18.5	
			
<b>BD-5908</b>	155.1 x 70.0 x 20.5	156.3 x 76.0 x 19.6	
			
<b>BD-5910</b>	105.0 x 43.0 x 16.3	<b>BD-5911</b>	96.0 x 42.6 x 15.1
			
<b>BD-5912</b>	156.4 x 74.2 x 19.3	<b>BD-5914</b>	154.2 x 74.0 x 19.4
			











<b>BD-5913</b>	156.5 x 60.8 x 18.3			
				
<b>BD-5915</b>	132.2 x 51.2 x 17.1			
				
<b>BD-5916</b>	123.0 x 53.5 x 18.0	<b>BD-5917</b>	101.9 x 47.0 x 17.5	
				
<b>BD-5918</b>	127.2 x 51.0 x 16.6		<b>BD-5919</b>	137.9 x 58.7 x 17.5
				
<b>BD-5920</b>	138.8 x 66.5 x 18.0		<b>BD-5921</b>	138.6 x 79.8 x 17.8
				











<b>BD-5922</b>	130.0 x 64.0 x 18.4	<b>BD-6101</b>	131.0 x 67.4 x 19.3
			
<b>BD-5923</b>	156.3 x 70.0 x 19.5		
			
<b>BD-6102</b>	151.0 x 61.5 x 16.9	<b>BD-6103</b>	122.8 x 47.5 x 17.5
			
<b>BD-6105</b>	105.0 x 55.2 x 17.8	<b>BD-6106</b>	131.0 x 47.5 x 18.2
			
<b>BD-6107</b>	141.4 x 47.8 x 17.4	<b>BD-6108</b>	64.1 x 57.2 x 16.0
			

<b>BD-6109</b>	64.1 x 57.2 x 16.0	<b>BD-6110</b>	64.1 x 57.2 x 16.0
			
<b>BD-6111</b>	86.3 x 57.0 x 18.0	<b>BD-6301</b>	100.1 x 64.0 x 19.0
			
<b>BD-6302</b>	123.2 x 51.9 x 15.7	<b>BD-6303</b>	145.0 x 62.6 x 18.1
			
<b>BD-6304</b>	129.0 x 55.6 x 18.0	<b>BD-6306</b>	87.0 x 53.2 x 16.2
			
<b>BD-6307</b>	130.0 x 63.2 x 18.3	<b>BD-6309</b>	131.2 x 47.5 x 18.0
			











<b>BD-6310</b>	130.0 x 55.3 x 18.1	<b>BD-6314</b>	136.9 x 59.5 x 18.3
			
<b>BD-6311</b>	156.3 x 66.4 x 18.2		
			
<b>BD-6312</b>	156.0 x 68.0 x 18.2	156.0 x 70.7 x 18.2	
			
<b>BD-6315</b>	155.2 x 66.5 x 18.0	155.2 x 66.5 x 18.0	
			
<b>BD-6316</b>	155.1 x 68.5 x 17.8	156.5 x 71.1 x 17.8	
			











<b>BD-6317</b>	155.2 x 64.7 x 18.0	155.2 x 59.4 x 18.0
		
<b>BD-6500</b>	157.0 x 67.5 x 18.7	
		
<b>BD-6501</b>	123.1 x 43.6 x 17.2	<b>BD-6700</b> 156.6 x 54.8 x 19.4
		
<b>BD-6701</b>	125.1 x 37.9 x 14.5	<b>BD-6702</b> 156.5 x 77.4 x 20.2
		
<b>BD-6900</b>	114.8 x 61.0 x 17.5	<b>BD-7000</b> 98.5 x 43.2 x 15.8
		











<b>BD-7101</b>	137.2 x 53.8 x 16.8	<b>BD-7102</b>	137.2 x 53.9 x 16.4
			
<b>BD-7103</b>	110.4 x 37.6 x 13.0	<b>BD-7104</b>	137.8 x 59.6 x 16.8
			
<b>BD-7105</b>	137.8 x 53.8 x 16.8	<b>BD-7106</b>	108.5 x 41.5 x 14.0
			
<b>BD-7107</b>	119.1 x 69.6 x 14.5	<b>BD-7108</b>	73.3 x 54.5 x 15.8
			
<b>BD-7109</b>	107.8 x 38.7 x 15.2	<b>BD-7111</b>	157.0 x 63.5 x 16.8
			











<b>BD-7112</b>	128.1 x 53.2 x 16.9	<b>BD-7302</b>	138.2 x 55.0 x 16.4
			
<b>BD-7304</b>	110.5 x 41.8 x 15.2	<b>BD-7311</b>	136.2 x 53.2 x 16.2
			
<b>BD-7313</b>	131.5 x 56.8 x 16.0	<b>BD-7501</b>	119.2 x 74.2 x 15.0
			
<b>BD-7503</b>	119.4 x 77.8 x 17.3	<b>BD-7504</b>	119.1 x 71.7 x 14.8
			
<b>BD-7505</b>	116.2 x 44.2 x 15.3	<b>BD-7506</b>	138.8 x 59.4 x 18.5
			























<b>BD-7507</b>	117.2 x 58.6 x 17.4	<b>BD-7508</b>	145.3 x 56.6 x 15.5
			
<b>BD-7510</b>	78.8 x 54.2 x 13.3	<b>BD-7511</b>	123.0 x 60.5 x 17.3
			
<b>BD-7516</b>	133.2 x 49.5 x 17.5	<b>BD-7517</b>	76.7 x 38.5 x 14.8
			
<b>BD-7518</b>	64.0 x 57.2 x 15.5	<b>BD-7519</b>	111.8 x 46.5 x 16.5
			
<b>BD-7520</b>	141.0 x 62.4 x 16.9	<b>BD-7521</b>	107.6 x 40.5 x 14.9
			











<b>BD-7522</b>	131.5 x 54.4 x 17.3	<b>BD-7523</b>	92.8 x 37.8 x 14.8
			
<b>BD-7524</b>	144.0 x 64.0 x 17.0	<b>BD-7525</b>	141.1 x 59.3 x 16.5
			
<b>BD-7526</b>	116.5 x 51.2 x 11.6	<b>BD-7527</b>	123.2 x 45.1 x 17.4
			
<b>BD-7529</b>	116.8 x 59.5 x 16.9	<b>BD-7530</b>	157.6 x 55.8 x 17.3
			
<b>BD-7531</b>	122.7 x 59.3 x 16.8	<b>BD-7532</b>	96.8 x 49.2 x 15.5
			











<b>BD-7533</b>	119.7 x 45.7 x 15.0	<b>BD-7534</b>	101.8 x 34.6 x 15.4
			
<b>BD-7538</b>	78.5 x 51.9 x 13.8	<b>BD-7539</b>	101.9 x 45.9 x 15.5
			
<b>BD-7540</b>	132.1 x 57.2 x 16.7	<b>BD-7541</b>	96.2 x 37.6 x 14.3
			
<b>BD-7542</b>	139.0 x 55.4 x 17.6	<b>BD-7543</b>	98.5 x 42.3 x 14.3
			
<b>BD-7544</b>	88.0 x 58.3 x 15.4	<b>BD-7545</b>	156.4 x 68.6 x 16.8
			

<b>BD-7546</b>	137.0 x 54.9 x 18.2	<b>BD-7547</b>	102.5 x 45.8 x 14.9
			
<b>BD-7548</b>	150.8 x 63.0 x 17.4	<b>BD-7549</b>	134.5 x 77.0 x 17.0
			
<b>BD-7550</b>	122.7 x 49.6 x 15.5	<b>BD-7558</b>	141.0 x 56.5 x 15.8
			
<b>BD-7566</b>	118.5 x 77.6 x 17.4	<b>BD-7572</b>	146.5 x 57.0 x 17.5
			
<b>BD-7574</b>	112.5 x 42.9 x 16.3	<b>BD-7580</b>	143.7 x 83.2 x 17.7
			










<b>BD-7581</b>	116.2 x 44.7 x 17.3	<b>BD-7589</b>	154.5 x 59.5 x 17.8
			
<b>BD-7590</b>	157.0 x 55.1 x 17.9	<b>BD-7592</b>	132.0 x 54.1 x 18.1
			
<b>BD-7593</b>	131.1 x 52.2 x 16.5		
			
<b>BD-7594</b>	150.2 x 58.5 x 17.3	151.5 x 61.0 x 17.3	
			
<b>BD-7596</b>	167.0 x 59.4 x 17.5	<b>BD-7597</b>	115.2 x 45.7 x 15.0
			







<b>BD-7598</b>	151.0 x 62.5 x 19.0	151.0 x 65.5 x 19.0	
			
<b>BD-7599</b>	109.0 x 49.9 x 16.5	<b>BD-7803</b>	110.2 x 69.0 x 17.3
			
<b>BD-7804</b>	152.1 x 50.4 x 16.8	<b>BD-7805</b>	126.2 x 39.1 x 15.0
			
<b>BD-7806</b>	125.1 x 64.9 x 16.4	<b>BD-7807</b>	113.9 x 51.4 x 17.0
			
<b>BD-7808</b>	128.0 x 66.9 x 17.3	<b>BD-7809</b>	90.0 x 54.2 x 13.1
			










<b>BD-7810</b>	155.9 x 58.1 x 19.0	<b>BD-7813</b>	157.0 x 73.9 x 18.8
			
<b>BD-7811</b>	157.0 x 69.2 x 18.6		
			
<b>BD-7812</b>	124.0 x 53.8 x 16.2		
			
<b>BD-7814</b>	155.3 x 75.3 x 20.6	156.6 x 74.3 x 19.1	
			
<b>BD-7815</b>	123.0 x 63.4 x 18.6	123.0 x 61.8 x 18.6	
			





<b>BD-7816</b>	156.5x74.4x18.5	155.3x75.2x19.8	
			
<b>BD-7817</b>	106.2 x 48.6 x 16.8	<b>BD-8001</b>	155.3 x 73.1 x 19.6
			
<b>BD-8002</b>	87.2 x 52.2 x 15.0	<b>BD-8003</b>	146.1 x 54.6 x 19.0
			
<b>BD-8004</b>	138.2 x 51.6 x 19.5	<b>BD-8005</b>	190.0 x 99.2 x 16.3
			
<b>BD-8006</b>	156.4 x 74.9 x 20	155.2 x 73.5 x 20	
			














<b>BD-8007</b>	117.2 x 73.1 x 16.2	<b>BD-8009</b>	119.0 x 69.4 x 16.1
			
<b>BD-8008</b>	142.2 x 51.0 x 17.2		
			
<b>BD-8011</b>	142.0 x 51.2 x 15.0		
			
<b>BD-8012</b>	138.0 x 51.1 x 17.1	<b>BD-8014</b>	119.5 x 69.5 x 16.0
			
<b>BD-8015</b>	131.4 x 62.6 x 18.8		
			

<b>BD-8016</b>	156.4 x 72.8 x 20.0		
			
<b>BD-8017</b>	141.7 x 50.7 x 16.8		
			
<b>BD-8018</b>	161.1 x 74.3 x 20.0		
			
<b>BD-8023</b>	91.0 x 81.1 x 18.0		
			
<b>BD-8019</b>	190.1 x 106.3 x 16.1	<b>BD-8024</b>	156.1 x 68.4 x 19.5
			

<p><b>BD-8028</b></p>	<p>131.7 x 77.3 x 16.8</p>	<p><b>BD-8029</b></p>	<p>187.4 x 76.0 x 17.0</p>
			
<p><b>BD-8027</b></p>	<p>156.1 x 68.5 x 19.5</p>		
			
<p><b>BD-8030</b></p>	<p>105.5 x 56.4 x 17.0</p>	<p><b>BD-8031</b></p>	<p>209.5 x 94.4 x 16.0</p>
			
<p><b>BD-8032</b></p>	<p>156.4 x 74.9 x 17.9</p>	<p>155.2 x 73.6 x 17.9</p>	
			
<p><b>BD-8033</b></p>	<p>116.2 x 59.0 x 17.5</p>		
			



<b>BD-8034</b>	141.5 x 54.0 x 18.9	
		
<b>BD-8038</b>	155.2 x 72.0 x 19.8	155.2 x 66.8 x 20.3
		

<b>BS-1800</b>	200.0 x 46.0
	
<b>BS-1801</b>	180.0 x 31.0
	
<b>BS-2800</b>	254.0 x 57.0
	
<b>BS-3000</b>	203.2 x 38.0
	
<b>BS-3001</b>	203.0 x 38.0
	

<b>BS-3600</b>	203.0 x 32.0		
			
<b>BS-3601</b>	180.0 x 36.0		
			
<b>BS-4601</b>	200.0 x 40.0	<b>BS-4602</b>	250.0 x 51.0
			
<b>BS-6300</b>	203.0 x 38.0		
			
<b>BS-6301</b>	180.0 x 37.0		
			



**BS-7501**

203.0 x 32.0



**BS-8001**

230.0 x 32.0









• **Cross Reference Lucas/TRW-LYNXauto**

<b>LUCAS/TRW</b>	<b>LYNXauto</b>	<b>LUCAS/TRW</b>	<b>LYNXauto</b>	<b>LUCAS/TRW</b>	<b>LYNXauto</b>	<b>LUCAS/TRW</b>	<b>LYNXauto</b>
GDB113	<b>BD-5333</b>	GDB957	<b>BD-5922</b>	GDB1168	<b>BD-7521</b>	GDB1350	<b>BD-5904</b>
GDB140	<b>BD-4603</b>	GDB962	<b>BD-5305</b>	GDB1177	<b>BD-5113</b>	GDB1351	<b>BD-5907</b>
GDB199	<b>BD-5905</b>	GDB969	<b>BD-6700</b>	GDB1182	<b>BD-7505</b>	GDB1352	<b>BD-5910</b>
GDB265	<b>BD-4602</b>	GDB976	<b>BD-5006</b>	GDB1186	<b>BD-3802</b>	GDB1353	<b>BD-6313</b>
GDB294	<b>BD-5322</b>	GDB987	<b>BD-5314</b>	GDB1187	<b>BD-3803</b>	GDB1354	<b>BD-3010</b>
GDB297	<b>BD-2817</b>	GDB989	<b>BD-7112</b>	GDB1189	<b>BD-1407</b>	GDB1357	<b>BD-8003</b>
GDB299	<b>BD-1405</b>	GDB990	<b>BD-7109</b>	GDB1193	<b>BD-6108</b>	GDB1357	<b>BD-8003</b>
GDB317	<b>BD-5335</b>	GDB995	<b>BD-3405</b>	GDB1194	<b>BD-2221</b>	GDB1358	<b>BD-3009</b>
GDB323	<b>BD-7533</b>	GDB1003	<b>BD-5701</b>	GDB1197	<b>BD-5521</b>	GDB1361	<b>BD-6106</b>
GDB325	<b>BD-3412</b>	GDB1005	<b>BD-5740</b>	GDB1198	<b>BD-5526</b>	GDB1362	<b>BD-2822</b>
GDB327	<b>BD-6105</b>	GDB1008	<b>BD-5708</b>	GDB1200	<b>BD-1213</b>	GDB1363	<b>BD-2823</b>
GDB329	<b>BD-7807</b>	GDB1010	<b>BD-3612</b>	GDB1204	<b>BD-3023</b>	GDB1366	<b>BD-1215</b>
GDB371	<b>BD-3017</b>	GDB1012	<b>BD-5110</b>	GDB1205	<b>BD-5302</b>	GDB1371	<b>BD-1218</b>
GDB375	<b>BD-2404</b>	GDB1023	<b>BD-5508</b>	GDB1212	<b>BD-2803</b>	GDB1373	<b>BD-5339</b>
GDB383	<b>BD-7304</b>	GDB1024	<b>BD-5105</b>	GDB1213	<b>BD-3013</b>	GDB1374	<b>BD-6500</b>
GDB392	<b>BD-6701</b>	GDB1029	<b>BD-5120</b>	GDB1215	<b>BD-5320</b>	GDB1378	<b>BD-5326</b>
GDB400	<b>BD-6301</b>	GDB1030	<b>BD-6310</b>	GDB1216	<b>BD-2213</b>	GDB1380	<b>BD-5920</b>
GDB404	<b>BD-1207</b>	GDB1040	<b>BD-5903</b>	GDB1218	<b>BD-8013</b>	GDB1383	<b>BD-2807</b>
GDB434	<b>BD-5304</b>	GDB1041	<b>BD-6308</b>	GDB1219	<b>BD-8010</b>	GDB1385	<b>BD-2220</b>
GDB442	<b>BD-7809</b>	GDB1044	<b>BD-1205</b>	GDB1220	<b>BD-5337</b>	GDB1386	<b>BD-1202</b>
GDB454	<b>BD-8004</b>	GDB1048	<b>BD-8014</b>	GDB1221	<b>BD-3020</b>	GDB1387	<b>BD-2813</b>
GDB458	<b>BD-2805</b>	GDB1049	<b>BD-1209</b>	GDB1222	<b>BD-3019</b>	GDB1388	<b>BD-7811</b>
GDB463	<b>BD-8012</b>	GDB1052	<b>BD-2806</b>	GDB1246	<b>BD-7804</b>	GDB1389	<b>BD-7812</b>
GDB466	<b>BD-2818</b>	GDB1059	<b>BD-5738</b>	GDB1258	<b>BD-2218</b>	GDB1391	<b>BD-8027</b>
GDB469	<b>BD-4605</b>	GDB1061	<b>BD-3421</b>	GDB1260	<b>BD-2203</b>	GDB1393	<b>BD-2814</b>
GDB472	<b>BD-3030</b>	GDB1068	<b>BD-7805</b>	GDB1261	<b>BD-1401</b>	GDB1396	<b>BD-2827</b>
GDB482	<b>BD-7806</b>	GDB1091	<b>BD-1210</b>	GDB1262	<b>BD-5338</b>	GDB1399	<b>BD-5340</b>
GDB496	<b>BD-3426</b>	GDB1092	<b>BD-8022</b>	GDB1264	<b>BD-1410</b>	GDB1403	<b>BD-1212</b>
GDB499	<b>BD-3428</b>	GDB1093	<b>BD-5000</b>	GDB1265	<b>BD-1413</b>	GDB1404	<b>BD-1424</b>
GDB533	<b>BD-7801</b>	GDB1094	<b>BD-5303</b>	GDB1266	<b>BD-1214</b>	GDB1405	<b>BD-6304</b>
GDB576	<b>BD-7800</b>	GDB1100	<b>BD-1406</b>	GDB1269	<b>BD-1416</b>	GDB1408	<b>BD-5347</b>
GDB737	<b>BD-4405</b>	GDB1104	<b>BD-6107</b>	GDB1270	<b>BD-6307</b>	GDB1411	<b>BD-5915</b>
GDB770	<b>BD-7508</b>	GDB1105	<b>BD-2808</b>	GDB1271	<b>BD-5914</b>	GDB1413	<b>BD-5317</b>
GDB773	<b>BD-4410</b>	GDB1106	<b>BD-2810</b>	GDB1274	<b>BD-8008</b>	GDB1414	<b>BD-8015</b>
GDB774	<b>BD-3402</b>	GDB1107	<b>BD-3011</b>	GDB1276	<b>BD-6109</b>	GDB1415	<b>BD-3025</b>
GDB791	<b>BD-8023</b>	GDB1108	<b>BD-3012</b>	GDB1280	<b>BD-6900</b>	GDB1418	<b>BD-3021</b>
GDB796	<b>BD-6112</b>	GDB1112	<b>BD-3014</b>	GDB1282	<b>BD-8024</b>	GDB1419	<b>BD-5108</b>
GDB797	<b>BD-7501</b>	GDB1113	<b>BD-3028</b>	GDB1283	<b>BD-5313</b>	GDB1420	<b>BD-5906</b>
GDB798	<b>BD-7591</b>	GDB1115	<b>BD-2815</b>	GDB1286	<b>BD-5520</b>	GDB1424	<b>BD-3033</b>
GDB808	<b>BD-6104</b>	GDB1117	<b>BD-2804</b>	GDB1289	<b>BD-5346</b>	GDB1425	<b>BD-2809</b>
GDB812	<b>BD-7803</b>	GDB1123	<b>BD-5316</b>	GDB1290	<b>BD-2802</b>	GDB1429	<b>BD-7813</b>
GDB814	<b>BD-2820</b>	GDB1124	<b>BD-3018</b>	GDB1291	<b>BD-2801</b>	GDB1434	<b>BD-3006</b>
GDB818	<b>BD-5301</b>	GDB1126	<b>BD-5501</b>	GDB1293	<b>BD-5306</b>	GDB1436	<b>BD-5919</b>
GDB820	<b>BD-1404</b>	GDB1127	<b>BD-5502</b>	GDB1299	<b>BD-2816</b>	GDB1437	<b>BD-8009</b>
GDB823	<b>BD-8002</b>	GDB1128	<b>BD-5509</b>	GDB1305	<b>BD-2222</b>	GDB1440	<b>BD-3024</b>
GDB826	<b>BD-1201</b>	GDB1129	<b>BD-5524</b>	GDB1306	<b>BD-8011</b>	GDB1442	<b>BD-5921</b>
GDB837	<b>BD-7808</b>	GDB1130	<b>BD-5311</b>	GDB1307	<b>BD-1216</b>	GDB1444	<b>BD-2825</b>
GDB848	<b>BD-5735</b>	GDB1139	<b>BD-5101</b>	GDB1308	<b>BD-5924</b>	GDB1446	<b>BD-4601</b>
GDB862	<b>BD-8021</b>	GDB1140	<b>BD-3029</b>	GDB1313	<b>BD-5522</b>	GDB1447	<b>BD-2207</b>
GDB870	<b>BD-5918</b>	GDB1143	<b>BD-7516</b>	GDB1314	<b>BD-5523</b>	GDB1448	<b>BD-2208</b>
GDB893	<b>BD-3601</b>	GDB1147	<b>BD-2824</b>	GDB1321	<b>BD-6309</b>	GDB1449	<b>BD-2209</b>
GDB896	<b>BD-3618</b>	GDB1148	<b>BD-2214</b>	GDB1322	<b>BD-2219</b>	GDB1450	<b>BD-2210</b>
GDB897	<b>BD-3015</b>	GDB1153	<b>BD-4200</b>	GDB1326	<b>BD-3027</b>	GDB1452	<b>BD-5001</b>
GDB905	<b>BD-6305</b>	GDB1154	<b>BD-7504</b>	GDB1330	<b>BD-1206</b>	GDB1454	<b>BD-5327</b>
GDB911	<b>BD-5312</b>	GDB1155	<b>BD-5008</b>	GDB1333	<b>BD-2819</b>	GDB1455	<b>BD-5334</b>
GDB915	<b>BD-5902</b>	GDB1156	<b>BD-5002</b>	GDB1334	<b>BD-5321</b>	GDB1456	<b>BD-5328</b>
GDB916	<b>BD-1411</b>	GDB1159	<b>BD-7810</b>	GDB1335	<b>BD-5315</b>	GDB1457	<b>BD-5329</b>
GDB917	<b>BD-1412</b>	GDB1160	<b>BD-7802</b>	GDB1342	<b>BD-5912</b>	GDB1459	<b>BD-8025</b>
GDB950	<b>BD-5336</b>	GDB1163	<b>BD-1208</b>	GDB1344	<b>BD-6501</b>	GDB1460	<b>BD-8018</b>
GDB951	<b>BD-1402</b>	GDB1164	<b>BD-3407</b>	GDB1348	<b>BD-1408</b>	GDB1461	<b>BD-3032</b>
GDB952	<b>BD-5909</b>	GDB1166	<b>BD-5913</b>	GDB1349	<b>BD-3016</b>	GDB1463	<b>BD-2201</b>

**• Cross Reference Lucas/TRW-LYNX*auto***



LUCAS/TRW	LYNX <i>auto</i>	LUCAS/TRW	LYNX <i>auto</i>	LUCAS/TRW	LYNX <i>auto</i>	LUCAS/TRW	LYNX <i>auto</i>
GDB1464	BD-2202	GDB1622	BD-1204	GDB3089	BD-3604	GDB3290	BD-7311
GDB1466	BD-6303	GDB1625	BD-1422	GDB3092	BD-5736	GDB3292	BD-6302
GDB1468	BD-6312	GDB1626	BD-1420	GDB3103	BD-5122	GDB3294	BD-5706
GDB1469	BD-6302	GDB1628	BD-5309	GDB3108	BD-1809	GDB3296	BD-3606
GDB1473	BD-5005	GDB1629	BD-5307	GDB3115	BD-5718	GDB3297	BD-3614
GDB1475	BD-1211	GDB1630	BD-5308	GDB3132	BD-5102	GDB3299	BD-3617
GDB1480	BD-5345	GDB1631	BD-5003	GDB3152	BD-7529	GDB3301	BD-4406
GDB1481	BD-5310	GDB1632	BD-5009	GDB3155	BD-7520	GDB3307	BD-7107
GDB1482	BD-2812	GDB1633	BD-6103	GDB3163	BD-7590	GDB3308	BD-7108
GDB1484	BD-2800	GDB1642	BD-5330	GDB3168	BD-5713	GDB3309	BD-5111
GDB1485	BD-2821	GDB1643	BD-5332	GDB3172	BD-1802	GDB3310	BD-5112
GDB1492	BD-5923	GDB1651	BD-8006	GDB3173	BD-4408	GDB3312	BD-5704
GDB1495	BD-2204	GDB1653	BD-8007	GDB3175	BD-3401	GDB3314	BD-7522
GDB1496	BD-2205	GDB1665	BD-3008	GDB3179	BD-5121	GDB3315	BD-7531
GDB1497	BD-5115	GDB1667	BD-5349	GDB3180	BD-5703	GDB3316	BD-7507
GDB1498	BD-1415	GDB1668	BD-5908	GDB3181	BD-5702	GDB3325	BD-3404
GDB1499	BD-1426	GDB1670	BD-8028	GDB3186	BD-3422	GDB3328	BD-7101
GDB1502	BD-1425	GDB1671	BD-8034	GDB3189	BD-3420	GDB3330	BD-1803
GDB1503	BD-2212	GDB1673	BD-7313	GDB3190	BD-3425	GDB3332	BD-5739
GDB1515	BD-5911	GDB1682	BD-2830	GDB3192	BD-5101	GDB3333	BD-7592
GDB1516	BD-1224	GDB1683	BD-3004	GDB3193	BD-5103	GDB3335	BD-7545
GDB1517	BD-2215	GDB1684	BD-7816	GDB3195	BD-1801	GDB3336	BD-7548
GDB1518	BD-2216	GDB1685	BD-7817	GDB3197	BD-7503	GDB3337	BD-7539
GDB1521	BD-2217	GDB1687	BD-6315	GDB3198	BD-7527	GDB3338	BD-7525
GDB1525	BD-3007	GDB1681	BD-2828	GDB3201	BD-3613	GDB3339	BD-7534
GDB1527	BD-1403	GDB1690	BD-2223	GDB3203	BD-4401	GDB3341	BD-5505
GDB1530	BD-1403	GDB1696	BD-5343	GDB3205	BD-7105	GDB3343	BD-4411
GDB1531	BD-1427	GDB1697	BD-5342	GDB3208	BD-5710	GDB3344	BD-4413
GDB1532	BD-3022	GDB1698	BD-5341	GDB3217	BD-7104	GDB3346	BD-1804
GDB1535	BD-3035	GDB1699	BD-5344	GDB3218	BD-7519	GDB3347	BD-1805
GDB1538	BD-3026	GDB1700	BD-5916	GDB3222	BD-5715	GDB3348	BD-1807
GDB1540	BD-6311	GDB1703	BD-2829	GDB3223	BD-7106	GDB3352	BD-3602
GDB1542	BD-5323	GDB1723	BD-3034	GDB3224	BD-4415	GDB3355	BD-3413
GDB1543	BD-5324	GDB1724	BD-3002	GDB3227	BD-3422	GDB3364	BD-7549
GDB1546	BD-5325	GDB1725	BD-3003	GDB3230	BD-5114	GDB3367	BD-4402
GDB1547	BD-8005	GDB1726	BD-1417	GDB3233	BD-7518	GDB3369	BD-4409
GDB1548	BD-8019	GDB1728	BD-1418	GDB3235	BD-7524	GDB3372	BD-7111
GDB1550	BD-1203	GDB1729	BD-1423	GDB3239	BD-5511	GDB3373	BD-7103
GDB1552	BD-6314	GDB1730	BD-1428	GDB3241	BD-4414	GDB3374	BD-7523
GDB1553	BD-1222	GDB1732	BD-3005	GDB3242	BD-7526	GDB3375	BD-3406
GDB1555	BD-8001	GDB1736	BD-5318	GDB3243	BD-7538	GDB3378	BD-3611
GDB1556	BD-8032	GDB1737	BD-5350	GDB3245	BD-4403	GDB3382	BD-7000
GDB1557	BD-8033	GDB1743	BD-5004	GDB3246	BD-5506	GDB3398	BD-7566
GDB1559	BD-1414	GDB1761	BD-6102	GDB3247	BD-5507	GDB3399	BD-7544
GDB1565	BD-7814	GDB1762	BD-8038	GDB3249	BD-7574	GDB3405	BD-5741
GDB1566	BD-7815	GDB1763	BD-8030	GDB3250	BD-3408	GDB3407	BD-3427
GDB1567	BD-6702	GDB1765	BD-1223	GDB3251	BD-7511	GDB3408	BD-3432
GDB1583	BD-3001	GDB1814	BD-1220	GDB3253	BD-5119	GDB3410	BD-7589
GDB1584	BD-5525	GDB1818	BD-2224	GDB3256	BD-3607	GDB3416	BD-5737
GDB1586	BD-8017	GDB1768	BD-1219	GDB3265	BD-1805	GDB3418	BD-3615
GDB1594	BD-6101	GDB1789	BD-6317	GDB3268	BD-3403	GDB3419	BD-3616
GDB1595	BD-6110	GDB1797	BD-5331	GDB3270	BD-5512	GDB3420	BD-3608
GDB1596	BD-6111	GDB1805	BD-1221	GDB3273	BD-5705	GDB3421	BD-4407
GDB1600	BD-5348	GDB1810	BD-1421	GDB3275	BD-7310	GDB3425	BD-7542
GDB1605	BD-2206	GDB1843	BD-1810	GDB3278	BD-7517	GDB3426	BD-7532
GDB1611	BD-1429	GDB1844	BD-1811	GDB3279	BD-7510	GDB3431	BD-3610
GDB1612	BD-1430	GDB1875	BD-8029	GDB3284	BD-3605	GDB3435	BD-5529
GDB1616	BD-8016	GDB3034	BD-3429	GDB3286	BD-7506	GDB3437	BD-5123
GDB1617	BD-1217	GDB3045	BD-5516	GDB3287	BD-5504	GDB3438	BD-3402
GDB1620	BD-2211	GDB3071	BD-2402	GDB3288	BD-7540	GDB3443	BD-7302
GDB1621	BD-5901	GDB3088	BD-5104	GDB3289	BD-7541	GDB3445	BD-3418



## • Cross Reference Lucas/TRW-LYNXauto

LUCAS/TRW	LYNXauto	LUCAS/TRW	LYNXauto	LUCAS/TRW	LYNXauto	LUCAS/TRW	LYNXauto
GDB3450	<b>BD-4404</b>						
GDB3454	<b>BD-7543</b>						
GDB3464	<b>BD-7505</b>						
GDB3467	<b>BD-5711</b>						
GDB3471	<b>BD-5116</b>						
GDB3472	<b>BD-5124</b>						
GDB3476	<b>BD-3423</b>						
GDB3477	<b>BD-3424</b>						
GDB3479	<b>BD-7598</b>						
GDB3482	<b>BD-3431</b>						
GDB3484	<b>BD-7596</b>						
GDB3491	<b>BD-7581</b>						
GDB3497	<b>BD-7597</b>						
GDB3499	<b>BD-3623</b>						
GDB3494	<b>BD-3620</b>						
GDB3505	<b>BD-5742</b>						
GDB3515	<b>BD-5743</b>						
GDB4084	<b>BD-3014</b>						
GDB4120	<b>BD-4202</b>						
GDB4133	<b>BD-4201</b>						
GDB4136	<b>BD-4203</b>						
GDB4173	<b>BD-7550</b>						
GDB4175	<b>BD-7599</b>						
GDB7043	<b>BD-3409</b>						
GDB7618	<b>BD-5503</b>						
GDB7682	<b>BD-7102</b>						
GDB7763	<b>BD-7580</b>						
GS8164	<b>BS-4602</b>						
GS8210	<b>BS-4601</b>						
GS8455	<b>BS-6300</b>						
GS8534	<b>BS-6301</b>						
GS8543	<b>BS-1800</b>						
GS8639	<b>BS-8001</b>						
GS8645	<b>BS-1801</b>						
GS8673	<b>BS-7501</b>						
GS8684	<b>BS-3601</b>						
GS8692	<b>BS-4400</b>						
GS8707	<b>BS-3600</b>						

• **Cross Reference Ferodo-LYNXauto**



<b>FERODO</b>	<b>LYNXauto</b>	<b>FERODO</b>	<b>LYNXauto</b>	<b>FERODO</b>	<b>LYNXauto</b>	<b>FERODO</b>	<b>LYNXauto</b>
FDB96	<b>BD-4603</b>	FDB686	<b>BD-5922</b>	FDB967	<b>BD-2808</b>	FDB1163	<b>BD-8024</b>
FDB173	<b>BD-5905</b>	FDB691	<b>BD-5701</b>	FDB968	<b>BD-2810</b>	FDB1166	<b>BD-5710</b>
FDB195	<b>BD-4602</b>	FDB693	<b>BD-5311</b>	FDB969	<b>BD-1213</b>	FDB1167	<b>BD-1213</b>
FDB211	<b>BD-1201</b>	FDB704	<b>BD-7802</b>	FVR970	<b>BD-8022</b>	FDB1168	<b>BD-2219</b>
FDB222	<b>BD-2820</b>	FDB707	<b>BD-5736</b>	FDB979	<b>BD-5312</b>	FDB1263	<b>BD-5704</b>
FCV239	<b>BD-5335</b>	FDB714	<b>BD-5120</b>	FDB980	<b>BD-5002</b>	FDB1276	<b>BD-3016</b>
FDB296	<b>BD-1405</b>	FDB715	<b>BD-5105</b>	FDB981	<b>BD-5008</b>	FDB1278	<b>BD-6313</b>
FDB308	<b>BD-7533</b>	FDB725	<b>BD-1406</b>	FDB985	<b>BD-1210</b>	FDB1285	<b>BD-7810</b>
FDB317	<b>BD-7806</b>	FDB732	<b>BD-5903</b>	FDB994	<b>BD-2804</b>	FDB1288	<b>BD-8011</b>
FDB328	<b>BD-5322</b>	FDB746	<b>BD-6112</b>	FDB995	<b>BD-2824</b>	FDB1289	<b>BD-1214</b>
FDB346	<b>BD-2817</b>	FDB748	<b>BD-3429</b>	FDB997	<b>BD-1401</b>	FDB1292	<b>BD-5920</b>
FDB370	<b>BD-2805</b>	FDB757	<b>BD-4405</b>	FDB998	<b>BD-1416</b>	FDB1293	<b>BD-5907</b>
FDB385	<b>BD-8012</b>	FDB759	<b>BD-5524</b>	FDB1000	<b>BD-2214</b>	FDB1294	<b>BD-5910</b>
FDB393	<b>BD-6105</b>	FDB763	<b>BD-5110</b>	FDB1002	<b>BD-2213</b>	FDB1295	<b>BD-5904</b>
FDB396	<b>BD-7304</b>	FDB764	<b>BD-5509</b>	FDB1003	<b>BD-2218</b>	FDB1299	<b>BD-2822</b>
FDB396	<b>BD-7304</b>	FDB765	<b>BD-5501</b>	FDB1009	<b>BD-2402</b>	FDB1300	<b>BD-1408</b>
FDB398	<b>BD-3030</b>	FDB766	<b>BD-3012</b>	FDB1011	<b>BD-5122</b>	FDB1301	<b>BD-6501</b>
FDB406	<b>BD-6310</b>	FDB767	<b>BD-3013</b>	FDB1013	<b>BD-5516</b>	FDB1303	<b>BD-5306</b>
FDB409	<b>BD-2818</b>	FDB772	<b>BD-3018</b>	FDB1014	<b>BD-3604</b>	FVR1304	<b>BD-5339</b>
FDB415	<b>BD-5301</b>	FDB774	<b>BD-8014</b>	FDB1015	<b>BD-3802</b>	FDB1305	<b>BD-5347</b>
FDB419	<b>BD-8004</b>	FDB775	<b>BD-1205</b>	FDB1017	<b>BD-3803</b>	FVR1306	<b>BD-5340</b>
FDB435	<b>BD-3601</b>	FDB776	<b>BD-3406</b>	FDB1021	<b>BD-7505</b>	FDB1310	<b>BD-5313</b>
FDB455	<b>BD-6104</b>	FDB777	<b>BD-3407</b>	FDB1024	<b>BD-7808</b>	FDB1311	<b>BD-5315</b>
FDB471	<b>BD-5006</b>	FDB779	<b>BD-1411</b>	FDB1025	<b>BD-5114</b>	FDB1312	<b>BD-8009</b>
FDB478	<b>BD-7521</b>	FVR785	<b>BD-8021</b>	FDB1033	<b>BD-3618</b>	FDB1318	<b>BD-3009</b>
FDB482	<b>BD-2404</b>	FDB789	<b>BD-7112</b>	FVR1038	<b>BD-5337</b>	FDB1319	<b>BD-3010</b>
FDB506	<b>BD-6701</b>	FDB790	<b>BD-7109</b>	FVR1039	<b>BD-5338</b>	FDB1321	<b>BD-7590</b>
FDB520	<b>BD-5000</b>	FDB796	<b>BD-5702</b>	FDB1040	<b>BD-2801</b>	FDB1322	<b>BD-5321</b>
FDB525	<b>BD-5902</b>	FDB797	<b>BD-7501</b>	FDB1044	<b>BD-5346</b>	FDB1323	<b>BD-1216</b>
FDB527	<b>BD-4605</b>	FDB799	<b>BD-5316</b>	FDB1049	<b>BD-5302</b>	FDB1325	<b>BD-4601</b>
FDB541	<b>BD-8002</b>	FDB800	<b>BD-5333</b>	FDB1050	<b>BD-5320</b>	FDB1327	<b>BD-7104</b>
FDB554	<b>BD-7508</b>	FDB803	<b>BD-5508</b>	FDB1052	<b>BD-2803</b>	FDB1333	<b>BD-7106</b>
FDB558	<b>BD-6305</b>	FDB804	<b>BD-5502</b>	FDB1054	<b>BD-8013</b>	FDB1334	<b>BD-2823</b>
FDB562	<b>BD-7805</b>	FDB809	<b>BD-7801</b>	FDB1055	<b>BD-3023</b>	FDB1336	<b>BD-1802</b>
FDB565	<b>BD-2806</b>	FDB813	<b>BD-7800</b>	FDB1056	<b>BD-2802</b>	FDB1337	<b>BD-1801</b>
FDB578	<b>BD-1412</b>	FDB845	<b>BD-6301</b>	FDB1062	<b>BD-6108</b>	FDB1349	<b>BD-2827</b>
FDB579	<b>BD-3017</b>	FDB850	<b>BD-1407</b>	FDB1063	<b>BD-2221</b>	FDB1355	<b>BD-6500</b>
FDB584	<b>BD-1402</b>	FDB854	<b>BD-5303</b>	FDB1066	<b>BD-2816</b>	FDB1356	<b>BD-5345</b>
FDB585	<b>BD-3412</b>	FDB859	<b>BD-5738</b>	FDB1068	<b>BD-5914</b>	FDB1368	<b>BD-7519</b>
FDB586	<b>BD-5909</b>	FDB867	<b>BD-7516</b>	FDB1072	<b>BD-8010</b>	FDB1369	<b>BD-1805</b>
FDB590	<b>BD-1209</b>	FDB868	<b>BD-7520</b>	FDB1073	<b>BD-1410</b>	FDB1370	<b>BD-2220</b>
FDB596	<b>BD-1208</b>	FDB869	<b>BD-3029</b>	FDB1075	<b>BD-1413</b>	FDB1376	<b>BD-2807</b>
FDB597	<b>BD-4410</b>	FDB871	<b>BD-5001</b>	FDB1081	<b>BD-3019</b>	FDB1378	<b>BD-6106</b>
FDB600	<b>BD-5708</b>	FDB876	<b>BD-6107</b>	FDB1082	<b>BD-3020</b>	FDB1381	<b>BD-3033</b>
FDB602	<b>BD-7591</b>	FDB877	<b>BD-2222</b>	FDB1083	<b>BD-8002</b>	FDB1382	<b>BD-7811</b>
FDB604	<b>BD-5735</b>	FDB878	<b>BD-6308</b>	FDB1091	<b>BD-5703</b>	FDB1383	<b>BD-7812</b>
FDB610	<b>BD-6900</b>	FDB884	<b>BD-3011</b>	FDB1092	<b>BD-5521</b>	FDB1384	<b>BD-5522</b>
FDB613	<b>BD-3426</b>	FDB897	<b>BD-7804</b>	FDB1093	<b>BD-5526</b>	FDB1391	<b>BD-7592</b>
FDB617	<b>BD-3015</b>	FDB901	<b>BD-5913</b>	FDB1094	<b>BD-8003</b>	FDB1392	<b>BD-7526</b>
FDB621	<b>BD-3428</b>	FDB904	<b>BD-3421</b>	FDB1094	<b>BD-8003</b>	FDB1393	<b>BD-3021</b>
FDB628	<b>BD-7807</b>	FDB905	<b>BD-3405</b>	FDB1095	<b>BD-5523</b>	FDB1394	<b>BD-5108</b>
FDB638	<b>BD-3612</b>	FDB909	<b>BD-3028</b>	FDB1096	<b>BD-5713</b>	FDB1395	<b>BD-7538</b>
FDB644	<b>BD-5314</b>	FDB912	<b>BD-2814</b>	FDB1101	<b>BD-8008</b>	FDB1396	<b>BD-2809</b>
FDB646	<b>BD-5305</b>	FDB913	<b>BD-3014</b>	FDB1108	<b>BD-1809</b>	FDB1398	<b>BD-1202</b>
FDB660	<b>BD-1404</b>	FDB913	<b>BD-3014</b>	FDB1112	<b>BD-2203</b>	FDB1399	<b>BD-2201</b>
FDB667	<b>BD-5740</b>	FDB929	<b>BD-4200</b>	FDB1113	<b>BD-2819</b>	FDB1400	<b>BD-5326</b>
FDB669	<b>BD-5304</b>	FDB941	<b>BD-5336</b>	FDB1124	<b>BD-6307</b>	FDB1410	<b>BD-2207</b>
FDB670	<b>BD-6700</b>	FDB950	<b>BD-5101</b>	FDB1125	<b>BD-4408</b>	FDB1411	<b>BD-2208</b>
FDB671	<b>BD-7803</b>	FDB950	<b>BD-5101</b>	FDB1131	<b>BD-8023</b>	FDB1412	<b>BD-2209</b>
FDB676	<b>BD-7809</b>	FDB954	<b>BD-1207</b>	FDB1135	<b>BD-6309</b>	FDB1413	<b>BD-2210</b>
FDB678	<b>BD-5918</b>	FDB956	<b>BD-3402</b>	FDB1137	<b>BD-2813</b>	FDB1414	<b>BD-5323</b>



# • Cross Reference Ferodo-LYNXauto

<b>FERODO</b>	<b>LYNXauto</b>	<b>FERODO</b>	<b>LYNXauto</b>	<b>FERODO</b>	<b>LYNXauto</b>	<b>FERODO</b>	<b>LYNXauto</b>
FDB1415	<b>BD-6109</b>	FDB1533	<b>BD-7311</b>	FDB1698	<b>BD-7549</b>	FDB1978	<b>BD-5318</b>
FDB1416	<b>BD-3007</b>	FDB1535	<b>BD-5912</b>	FDB1699	<b>BD-1803</b>	FDB1980	<b>BD-5319</b>
FDB1419	<b>BD-8015</b>	FDB1536	<b>BD-4414</b>	FDB1704	<b>BD-3413</b>	FDB1986	<b>BD-1804</b>
FDB1420	<b>BD-6304</b>	FDB1540	<b>BD-6302</b>	FDB1707	<b>BD-5111</b>	FDB1996	<b>BD-5004</b>
FDB1422	<b>BD-5520</b>	FDB1542	<b>BD-2204</b>	FDB1715	<b>BD-7525</b>	FDB4002	<b>BD-4203</b>
FDB1423	<b>BD-5906</b>	FDB1543	<b>BD-2205</b>	FDB1725	<b>BD-6101</b>	FDB4003	<b>BD-6102</b>
FDB1424	<b>BD-5915</b>	FDB1544	<b>BD-6314</b>	FDB1726	<b>BD-6110</b>	FDB4046	<b>BD-7546</b>
FDB1425	<b>BD-3006</b>	FDB1551	<b>BD-7310</b>	FDB1727	<b>BD-6111</b>	FDB4050	<b>BD-1223</b>
FDB1426	<b>BD-5327</b>	FDB1556	<b>BD-2212</b>	FDB1728	<b>BD-2206</b>	FDB4055	<b>BD-5349</b>
FDB1427	<b>BD-5334</b>	FDB1557	<b>BD-5119</b>	FDB1733	<b>BD-3602</b>	FDB4057	<b>BD-8038</b>
FDB1428	<b>BD-5317</b>	FDB1564	<b>BD-7524</b>	FDB1735	<b>BD-4411</b>	FDB4111	<b>BD-3615</b>
FDB1437	<b>BD-7529</b>	FDB1565	<b>BD-5102</b>	FDB1736	<b>BD-4413</b>	FDB4189	<b>BD-5331</b>
FDB1439	<b>BD-3422</b>	FDB1568	<b>BD-3022</b>	FDB1737	<b>BD-3607</b>	FDB4229	<b>BD-7580</b>
FDB1440	<b>BD-6311</b>	FDB1569	<b>BD-4401</b>	FDB1748	<b>BD-1419</b>	FDB4230	<b>BD-7581</b>
FDB1441	<b>BD-6312</b>	FDB1571	<b>BD-5115</b>	FDB1749	<b>BD-5308</b>	FSB59	<b>BS-4602</b>
FDB1444	<b>BD-3408</b>	FDB1573	<b>BD-7540</b>	FDB1750	<b>BD-5309</b>	FSB240	<b>BS-4601</b>
FDB1446	<b>BD-5121</b>	FDB1574	<b>BD-7541</b>	FDB1765	<b>BD-8016</b>	FSB335	<b>BS-1800</b>
FDB1451	<b>BD-1215</b>	FDB1577	<b>BD-5715</b>	FDB1770	<b>BD-6306</b>	FSB519	<b>BS-6301</b>
FDB1452	<b>BD-5921</b>	FDB1580	<b>BD-3422</b>	FDB1773	<b>BD-1414</b>	FSB565	<b>BS-3000</b>
FDB1454	<b>BD-5718</b>	FDB1593	<b>BD-5307</b>	FVR1777	<b>BD-5343</b>	FSB566	<b>BS-1801</b>
FDB1455	<b>BD-5103</b>	FDB1594	<b>BD-3001</b>	FVR1778	<b>BD-5341</b>	FSB582	<b>BS-7501</b>
FDB1456	<b>BD-7503</b>	FDB1595	<b>BD-4406</b>	FVR1779	<b>BD-5344</b>	FSB606	<b>BS-3601</b>
FDB1457	<b>BD-7527</b>	FDB1596	<b>BD-5512</b>	FVR1780	<b>BD-5342</b>	FSB612	<b>BS-3602</b>
FDB1461	<b>BD-3032</b>	FDB1602	<b>BD-4403</b>	FDB1782	<b>BD-5310</b>	FSB635	<b>BS-3001</b>
FDB1463	<b>BD-1212</b>	FDB1604	<b>BD-5507</b>	FDB1783	<b>BD-4409</b>	FSB642	<b>BS-6300</b>
FDB1466	<b>BD-2812</b>	FDB1605	<b>BD-3614</b>	FDB1784	<b>BD-2211</b>		
FDB1468	<b>BD-2800</b>	FDB1606	<b>BD-3605</b>	FDB1786	<b>BD-5737</b>		
FDB1469	<b>BD-2821</b>	FDB1607	<b>BD-4415</b>	FDB1788	<b>BD-1206</b>		
FDB1470	<b>BD-2826</b>	FDB1608	<b>BD-5328</b>	FDB1790	<b>BD-6103</b>		
FDB1473	<b>BD-5005</b>	FDB1610	<b>BD-7518</b>	FDB1807	<b>BD-1420</b>		
FDB1476	<b>BD-2202</b>	FDB1612	<b>BD-7105</b>	FDB1816	<b>BD-3804</b>		
FDB1478	<b>BD-2215</b>	FDB1613	<b>BD-5009</b>	FDB1826	<b>BD-8006</b>		
FDB1479	<b>BD-2216</b>	FDB1615	<b>BD-5003</b>	FDB1830	<b>BD-5330</b>		
FDB1480	<b>BD-2217</b>	FDB1617	<b>BD-5739</b>	FDB1831	<b>BD-5332</b>		
FDB1481	<b>BD-3025</b>	FDB1619	<b>BD-5112</b>	FDB1832	<b>BD-1222</b>		
FDB1482	<b>BD-3027</b>	FDB1620	<b>BD-7522</b>	FDB1833	<b>BD-6702</b>		
FDB1483	<b>BD-1403</b>	FDB1621	<b>BD-5504</b>	FDB1839	<b>BD-5505</b>		
FDB1483	<b>BD-1403</b>	FDB1625	<b>BD-8005</b>	FDB1840	<b>BD-3611</b>		
FDB1484	<b>BD-8025</b>	FDB1626	<b>BD-8019</b>	FDB1859	<b>BD-3427</b>		
FDB1492	<b>BD-8026</b>	FDB1627	<b>BD-8007</b>	FDB1862	<b>BD-3432</b>		
FDB1493	<b>BD-5348</b>	FDB1628	<b>BD-1415</b>	FDB1865	<b>BD-6316</b>		
FDB1495	<b>BD-7813</b>	FDB1629	<b>BD-1217</b>	FDB1866	<b>BD-6315</b>		
FDB1496	<b>BD-3024</b>	FDB1630	<b>BD-2815</b>	FDB1875	<b>BD-7313</b>		
FDB1497	<b>BD-8018</b>	FDB1631	<b>BD-7814</b>	FDB1877	<b>BD-8028</b>		
FDB1498	<b>BD-3613</b>	FDB1632	<b>BD-7815</b>	FDB1885	<b>BD-3008</b>		
FDB1502	<b>BD-7504</b>	FDB1633	<b>BD-1211</b>	FDB1889	<b>BD-1807</b>		
FDB1506	<b>BD-3425</b>	FDB1634	<b>BD-8017</b>	FDB1890	<b>BD-7594</b>		
FDB1511	<b>BD-5919</b>	FDB1636	<b>BD-1204</b>	FDB1897	<b>BD-3004</b>		
FDB1512	<b>BD-5329</b>	FDB1639	<b>BD-7101</b>	FDB1905	<b>BD-1805</b>		
FDB1513	<b>BD-7593</b>	FDB1640	<b>BD-5908</b>	FDB1911	<b>BD-7506</b>		
FDB1514	<b>BD-7511</b>	FDB1641	<b>BD-1203</b>	FDB1917	<b>BD-3005</b>		
FDB1515	<b>BD-6303</b>	FDB1648	<b>BD-7548</b>	FDB1920	<b>BD-5916</b>		
FDB1518	<b>BD-8027</b>	FDB1649	<b>BD-7539</b>	FDB1922	<b>BD-5917</b>		
FDB1520	<b>BD-5923</b>	FDB1654	<b>BD-3026</b>	FSL1928	<b>BD-3002</b>		
FDB1521	<b>BD-5911</b>	FDB1658	<b>BD-3404</b>	FVR1929	<b>BD-3034</b>		
FDB1523	<b>BD-4202</b>	FDB1659	<b>BD-4201</b>	FSL1930	<b>BD-3003</b>		
FDB1526	<b>BD-5325</b>	FDB1661	<b>BD-5324</b>	FDB1931	<b>BD-5901</b>		
FDB1528	<b>BD-7507</b>	FDB1669	<b>BD-3403</b>	FDB1936	<b>BD-7589</b>		
FDB1529	<b>BD-7531</b>	FDB1670	<b>BD-3617</b>	FDB1937	<b>BD-7000</b>		
FDB1530	<b>BD-7574</b>	FDB1682	<b>BD-5705</b>	FDB1947	<b>BD-7103</b>		
FDB1531	<b>BD-7510</b>	FDB1686	<b>BD-7517</b>	FDB1956	<b>BD-4407</b>		

• **Cross Reference KASHIYAMA-LYNXauto / NISSHINBO-LYNXauto**



<b>NISSHINBO</b>	<b>LYNXauto</b>	<b>NISSHINBO</b>	<b>LYNXauto</b>	<b>KASHIYAMA</b>	<b>LYNXauto</b>	<b>KASHIYAMA</b>	<b>LYNXauto</b>
PF-1077	<b>BD-7533</b>	PF-6340	<b>BD-2402</b>	D0027M	<b>BD-2402</b>	D5128M	<b>BD-3404</b>
PF-1219	<b>BD-7501</b>	PF-7249	<b>BD-7109</b>	D1092M	<b>BD-5708</b>	D6024M	<b>BD-5508</b>
PF-1228	<b>BD-7520</b>	PF-7390	<b>BD-7104</b>	D1116M	<b>BD-5710</b>	D6039M	<b>BD-5501</b>
PF-1237	<b>BD-7508</b>	PF-7398	<b>BD-7105</b>	D1124M	<b>BD-7108</b>	D6054M	<b>BD-5502</b>
PF-1242	<b>BD-7504</b>	PF-7415	<b>BD-7106</b>	D1142M	<b>BD-3607</b>	D6067M	<b>BD-5509</b>
PF-1243	<b>BD-7505</b>	PF-7460	<b>BD-7101</b>	D1165M	<b>BD-5705</b>	D6086M	<b>BD-5511</b>
PF-1267	<b>BD-7558</b>	PF-7463	<b>BD-7107</b>	D1208M	<b>BD-5110</b>	D6089	<b>BD-5512</b>
PF-1321	<b>BD-7521</b>	PF-7493	<b>BD-7102</b>	D1214M	<b>BD-5736</b>	D6108	<b>BD-5504</b>
PF-1324	<b>BD-7524</b>	PF-7499	<b>BD-7111</b>	D1218M	<b>BD-5715</b>	D6109	<b>BD-5503</b>
PF-1401	<b>BD-7529</b>	PF-7501	<b>BD-7103</b>	D1230	<b>BD-5713</b>	D7020M	<b>BD-7109</b>
PF-1411	<b>BD-7503</b>	PF-8254	<b>BD-3405</b>	D1231M	<b>BD-5725</b>	D7036	<b>BD-7104</b>
PF-1412	<b>BD-7527</b>	PF-8263	<b>BD-3412</b>	D1233M	<b>BD-3409</b>	D7037	<b>BD-7107</b>
PF-1421	<b>BD-7518</b>	PF-8264	<b>BD-3406</b>	D1244M	<b>BD-5706</b>	D7039M	<b>BD-7105</b>
PF-1424	<b>BD-7510</b>	PF-8265	<b>BD-3407</b>	D2023	<b>BD-7533</b>	D7042M	<b>BD-7106</b>
PF-1430	<b>BD-7507</b>	PF-8397	<b>BD-3401</b>	D2053M	<b>BD-7521</b>	D7055M	<b>BD-7101</b>
PF-1457	<b>BD-7506</b>	PF-8423	<b>BD-3408</b>	D2082M	<b>BD-7501</b>	D7058	<b>BD-7102</b>
PF-1458	<b>BD-7523</b>	PF-8485	<b>BD-3404</b>	D2088	<b>BD-7520</b>	D7060M	<b>BD-7111</b>
PF-1470	<b>BD-7531</b>	PF-8509	<b>BD-3403</b>	D2092	<b>BD-7505</b>	D7064M	<b>BD-7103</b>
PF-1471	<b>BD-7519</b>	PF-9118	<b>BD-7304</b>	D2094M	<b>BD-7504</b>	D9044	<b>BD-7302</b>
PF-1472	<b>BD-7526</b>			D2117M	<b>BD-7503</b>	D6128M	<b>BD-5529</b>
PF-1479	<b>BD-7522</b>			D2126M	<b>BD-7524</b>	D2266M	<b>BD-7566</b>
PF-1482	<b>BD-7549</b>			D2166	<b>BD-7529</b>	D1282M	<b>BD-5742</b>
PF-1494	<b>BD-7544</b>			D2173M	<b>BD-7518</b>	D1284M	<b>BD-5743</b>
PF-1497	<b>BD-7525</b>			D2174M	<b>BD-7519</b>	D5162M	<b>BD-3431</b>
PF-1498	<b>BD-7534</b>			D2179	<b>BD-7527</b>	D5066M	<b>BD-3402</b>
PF-1508	<b>BD-7550</b>			D2180	<b>BD-7507</b>	D5150M	<b>BD-3432</b>
PF-1521	<b>BD-7530</b>			D2183M	<b>BD-7526</b>	D2108	<b>BD-7558</b>
PF-1522	<b>BD-7532</b>			D2188M	<b>BD-7510</b>		
PF-1530	<b>BD-7572</b>			D2217	<b>BD-7531</b>		
PF-1541	<b>BD-7580</b>			D2218	<b>BD-7506</b>		
PF-1542	<b>BD-7581</b>			D2219	<b>BD-7523</b>		
PF-2176A	<b>BD-5708</b>			D2222	<b>BD-7522</b>		
PF-2201A	<b>BD-5701</b>			D2224M	<b>BD-7540</b>		
PF-2221	<b>BD-7108</b>			D2227	<b>BD-7541</b>		
PF-2224	<b>BD-5702</b>			D2228M	<b>BD-7549</b>		
PF-2245	<b>BD-3607</b>			D2233	<b>BD-7548</b>		
PF-2261	<b>BD-5705</b>			D2236	<b>BD-7545</b>		
PF-2356	<b>BD-5703</b>			D2243M	<b>BD-7544</b>		
PF-2375	<b>BD-5110</b>			D2249	<b>BD-7525</b>		
PF-2413	<b>BD-5715</b>			D2250	<b>BD-7534</b>		
PF-2435	<b>BD-3409</b>			D2254M	<b>BD-7543</b>		
PF-2466	<b>BD-5706</b>			D2269	<b>BD-7532</b>		
PF-3174	<b>BD-5508</b>			D2270	<b>BD-7530</b>		
PF-3233	<b>BD-5501</b>			D3027	<b>BD-5104</b>		
PF-3271	<b>BD-5509</b>			D3062M	<b>BD-5105</b>		
PF-3280	<b>BD-5502</b>			D3084M	<b>BD-5101</b>		
PF-3391	<b>BD-5511</b>			D3109	<b>BD-5103</b>		
PF-3414	<b>BD-5506</b>			D3114	<b>BD-5115</b>		
PF-3417	<b>BD-5512</b>			D3120	<b>BD-5108</b>		
PF-3450	<b>BD-5507</b>			D3122M	<b>BD-5111</b>		
PF-3462	<b>BD-5503</b>			D3125M	<b>BD-5112</b>		
PF-3469	<b>BD-5504</b>			D3128	<b>BD-3001</b>		
PF-5203	<b>BD-5104</b>			D3146M	<b>BD-5118</b>		
PF-5232	<b>BD-5105</b>			D5019M	<b>BD-3412</b>		
PF-5239	<b>BD-5101</b>			D5056M	<b>BD-3401</b>		
PF-5418	<b>BD-5119</b>			D5060M	<b>BD-3405</b>		
PF-5425	<b>BD-5103</b>			D5070M	<b>BD-3406</b>		
PF-5483	<b>BD-5111</b>			D5073M	<b>BD-3407</b>		
PF-5495	<b>BD-5108</b>			D5100M	<b>BD-3403</b>		
PF-5507	<b>BD-3001</b>			D5119M	<b>BD-3408</b>		
PF-5526	<b>BD-5112</b>			D5125M	<b>BD-3413</b>		



# • Cross Reference OE-LYNXauto



OE	LYNXauto	OE	LYNXauto	OE	LYNXauto	OE	LYNXauto
1205557	BD-1206	12799240	BD-6302	1694200320	BD-5308	26296-XA010	BD-7111
1205695	BD-3024	13301234	BD-1810	1694200720	BD-5308	26696-AF000	BD-7106
1206062	BD-3021	13319294	BD-1811	1694200820	BD-5309	26696-AG030	BD-7103
1219892	BD-3007	13322091	BD-5901	1694200920	BD-5308	26696-FA000	BD-7108
1223682	BD-3001	1566096	BD-5901	1694201020	BD-5307	26696-FE060	BD-7108
1237132	BD-3024	1605000	BD-5907	18029757	BD-5924	2701944	BD-7807
1250688	BD-3006	1605002	BD-5919	18045381	BD-5924	271184	BD-7806
1318139	BD-3033	1605003	BD-5913	191698151A	BD-8012	271336	BD-7802
1318147	BD-3032	1605004	BD-5922	191698151F	BD-8012	271824	BD-7802
1343513	BD-3025	1605005	BD-5902	191698151H	BD-8004	271958	BD-7809
1345337	BD-3025	1605025	BD-5910	191698151K	BD-8004	271979	BD-7808
1355950	BD-3022	1605032	BD-5912	1E07-33-23Z	BD-5108	272370	BD-7813
1356392	BD-3008	1605036	BD-5914	1H0698151A	BD-8013	272779	BD-7800
1360303	BD-3022	1605036	BD-5914	1H0698151B	BD-8011	272780	BD-7801
1371403	BD-3034	1605042	BS-1800	1HM698151	BD-8009	272911	BD-7802
1379971	BD-3004	1605081	BD-5915	1J0698151A	BD-8003	274331	BD-7814
1386603	BD-3027	1605086	BD-5911	1J0698151B	BD-8003	274528	BD-7815
1425406	BD-3009	1605092	BD-5915	1J0698151D	BD-1202	275895	BD-7801
1425407	BD-3010	1605138	BD-6702	1J0698151E	BD-1202	291698151A	BD-5335
1433952	BD-3002	1605233	BD-5911	1J0698151F	BD-1202	2D0698151	BD-5337
1433958	BD-3003	1605252	BD-5908	1J0698151G	BD-1202	2D0698151C	BD-5337
1439867	BD-3005	1605283	BD-5923	1J0698151H	BD-8003	2D0698451A	BD-5338
1458247	BD-3004	1605283	BD-5923	1J0698151J	BD-8003	2D0698451B	BD-5340
1488962	BD-3002	1605353	BD-5916	1J0698151K	BD-1212	2E0698151	BD-5341
1501265	BD-3035	1605356	BD-5917	1J0698151M	BD-1212	2E0698151A	BD-5343
1508074	BD-3001	1605359	BD-5916	1J0698451B	BD-1206	2E0698451	BD-5342
1521329	BD-3008	1605728	BD-5909	1J0698451R	BD-1206	2E0698451A	BD-5344
1522073	BD-3008	1605782	BD-5922	1J0698525B	BS-8001	2E0698451B	BD-5344
1554523	BD-3034	1605799	BD-5902	1K0698151B	BD-8016	2H0698151	BD-3002
1554524	BD-3003	1605824	BD-5903	1K0698151	BD-1203	3395842	BD-3029
1560026	BD-3003	1605825	BD-5918	1K0698151A	BD-1202	3401278	BD-5101
1605019	BD-3803	1605855	BD-5913	1K0698151C	BD-1203	30620770	BD-5523
1605454	BD-1402	1605870	BD-5905	1K0698151D	BD-1202	30630555	BD-5522
1605454	BD-1801	1605877	BD-5909	1K0698151E	BD-1203	30630612	BD-5522
1605746	BD-1402	1605907	BD-5903	1K0698451	BD-1204	30681739	BD-3001
1605789	BD-1402	1605947	BD-5924	1K0698451B	BD-1204	30715023	BD-3001
1605808	BD-1402	1605957	BD-5904	1K0698451D	BD-1204	30742030	BD-3001
1605852	BD-3802	1605961	BD-5910	1K0698451F	BD-1204	30736610	BD-5901
1605911	BD-1402	1605964	BD-5915	1K0698451G	BD-1204	30769199	BD-5522
1605911	BD-1801	1605973	BD-6302	1S712M008BC	BD-3007	30793618	BD-3001
1638880	BD-3030	1605975	BD-5923	2101-3501089	BD-4603	30793941	BD-3004
1647730	BD-3017	1605976	BD-5906	2101-3501089	BD-4603	312624680	BD-5523
1652206	BD-3030	1605978	BD-5919	2101-3502090	BS-4602	3342534	BD-7805
1659938	BD-3020	1605980	BD-5921	2108-3501080	BD-4601	3344061	BD-7803
1682005	BD-3005	1605992	BD-5908	2108-3501089	BD-4605	33447038	BD-7804
1712024	BD-3001	1605995	BD-5911	2108-3502090	BS-4601	3344787	BD-7803
1721086	BD-3034	1605996	BD-5904	2110-3501080	BD-4601	3345670	BD-5526
1954460	BD-3028	1634200020	BD-5326	2121-3501090	BD-4602	357698151	BD-1201
1956495	BD-3028	1634200320	BD-5326	26296-AA000	BD-7112	34111160356	BD-1406
1957042	BD-3028	1634200520	BD-5328	26296-AA061	BD-7109	34111156899	BD-1404
11046152	BD-1402	1634200920	BD-5329	26296-AA082	BD-7109	34111157039	BD-1411
11046952012	BD-1402	1634201120	BD-5329	26296-AA120	BD-7112	34111157570	BD-1411
11046952012	BD-1801	1644201320	BD-5331	26296-AC021	BD-7105	34111157748	BD-1404
1048308	BD-3016	1644201820	BD-5330	26296-AC050	BD-7104	34111158316	BD-1404
1048310	BD-3016	1644201920	BD-5332	26296-AE120	BD-7107	34111159259	BD-1411
11046148	BD-5903	1684200120	BD-5306	26296-AE140	BD-7104	34111160450	BD-1411
1125669	BS-3001	1684200420	BD-5310	26296-AE200	BD-7102	34111161057	BD-1404
1126158	BS-3000	1684200720	BD-5306	26296-AG050	BD-7111	34111161347	BD-1404
1130753	BD-3016	1684200820	BD-5306	26296-FA100	BD-7107	34111161349	BD-1404
1233679	BD-5901	1694200120	BD-5309	26296-FE081	BD-7101	34111161445	BD-1406
12759808	BD-5914	1694200220	BD-5307	26296-SA010	BD-7101	34111162210	BD-1416





### • Cross Reference OE-LYNXauto

OE	LYNXauto	OE	LYNXauto	OE	LYNXauto	OE	LYNXauto
34111162481	BD-1404	34211156749	BD-1405	425146	BD-2222	425423	BD-2201
34111163227	BD-1401	34211157925	BD-1405	425150	BD-2213	425428	BD-1206
34111163307	BD-1401	34211157926	BD-1405	425151	BD-2213	425440	BD-2211
34111163387	BD-1410	34211158643	BD-1405	425152	BD-2220	425442	BD-2222
34111163850	BD-1406	34211158912	BD-1405	425154	BD-2203	425454	BD-2213
34111163921	BD-1416	34211159003	BD-1405	425155	BD-2203	425457	BD-2212
34111163922	BD-1416	34211159273	BD-1405	425160	BD-2221	425458	BD-2215
34111163953	BD-1410	34211159276	BD-1405	425167	BD-2219	425468	BD-2217
34111164330	BD-1410	34211159912	BD-1405	425170	BD-2219	425475	BD-2201
34111164331	BD-1410	34211163324	BD-1403	425196	BD-2222	425484	BD-2220
34111164498	BD-1408	34211163326	BD-1403	425197	BD-2222	425485	BD-2203
34111164500	BD-1408	34211163395	BD-1413	425203	BD-2220	425488	BD-2206
34111164737	BD-1406	34211164581	BD-1403	425214	BD-2207	425489	BD-2202
34111165227	BD-1401	34211164582	BD-1403	425215	BD-2208	4077636	BD-3033
34111165555	BD-1408	34211165233	BD-1407	425216	BD-2209	4095132	BD-3032
34112227863	BD-1416	34212226013	BD-1405	425217	BD-2210	4096346	BD-5115
34112229031	BD-1401	34213403241	BD-1403	425218	BD-2201	4346371	BD-3022
34112229935	BD-1411	34216750160	BD-1403	425220	BD-2212	4588141	BD-5115
34112282090	BD-1401	34216752632	BD-1403	425221	BD-2201	437698451	BD-1208
34112282165	BD-1401	34216761238	BD-1407	425222	BD-2202	443698451	BD-1208
34112282166	BD-1401	34216761240	BD-1403	425223	BD-1206	447698451	BD-1208
34112282555	BD-1411	34216761247	BD-1403	425224	BD-2809	449187725	BD-2402
34112282556	BD-1401	34216761248	BD-1403	425226	BD-2809	449187728	BD-2402
34113427503	BD-1401	34216761250	BD-1403	425231	BD-2212	449287705	BD-2404
34114074370	BD-1417	34216761251	BD-1403	425236	BD-2204	41060-0023R	BD-5725
34116752482	BD-1406	34216761281	BD-1413	425237	BD-2205	41060-00QAE	BD-6303
34116753668	BD-1415	34216763043	BD-1419	425238	BD-2201	41060-1N090	BD-5703
34116761237	BD-1408	34216763044	BD-1419	425241	BD-1206	41060-2F025	BD-5735
34116761244	BD-1408	357698151A	BD-8014	425243	BD-2215	41060-2F526	BD-5713
34116761252	BD-1401	357698151B	BD-1205	425244	BD-2216	41060-2N290	BD-5710
34116761277	BD-1410	357698151D	BD-8014	425245	BD-2216	41060-2X825	BD-3028
34116761279	BD-1410	3A0698151	BD-1213	425247	BD-2217	41060-3H085	BD-5704
34116763089	BD-1415	3A0698151A	BD-1213	425248	BD-2208	41060-40V92	BD-5701
34116763617	BD-1409	3C0698151	BD-1203	425249	BD-2209	41060-44F92	BD-5708
34116763618	BD-1409	3C0698151A	BD-1203	425250	BD-2202	410604775R	BD-5739
34116763618	BD-1414	3C0698151B	BD-1203	425253	BD-2202	41060-4M490	BD-3409
34116764540	BD-1415	3C0698151C	BD-1203	425257	BD-2222	41060-50Y94	BD-5110
34116767191	BD-1415	3C0698151D	BD-1203	425258	BD-2204	41060-63C90	BD-5110
34116769099	BD-1409	3C0698451	BD-1204	425259	BD-2201	41060-6F625	BD-5738
34116769099	BD-1414	3C0698451A	BD-1204	425260	BD-2206	41060-72J25	BD-5740
34116769100	BD-1409	3C0698451C	BD-1204	425274	BD-2222	41060-89E90	BD-5701
34116771868	BD-1409	3C0698451E	BD-8030	425287	BD-2207	41060-99B25	BD-5738
34116776161	BD-1415	3M51-2K021-AB	BD-3001	425288	BD-2208	41060-9C125	BD-3028
34116778048	BD-1418	415188	BD-2219	425289	BD-2209	41060-9C525	BD-3028
34116778403	BD-1417	425104	BD-2222	425290	BD-2210	41060-9C526	BD-3028
34116779293	BD-1417	425109	BD-2214	425306	BD-2219	41060-AR090	BD-5725
34116799166	BD-1414	425110	BD-2214	425322	BD-2211	41060-BM525	BD-5713
34119058982	BD-1404	425111	BD-2218	425323	BD-2206	41060-CC090	BD-5725
34119058989	BD-1404	425112	BD-2218	425325	BD-2211	41060-CG00J	BD-5737
34119070047	BD-1406	425116	BD-2808	425334	BD-2210	41060-CG090	BD-5737
34211154221	BD-1412	425117	BD-2808	425343	BD-2206	41060-VB290	BD-5715
34211154221	BD-1412	425118	BD-2810	425344	BD-2206	41060-VC290	BD-5715
34211158270	BD-1412	425119	BD-2810	425345	BD-2204	41060-VH385	BD-5704
34211160533	BD-1407	425125	BD-2213	425346	BD-2208	4144200120	BD-5310
34211161455	BD-1407	425126	BD-2213	425369	BD-2204	4144200220	BD-5345
34211162447	BD-1407	425132	BD-2221	425372	BD-2205	4241J1	BS-6301
34214398213	BD-6501	425134	BD-2219	425384	BD-2204	425037	BD-6104
34216750190	BD-6501	425139	BD-2219	425396	BD-1206	425070	BD-6301
34211153913	BD-1405	425142	BD-2219	425398	BD-2211	425077	BD-6104
34211154398	BD-1405	425143	BD-2221	425399	BD-2211	425082	BD-6104
34211154399	BD-1405	425144	BD-2221	425418	BD-2202	425088	BD-6105









<b>LYNX №</b>	<b>APPLICATION</b>
<b>BD-1201</b>	AUDI 80/90, VW Passat
<b>BD-1202</b>	AUDI A3, SKODA Octavia, SEAT Leon/Toledo, VW Beetle/Bora/Caddy/Golf
<b>BD-1203</b>	AUDI A3, VW Golf V/Jetta V/Passat B6, SKODA Octavia/Superb
<b>BD-1204</b>	AUDI A3/A4, SKODA Octavia/Superb, VW Golf/Passat/Touran
<b>BD-1205</b>	AUDI 80/A4, CHERY Tiggo, SEAT Ibiza/Inca/Toledo, VW Caddy/Corrado/Golf/Passat
<b>BD-1206</b>	AUDI A3/A4/A6/A8, RENAULT Avantime/Megane/Scenic, PEUGEOT 307, SEAT Alhambra/Cordoba/Ibiza/Leon, SKODA Octavia, VW Bora/Golf/Passat
<b>BD-1207</b>	AUDI 80/90/100/200
<b>BD-1208</b>	AUDI 80/90/100/200/A4/A6/A8/S6/V8
<b>BD-1209</b>	AUDI 100/A6
<b>BD-1210</b>	AUDI 100 Quattro/A6/A8
<b>BD-1211</b>	AUDI A2, VW Lupo
<b>BD-1212</b>	AUDI A3, SEAT Toledo, VW Bora/Golf
<b>BD-1213</b>	AUDI A3/A4, SEAT Leon/Toledo, VW Bora/Golf/Passat, VOLVO V70
<b>BD-1213</b>	AUDI A3/A4, VW Bora/Golf/Passat
<b>BD-1214</b>	AUDI A4, VW Passat
<b>BD-1215</b>	AUDI A4, VW Passat
<b>BD-1216</b>	AUDI A4/A6, FORD Galaxy, SEAT Leon, SKODA Superb, VW Passat
<b>BD-1217</b>	AUDI A4/A6/A8
<b>BD-1218</b>	AUDI A6/S6 Quattro
<b>BD-1219</b>	AUDI A4 / Q5
<b>BD-1220</b>	AUDI A4/A5
<b>BD-1221</b>	AUDI A4
<b>BD-1222</b>	VW Phaeton
<b>BD-1223</b>	AUDI A4 / Q5
<b>BD-1224</b>	AUDI A8
<b>BD-1401</b>	BMW 530/540/740/X5
<b>BD-1402</b>	DAEWOO Aranos/Espero/Nexia, OPEL Astra/Calibra/Kadett/Omega/Vectra
<b>BD-1403</b>	BMW 325/330/540/725/730/735/740/750/X3
<b>BD-1403</b>	BMW 7 (E38)/X3/X5, LAND ROVER
<b>BD-1404</b>	BMW 316/318/320/324/325, MERCEDES-BENZ 190
<b>BD-1405</b>	BMW 316/318/320/323/324/325/518/520/524/525/528/535/628/635
<b>BD-1406</b>	BMW 316/318/320/323/325/328/Z3
<b>BD-1407</b>	BMW 316/318/320/323/325/328/Z3
<b>BD-1408</b>	BMW 316/318/320/323/325/328/Z3
<b>BD-1410</b>	BMW 325/330/520/523/525/528/530/535/X3
<b>BD-1411</b>	BMW 518/520/524/525/530/535/540/735/740/750/M3/M5
<b>BD-1412</b>	BMW 518/520/524/525/530/535/540/730/735/740/750/M5
<b>BD-1413</b>	BMW 520/523/525/528/530/535/540
<b>BD-1414</b>	BMW 318/320/325/330/520/523/525
<b>BD-1415</b>	BMW 530/540/545/730/735/740/745
<b>BD-1416</b>	BMW 7 (E38)
<b>BD-1417</b>	BMW X5 (E70)
<b>BD-1418</b>	BMW X5 (E70)
<b>BD-1419</b>	BMW 5 (E60)
<b>BD-1420</b>	BMW 3 series
<b>BD-1421</b>	BMW 3 series
<b>BD-1422</b>	BMW 3 series
<b>BD-1423</b>	BMW 3 series
<b>BD-1424</b>	BMW 5 series
<b>BD-1425</b>	BMW 5 series
<b>BD-1426</b>	BMW 7 series
<b>BD-1427</b>	BMW X3
<b>BD-1428</b>	BMW X5
<b>BD-1429</b>	BMW 1 series
<b>BD-1430</b>	BMW 1 series
<b>BD-1801</b>	CHEVROLET Lanos/Spark, DAEWOO Lanos/Matiz/Nexia
<b>BD-1802</b>	DAEWOO Nubira/Leganza
<b>BD-1803</b>	CHEVROLET Aveo
<b>BD-1804</b>	CHEVROLET Epica
<b>BD-1805</b>	CHEVROLET Lacetti, DAEWOO Lanos/Leganza/Espero/Nexia/Nubira
<b>BD-1805</b>	CHEVROLET Lacetti
<b>BD-1807</b>	CHEVROLET Lacetti
<b>BD-1808</b>	CHEVROLET Epica
<b>BD-1809</b>	DAEWOO Tico
<b>BD-1810</b>	CHEVROLET Cruze, OPEL Astra J
<b>BD-1811</b>	CHEVROLET Cruze, OPEL Astra J
<b>BD-2201</b>	CITROEN C4/Berlingo/Xsara/Xsara Picasso, PEUGEOT 206/207/307/1007/Partner
<b>BD-2202</b>	CITROEN C4, PEUGEOT 207/307
<b>BD-2203</b>	CITROEN Berlingo/Xsara, PEUGEOT 306/Partner

## • Применяемость



LYNX №	APPLICATION
BD-2204	CITROEN C3
BD-2205	CITROEN C3
BD-2206	CITROEN C4
BD-2207	CITROEN C5
BD-2208	CITROEN C5
BD-2209	CITROEN C5
BD-2210	CITROEN C5
BD-2211	CITROEN C4
BD-2212	CITROEN C8, PEUGEOT 807
BD-2213	CITROEN Dispatch/Jumpy, FIAT Scudo/Ulysse, PEUGEOT 806/Expert
BD-2214	CITROEN Evasion/Synergie, FIAT Scudo/Ulysse, PEUGEOT 806/Expert
BD-2215	CITROEN Jumper, FIAT Ducato, PEUGEOT Boxer
BD-2216	CITROEN Jumper/Relay, FIAT Ducato, PEUGEOT Boxer
BD-2217	CITROEN Jumper, FIAT Ducato, PEUGEOT Boxer
BD-2218	CITROEN Evasion/Synergie, FIAT Ulysse, PEUGEOT 806
BD-2219	CITROEN Saxo/Xsara, PEUGEOT 106/306
BD-2220	CITROEN Xsara, PEUGEOT 206/306
BD-2221	CITROEN Xsara, PEUGEOT 306/406/607
BD-2222	CITROEN Xsara/ZX, PEUGEOT 205/206/306, RENAULT 5/9/19
BD-2223	CITROEN C4
BD-2224	CITROEN C5
BD-2402	DAIHATSU Charade/Gran Move
BD-2404	DAIHATSU Charade/Gran Move, FORD Capri, MAZDA 323/MX3
BD-2800	FIAT Bravo/Stilo
BD-2801	FIAT Brava/Bravo/Marea, LANCIA Delta
BD-2802	ALFA ROMEO 145/146, FIAT Barchetta/Brava/Bravo/Marea, LANCIA Dedra/Delta
BD-2803	ALFA ROMEO 145/146/147/156, FIAT Bravo/Marea, LANCIA Dedra/Delta/Lybra
BD-2804	FIAT Croma, LANCIA Dedra/Kappa
BD-2805	ALFA ROMEO 145/146/155, FIAT Argenta/Panda/Punto/Regata/Ritmo/Tempra/Tipo/Uno, LANCIA Dedra/Delta
BD-2806	FIAT Croma, LANCIA Thema
BD-2807	FIAT Doblo/Palio Weekend/Punto/Strada Pickup
BD-2808	CITROEN Jumper, FIAT Ducato, PEUGEOT Boxer
BD-2809	CITROEN Jumper, FIAT Ducato, PEUGEOT Boxer
BD-2810	CITROEN Jumper, FIAT Ducato, PEUGEOT Boxer
BD-2812	FIAT Stilo
BD-2813	FIAT Marea
BD-2814	FIAT Palio Weekend
BD-2815	FIAT Panda
BD-2816	FIAT Panda/Punto/Seicento
BD-2817	FIAT 131 Mirafiori/Panda/Regata/Ritmo/Uno, SEAT Ibiza/Malaga/Marbella/Ronda
BD-2818	ALFA ROMEO 146/155/Spider, FIAT Barchetta/Brava/Bravo/Marea/Punto/Tempra/Tipo/Uno, LANCIA Dedra/Delta
BD-2819	ALFA ROMEO 145/146/GTV/Spider, FIAT Bravo, LANCIA Dedra/Delta
BD-2820	ALFA ROMEO 164, FIAT Croma, LANCIA Delta/Thema
BD-2821	FIAT Multipla/Stilo
BD-2822	ALFA ROMEO 166, LANCIA Kappa
BD-2823	ALFA ROMEO 166, LANCIA Kappa
BD-2824	ALFA ROMEO 156/166, LANCIA Kappa
BD-2825	ALFA ROMEO 147/156, LANCIA Lybra
BD-2826	LANCIA Thesis
BD-2827	ALFA ROMEO 147, LANCIA Lybra
BD-2829	FIAT Ducato, PEUGEOT Boxer
BD-2830	CITROEN Jumper, FIAT Ducato, PEUGEOT Boxer
BD-3001	FORD C-Max/Focus II/Kuga, MAZDA 3/5, VOLVO S40
BD-3002	FORD Transit
BD-3003	FORD Transit
BD-3004	FORD Galaxy/Mondeo/S-Max, LAND ROVER Freelander, VOLVO S80
BD-3005	FORD Galaxy/Mondeo/S-Max, VOLVO S80
BD-3006	FORD Mondeo, JAGUAR X-Type
BD-3007	FORD Mondeo, JAGUAR X-Type
BD-3008	FORD Mondeo
BD-3009	FORD Focus
BD-3010	FORD Focus
BD-3011	FORD Cougar/Mondeo/Scorpio
BD-3012	FORD Cougar/Mondeo/Scorpio
BD-3013	FORD Mondeo/Scorpio
BD-3014	FORD Cougar/Mondeo
BD-3014	FORD Mondeo
BD-3015	FORD Escort/Orion
BD-3016	FORD Escort



<b>LYNX №</b>	<b>APPLICATION</b>
<b>BD-3017</b>	FORD Escort/Sierra/Scorpio
<b>BD-3018</b>	FORD Escort/Orion, KIA Sephia
<b>BD-3019</b>	FORD Fiesta/Puma
<b>BD-3020</b>	FORD Fiesta/Ka, MAZDA 121
<b>BD-3021</b>	FORD Fiesta/KA
<b>BD-3022</b>	FORD Tourneo Connect/Transit
<b>BD-3023</b>	FORD Galaxy, SEAT Alhambra, VW Sharan
<b>BD-3024</b>	FORD Galaxy, SEAT Alhambra, VW Sharan
<b>BD-3025</b>	FORD Galaxy, SEAT Alhambra, VW Sharan
<b>BD-3026</b>	FORD Galaxy, SEAT Alhambra, VW Sharan
<b>BD-3027</b>	FORD Galaxy, SEAT Alhambra, VW Sharan
<b>BD-3028</b>	FORD Maverick, NISSAN Serena/Terrano
<b>BD-3029</b>	FORD Probe, MAZDA 626/MX6/Xedos
<b>BD-3030</b>	FORD Escort/Granada/Sierra/Scorpio
<b>BD-3032</b>	FORD Transit
<b>BD-3033</b>	FORD Transit
<b>BD-3034</b>	FORD Transit
<b>BD-3401</b>	HONDA Civic 4D
<b>BD-3402</b>	HONDA Accord/Civic/ Legend/Prelude, ROVER 618/620/623
<b>BD-3403</b>	HONDA Civic
<b>BD-3404</b>	HONDA CR-V
<b>BD-3405</b>	Acura Legend/NSX, HONDA Accord/Civic/CR-V/HR-V/Legend/Prelude/Shuttle, ROVER 620/623
<b>BD-3406</b>	HONDA Civic/CRX
<b>BD-3407</b>	HONDA Civic/Jazz
<b>BD-3408</b>	HONDA Civic/S2000
<b>BD-3409</b>	NISSAN Almera Classic
<b>BD-3412</b>	HONDA Civic
<b>BD-3413</b>	HONDA Accord VIII
<b>BD-3418</b>	HONDA CR-V III
<b>BD-3420</b>	HONDA Accord
<b>BD-3421</b>	HONDA Accord/Prelude, ROVER 618/620
<b>BD-3422</b>	HONDA Accord, NISSAN Primera
<b>BD-3423</b>	HONDA Accord IX
<b>BD-3424</b>	HONDA Accord IX
<b>BD-3425</b>	HONDA Accord
<b>BD-3426</b>	HONDA Civic/Concerto, MG ZR/ZS, ROVER 25/45/214/216/218/220/418/420/825
<b>BD-3427</b>	HONDA Civic 5D
<b>BD-3428</b>	HONDA Civic/Concerto/Prelude, ROVER
<b>BD-3429</b>	HONDA Legend/Prelude
<b>BD-3431</b>	HONDA Accord
<b>BD-3601</b>	HYUNDAI Accent/Excel/Getz/Pony/S-Coupe/Santa-Fe
<b>BD-3602</b>	HYUNDAI Sonata/NF/Tucson, KIA Magentis
<b>BD-3604</b>	HYUNDAI H100/H150/Satellite
<b>BD-3605</b>	HYUNDAI Getz/Elantra/Sonata/Santa Fe/Tucson, KIA Magentis/Sportage
<b>BD-3606</b>	HYUNDAI Terracan
<b>BD-3607</b>	HYUNDAI Coupe/Elantra/Lantra/Sonata/Tiburon
<b>BD-3608</b>	HYUNDAI Accent, KIA Rio
<b>BD-3610</b>	HYUNDAI Elantra
<b>BD-3611</b>	HYUNDAI Elantra/Matrix
<b>BD-3612</b>	HYUNDAI Elantra, KIA Cerato, NISSAN Maxima
<b>BD-3613</b>	HYUNDAI H1/Satellite/Starex
<b>BD-3614</b>	HYUNDAI Santa-Fe, SSANGYONG Kyron
<b>BD-3615</b>	HYUNDAI Santa-Fe, KIA Sorento
<b>BD-3616</b>	HYUNDAI Santa-Fe
<b>BD-3617</b>	HYUNDAI Terracan
<b>BD-3618</b>	HYUNDAI Sonata
<b>BD-3619</b>	HYUNDAI Solaris, KIA Rio
<b>BD-3620</b>	HYUNDAI Solaris, KIA Rio
<b>BD-3623</b>	HYUNDAI Santa Fe, KIA Sorento
<b>BD-3802</b>	ISUZU Trooper, OPEL Frontera/Monterey
<b>BD-3803</b>	GREAT WALL Hover, ISUZU Trooper, OPEL Frontera
<b>BD-3804</b>	GREAT WALL Hover
<b>BD-4200</b>	JEEP Cherokee/Grand Cherokee/Wrangler, KIA Carnival/Sedona
<b>BD-4201</b>	JEEP Grand Cherokee
<b>BD-4202</b>	JEEP Grand Cherokee
<b>BD-4203</b>	JEEP Grand Cherokee
<b>BD-4401</b>	KIA Credos/Shuma/Spectra
<b>BD-4402</b>	KIA Cerato
<b>BD-4403</b>	KIA Clarus/Rio/Shuma/Spectra

## • Применяемость



LYNX №	APPLICATION
BD-4404	KIA Cee'd/Cerato, HYUNDAI i30
BD-4405	KIA
BD-4406	KIA Carnival/Sedona
BD-4407	KIA Cee'd/Rio II, HYUNDAI Accent/i30
BD-4408	KIA Clarus/Credos
BD-4409	KIA Picanto
BD-4410	HONDA Pride, MAZDA 121
BD-4411	KIA Sorento
BD-4413	KIA Sorento
BD-4414	KIA Sportage
BD-4415	KIA Shuma
BD-4601	LADA 2110-2115 / 1117-1119 / 2170
BD-4602	CHEVROLET Niva, LADA 2121/21213
BD-4603	LADA 2101-2107
BD-4605	ISH Oda, LADA Samara
BD-5000	LAND ROVER Defender 90/Discovery/Range Rover
BD-5001	LAND ROVER Defender 90/110
BD-5002	LAND ROVER Discovery/Range Rover
BD-5003	LAND ROVER
BD-5004	LAND ROVER
BD-5005	LAND ROVER FreeLANDer
BD-5006	LAND ROVER Defender 90/Discovery/Range Rover
BD-5008	LAND ROVER Range Rover
BD-5009	LAND ROVER Range Rover
BD-5101	FORD Probe, MAZDA 626/Xedos
BD-5101	MAZDA 323/626/Premacy
BD-5102	SUZUKI Grand Vitara/Vitara
BD-5103	MAZDA 323
BD-5104	MAZDA 323/626/6/Premacy
BD-5105	MAZDA 121/323, KIA Rio
BD-5108	FORD Fiesta/Fusion/Puma, MAZDA 2/Demio
BD-5110	NISSAN 100NX/Sunny
BD-5111	MAZDA 6
BD-5112	MAZDA 6
BD-5113	MAZDA E/MPV
BD-5114	MAZDA Xedos 9
BD-5115	FORD Maverick, MAZDA Tribute
BD-5116	MAZDA CX-7
BD-5118	MAZDA 6 (07-)
BD-5119	MAZDA 626
BD-5120	MAZDA 323/MX-3
BD-5121	MAZDA 929/MPV/Xedos
BD-5122	MAZDA MX-5
BD-5123	MAZDA 2 (DE)
BD-5124	MAZDA CX-7
BD-5301	MERCEDES-BENZ 190/E-Class (W201/W124/S124/C124)
BD-5302	MERCEDES-BENZ C-Class/CLK-Class/E-Class/SLK-Class (W202/S202/G208/W210/S210/R170)
BD-5303	MERCEDES-BENZ C-Class (W202/S202)
BD-5304	MERCEDES-BENZ 190 (W201)
BD-5305	MERCEDES-BENZ 190/E-Class/SL-Class (W201/W124/S124/C124/W210/R129)
BD-5306	MERCEDES-BENZ A-Class (W168)
BD-5307	MERCEDES-BENZ A-Class
BD-5308	MERCEDES-BENZ A-Class/B-Class
BD-5309	MERCEDES-BENZ B-Class
BD-5310	MERCEDES-BENZ A-Class/Vaneo (W168/W414)
BD-5311	MERCEDES-BENZ 190/C-Class/E-Class (W201/W202/W124/C124)
BD-5312	MERCEDES-BENZ 190/C-Class/E-Class (W201/W202/W124/C124)
BD-5313	MERCEDES-BENZ C-Class (W202)
BD-5314	MERCEDES-BENZ 190/C-Class/E-Class (W201/W202/S202/W124/S124/C124)
BD-5315	MERCEDES-BENZ C-Class/CLK-Class/E-Class/SLK-Class (W202/S202/W203/CL203/C208/C209/W210)
BD-5316	MERCEDES-BENZ S-Class/C-Class/E-Class/CLK-Class/SL-Class (W140/C140/C202/C203/C208/W210)
BD-5317	MERCEDES-BENZ C-Class/CLK-Class (W203/CL203/S203/C209)
BD-5318	MERCEDES-BENZ C-Class
BD-5319	MERCEDES-BENZ C-Class
BD-5320	MERCEDES-BENZ E-Class/CLK-Class (W210/S210/C208)
BD-5321	MERCEDES-BENZ E-Class(W210)
BD-5322	MERCEDES-BENZ 190 (W201)
BD-5323	MERCEDES-BENZ E-Class (W211/S211)
BD-5324	MERCEDES-BENZ E-Class/S-Class (W211/W220)





<b>LYNX №</b>	<b>APPLICATION</b>
<b>BD-5325</b>	MERCEDES-BENZ E-Class (W211/S211/W212)
<b>BD-5326</b>	MERCEDES-BENZ M-Class (W163)
<b>BD-5327</b>	MERCEDES-BENZ M-Class/S-Class/SL-Class (W163/W220/R129)
<b>BD-5328</b>	MERCEDES-BENZ ML
<b>BD-5329</b>	MERCEDES-BENZ ML
<b>BD-5330</b>	MERCEDES-BENZ ML
<b>BD-5331</b>	MERCEDES-BENZ GL
<b>BD-5332</b>	MERCEDES-BENZ ML
<b>BD-5333</b>	MERCEDES-BENZ (W140)
<b>BD-5334</b>	MERCEDES-BENZ S-Class (W220)
<b>BD-5335</b>	MERCEDES-BENZ G-Class, VW LT
<b>BD-5336</b>	MERCEDES-BENZ G-Class (W460/W463), MB100
<b>BD-5337</b>	MERCEDES-BENZ Sprinter/Vito
<b>BD-5338</b>	MERCEDES-BENZ Sprinter, VW LT
<b>BD-5339</b>	MERCEDES-BENZ Vito/V-Class
<b>BD-5340</b>	MERCEDES-BENZ G-Class/Sprinter, VW LT
<b>BD-5341</b>	MERCEDES-BENZ Sprinter
<b>BD-5342</b>	MERCEDES-BENZ Sprinter
<b>BD-5343</b>	MERCEDES-BENZ Sprinter
<b>BD-5344</b>	MERCEDES-BENZ Sprinter
<b>BD-5345</b>	MERCEDES-BENZ Vaneo
<b>BD-5346</b>	MERCEDES-BENZ Vito/V-Class
<b>BD-5347</b>	MERCEDES-BENZ Vito/V-Class
<b>BD-5348</b>	MERCEDES-BENZ Viano
<b>BD-5349</b>	MERCEDES-BENZ W221
<b>BD-5350</b>	MERCEDES-BENZ E-Class (W212)
<b>BD-5501</b>	MAZDA Challenger/Eclipse/Galant/Montero/Outlander/Pajero/Space, PEUGEOT 4007, CITROEN C-Crosser
<b>BD-5502</b>	MAZDA Montero/Pajero/Shogun/Sigma/Space
<b>BD-5503</b>	MAZDA Lancer
<b>BD-5504</b>	MAZDA Galant/Lancer IX-X/Outlander
<b>BD-5505</b>	MAZDA Lancer/Outlander
<b>BD-5507</b>	MAZDA Pajero/Outlander XL, PEUGEOT 4007, CITROEN C-Crosser
<b>BD-5508</b>	CHRYSLER Sebring, MITSUBISHI Eclipse/Galant/Pajero/Sapporo/Space
<b>BD-5509</b>	HYUNDAI Santamo, MITSUBISHI Colt/Eclipse/Galant/Lancer/Santamo/Space
<b>BD-5511</b>	MAZDA Pajero
<b>BD-5512</b>	MAZDA Pajero Pinin
<b>BD-5516</b>	MAZDA Carisma/Colt/Lancer, Proton
<b>BD-5520</b>	MAZDA L200/L300/L400
<b>BD-5521</b>	MAZDA Carisma
<b>BD-5522</b>	MAZDA Carisma, VOLVO S40/V40
<b>BD-5523</b>	MAZDA Carisma/Space Star, VOLVO S40/V40
<b>BD-5524</b>	MAZDA Colt/Lancer, Proton
<b>BD-5525</b>	MAZDA Colt
<b>BD-5526</b>	MAZDA Carisma/Space Star, VOLVO S40/V40
<b>BD-5529</b>	MAZDA L200/Pajero Sport
<b>BD-5701</b>	NISSAN 200SX/Maxima
<b>BD-5702</b>	NISSAN Almera/Maxima/Primera/Sunny
<b>BD-5703</b>	NISSAN Almera
<b>BD-5704</b>	NISSAN X-Trail
<b>BD-5705</b>	NISSAN Maxima QX
<b>BD-5706</b>	NISSAN Qashqai/X-Trail, SUZUKI Grand Vitara
<b>BD-5708</b>	NISSAN Prairie/Primera, SSANGYONG Rexton, HYUNDAI Coupe/Elantra/Sonata/Tiburon
<b>BD-5710</b>	NISSAN Almera
<b>BD-5711</b>	NISSAN Qashqai/X-Trail
<b>BD-5713</b>	NISSAN Almera/Primera
<b>BD-5715</b>	NISSAN Patrol GR
<b>BD-5718</b>	NISSAN Almera
<b>BD-5725</b>	NISSAN Murano
<b>BD-5735</b>	NISSAN Almera/Primera
<b>BD-5736</b>	NISSAN Almera/Primera
<b>BD-5737</b>	INFINITI FX, NISSAN Maxima
<b>BD-5738</b>	NISSAN Micra
<b>BD-5739</b>	NISSAN Micra/Note/Tiida, RENAULT Clio, SUZUKI Swift
<b>BD-5740</b>	NISSAN Primera
<b>BD-5741</b>	NISSAN Pathfinder
<b>BD-5742</b>	INFINITI FX
<b>BD-5743</b>	INFINITI FX
<b>BD-5901</b>	FORD C-Max/Focus II, MAZDA 3/5, VOLVO S40
<b>BD-5902</b>	OPEL Omega/Vectra, SAAB 900/9-3/9-5

## • Применяемость



LYNX №	APPLICATION
BD-5903	DAEWOO Lanos/Nexia, OPEL Astra/Corsa/Tigra/Vectra
BD-5904	OPEL Astra/Zafira
BD-5905	DAEWOO Nexia, OPEL Ascona/Corsa/Kadett/Omega/Rekord/Vectra
BD-5906	OPEL Agila, SUZUKI Wagon R+
BD-5907	OPEL Astra G
BD-5908	OPEL Astra H
BD-5909	OPEL Astra/Calibra/Kadet, SAAB 900
BD-5910	OPEL AstraG/Zafira
BD-5911	OPEL Astra/Meriva/Zafira
BD-5912	ISUZU Rodeo, SAAB 9-3/9-5
BD-5913	OPEL Calibra/Omega/Vectra, SAAB 900
BD-5914	OPEL Calibra/Vectra, SAAB 900
BD-5915	OPEL Combo/Corsa
BD-5916	OPEL Corsa D
BD-5917	OPEL Corsa D
BD-5918	ISUZU Campo/Trooper, OPEL Campo/Frontera
BD-5919	OPEL Frontera
BD-5920	OPEL Movano, RENAULT Master
BD-5921	OPEL Movano, RENAULT Master
BD-5922	OPEL Omega
BD-5923	OPEL Vectra/Zafira, SAAB 9-3
BD-5924	OPEL Sintra
BD-6101	PEUGEOT 407
BD-6102	PEUGEOT 308
BD-6103	PEUGEOT 107, TOYOTA Aygo
BD-6104	PEUGEOT 205/309
BD-6105	PEUGEOT 106/205/305/309/405, RENAULT 5/9/11/18/19/21/Clio/Express/Fuego
BD-6106	PEUGEOT 206/306
BD-6107	PEUGEOT 306
BD-6108	PEUGEOT 406
BD-6109	PEUGEOT 406/607
BD-6110	PEUGEOT 407
BD-6111	PEUGEOT 407
BD-6112	PEUGEOT 605
BD-6301	RENAULT 5/9/11/18/19/21/25/Clio/Espace/Express/Extra/Fuego/Logan/Megane/Scenic
BD-6302	NISSAN Primera, OPEL Vectra, RENAULT Laguna, SAAB 9-3
BD-6302	NISSAN Primera, OPEL Vectra, RENAULT Laguna, SAAB 9-3
BD-6303	NISSAN Primastar, OPEL Vivaro, RENAULT Avantime/Espace/Trafic
BD-6304	RENAULT Clio II/Megane/Megane Grandtour/Scenic/Safrane
BD-6305	RENAULT R19/Clio/Megane
BD-6306	RENAULT Clio
BD-6307	RENAULT Espace
BD-6308	RENAULT R21/Espace/Laguna/Safrane
BD-6309	RENAULT Kangoo
BD-6310	RENAULT Laguna/Megane/Safrane
BD-6311	RENAULT Laguna
BD-6312	RENAULT Laguna
BD-6313	RENAULT Laguna
BD-6314	RENAULT Megane/Megane II/Scenic II
BD-6315	RENAULT Megane II
BD-6316	RENAULT Megane
BD-6317	RENAULT Fluence / Megane III
BD-6500	MG, ROVER 75
BD-6501	BMW 318/320/323/325/328, ROVER 75, SAAB 9-5
BD-6700	SAAB 900/9000
BD-6701	SAAB 900/9000
BD-6702	SAAB 9-3
BD-6900	FORD Sierra, SKODA Favorit/Forman/Felicia
BD-7000	SSANGYONG Actyon/Kyron
BD-7101	SUBARU Forester
BD-7102	SUBARU Legacy IV
BD-7103	SUBARU Legacy IV/Outback
BD-7104	SUBARU Forester/Impreza
BD-7105	SUBARU Impreza/Legacy
BD-7106	SUBARU Forester/Legacy III-IV
BD-7107	SUBARU Impreza II
BD-7108	SUBARU Impreza
BD-7109	SUBARU Impreza/Legacy
BD-7111	SUBARU Outback/Legacy



<b>LYNX №</b>	<b>APPLICATION</b>
BD-7112	SUBARU Impreza/Legacy
BD-7302	SUZUKI Grand Vitara
BD-7304	SUZUKI Jimny/Samurai
BD-7304	SUZUKI Jimny
BD-7310	SUZUKI Baleno
BD-7311	SUZUKI Liana
BD-7313	SUZUKI SX4
BD-7501	TOYOTA Hi-Lux/Land Cruiser, VW Taro
BD-7503	TOYOTA Land Cruiser 100
BD-7504	TOYOTA Land Cruiser
BD-7505	TOYOTA Land Cruiser
BD-7506	LEXUS RX300
BD-7507	TOYOTA Celica/Corolla Verso
BD-7508	TOYOTA Dyna/Hiace
BD-7510	CHERY Tiggo, TOYOTA RAV4
BD-7511	TOYOTA RAV-4
BD-7516	TOYOTA Camry/Carina/Celica/Corolla/Picnic/RAV 4
BD-7517	TOYOTA Camry
BD-7518	LEXUS GS/IS
BD-7519	TOYOTA Yaris
BD-7520	LEXUS LS/SC, TOYOTA Camry/Celica
BD-7521	TOYOTA Camry/Carina/Celica/Corolla/Corona
BD-7522	TOYOTA Camry
BD-7523	TOYOTA Camry
BD-7524	LEXUS GS, TOYOTA Supra
BD-7525	LEXUS RX300
BD-7526	TOYOTA Corolla Verso/Prius/Yaris/Yaris Verso
BD-7527	TOYOTA Land Cruiser 100
BD-7529	TOYOTA Camry
BD-7530	TOYOTA Camry
BD-7531	TOYOTA Avensis Verso
BD-7532	TOYOTA Camry (V40)/RAV4
BD-7533	TOYOTA Camry/Carina/Celica/Corolla/MR2/Paseo/Starlet/Tercel
BD-7534	LEXUS RX300/RX350
BD-7538	TOYOTA Corolla/Celica/Yaris
BD-7539	TOYOTA Avensis/Corolla Verso
BD-7540	TOYOTA Corolla/Corolla Verso
BD-7541	TOYOTA Corolla/Corolla Verso
BD-7542	TOYOTA Auris/Corolla
BD-7543	TOYOTA Auris/Corolla
BD-7544	LEXUS GS/IS
BD-7545	TOYOTA Avensis/Avensis Verso
BD-7546	TOYOTA Auris/Corolla
BD-7547	TOYOTA Auris/Corolla
BD-7548	TOYOTA Avensis/Corolla Verso
BD-7549	TOYOTA Land Cruiser
BD-7558	TOYOTA Avensis
BD-7566	LEXUS GS
BD-7572	TOYOTA RAV-4
BD-7574	TOYOTA Avensis Verso/Previa
BD-7580	TOYOTA Land Cruiser (J200)
BD-7581	TOYOTA Land Cruiser (J200)
BD-7589	LEXUS IS
BD-7590	TOYOTA Avensis
BD-7591	TOYOTA Camry/Carina/Celica
BD-7592	TOYOTA Corolla
BD-7593	TOYOTA Yaris
BD-7594	TOYOTA Yaris
BD-7596	LEXUS RX
BD-7597	LEXUS RX
BD-7598	TOYOTA Avensis (T27)
BD-7599	TOYOTA Avensis (T27)
BD-7800	VOLVO 240
BD-7801	VOLVO 240/740/940
BD-7802	VOLVO 240/740/850/940/C70/S70/V70
BD-7803	VOLVO 440/460/480
BD-7804	VOLVO 440/460/480
BD-7805	VOLVO 440/460/480
BD-7806	VOLVO 740/760/940/960

## • Применяемость



LYNX №	APPLICATION
BD-7807	VOLVO 740/760/940/960
BD-7808	VOLVO 940/960/S90/V90
BD-7809	VOLVO 740/760/940/960/V70/S90/V90
BD-7810	VOLVO 850/C70/S70/V70
BD-7811	VOLVO S60/V70/XC70/S80/XC90
BD-7812	VOLVO S60/V70/XC70/S80
BD-7813	SKODA Superb, VOLVO C70/S70/V70
BD-7814	VOLVO XC90
BD-7815	VOLVO XC90
BD-7816	VOLVO XC70
BD-7817	VOLVO XC70
BD-8001	VW Multivan/Transporter T5
BD-8002	AUDI A3/A4/A6/A8, FORD Galaxy, PEUGEOT 307, SEAT Alhambra/Cordoba/Ibiza/Leon, SKODA Octavia, VW Bora/Golf/Passat
BD-8003	AUDI A3, SEAT Toledo, SKODA Fabia/Octavia, VW Beetle/Bora/Golf
BD-8003	AUDI A3, SKODA Fabia/Octavia, SEAT Ibiza/Leon/Toledo, VW Bora/Golf
BD-8004	SEAT Cordoba/Ibiza/Toledo, VW Caddy/Golf/Jetta/Passat/Santana/Scirocco/Vento
BD-8005	VW Touareg
BD-8006	VW Touareg
BD-8007	VW Touareg, PORSCHE Cayenne
BD-8008	SEAT Arosa, SKODA Fabia, VW Lupo/Polo
BD-8009	SEAT Arosa/Cordoba/Ibiza/Inca, VW Caddy/Golf/Lupo/Polo
BD-8010	SEAT Cordoba, VW Polo
BD-8011	SEAT Cordoba/Ibiza, VW Golf/Polo
BD-8012	SEAT Cordoba/Ibiza, VW Golf/Polo/Jetta/Passat
BD-8013	SEAT Cordoba/Ibiza/Toledo, VW Golf/Polo/Vento
BD-8014	SEAT Cordoba/Corrado/Ibiza/Inca/Toledo, VW Caddy/Corrado/Golf/Jetta/Passat/Scirocco/Vento
BD-8015	SEAT Ibiza, SKODA Fabia, VW Polo
BD-8016	VW Passat
BD-8017	VW Polo
BD-8018	VW Sharan
BD-8019	VW Touareg
BD-8021	VW Caravelle/Multivan/Transporter
BD-8022	VW Caravelle/Multivan/Transporter
BD-8023	VW Caravelle/Multivan/Transporter
BD-8024	VW Caravelle/Multivan/Transporter
BD-8025	VW Caravelle/Multivan/Transporter
BD-8026	VW Caravelle/Transporter
BD-8027	VW Caravelle/Transporter
BD-8028	VW Touareg (7P5)
BD-8029	VW Touareg (7P5)
BD-8030	VW Passat B6 (3C2) / Tiguan
BD-8032	VW Transporter T5
BD-8033	VW Transporter T5
BD-8034	VW Transporter T5
BD-8035	VW Polo
BD-8037	VW Polo
BD-8038	VW Tiguan
BS-1800	DAEWOO Espero/Nexia, CHEVROLET Lanos, OPEL Astra F
BS-1801	DAEWOO Matiz
BS-3000	FORD Focus
BS-3001	FORD Fusion/Fiesta, MAZDA 2
BS-3600	HYUNDAI Getz
BS-3601	HYUNDAI Accent
BS-3602	KIA Rio
BS-4400	KIA Shuma/Spectra
BS-4601	LADA 2108-2115/1117-1119 Kalina
BS-4602	LADA 2101-2107
BS-6300	RENAULT Clio/Logan
BS-6301	RENAULT Clio, PEUGEOT 206
BS-7501	TOYOTA Yaris
BS-8001	VW Polo